

2023 ODAV Pavement Evaluation Program Cape Blanco State Airport

Sixes, Oregon

December 29, 2023

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY	1
3	PAVEMENT CONDITION INSPECTION RESULTS	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results	5
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	8
	4.1 Introduction.....	8
	4.2 Future Condition Analysis	8
	4.3 Functional Remaining Life.....	8
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	10
	5.1 Introduction.....	10
	5.2 Recommended Localized Maintenance.....	10
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan.....	10
6	LIMITATIONS.....	12

TABLES

Table 3-1:	ASTM PCI Rating Scale.....	5
Table 5-1:	Localized Maintenance Quantities.....	10
Table 5-2:	Surface Treatment, Rehabilitation, And Reconstruction Quantities	10

FIGURES

Figure 2.1:	Cape Blanco State Airport Location Map
Figure 2.2:	Cape Blanco State Airport Percent Of Pavement Area By Surface Type
Figure 2.3:	Cape Blanco State Airport Pavement Area By Branch Use
Figure 2.4:	Cape Blanco State Airport Pavement Inventory
Figure 3.1:	Cape Blanco State Airport 2023 PCI Survey Results
Figure 3.2:	Cape Blanco State Airport Pavement Condition Rating By Percent Of Area
Figure 4.1:	Cape Blanco State Airport Future Pavement Condition
Figure 5.1:	Cape Blanco State Airport 5-Year Pavement Management Plan

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan
Appendix E:	Reinspection Report
Appendix F:	Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a five-year plan comprised of maintenance, surface treatment, rehabilitation, and reconstruction projects for the Cape Blanco State Airport in Sixes, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Cape Blanco State Airport in 2023 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Cape Blanco State Airport is located in Sixes, Oregon, and is owned and operated by the ODAV. The airport consists of one runway, two diverging taxiways, and an apron that serve a variety of general aviation, air taxi, and military aircraft. The general location of the airport is shown below on the Cape Blanco State Airport Location Map, Figure 2.1.



Figure 2.1: CAPE BLANCO STATE AIRPORT LOCATION MAP

The airside pavements at the Cape Blanco State Airport are comprised of asphalt concrete (AC). The airport pavements, delineated by surface type and branch use, are shown on the Cape Blanco State Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on the Cape Blanco Pavement Area by Branch Use, Figure 2.3, shown below. The pavement inventory, including work history for each pavement section, is displayed spatially on the Cape Blanco State Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report, Table 1F.




Figure 2.2: CAPE BLANCO STATE AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3: CAPE BLANCO STATE AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE



3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Cape Blanco State Airport in July 2023. The 2023 survey work was performed on sections last inspected in 2019 in order to update the Cape Blanco State Airport inspection data. GRI performed the 2023 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

Table 3-1: ASTM PCI RATING SCALE



PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Cape Blanco State Airport is approximately 52. The section PCIs ranged from a low of 32 to a high of 59. The primary distresses observed during the inspection were weathering, block cracking, depression, and patching on AC-surfaced pavements. Section PCIs following our pavement survey are displayed below spatially on the Cape Blanco State Airport 2023 PCI Survey Results, Figure 3.1.



SECTION PCI



The condition distribution of the network by percent of total pavement area is provided on the Cape Blanco State Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2023 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2: CAPE BLANCO STATE AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Cape Blanco State Airport are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis



Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 52 to a value of 47 in 2028 and 41 in 2033 if no maintenance or rehabilitation work is performed. The projected pavement condition in 5 years and 10 years for each pavement section at Cape Blanco State Airport is displayed spatially on the Cape Blanco State Airport Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.

4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Cape Blanco State Airport. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Cape Blanco State Airport are summarized in Table 2C in Appendix C.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priorities and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Quantity
Asphalt Concrete Crack Sealing	268,785

5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan


To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the Cape Blanco State Airport 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

Treatment Type	Quantity, square feet
Reconstruction	765,000
Overlay	74,608
Fog Seal	0
Slurry Seal	43,408



ACTION TIMING		ACTION	
	2024		FOG SEAL
	2025		SLURRY SEAL
	2026	<div style="position: absolute; top: 50%; left: 50%; transform: translate(-50%, -50%); width: 100%; height: 100%; border-top: 1px dashed black; border-bottom: 1px dashed black;"></div>	OVERLAY
	2027		RECONSTRUCTION
	2028		ROUTINE MAINTENANCE




6 LIMITATIONS

This report has been prepared to assist the Oregon Department of Aviation (ODAV) with pavement-related project planning for the Cape Blanco State Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Cape Blanco State Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025

Lindsy A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Engineering Staff

This document has been submitted electronically.

APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Cape Blanco State Airport is located in Sixes, Oregon, and is owned and operated by the Oregon Department of Aviation (ODAV). The pavement network/facilities at Cape Blanco State Airport serve a variety of general aviation, air taxi, and military aircraft. Cape Blanco State Airport consists of one runway, two diverging taxiways, and an apron. Airside pavements consist of asphalt concrete (AC).

The current airport pavement management system (APMS) network at Cape Blanco State Airport has an approximate area of 883,016 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Cape Blanco State Airport contains 4 branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as “*a contiguous pavement area having uniform construction, maintenance, usage history, and condition.*” All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Cape Blanco State Airport contains 12 sections that are managed by the Oregon Department of Aviation (ODAV), which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement’s prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

n = number of sample units to be inspected

N = total number of samples in the pavement sections

e = allowable error

s = section standard deviation

For the 2023 Cape Blanco State Airport PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible and rigid pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Cape Blanco State Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A: CAPE BLANCO STATE AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01CB	Apron 01 Cape Blanco	1	31,200
R14CB	Runway 14/32 Cape Blanco	9	765,000
T01CB	Taxiway 01 Cape Blanco	1	43,408
T02CB	Taxiway 02 Cape Blanco	1	43,408

Table 2A: CAPE BLANCO STATE AIRPORT CURRENT PAVEMENT INVENTORY

BranchID	Branch Name	Branch Use	SectionID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type
A01CB	Apron 01 Cape Blanco	APRON	01	Taxiway 01	Hangars	P	190	180	31,200	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	01A	Runway 32 End	R14CB-02	P	200	25	5,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	01B	Runway 32 End	R14CB-02	P	200	100	20,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	01C	Runway 32 End	R14CB-02	P	200	25	5,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	02A	R14CB-01	R14CB-03	P	4,700	25	117,500	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	02B	R14CB-01	R14CB-03	P	4,700	100	470,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	02C	R14CB-01	R14CB-03	P	4,700	25	117,500	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	03A	R14CB-02	R14 End	P	200	25	5,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	03B	R14CB-02	R14 End	P	200	100	20,000	9/3/1945	AC
R14CB	Runway 14/32 Cape Blanco	RUNWAY	03C	R14CB-02	R14 End	P	200	25	5,000	9/3/1945	AC
T01CB	Taxiway 01 Cape Blanco	TAXIWAY	01	Runway 14/32	Apron 01	P	836	50	43,408	9/3/1945	AC
T02CB	Taxiway 02 Cape Blanco	TAXIWAY	01	Runway 14/32	Apron 01	P	836	50	43,408	9/3/1945	AC

Abbreviations:

P = Primary pavement


LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)

AC = Asphalt Concrete

Table 3A: EXAMPLE SAMPLE RATES FOR AC PAVEMENTS


AC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n
1	1
2-3	2
4-6	3
7-13	4
14-38	5
39+	6

Note: AC = Asphalt Concrete



LEGEND

- SECTION
- SAMPLE UNIT



**CAPE BLANCO STATE AIRPORT
SAMPLE UNIT LAYOUT**

APPENDIX B

Pavement Index Condition Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC and AAC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE AND RIGID PAVEMENT

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load
42	Bleeding	Other
43	Block Cracking	Climate/ Durability
44	Corrugation	Other
45	Depression	Other
46	Jet Blast	Other
47	Joint Reflection Cracking	Climate/ Durability
48	Longitudinal & Transverse Cracking	Climate/ Durability
49	Oil Spillage	Other
50	Patching	Climate/ Durability
51	Polished Aggregate	Other
52	Raveling	Climate/ Durability
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional”– defined as nonrepresentative instead of random- are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

“The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.”

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, and patching.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Cape Blanco State Airport pavement network consists of 4 branches and 12 sections. A total of 40 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2023 PCI survey, the area-weighted average PCI for the entire pavement network at Cape Blanco State Airport is approximately 52, which corresponds to a PCI rating of Poor.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2023 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Cape Blanco State Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B: CAPE BLANCO STATE AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01CB	1	31,200	APRON	48	Poor
R14CB	9	765,000	RUNWAY	52	Poor
T01CB	1	43,408	TAXIWAY	44	Poor
T02CB	1	43,408	TAXIWAY	59	Fair

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	1	31,200	48
RUNWAY	9	765,000	52
TAXIWAY	2	86,816	51
ALL	12	883,016	52

Abbreviation: PCI = Pavement Condition Index

Table 3B: CAPE BLANCO STATE AIRPORT 2023 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01CB	01	9/3/1945	AC	APRON	7/1/2023	78	48	Poor	100	0	0
R14CB	01A	9/3/1945	AC	RUNWAY	7/1/2023	78	40	Very Poor	100	0	0
R14CB	01B	9/3/1945	AC	RUNWAY	7/1/2023	78	59	Fair	100	0	0
R14CB	01C	9/3/1945	AC	RUNWAY	7/1/2023	78	40	Very Poor	100	0	0
R14CB	02A	9/3/1945	AC	RUNWAY	7/1/2023	78	39	Very Poor	100	0	0
R14CB	02B	9/3/1945	AC	RUNWAY	7/1/2023	78	59	Fair	100	0	0
R14CB	02C	9/3/1945	AC	RUNWAY	7/1/2023	78	37	Very Poor	100	0	0
R14CB	03A	9/3/1945	AC	RUNWAY	7/1/2023	78	32	Very Poor	66	0	34
R14CB	03B	9/3/1945	AC	RUNWAY	7/1/2023	78	56	Fair	74	0	26
R14CB	03C	9/3/1945	AC	RUNWAY	7/1/2023	78	43	Poor	100	0	0
T01CB	01	9/3/1945	AC	TAXIWAY	7/1/2023	78	44	Poor	100	0	0
T02CB	01	9/3/1945	AC	TAXIWAY	7/1/2023	78	59	Fair	100	0	0

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

Table 4B: CAPE BLANCO STATE AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2023 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2019 Survey			2023 Survey				Rate of Deterioration
					PCI	PCI Category	Inspection Date	PCI	PCI Category	Age ³	Δ PCI/yr ⁴	
A01CB	01	AC	31,200	9/3/45	49	Poor	5/13/2019	48	Poor	74	-0.15	NORMAL
R14CB	01A	AC	5,000	9/3/45	49	Poor	5/13/2019	40	Very Poor	74	-2	NORMAL
R14CB	01B	AC	20,000	9/3/45	60	Fair	5/13/2019	59	Fair	74	-0.15	NORMAL
R14CB	01C	AC	5,000	9/3/45	44	Poor	5/13/2019	40	Very Poor	74	-1	NORMAL
R14CB	02A	AC	117,500	9/3/45	49	Poor	5/13/2019	39	Very Poor	74	-2.44	NORMAL
R14CB	02B	AC	470,000	9/3/45	60	Fair	5/13/2019	59	Fair	74	0	NORMAL
R14CB	02C	AC	117,500	9/3/45	54	Poor	5/13/2019	37	Very Poor	74	-4.13	HIGH
R14CB	03A	AC	5,000	9/3/45	36	Very Poor	5/13/2019	32	Very Poor	74	-1	NORMAL
R14CB	03B	AC	20,000	9/3/45	56	Fair	5/13/2019	56	Fair	74	0.02	NONE
R14CB	03C	AC	5,000	9/3/45	49	Poor	5/13/2019	43	Poor	74	-1	NORMAL
T01CB	01	AC	43,408	9/3/45	55	Poor	5/13/2019	44	Poor	74	-2.78	NORMAL
T02CB	01	AC	43,408	9/3/45	51	Poor	5/13/2019	59	Fair	74	2	NONE

APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Cape Blanco State Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use three distinct models for the following “families” of pavements at Cape Blanco State Airport. For each model, we reviewed the data in order to filter out any inconsistent or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 3C below.




Figure 1C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC RUNWAYS




Figure 3C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Cape Blanco State Airport:

- Runways – 55
- Taxiways/Taxilanes – 50
- Aprons – 45

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Cape Blanco State Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition.

This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Cape Blanco State Airport, the time until rehabilitation, and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT AND FUTURE PCI

BranchID	SectionID	<u>Past Inspection PCI</u>	<u>Current PCI</u>	<u>Predicted Future PCI</u>	
		2019	2023	2028	2033
A01CB	01	49	48	43	39
R14CB	01A	49	40	35	30
R14CB	01B	60	59	54	49
R14CB	01C	44	40	35	30
R14CB	02A	49	39	34	29
R14CB	02B	60	59	54	49
R14CB	02C	54	37	32	27
R14CB	03A	36	32	27	22
R14CB	03B	56	56	51	46
R14CB	03C	49	43	38	33
T01CB	01	55	44	37	30
T02CB	01	51	59	52	45

Table 2C: CAPE BLANCO STATE AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service
A01CB	01	AC	48	0 - 5	45	6 - 10
R14CB	01A	AC	40	0 - 5	55	0 - 5
R14CB	01B	AC	59	0 - 5	55	16 - 20
R14CB	01C	AC	40	0 - 5	55	0 - 5
R14CB	02A	AC	39	0 - 5	55	0 - 5
R14CB	02B	AC	59	0 - 5	55	16 - 20
R14CB	02C	AC	37	0 - 5	55	0 - 5
R14CB	03A	AC	32	0 - 5	55	0 - 5
R14CB	03B	AC	56	0 - 5	55	11 - 15
R14CB	03C	AC	43	0 - 5	55	0 - 5
T01CB	01	AC	44	0 - 5	50	0 - 5
T02CB	01	AC	59	6 - 10	50	11 - 15

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

¹ Major M&R (Maintenance and Rehabilitation) Trigger PCI = Critical PCI

APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the Cape Blanco State five years. The purpose of this analysis is to determine the M&R needs of the Cape Blanco State Airport pavement network condition over time. We used PAVER v7.1.1 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2024. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction – Considered for pavements with a PCI less than 40.
- Rehabilitation (AC Overlay) – Considered for pavements between 40 PCI and the critical PCI, and for pavements exhibiting significant load-related distresses.
- Surface Treatment – Treatments (fog seal, slurry seal, thin AC overlay) applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance – Maintenance performed on a routine basis such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2019 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Cape Blanco State Airport and information provided by the ODAV Pavement Maintenance Program (PMP) project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Cape Blanco State Airport. The costs represent the fully loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: REGION 1 UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major M&R	Complete Reconstruction with AC	\$17.32	Sq Ft
	Cold Mill and Overlay – 2 Inches Thick	\$7.64	Sq Ft
Surface Treatment (Global) M&R	Surface Treatment - Slurry Seal	\$0.52	Sq Ft
	Surface Treatment - Fog Seal	\$0.31	Sq Ft
Localized Preventive M&R	Crack Sealing - AC	\$3.12	Ft
	Crack Sealing - PCC	\$23.4	Ft
	Crack Sealing – Wide Cracks	\$51.48	Ft
	Joint Sealing - PCC	\$7.80	Ft
	AC Patching – Full Depth	\$78.00	Sq Ft
	PCC Patching – Full Depth	\$156.00	Sq Ft

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: CAPE BLANCO STATE AIRPORT NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01CB	01	Block Cracking	Medium	Crack Sealing - AC	1,752	Ft	\$3.12	\$5,466	\$29,670
A01CB	01	Block Cracking	Low	Crack Sealing - AC	7,758	Ft	\$3.12	\$24,205	
R14CB	01A	Block Cracking	Medium	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	\$4,755
R14CB	01A	Block Cracking	Low	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	
R14CB	01B	Block Cracking	Low	Crack Sealing - AC	6,096	Ft	\$3.12	\$19,019	\$19,019
R14CB	01C	Block Cracking	Medium	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	\$4,755
R14CB	01C	Block Cracking	Low	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	
R14CB	02A	Block Cracking	Low	Crack Sealing - AC	17,907	Ft	\$3.12	\$55,870	\$111,739
R14CB	02A	Block Cracking	Medium	Crack Sealing - AC	17,907	Ft	\$3.12	\$55,870	
R14CB	02B	Block Cracking	Low	Crack Sealing - AC	143,256	Ft	\$3.12	\$446,958	\$446,958
R14CB	02C	Block Cracking	Medium	Crack Sealing - AC	17,907	Ft	\$3.12	\$55,870	\$111,739
R14CB	02C	Block Cracking	Low	Crack Sealing - AC	17,907	Ft	\$3.12	\$55,870	
R14CB	03A	Block Cracking	Medium	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	\$4,755
R14CB	03A	Block Cracking	Low	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	
R14CB	03B	Block Cracking	Low	Crack Sealing - AC	6,096	Ft	\$3.12	\$19,019	\$19,019
R14CB	03C	Block Cracking	Medium	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	\$4,755
R14CB	03C	Block Cracking	Low	Crack Sealing - AC	762	Ft	\$3.12	\$2,377	
T01CB	01	Block Cracking	Low	Crack Sealing - AC	10,657	Ft	\$3.12	\$33,249	\$41,280
T01CB	01	Block Cracking	Medium	Crack Sealing - AC	2,574	Ft	\$3.12	\$8,031	
T02CB	01	Block Cracking	Low	Crack Sealing - AC	12,870	Ft	\$3.12	\$40,156	\$40,156

Abbreviations:

AC = Asphalt Concrete; Ft = Feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2024	T02CB	01	TAXIWAY	AC	59	Slurry Seal	43,408	\$0.52	\$22,572
2025	R14CB	01A	RUNWAY	AC	40	Reconstruction	5,000	\$17.32	\$86,600
	R14CB	01B	RUNWAY	AC	59	Reconstruction	20,000	\$17.32	\$346,400
	R14CB	01C	RUNWAY	AC	40	Reconstruction	5,000	\$17.32	\$86,600
	R14CB	02A	RUNWAY	AC	39	Reconstruction	117,500	\$17.32	\$2,035,090
	R14CB	02B	RUNWAY	AC	59	Reconstruction	470,000	\$17.32	\$8,140,400
	R14CB	02C	RUNWAY	AC	37	Reconstruction	117,500	\$17.32	\$2,035,090
	R14CB	03A	RUNWAY	AC	32	Reconstruction	5,000	\$17.32	\$86,600
	R14CB	03B	RUNWAY	AC	56	Reconstruction	20,000	\$17.32	\$346,398
	R14CB	03C	RUNWAY	AC	43	Reconstruction	5,000	\$17.32	\$86,600
2026	T01CB	01	TAXIWAY	AC	44	Overlay	43,408	\$7.64	\$331,637
	A01CB	01	APRON	AC	48	Overlay	31,200	\$7.64	\$238,368

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

Cost Summary	
2024 Total Project Cost	\$22,572
2025 Total Project Cost	\$13,581,413
2026 Total Project Cost	\$238,368
2027 Total Project Cost	\$0
2028 Total Project Cost	\$0
Total 5-Year Project Cost	\$13,842,353

APPENDIX E

Reinspection Report

Re-Inspection Report

ODA_2023Survey_11-21-23

Generated Date 12/5/2023

Page 1 of 13

Network:	CapeBlanco		Name:	Cape Blanco State					
Branch:	A01CB	Name:	Apron 01 Cape Blanco	Use:	APRON	Area:	31,200 SqFt		
Section:	01	of 1	From:	Taxiway 01	To:	Hangars	Last Const.:	9/3/1945	
Surface:	AC	Family:	2023_Region1_Cat5_Apron_AC	Zone:	5S6	Category:	D	Rank:	P
Area:	31,200 SqFt	Length:	190 Ft	Width:	180 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1945	Work Type:	New Construction - Initial	Code:	NC-IN	Is Major M&R:	True		
Work Date:	9/1/1945	Work Type:	Subbase - Aggregate	Code:	SB-AG	Is Major M&R:	False		
Work Date:	9/2/1945	Work Type:	Base Course - Aggregate	Code:	BA-AG	Is Major M&R:	False		
Work Date:	9/3/1945	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True		
Work Date:	9/1/1950	Work Type:	Surface Treatment - Slurry Seal	Code:	ST-SS	Is Major M&R:	False		
Last Insp. Date:	7/1/2023	TotalSamples:	7	Surveyed:	4				
Conditions:	PCI: 48								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5000.00 SqFt	PCI:	48		
Sample Comments:									
43	BLOCK CR	L	4000.00	SqFt					
43	BLOCK CR	M	1000.00	SqFt					
57	WEATHERING	M	5000.00	SqFt					
Sample Number:	03	Type:	R	Area:	4500.00 SqFt	PCI:	49		
Sample Comments:									
43	BLOCK CR	L	3750.00	SqFt					
43	BLOCK CR	M	750.00	SqFt					
57	WEATHERING	M	4500.00	SqFt					
Sample Number:	04	Type:	R	Area:	5000.00 SqFt	PCI:	48		
Sample Comments:									
43	BLOCK CR	L	4000.00	SqFt					
43	BLOCK CR	M	1000.00	SqFt					
57	WEATHERING	M	5000.00	SqFt					
Sample Number:	07	Type:	R	Area:	4500.00 SqFt	PCI:	49		
Sample Comments:									
43	BLOCK CR	L	3750.00	SqFt					
43	BLOCK CR	M	750.00	SqFt					
57	WEATHERING	M	4500.00	SqFt					

Network:	CapeBlanco			Name:	Cape Blanco State							
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt		
Section:	02C		of	9		From:	R14CB-01		To:	R14CB-03		
Surface:	AC		Family:	2023_Region1_Cat5_Run way_AC		Zone:	5S6		Category:	D		
Area:	117,500 SqFt		Length:	4,700 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1945		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True
Work Date:	9/1/1945		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	9/2/1945		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	9/3/1945		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1950		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/2014		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	24		Surveyed:	6					
Conditions:	PCI: 37											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	36		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								
57	WEATHERING		H	1000.00 SqFt								
Sample Number:	05		Type:	R		Area:	5000.00 SqFt		PCI:	36		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								
57	WEATHERING		H	1000.00 SqFt								
Sample Number:	09		Type:	R		Area:	5000.00 SqFt		PCI:	36		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								
57	WEATHERING		H	1000.00 SqFt								
Sample Number:	13		Type:	R		Area:	5000.00 SqFt		PCI:	36		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								
57	WEATHERING		H	1000.00 SqFt								
Sample Number:	18		Type:	R		Area:	5000.00 SqFt		PCI:	40		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	4500.00 SqFt								
57	WEATHERING		H	500.00 SqFt								
Sample Number:	21		Type:	R		Area:	5000.00 SqFt		PCI:	40		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								

57	WEATHERING	M	4500.00	SqFt
57	WEATHERING	H	500.00	SqFt

Network:	CapeBlanco			Name:	Cape Blanco State							
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt		
Section:	03C		of	9	From:	R14CB-02			To:	R14 End		
Surface:	AC		Family:	2023_Region1_Cat5_Run way_AC		Zone:	5S6			Category:	D	
Area:	5,000 SqFt		Length:	200 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1945		Work Type: New Construction - Initial				Code:	NC-IN		Is Major M&R:	True	
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/2014		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 43											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	43		
Sample Comments:												
43	BLOCK CR		L	2500.00 SqFt								
43	BLOCK CR		M	2500.00 SqFt								
57	WEATHERING		M	5000.00 SqFt								

Network:	CapeBlanco			Name:	Cape Blanco State							
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt		
Section:	01C	of	9	From:	Runway 32 End			To:	R14CB-02		Last Const.:	9/3/1945
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC		Zone:	5S6		Category:	D		Rank:	P
Area:	5,000 SqFt		Length:	200 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	8/1/1945		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True
Work Date:	9/1/1945		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	9/2/1945		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	9/3/1945		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1950		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/2014		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 40											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	5000.00 SqFt			PCI:	40			
Sample Comments:												
43	BLOCK CR	L	2500.00	SqFt								
43	BLOCK CR	M	2500.00	SqFt								
57	WEATHERING	M	4500.00	SqFt								
57	WEATHERING	H	500.00	SqFt								

Network:	CapeBlanco			Name:	Cape Blanco State					
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY	Area:	765,000 SqFt	
Section:	02B	of	9	From:	R14CB-01		To:	R14CB-03		
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC	Zone:	5S6		Category:	D		
Area:	470,000 SqFt		Length:	4,700 Ft		Width:	100 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	9/1/1945		Work Type:			Subbase - Aggregate		Code:	SB-AG	
								Is Major M&R:	True	
Work Date:	9/2/1945		Work Type:			Base Course - Aggregate		Code:	BA-AG	
								Is Major M&R:	True	
Work Date:	9/3/1945		Work Type:			New Construction - AC		Code:	NC-AC	
								Is Major M&R:	True	
Work Date:	9/1/1950		Work Type:			Surface Treatment - Slurry Seal		Code:	ST-SS	
								Is Major M&R:	False	
Work Date:	10/1/2001		Work Type:			Surface Treatment - Slurry Seal		Code:	ST-SS	
								Is Major M&R:	False	
Work Date:	9/1/2006		Work Type:			Crack Sealing - AC		Code:	CS-AC	
								Is Major M&R:	False	
Work Date:	9/2/2006		Work Type:			Surface Treatment - Slurry Seal		Code:	ST - SS	
								Is Major M&R:	False	
Work Date:	6/1/2011		Work Type:			Crack Sealing - AC		Code:	CS-AC	
								Is Major M&R:	False	
Work Date:	9/1/2014		Work Type:			Surface Treatment - Slurry Seal		Code:	ST-SS	
								Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	94		Surveyed:				6
Conditions:	PCI: 59		Inspection Comments:							
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						
Sample Number:	18	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						
Sample Number:	35	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						
Sample Number:	52	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						
Sample Number:	69	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						
Sample Number:	86	Type:	R	Area:	5000.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	5000.00	SqFt						
57	WEATHERING	L	5000.00	SqFt						

Network:	CapeBlanco			Name:	Cape Blanco State							
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt		
Section:	03B of 9		From:	R14CB-02			To:	R14 End		Last Const.:	9/3/1945	
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC		Zone:	5S6		Category:	D		Rank:	P
Area:	20,000 SqFt		Length:	200 Ft		Width:	100 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	True	
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	10/1/2001		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/2006		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/2006		Work Type: Surface Treatment - Slurry Seal				Code:	ST - SS		Is Major M&R:	False	
Work Date:	6/1/2011		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2014		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	4		Surveyed:	3					
Conditions:	PCI: 56											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	49		
Sample Comments:												
43	BLOCK CR		L	5000.00 SqFt								
45	DEPRESSION		L	120.00 SqFt								
45	DEPRESSION		M	60.00 SqFt								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	59		
Sample Comments:												
43	BLOCK CR		L	5000.00 SqFt								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	03		Type:	R		Area:	5000.00 SqFt		PCI:	59		
Sample Comments:												
43	BLOCK CR		L	5000.00 SqFt								
57	WEATHERING		L	5000.00 SqFt								

Network:	CapeBlanco			Name:	Cape Blanco State								
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt			
Section:	02A		of	9	From:	R14CB-01		To:	R14CB-03		Last Const.:	9/3/1945	
Surface:	AC		Family:	2023_Region1_Cat5_Run way_AC		Zone:	5S6		Category:	D		Rank:	P
Area:	117,500 SqFt		Length:	4,700 Ft		Width:	25 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	9/1/1945		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	True	
Work Date:	9/2/1945		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/3/1945		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1950		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/2014		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	24		Surveyed:	6						
Conditions:	PCI: 39												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	40			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
57	WEATHERING		H	500.00 SqFt									
Sample Number:	05		Type:	R		Area:	5000.00 SqFt		PCI:	40			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
57	WEATHERING		H	500.00 SqFt									
Sample Number:	09		Type:	R		Area:	5000.00 SqFt		PCI:	40			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
57	WEATHERING		H	500.00 SqFt									
Sample Number:	13		Type:	R		Area:	5000.00 SqFt		PCI:	40			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
57	WEATHERING		H	500.00 SqFt									
Sample Number:	18		Type:	R		Area:	5000.00 SqFt		PCI:	40			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
57	WEATHERING		H	500.00 SqFt									
Sample Number:	22		Type:	R		Area:	5000.00 SqFt		PCI:	36			
Sample Comments:													
43	BLOCK CR		L	2500.00 SqFt									
43	BLOCK CR		M	2500.00 SqFt									
57	WEATHERING		M	4000.00 SqFt									
57	WEATHERING		H	1000.00 SqFt									

Network:	CapeBlanco		Name:	Cape Blanco State										
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY	Area:	765,000 SqFt					
Section:	01A of 9		From:	Runway 32 End			To:	R14CB-02		Last Const.:	9/3/1945			
Surface:	AC		Family:	2023_Region1_Cat5_Runway_AC		Zone:	5S6		Category:	D		Rank:	P	
Area:	5,000 SqFt		Length:	200 Ft		Width:	25 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: True				
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True				
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True				
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False				
Work Date:	9/1/2014		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False				
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed: 1								
Conditions:	PCI: 40													
Inspection Comments:														
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	40				
Sample Comments:														
43	BLOCK CR		L	2500.00 SqFt										
43	BLOCK CR		M	2500.00 SqFt										
57	WEATHERING		M	4500.00 SqFt										
57	WEATHERING		H	500.00 SqFt										

Network:	CapeBlanco			Name:	Cape Blanco State						
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY	Area:	765,000 SqFt		
Section:	03A	of	9	From:	R14CB-02		To:	R14 End	Last Const.:	9/3/1945	
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC	Zone:	5S6		Category:	D	Rank:	P	
Area:	5,000 SqFt		Length:	200 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:			Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	True
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/2014		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:		1		Surveyed:		1		
Conditions:	PCI:	32									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	32			
Sample Comments:											
43	BLOCK CR		L	2500.00	SqFt						
43	BLOCK CR		M	2500.00	SqFt						
45	DEPRESSION		L	400.00	SqFt						
45	DEPRESSION		M	100.00	SqFt						
57	WEATHERING		M	5000.00	SqFt						

Network:	CapeBlanco			Name:	Cape Blanco State						
Branch:	R14CB		Name:	Runway 14/32 Cape Blanco		Use:	RUNWAY		Area:	765,000 SqFt	
Section:	01B of 9		From:	Runway 32 End			To:	R14CB-02		Last Const.:	9/3/1945
Surface:	AC		Family:	2023_Region1_Cat5_Runway_AC		Zone:	5S6		Category:	D Rank: P	
Area:	20,000 SqFt		Length:	200 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: True	
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True	
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Work Date:	10/1/2001		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Work Date:	9/1/2006		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/2/2006		Work Type: Surface Treatment - Slurry Seal				Code:	ST - SS		Is Major M&R: False	
Work Date:	6/1/2011		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/1/2014		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Last Insp. Date:	7/1/2023		TotalSamples:	4		Surveyed: 3					
Conditions:	PCI: 59										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	59	
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	59	
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	03		Type:	R		Area:	5000.00 SqFt		PCI:	59	
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
57	WEATHERING		L	5000.00 SqFt							

Network:	CapeBlanco			Name:	Cape Blanco State						
Branch:	T01CB		Name:	Taxiway 01 Cape Blanco		Use:	TAXIWAY	Area:	43,408 SqFt		
Section:	01	of	1	From:	Runway 14/32		To:	Apron 01		Last Const.:	9/3/1945
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC	Zone:	5S6		Category:	D		Rank:	P
Area:	43,408 SqFt		Length:	836 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	9/1/1945		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: False	
Work Date:	9/2/1945		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	9/3/1945		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Last Insp. Date:	7/1/2023		TotalSamples:	9		Surveyed:		4			
Conditions:	PCI: 44										
Inspection Comments:											
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	43			
Sample Comments:											
43	BLOCK CR	L	4000.00	SqFt							
43	BLOCK CR	M	1000.00	SqFt							
57	WEATHERING	M	4500.00	SqFt							
57	WEATHERING	H	500.00	SqFt							
Sample Number:	04	Type:	R	Area:	5000.00 SqFt		PCI:	43			
Sample Comments:											
43	BLOCK CR	L	4000.00	SqFt							
43	BLOCK CR	M	1000.00	SqFt							
57	WEATHERING	M	4500.00	SqFt							
57	WEATHERING	H	500.00	SqFt							
Sample Number:	06	Type:	R	Area:	5000.00 SqFt		PCI:	43			
Sample Comments:											
43	BLOCK CR	L	4000.00	SqFt							
43	BLOCK CR	M	1000.00	SqFt							
57	WEATHERING	M	4500.00	SqFt							
57	WEATHERING	H	500.00	SqFt							
Sample Number:	08	Type:	R	Area:	5560.00 SqFt		PCI:	44			
Sample Comments:											
43	BLOCK CR	L	4560.00	SqFt							
43	BLOCK CR	M	1000.00	SqFt							
57	WEATHERING	M	5000.00	SqFt							
57	WEATHERING	H	560.00	SqFt							

Network:	CapeBlanco			Name:	Cape Blanco State							
Branch:	T02CB		Name:	Taxiway 02 Cape Blanco			Use:	TAXIWAY	Area:	43,408 SqFt		
Section:	01	of	1	From:	Runway 14/32			To:	Apron 01		Last Const.:	9/3/1945
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC	Zone:	5S6			Category:	D		Rank:	P
Area:	43,408 SqFt		Length:	836 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	9/1/1945		Work Type: Subbase - Aggregate					Code:	SB-AG		Is Major M&R:	False
Work Date:	9/2/1945		Work Type: Base Course - Aggregate					Code:	BA-AG		Is Major M&R:	False
Work Date:	9/3/1945		Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1950		Work Type: Surface Treatment - Slurry Seal					Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	9			Surveyed:	4				
Conditions:	PCI:	59										
Inspection Comments:												
Sample Number:	02	Type:	R	Area:	5000.00 SqFt			PCI:	59			
Sample Comments:												
43	BLOCK CR	L	5000.00 SqFt									
57	WEATHERING	M	5000.00 SqFt									
Sample Number:	04	Type:	R	Area:	5000.00 SqFt			PCI:	59			
Sample Comments:												
43	BLOCK CR	L	5000.00 SqFt									
57	WEATHERING	M	5000.00 SqFt									
Sample Number:	06	Type:	R	Area:	5000.00 SqFt			PCI:	57			
Sample Comments:												
43	BLOCK CR	L	5000.00 SqFt									
50	PATCHING	L	5.00 SqFt									
50	PATCHING	L	5.00 SqFt									
57	WEATHERING	M	5000.00 SqFt									
Sample Number:	08	Type:	R	Area:	5560.00 SqFt			PCI:	61			
Sample Comments:												
43	BLOCK CR	L	5000.00 SqFt									
57	WEATHERING	M	5000.00 SqFt									

APPENDIX F

Work History Report

12/4/2023

Work History Report

Page 1 of 4

Pavement Database: ODA_2023Survey_MASTER DB-12-4-2023_12pm

Network: Cape Blanco State		Branch: A01CB	Apron 01 Cape Bla		Section: 01	Surface: AC
L.C.D. 9/3/1945	Use: APRON	Rank: P	Length: 190.00 (Ft)	Width: 180.00 (Ft)	True Area:	31200 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1950
9/3/1945	NC-AC	New Construction - AC	0.00	2.50	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input type="checkbox"/>	
1/1/1945	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Cape Blanco State		Branch: R14CB	Runway 14/32 Cap		Section: 01A	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 25.00 (Ft)	True Area:	5000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input checked="" type="checkbox"/>	

Network: Cape Blanco State		Branch: R14CB	Runway 14/32 Cap		Section: 01B	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 100.00 (Ft)	True Area:	20000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2011 circa 2006
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2006	ST - SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
10/1/2001	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1950
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input checked="" type="checkbox"/>	

Network: Cape Blanco State		Branch: R14CB	Runway 14/32 Cap		Section: 01C	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 25.00 (Ft)	True Area:	5000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input type="checkbox"/>	
8/1/1945	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

12/4/2023

Work History Report

Page 2 of 4

Pavement Database: ODA_2023Survey_MASTER DB-12-4-2023_12pm

Network: Cape Blanco State		Branch: R14CB		Runway 14/32 Cap		Section: 02A	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 4,700.00 (Ft)	Width: 25.00 (Ft)	True Area: 117500 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950	
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>		
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input checked="" type="checkbox"/>		

Network: Cape Blanco State		Branch: R14CB		Runway 14/32 Cap		Section: 02B	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 4,700.00 (Ft)	Width: 100.00 (Ft)	True Area: 470000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2011 circa 2006	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/2/2006	ST - SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>		
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
10/1/2001	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1950	
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>		
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input checked="" type="checkbox"/>		

Network: Cape Blanco State		Branch: R14CB		Runway 14/32 Cap		Section: 02C	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 4,700.00 (Ft)	Width: 25.00 (Ft)	True Area: 117500 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950	
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>		
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>		
1/1/1945	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Cape Blanco State		Branch: R14CB		Runway 14/32 Cap		Section: 03A	Surface: AC
L.C.D. 9/3/1945	Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 25.00 (Ft)	True Area: 5000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950	
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>		
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input checked="" type="checkbox"/>		

12/4/2023

Work History Report

Page 3 of 4

Pavement Database: ODA_2023Survey_MASTER DB-12-4-2023_12pm

Network: Cape Blanco State		Branch: R14CB	Runway 14/32 Cap	Section: 03B	Surface:AC	
L.C.D. 9/3/1945		Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 100.00 (Ft)	True Area: 20000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2011 circa 2006 circa 1950
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2006	ST - SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
10/1/2001	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input checked="" type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input checked="" type="checkbox"/>	

Network: Cape Blanco State		Branch: R14CB		Runway 14/32 Cap		Section: 03C		Surface:AC	
L.C.D. 9/3/1945		Use: RUNWAY		Rank: P		Length: 200.00 (Ft)		Width: 25.00 (Ft) True Area: 5000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	circa 1950			
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>				
9/3/1945	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>				
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>				
9/1/1945	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>				
1/1/1945	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>				

Network: Cape Blanco State		Branch: T01CB	Taxiway 01 Cape	Section: 01	Surface:AC	
L.C.D. 9/3/1945		Use: TAXIWAY	Rank: P	Length: 836.00 (Ft)	Width: 50.00 (Ft)	True Area: 43408 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1950
9/3/1945	NC-AC	New Construction - AC	0.00	2.50	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input type="checkbox"/>	

Network: Cape Blanco State		Branch: T02CB	Taxiway 02 Cape	Section: 01	Surface:AC	
L.C.D. 9/3/1945		Use: TAXIWAY	Rank: P	Length: 836.00 (Ft)	Width: 50.00 (Ft)	True Area: 43408 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/1950	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1950
9/3/1945	NC-AC	New Construction - AC	0.00	2.50	<input checked="" type="checkbox"/>	
9/2/1945	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	
9/1/1945	SB-AG	Subbase - Aggregate	0.00	7.00	<input type="checkbox"/>	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	12	883,016.00	9.00	0.00
Crack Sealing - AC	6	1,020,000.00	0.00	0.00
New Construction - AC	12	883,016.00	2.12	0.22
New Construction - Initial	4	158,700.00	0.00	0.00
Subbase - Aggregate	12	883,016.00	5.50	1.50
Surface Treatment - Slurry Seal	27	2,668,016.01	0.28	0.25