

2023 ODAV Pavement Evaluation Program Gold Beach Municipal Airport

Gold Beach, Oregon

December 29, 2023

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

| | | |
|----------|---|-----------|
| 1 | OVERVIEW..... | 1 |
| 2 | PAVEMENT INVENTORY | 1 |
| 3 | PAVEMENT CONDITION INSPECTION RESULTS..... | 5 |
| | 3.1 Introduction..... | 5 |
| | 3.2 Pavement Condition Index Survey Results | 5 |
| 4 | FUTURE PAVEMENT CONDITION ANALYSIS..... | 8 |
| | 4.1 Introduction..... | 8 |
| | 4.2 Future Condition Analysis | 8 |
| | 4.3 Functional Remaining Life..... | 8 |
| 5 | MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS | 10 |
| | 5.1 Introduction..... | 10 |
| | 5.2 Recommended Localized Maintenance..... | 10 |
| | 5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan..... | 10 |
| 6 | LIMITATIONS..... | 12 |

TABLES

| | | |
|------------|--|----|
| Table 3-1: | ASTM PCI Rating Scale..... | 5 |
| Table 5-1: | Localized Maintenance Quantities..... | 10 |
| Table 5-2: | Surface Treatment, Rehabilitation, And Reconstruction Quantities | 10 |

FIGURES

| | |
|-------------|---|
| Figure 2.1: | Gold Beach Municipal Airport Location Map |
| Figure 2.2: | Gold Beach Municipal Airport Pavement Area by Surface Type |
| Figure 2.3: | Gold Beach Municipal Airport Pavement Area by Branch Use |
| Figure 2.4: | Gold Beach Municipal Airport Pavement Inventory |
| Figure 3.1: | Gold Beach Municipal Airport 2023 PCI Survey Results |
| Figure 3.2: | Gold Beach Municipal Airport Pavement Condition Rating by Percent of Area |
| Figure 4.1: | Gold Beach Municipal Airport Future Pavement Condition |
| Figure 5.1: | Gold Beach Municipal Airport 5-Year Pavement Management Plan |

APPENDICES

| | |
|-------------|--|
| Appendix A: | Pavement Inventory Report and Maps |
| Appendix B: | Pavement Condition Index Survey Results |
| Appendix C: | Future Pavement Condition Analysis |
| Appendix D: | Unit Cost Data and Maintenance and Rehabilitation Plan |
| Appendix E: | Reinspection Report |
| Appendix F: | Work History Report |

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a five-year plan comprised of maintenance, surface treatment, rehabilitation, and reconstruction projects for the Gold Beach Municipal Airport in Gold Beach, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Gold Beach Municipal Airport in 2023 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Gold Beach Municipal Airport is located in Gold Beach, Oregon, and is owned and operated by the Port of Gold Beach. The airport consists of a single runway, a primary taxiway, multiple connector taxiways, and an apron that serves a variety of general aviation and military aircraft. The general location of the airport is shown below on the Gold Beach Municipal Airport Location Map, Figure 2.1.



Figure 2.1: GOLD BEACH MUNICIPAL AIRPORT LOCATION MAP

The airside pavements at the Gold Beach Municipal Airport are comprised of asphalt concrete (AC). The airport pavements, delineated by surface type and branch use, are shown on the Gold Beach Municipal Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on the Gold Beach Municipal Airport Pavement Area by Branch Use, Figure 2.3, shown below. The pavement inventory, including work history for each pavement section, is displayed spatially on the Gold Beach Municipal Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report, Table 1F.




Figure 2.2: GOLD BEACH MUNICIPAL AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3: GOLD BEACH MUNICIPAL AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE










3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Gold Beach Municipal Airport in July 2023. The 2023 survey work was performed on sections last inspected in 2019 in order to update the Gold Beach Municipal Airport inspection data. GRI performed the 2023 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

Table 3-1: ASTM PCI RATING SCALE

| PCI Color Legend | PCI Range | PCI Rating and Definition |
|---|-----------|---|
|  | 86 – 100 | GOOD: Pavement has minor or no distresses and should require only routine maintenance. |
|  | 71 – 85 | SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance. |
|  | 56 – 70 | FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major. |
|  | 41 – 55 | POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major. |
|  | 26 – 40 | VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major. |
|  | 11 – 25 | SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed. |
|  | 0 – 10 | FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required. |


3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Gold Beach Municipal Airport is approximately 85. The section PCIs ranged from a low of 55 to a high of 99. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, block cracking, and patching on AC-surfaced pavements. Section PCIs following our pavement survey are displayed below spatially on the 2023 PCI Survey Results Gold Beach Municipal Airport, Figure 3.1.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



The condition distribution of the network by percent of total pavement area is provided on the Gold Beach Municipal Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2023 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2: GOLD BEACH MUNICIPAL AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Gold Beach Municipal Airport are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 85 to a value of 80 in 2028 and 74 in 2033 if no maintenance or rehabilitation work is performed. The projected pavement condition in 5 years and 10 years for each pavement section at Gold Beach Municipal Airport is displayed spatially on the Future Pavement Condition Gold Beach Municipal Airport, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Gold Beach Municipal Airport. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Gold Beach Municipal Airport are summarized in Table 2C in Appendix C.

PREDICTED CONDITION IN 2028




PREDICTED CONDITION IN 2033



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priorities and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


| Localized Maintenance Operation | Quantity |
|--------------------------------------|--------------------|
| Asphalt Concrete Crack Sealing | 18,008 linear feet |
| Asphalt Concrete Full-Depth Patching | 16 square feet |

5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan

To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the 5-Year Pavement Management Plan Gold Beach Municipal Airport, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

| Treatment Type | Quantity, square feet |
|----------------|-----------------------|
| Reconstruction | 0 |
| Overlay | 4,042 |
| Fog Seal | 217,865 |
| Slurry Seal | 19,387 |




ACTION TIMING

- 2024
- 2025
- 2026
- 2027
- 2028

ACTION

- FOG SEAL
- SLURRY SEAL
- OVERLAY
- RECONSTRUCTION
- ROUTINE MAINTENANCE




6 LIMITATIONS

This report has been prepared to assist the ODAV with pavement-related project planning for the Gold Beach Municipal Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Gold Beach Municipal Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025
Lindsy A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Engineering Staff

This document has been submitted electronically.

APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Gold Beach Municipal Airport is located in Gold Beach, Oregon, and is owned and operated by the Port of Gold Beach. The pavement network/facilities at Gold Beach Municipal Airport serve a variety of general aviation aircraft and military aircraft. Gold Beach Municipal Airport consists of a single runway, a primary taxiway, multiple connector taxiways, and an apron. Airside pavements are comprised of asphalt concrete (AC).

The current airport pavement management system (APMS) network at Gold Beach Municipal Airport has an approximate area of 615,678 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Gold Beach Municipal Airport contains nine branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as “*a contiguous pavement area having uniform construction, maintenance, usage history, and condition.*” All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Gold Beach Municipal Airport contains 15 sections that are managed by the Port of Gold Beach, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement’s prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet and $20 \text{ slabs} \pm 8 \text{ slabs}$ for rigid pavements. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2023 Gold Beach Municipal Airport PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Gold Beach Municipal Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A: GOLD BEACH MUNICIPAL AIRPORT PAVEMENT BRANCHES

| Facility Designation (Branch ID) | Branch Name | Number of Sections | Approximate Area, square feet |
|-------------------------------------|-------------------------|--------------------|----------------------------------|
| A01GB | Apron 01 Gold Beach | 4 | 259,373 |
| ASRUNUPGB | South Run-Up Apron | 1 | 13,318 |
| R16GB | Runway 16/34 Gold Beach | 1 | 240,000 |
| T01GB | Taxiway 01 Gold Beach | 1 | 4,395 |
| T02GB | Taxiway 02 Gold Beach | 2 | 5,678 |
| TA1GB | Taxiway A1 Gold Beach | 2 | 4,568 |
| TA2GB | Taxiway A2 Gold Beach | 1 | 4,679 |
| TA3BG | Taxiway A3 Gold Beach | 2 | 4,109 |
| TAGB | Taxiway A Gold Beach | 1 | 79,558 |

Table 2A: GOLD BEACH MUNICIPAL AIRPORT CURRENT PAVEMENT INVENTORY

| BranchID | Branch Name | Branch Use | SectionID | From | To | Rank | Length, feet | Width, feet | Approximate Area, square feet | LCD | Surface Type |
|-----------|-------------------------|------------|-----------|------------------------|---------------|------|--------------|-------------|-------------------------------|-----------|--------------|
| A01GB | Apron 01 Gold Beach | APRON | 01 | Taxiway A | Hangars | P | 625 | 200 | 117,218 | 9/1/1984 | AC |
| A01GB | Apron 01 Gold Beach | APRON | 02 | A01GB-01 | A01GB-03 | P | 265 | 120 | 31,810 | 9/1/1963 | AC |
| A01GB | Apron 01 Gold Beach | APRON | 03 | A01GB-02 | Hangars | S | 340 | 300 | 100,647 | 9/1/1984 | AC |
| A01GB | Apron 01 Gold Beach | APRON | 04 | Taxiway A | Section 01 | S | 654 | 15 | 9,698 | 10/3/2012 | AC |
| ASRUNUPGB | South Run-Up Apron | APRON | 01 | South End of Taxiway A | East | P | 263 | 62 | 13,318 | 10/3/2012 | AC |
| R16GB | Runway 16/34 Gold Beach | RUNWAY | 01 | Runway 34 End | Runway 16 End | P | 3,200 | 75 | 240,000 | 9/4/2006 | AC |
| T01GB | Taxiway 01 Gold Beach | TAXIWAY | 01 | A01GB-04 | A01BG-02 | P | 100 | 40 | 4,395 | 9/1/1963 | AC |
| T02GB | Taxiway 02 Gold Beach | TAXIWAY | 01 | Taxiway A | Section 02 | P | 40 | 15 | 1,636 | 10/3/2012 | AC |
| T02GB | Taxiway 02 Gold Beach | TAXIWAY | 02 | T02GB-01 | A01GB-02 | P | 100 | 40 | 4,042 | 9/1/1963 | AC |
| TA1GB | Taxiway A1 Gold Beach | TAXIWAY | 01 | Runway 34 End | Section 02 | P | 56 | 40 | 2,678 | 9/4/2006 | AC |
| TA1GB | Taxiway A1 Gold Beach | TAXIWAY | 02 | Section 01 | Taxiway A | P | 36 | 40 | 1,890 | 10/3/2012 | AC |
| TA2GB | Taxiway A2 Gold Beach | TAXIWAY | 01 | Runway 16/34 | Taxiway A | P | 86 | 35 | 4,679 | 9/4/2006 | AC |
| TA3BG | Taxiway A3 Gold Beach | TAXIWAY | 01 | Runway 16 End | Taxiway A | P | 57 | 40 | 2,688 | 9/4/2006 | AC |
| TA3BG | Taxiway A3 Gold Beach | TAXIWAY | 02 | Section 01 | Taxiway A | P | 40 | 40 | 1,421 | 10/2/2012 | AC |
| TAGB | Taxiway A Gold Beach | TAXIWAY | 01 | Taxiway A1 | TAXiway A3 | P | 3,175 | 25 | 79,558 | 10/3/2012 | AC |

Abbreviations:

P = Primary pavement, S = Secondary pavement


LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)

AC = Asphalt Concrete

Table 3A: EXAMPLE SAMPLE RATES FOR AC PAVEMENTS


| AC Sampling Rate | |
|---------------------------------|---------------------------|
| Total Number of Sample Units, N | Sample Units to Survey, n |
| 1 | 1 |
| 2-3 | 2 |
| 4-6 | 3 |
| 7-13 | 4 |
| 14-38 | 5 |
| 39+ | 6 |

Note: AC = Asphalt Concrete



LEGEND

- SECTION
- SAMPLE UNIT



**GOLD BEACH MUNICIPAL AIRPORT
SAMPLE UNIT LAYOUT**

APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavements (e.g., AC and AAC) are presented in Table 1B. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE PAVEMENT

| Flexible Pavement | | |
|-------------------|------------------------------------|---------------------|
| PAVER Code | Pavement Distress | Related Cause |
| 41 | Alligator Cracking | Load |
| 42 | Bleeding | Other |
| 43 | Block Cracking | Climate/ Durability |
| 44 | Corrugation | Other |
| 45 | Depression | Other |
| 46 | Jet Blast | Other |
| 47 | Joint Reflection Cracking | Climate/ Durability |
| 48 | Longitudinal & Transverse Cracking | Climate/ Durability |
| 49 | Oil Spillage | Other |
| 50 | Patching | Climate/ Durability |
| 51 | Polished Aggregate | Other |
| 52 | Raveling | Climate/ Durability |
| 53 | Rutting | Load |
| 54 | Shoving | Other |
| 55 | Slippage Cracking | Other |
| 56 | Swelling | Other |
| 57 | Weathering | Climate/ Durability |

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional”– defined as nonrepresentative instead of random- are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

“The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.”

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling.
- **Other factors:** Includes oil spillage, bleeding, and patching.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Gold Beach Municipal Airport pavement network consists of 9 branches and 15 sections. A total of 37 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2023 PCI survey, the area-weighted average PCI for the entire pavement network at Gold Beach Municipal Airport is approximately 85, which corresponds to a PCI rating of Satisfactory.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2023 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Gold Beach Municipal Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B: GOLD BEACH MUNICIPAL AIRPORT CURRENT BRANCH CONDITION REPORT

| Branch ID | Number of Sections | Approximate Area, square feet | Use | Area Weighted Average Branch PCI | PCI Category |
|-----------|--------------------|-------------------------------|---------|----------------------------------|--------------|
| A01GB | 4 | 259,373 | APRON | 79 | Satisfactory |
| ASRUNUPGB | 1 | 13,318 | APRON | 94 | Good |
| R16GB | 1 | 240,000 | RUNWAY | 89 | Good |
| T01GB | 1 | 4,395 | TAXIWAY | 65 | Fair |
| T02GB | 2 | 5,678 | TAXIWAY | 65 | Fair |
| TA1GB | 2 | 4,568 | TAXIWAY | 90 | Good |
| TA2GB | 1 | 4,679 | TAXIWAY | 90 | Good |
| TA3BG | 2 | 4,109 | TAXIWAY | 90 | Good |
| TAGB | 1 | 79,558 | TAXIWAY | 93 | Good |

| Use Category | Number of Sections | Total Area, square feet | Area Weighted Average PCI |
|--------------|--------------------|-------------------------|---------------------------|
| APRON | 5 | 272,691 | 80 |
| RUNWAY | 1 | 240,000 | 89 |
| TAXIWAY | 9 | 102,987 | 90 |
| ALL | 15 | 615,678 | 85 |

Abbreviation: PCI = Pavement Condition Index

Table 3B: GOLD BEACH MUNICIPAL AIRPORT 2023 PAVEMENT CONDITION INDEX SURVEY RESULTS

| BranchID | SectionID | Last Construction Date | Surface Type | Use | Last Inspection Date | Age at Inspection | PCI | PCI Category | PCI % Climate | PCI % Load | PCI % Other |
|-----------|-----------|------------------------|--------------|---------|----------------------|-------------------|-----|--------------|---------------|------------|-------------|
| A01GB | 01 | 9/1/1984 | AC | APRON | 7/1/2023 | 39 | 74 | Satisfactory | 74 | 0 | 26 |
| A01GB | 02 | 9/1/1963 | AC | APRON | 7/1/2023 | 60 | 99 | Good | 100 | 0 | 0 |
| A01GB | 03 | 9/1/1984 | AC | APRON | 7/1/2023 | 39 | 78 | Satisfactory | 100 | 0 | 0 |
| A01GB | 04 | 10/3/2012 | AC | APRON | 7/1/2023 | 11 | 94 | Good | 100 | 0 | 0 |
| ASRUNUPGB | 01 | 10/3/2012 | AC | APRON | 7/1/2023 | 11 | 94 | Good | 100 | 0 | 0 |
| R16GB | 01 | 9/4/2006 | AC | RUNWAY | 7/1/2023 | 17 | 89 | Good | 100 | 0 | 0 |
| T01GB | 01 | 9/1/1963 | AC | TAXIWAY | 7/1/2023 | 60 | 65 | Fair | 100 | 0 | 0 |
| T02GB | 01 | 10/3/2012 | AC | TAXIWAY | 7/1/2023 | 11 | 89 | Good | 100 | 0 | 0 |
| T02GB | 02 | 9/1/1963 | AC | TAXIWAY | 7/1/2023 | 60 | 55 | Poor | 85 | 15 | 0 |
| TA1GB | 01 | 9/4/2006 | AC | TAXIWAY | 7/1/2023 | 17 | 90 | Good | 100 | 0 | 0 |
| TA1GB | 02 | 10/3/2012 | AC | TAXIWAY | 7/1/2023 | 11 | 90 | Good | 100 | 0 | 0 |
| TA2GB | 01 | 9/4/2006 | AC | TAXIWAY | 7/1/2023 | 17 | 90 | Good | 100 | 0 | 0 |
| TA3BG | 01 | 9/4/2006 | AC | TAXIWAY | 7/1/2023 | 17 | 90 | Good | 100 | 0 | 0 |
| TA3BG | 02 | 10/2/2012 | AC | TAXIWAY | 7/1/2023 | 11 | 90 | Good | 100 | 0 | 0 |
| TAGB | 01 | 10/3/2012 | AC | TAXIWAY | 7/1/2023 | 11 | 93 | Good | 100 | 0 | 0 |

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

Table 4B: GOLD BEACH MUNICIPAL AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2023 RESULTS

| Branch ID | Section ID | Surface Type ¹ | Approximate Area, square feet | LCD ² | 2019 Survey | | | 2023 Survey | | Age ⁴ | Δ PCI/yr ⁵ | Rate of Deterioration |
|-----------|------------|---------------------------|-------------------------------|------------------|------------------|--------------|-----------------|-------------|--------------|------------------|------------------------------|-----------------------|
| | | | | | PCI ³ | PCI Category | Inspection Date | PCI | PCI Category | | | |
| A01GB | 01 | AC | 117,218 | 9/1/84 | 76 | Satisfactory | 5/13/2019 | 74 | Satisfactory | 35 | -0.48 | NORMAL |
| A01GB | 02 | AC | 31,810 | 9/1/63 | 68 | Fair | 5/13/2019 | 99 | Good | 56 | 7 | NONE |
| A01GB | 03 | AC | 100,647 | 9/1/84 | 71 | Satisfactory | 5/13/2019 | 78 | Satisfactory | 35 | 1.69 | NONE |
| A01GB | 04 | AC | 9,698 | 10/3/12 | 94 | Good | 5/13/2019 | 94 | Good | 7 | 0 | NONE |
| ASRUNUPGB | 01 | AC | 13,318 | 10/3/12 | 94 | Good | 5/13/2019 | 94 | Good | 7 | 0.00 | NONE |
| R16GB | 01 | AC | 240,000 | 9/4/06 | 97 | Good | 5/13/2019 | 89 | Good | 13 | -2 | NORMAL |
| T01GB | 01 | AC | 4,395 | 9/1/63 | 58 | Fair | 5/13/2019 | 65 | Fair | 56 | 1.69 | NONE |
| T02GB | 01 | AC | 1,636 | 10/3/12 | 94 | Good | 5/13/2019 | 89 | Good | 7 | -1 | NORMAL |
| T02GB | 02 | AC | 4,042 | 9/1/63 | 63 | Fair | 5/13/2019 | 55 | Poor | 56 | -1.93 | NORMAL |
| TA1GB | 01 | AC | 2,678 | 9/4/06 | 83 | Satisfactory | 5/13/2019 | 90 | Good | 13 | 2 | NONE |
| TA1GB | 02 | AC | 1,890 | 10/3/12 | 94 | Good | 5/13/2019 | 90 | Good | 7 | -0.97 | NORMAL |
| TA2GB | 01 | AC | 4,679 | 9/4/06 | 87 | Good | 5/13/2019 | 90 | Good | 13 | 1 | NONE |
| TA3BG | 01 | AC | 2,688 | 9/4/06 | 90 | Good | 5/13/2019 | 90 | Good | 13 | 0.00 | NONE |
| TA3BG | 02 | AC | 1,421 | 10/2/12 | 94 | Good | 5/13/2019 | 90 | Good | 7 | -1 | NORMAL |
| TAGB | 01 | AC | 79,558 | 10/3/12 | 94 | Good | 5/13/2019 | 93 | Good | 7 | -0.24 | NORMAL |

Abbreviations:

¹ AC = Asphalt Concrete, PCI = Pavement Condition Index

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

³ PCI = Pavement Condition Index

⁴ Age = Pavement age in years at the time of the PCI survey in 2019

⁵ Δ PCI/yr = Change in PCI points per year between 2019 survey and 2023 survey

APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Gold Beach Municipal Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use three distinct models for the following “families” of pavements at Gold Beach Municipal Airport. For each model, we reviewed the data in order to filter out any inconsistent or inaccurate data or any data that fell outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 4C below.




Figure 1C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC RUNWAYS




Figure 3C: CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Gold Beach Municipal Airport:

- Runways – 60
- Taxiways/Taxilanes – 55
- Aprons – 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Gold Beach Municipal Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition.

This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Gold Beach Municipal Airport, the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT AND FUTURE PCI

| BranchID | SectionID | Past Inspection PCI | Current PCI | Predicted Future PCI | |
|-----------|-----------|---------------------|-------------|----------------------|------|
| | | 2019 | 2023 | 2028 | 2033 |
| A01GB | 01 | 76 | 74 | 68 | 63 |
| A01GB | 02 | 68 | 99 | 93 | 88 |
| A01GB | 03 | 71 | 78 | 72 | 67 |
| A01GB | 04 | 94 | 94 | 88 | 83 |
| ASRUNUPGB | 01 | 94 | 94 | 88 | 83 |
| R16GB | 01 | 97 | 89 | 84 | 79 |
| T01GB | 01 | 58 | 65 | 54 | 37 |
| T02GB | 01 | 94 | 89 | 83 | 78 |
| T02GB | 02 | 63 | 55 | 38 | 20 |
| TA1GB | 01 | 83 | 90 | 84 | 79 |
| TA1GB | 02 | 94 | 90 | 84 | 79 |
| TA2GB | 01 | 87 | 90 | 84 | 79 |
| TA3BG | 01 | 90 | 90 | 84 | 79 |
| TA3BG | 02 | 94 | 90 | 84 | 79 |
| TAGB | 01 | 94 | 93 | 87 | 81 |

Abbreviation: PCI = Pavement Condition Index

Table 2C: GOLD BEACH MUNICIPAL AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

| Branch ID | Section ID | Surface Type | Current PCI | Years to Major M&R | Major M&R Trigger PCI ¹ | Years to End of Functional Service Life |
|-----------|------------|--------------|-------------|--------------------|------------------------------------|---|
| A01GB | 01 | AC | 74 | > 20 | 50 | > 20 |
| A01GB | 02 | AC | 99 | > 20 | 50 | > 20 |
| A01GB | 03 | AC | 78 | > 20 | 50 | > 20 |
| A01GB | 04 | AC | 94 | > 20 | 50 | > 20 |
| ASRUNUPGB | 01 | AC | 94 | > 20 | 50 | > 20 |
| R16GB | 01 | AC | 89 | > 20 | 60 | > 20 |
| T01GB | 01 | AC | 65 | 0 - 5 | 55 | 6 - 10 |
| T02GB | 01 | AC | 89 | > 20 | 55 | > 20 |
| T02GB | 02 | AC | 55 | 0 - 5 | 55 | 0 - 5 |
| TA1GB | 01 | AC | 90 | > 20 | 55 | > 20 |
| TA1GB | 02 | AC | 90 | > 20 | 55 | > 20 |
| TA2GB | 01 | AC | 90 | > 20 | 55 | > 20 |
| TA3BG | 01 | AC | 90 | > 20 | 55 | > 20 |
| TA3BG | 02 | AC | 90 | > 20 | 55 | > 20 |
| TAGB | 01 | AC | 93 | > 20 | 55 | > 20 |

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

¹ Major M&R (Maintenance and Rehabilitation) Trigger PCI = Critical PCI

APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Gold Beach Municipal Airport pavement network condition over time. We used PAVER v7.0.8 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2024. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction – Considered for pavements with a PCI less than 40.
- Rehabilitation (AC Overlay) – Considered for pavements between 40 PCI and the critical PCI and for pavements exhibiting significant load-related distresses.
- Surface Treatment – Treatments (fog seal, slurry seal, thin AC overlay) are applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance – Maintenance performed on a routine basis, such as crack sealing, wide crack repair, and patching.

It should be noted that the 5-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use

to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

| Branch Use | Section Rank | | |
|------------|--------------|-----------|----------|
| | Primary | Secondary | Tertiary |
| RUNWAY | 1 | 3 | 6 |
| TAXIWAY | 2 | 5 | 8 |
| APRON | 4 | 7 | 9 |

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type costs to PCI. We reviewed the unit costs from the 2019 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Gold Beach Municipal Airport and information provided by the ODAV Pavement Maintenance Program (PMP) project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Gold Beach Municipal Airport. The costs represent the fully-loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: REGION 1 UNIT COST DATA

| Type of M&R | Work Type | Unit Cost | Work Unit |
|--------------------------------|--|-----------|-----------|
| Major M&R | Complete Reconstruction with AC | \$17.32 | Sq Ft |
| | Cold Mill and Overlay – 2 Inches Thick | \$7.64 | Sq Ft |
| Surface Treatment (Global) M&R | Surface Treatment - Slurry Seal | \$0.52 | Sq Ft |
| | Surface Treatment - Fog Seal | \$0.31 | Sq Ft |
| Localized Preventive M&R | Crack Sealing - AC | \$3.12 | Ft |
| | Crack Sealing - PCC | \$23.4 | Ft |
| | Crack Sealing – Wide Cracks | \$51.48 | Ft |
| | Joint Sealing – PCC | \$7.80 | Ft |
| | AC Patching – Full Depth | \$78.00 | Sq Ft |
| | PCC Patching – Full Depth | \$156.00 | Sq Ft |

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: GOLD BEACH MUNICIPAL AIRPORT NETWORK MAINTENANCE REPORT

| Branch ID | Section ID | Distress | Severity | Action | Work Quantity | Unit | Unit Cost | Work Cost | Section Total |
|-----------|------------|-------------------------|----------|--------------------|---------------|------|-----------|-----------|---------------|
| A01GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 7,797 | Ft | \$3.12 | \$24,328 | \$24,328 |
| A01GB | 02 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 3 | Ft | \$3.12 | \$10 | \$10 |
| A01GB | 03 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 6,204 | Ft | \$3.12 | \$19,356 | \$19,356 |
| R16GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 2,446 | Ft | \$3.12 | \$7,632 | \$7,632 |
| T01GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 425 | Ft | \$3.12 | \$1,326 | \$2,653 |
| T01GB | 01 | Block Cracking | Low | Crack Sealing - AC | 425 | Ft | \$3.12 | \$1,327 | |
| T02GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 24 | Ft | \$3.12 | \$75 | \$75 |
| T02GB | 02 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 452 | Ft | \$3.12 | \$1,410 | \$3,119 |
| T02GB | 02 | Block Cracking | Low | Crack Sealing - AC | 146 | Ft | \$3.12 | \$456 | |
| T02GB | 02 | Alligator Cracking | Medium | Patching - AC Deep | 16 | SqFt | \$78.00 | \$1,252 | |
| TA1GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 8 | Ft | \$3.12 | \$25 | \$25 |
| TA1GB | 02 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 8 | Ft | \$3.12 | \$25 | \$25 |
| TA2GB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 25 | Ft | \$3.12 | \$79 | \$79 |
| TA3BG | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 9 | Ft | \$3.12 | \$28 | \$28 |
| TA3BG | 02 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 9 | Ft | \$3.12 | \$28 | \$28 |
| TAGB | 01 | Long. & Trans. Cracking | Low | Crack Sealing - AC | 27 | Ft | \$3.12 | \$83 | \$83 |

Abbreviations:

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; Ft = Feet; SqFt = Square Feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

| Action Year | Branch ID | Section ID | Branch Use | Surface Type | Current PCI | Action | Area, square feet | Unit Cost per square foot | Total Cost |
|-------------|-----------|------------|------------|--------------|-------------|-------------|-------------------|---------------------------|------------|
| 2024 | T02GB | 02 | TAXIWAY | AC | 55 | Overlay | 4,042 | \$7.64 | \$30,882 |
| 2025 | A01GB | 01 | APRON | AC | 74 | Fog Seal | 117,218 | \$0.31 | \$36,337 |
| | A01GB | 03 | APRON | AC | 78 | Fog Seal | 100,647 | \$0.31 | \$31,200 |
| 2027 | T01GB | 01 | TAXIWAY | AC | 65 | Slurry Seal | 4,395 | \$0.52 | \$2,285 |
| | T02GB | 01 | TAXIWAY | AC | 89 | Slurry Seal | 1,636 | \$0.52 | \$851 |
| | TA1GB | 01 | TAXIWAY | AC | 90 | Slurry Seal | 2,678 | \$0.52 | \$1,393 |
| | TA1GB | 02 | TAXIWAY | AC | 90 | Slurry Seal | 1,890 | \$0.52 | \$983 |
| | TA2GB | 01 | TAXIWAY | AC | 90 | Slurry Seal | 4,679 | \$0.52 | \$2,433 |
| | TA3BG | 01 | TAXIWAY | AC | 90 | Slurry Seal | 2,688 | \$0.52 | \$1,398 |
| | TA3BG | 02 | TAXIWAY | AC | 90 | Slurry Seal | 1,421 | \$0.52 | \$739 |

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

| Cost Summary | |
|----------------------------------|------------------|
| 2024 Total Project Cost | \$30,882 |
| 2025 Total Project Cost | \$67,538 |
| 2026 Total Project Cost | \$0 |
| 2027 Total Project Cost | \$10,081 |
| 2028 Total Project Cost | \$0 |
| Total 5-Year Project Cost | \$108,501 |

APPENDIX E

Reinspection Report

Re-Inspection Report

ODA_2023Survey_11-21-23

Generated Date 12/5/2023

Page 1 of 15

| | | | | | | |
|-----------------------------|--------------|----------------------|---------------------------------|----------------------|--------------|-------------------------|
| Network: | Gold Beach | | Name: | Gold Beach Municipal | | |
| Branch: | A01GB | Name: | Apron 01 Gold Beach | | Use: | APRON |
| Area: | 259,373 SqFt | | | | | |
| Section: | 03 | of 4 | From: | A01GB-02 | | To: Hangars |
| Last Const.: | 9/1/1984 | | | | | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Apron_AC | Zone: | 4S1 | Category: D |
| Rank: | S | | | | | |
| Area: | 100,647 SqFt | Length: | 340 Ft | Width: | 300 Ft | |
| Slabs: | | Slab Length: | Ft | Slab Width: | Ft | Joint Length: Ft |
| Shoulder: | | Street Type: | | Grade: | 0 | Lanes: 0 |
| Section Comments: | | | | | | |
| Work Date: | 9/1/1984 | Work Type: | Base Course - Aggregate | | Code: | BA-AG |
| Is Major M&R: | False | | | | | |
| Work Date: | 9/1/1984 | Work Type: | New Construction - AC | | Code: | NC-AC |
| Is Major M&R: | True | | | | | |
| Work Date: | 9/1/2003 | Work Type: | Surface Treatment - Slurry Seal | | Code: | ST-SS |
| Is Major M&R: | False | | | | | |
| Work Date: | 9/1/2003 | Work Type: | Crack Sealing - AC | | Code: | CS-AC |
| Is Major M&R: | False | | | | | |
| Work Date: | 6/1/2011 | Work Type: | Crack Sealing - AC | | Code: | CS-AC |
| Is Major M&R: | False | | | | | |
| Last Insp. Date: | 7/1/2023 | TotalSamples: | 20 | Surveyed: | 5 | |
| Conditions: | PCI: | 78 | | | | |
| Inspection Comments: | | | | | | |
| Sample Number: | 04 | Type: | R | Area: | 5000.00 SqFt | PCI: 71 |
| Sample Comments: | | | | | | |
| 48 | L & T CR | L | 172.00 | Ft | | |
| 48 | L & T CR | L | 363.00 | Ft | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | |
| Sample Number: | 06 | Type: | R | Area: | 5000.00 SqFt | PCI: 77 |
| Sample Comments: | | | | | | |
| 48 | L & T CR | L | 339.00 | Ft | | |
| 48 | L & T CR | L | 4.00 | Ft | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | |
| Sample Number: | 08 | Type: | R | Area: | 5000.00 SqFt | PCI: 82 |
| Sample Comments: | | | | | | |
| 48 | L & T CR | L | 11.00 | Ft | | |
| 48 | L & T CR | L | 206.00 | Ft | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | |
| Sample Number: | 09 | Type: | R | Area: | 5000.00 SqFt | PCI: 81 |
| Sample Comments: | | | | | | |
| 48 | L & T CR | L | 230.00 | Ft | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | |
| Sample Number: | 13 | Type: | R | Area: | 5000.00 SqFt | PCI: 82 |
| Sample Comments: | | | | | | |
| 48 | L & T CR | L | 75.00 | Ft | | |
| 48 | L & T CR | L | 141.00 | Ft | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | |

| | | | | | | | | | | | | | |
|----------------------|--------------|---------|----------------------------|---------------------|----------------------|-----------|---------------------------------|---------------|---------|--------------|--------------|---------------|-------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | | | |
| Branch: | A01GB | | Name: | Apron 01 Gold Beach | | Use: | APRON | | Area: | 259,373 SqFt | | | |
| Section: | 01 | of | 4 | From: | Taxiway A | | | To: | Hangars | | Last Const.: | 9/1/1984 | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Apron_AC | | Zone: | 4S1 | | Category: | D | | Rank: | P | |
| Area: | 117,218 SqFt | | Length: | 625 Ft | | Width: | 200 Ft | | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | |
| Work Date: | 9/1/1984 | | Work Type: | | | | Base Course - Aggregate | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 9/1/1984 | | Work Type: | | | | New Construction - AC | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 9/1/2003 | | Work Type: | | | | Surface Treatment - Slurry Seal | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: | | | | Crack Sealing - AC | | Code: | CS-AC | | Is Major M&R: | False |
| Work Date: | 6/1/2011 | | Work Type: | | | | Crack Sealing - AC | | Code: | CS-AC | | Is Major M&R: | False |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 23 | | Surveyed: | 5 | | | | | | |
| Conditions: | PCI: 74 | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 72 | | | | | |
| Sample Comments: | | | | | | | | | | | | | |
| 45 | DEPRESSION | L | 220.00 | SqFt | | | | | | | | | |
| 48 | L & T CR | L | 97.00 | Ft | | | | | | | | | |
| 48 | L & T CR | L | 73.00 | Ft | | | | | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | | | | | |
| Sample Number: | 08 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 69 | | | | | |
| Sample Comments: | | | | | | | | | | | | | |
| 45 | DEPRESSION | L | 120.00 | SqFt | | | | | | | | | |
| 48 | L & T CR | L | 409.00 | Ft | | | | | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | | | | | |
| Sample Number: | 11 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 77 | | | | | |
| Sample Comments: | | | | | | | | | | | | | |
| 48 | L & T CR | L | 86.00 | Ft | | | | | | | | | |
| 48 | L & T CR | L | 252.00 | Ft | | | | | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | | | | | |
| Sample Number: | 15 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 76 | | | | | |
| Sample Comments: | | | | | | | | | | | | | |
| 48 | L & T CR | L | 369.00 | Ft | | | | | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | | | | | |
| Sample Number: | 16 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 75 | | | | | |
| Sample Comments: | | | | | | | | | | | | | |
| 48 | L & T CR | L | 77.00 | Ft | | | | | | | | | |
| 48 | L & T CR | L | 300.00 | Ft | | | | | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|---------|--|----------------------|--------------|-----------|--------|---------------|-------|---------------|----------|---|
| Network: | Gold Beach | | Name: | Gold Beach Municipal | | | | | | | | |
| Branch: | A01GB | | Name: | Apron 01 Gold Beach | | Use: | APRON | | Area: | 259,373 SqFt | | |
| Section: | 02 | of 4 | From: | A01GB-01 | | | To: | A01GB-03 | | Last Const.: | 9/1/1963 | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Apron_AC | | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 31,810 SqFt | | Length: | 265 Ft | | Width: | 120 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False | |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False | |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False | |
| Work Date: | 6/1/2011 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 7 | | Surveyed: | 4 | | | | | |
| Conditions: | PCI: 99 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 02 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 100 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| <No Distress> | | | | | | | | | | | | |
| Sample Number: | 03 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 98 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 2.00 Ft | | | | | | | | |
| Sample Number: | 05 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 100 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| <No Distress> | | | | | | | | | | | | |
| Sample Number: | 06 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 100 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| <No Distress> | | | | | | | | | | | | |

| | | | | | | | | | | | | |
|-----------------------------|---------------------|----------------|---|---------------------|----------------------|------------------|--------------|------------------|----------------------|--------------------------------|---------------------|-----------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | | |
| Branch: | A01GB | | Name: | Apron 01 Gold Beach | | Use: | APRON | | Area: | 259,373 SqFt | | |
| Section: | 04 | of | 4 | From: | Taxiway A | | | To: | Section 01 | | Last Const.: | 10/3/2012 |
| Surface: | AC | Family: | 2023_Region1_Cat4_Apron_AC | | Zone: | 4S1 | | Category: | D | | Rank: | S |
| Area: | 9,698 SqFt | | Length: | 654 Ft | | Width: | 15 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | | Ft | |
| Shoulder: | Street Type: | | | | Grade: | | 0 | | Lanes: | | 0 | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: False | | |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: False | | |
| Work Date: | 10/3/2012 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: True | | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 2 | | Surveyed: | | 2 | | | | |
| Conditions: | PCI: 94 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 6000.00 SqFt | | | PCI: | 94 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 6000.00 SqFt | | | | | | | | |
| Sample Number: | 02 | Type: | R | Area: | 3698.00 SqFt | | | PCI: | 94 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 3698.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|------------------------------------|------------------------|-------------|--------------|-----------|--------|---------------|---------------------|-----------|
| Network: | Gold Beach | | Name: | Gold Beach Municipal | | | | | | | |
| Branch: | ASRUNUPGB | | Name: | South Run-Up Apron | | Use: | APRON | | Area: | 13,318 SqFt | |
| Section: | 01 | of 1 | From: | South End of Taxiway A | | | To: | East | | Last Const.: | 10/3/2012 |
| Surface: | AC | Family: | 2023_Region1_Cat4_Apron_AC | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 13,318 SqFt | | Length: | 263 Ft | | Width: | 62 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | | Ft |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | | 0 | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: False | |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: False | |
| Work Date: | 10/3/2012 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: True | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 2 | | Surveyed: | | 2 | | | |
| Conditions: | PCI: | 94 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | | 6594.00 SqFt | | PCI: | 94 | | |
| Sample Comments: | | | | | | | | | | | |
| 57 | WEATHERING | | L | 6594.00 SqFt | | | | | | | |
| Sample Number: | 02 | Type: | R | Area: | | 6723.00 SqFt | | PCI: | 94 | | |
| Sample Comments: | | | | | | | | | | | |
| 57 | WEATHERING | | L | 6723.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|---------|--|-------------------------|----------------------|-----------|--------|---------------|---------------|---------------------|--------------|----------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | | |
| Branch: | R16GB | | Name: | Runway 16/34 Gold Beach | | Use: | RUNWAY | | Area: | 240,000 SqFt | | |
| Section: | 01 | of 1 | | From: | Runway 34 End | | | To: | Runway 16 End | | Last Const.: | 9/4/2006 |
| Surface: | AC | Family: | 2023_Region1_Cat4_Runway_AC | | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 240,000 SqFt | | Length: | 3,200 Ft | | Width: | 75 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: False | | |
| Work Date: | 9/2/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: True | | |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: False | | |
| Work Date: | 9/1/2003 | | Work Type: Patching - AC Deep | | | | Code: | PA-AD | | Is Major M&R: False | | |
| Work Date: | 9/1/2006 | | Work Type: Subgrade - Compacted | | | | Code: | SG-CO | | Is Major M&R: False | | |
| Work Date: | 9/2/2006 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: False | | |
| Work Date: | 9/3/2006 | | Work Type: Base Course - Crushed Aggregate | | | | Code: | BA-CA | | Is Major M&R: False | | |
| Work Date: | 9/4/2006 | | Work Type: Complete Reconstruction - AC | | | | Code: | CR-AC | | Is Major M&R: True | | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 43 | | Surveyed: | 6 | | | | | |
| Conditions: | PCI: 89 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 89 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 45.00 Ft | | | | | | | | |
| 48 | L & T CR | | L | 28.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |
| Sample Number: | 09 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 89 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 75.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |
| Sample Number: | 17 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 89 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 78.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |
| Sample Number: | 25 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 90 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 25.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |
| Sample Number: | 33 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 89 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 75.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |
| Sample Number: | 41 | Type: | R | Area: | 5625.00 SqFt | | | PCI: | 90 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 18.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5625.00 SqFt | | | | | | | | |

| | | | | | | | | | |
|-----------------------------|---------------------|----------------|---|-----------------------|----------------------|------------------|------------------|---------------|--------------------------------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | |
| Branch: | T01GB | | Name: | Taxiway 01 Gold Beach | | Use: | TAXIWAY | Area: | 4,395 SqFt |
| Section: | 01 | of | 1 | From: | A01GB-04 | | To: | A01BG-02 | Last Const.: 9/1/1963 |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | Zone: | 4S1 | | Category: | D | Rank: P |
| Area: | 4,395 SqFt | | Length: | 100 Ft | | Width: | 40 Ft | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: Ft |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 |
| Section Comments: | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | Is Major M&R: False |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | Is Major M&R: True |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | Is Major M&R: False |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | Is Major M&R: False |
| Work Date: | 6/1/2011 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | Is Major M&R: False |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | |
| Conditions: | PCI: 65 | | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 4395.00 SqFt | | PCI: | 65 | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 750.00 | SqFt | | | | | |
| 43 | BLOCK CR | L | 645.00 | SqFt | | | | | |
| 48 | L & T CR | L | 71.00 | Ft | | | | | |
| 48 | L & T CR | L | 299.00 | Ft | | | | | |
| 48 | L & T CR | L | 55.00 | Ft | | | | | |
| 57 | WEATHERING | L | 4395.00 | SqFt | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|--|-----------------------|----------------------|-------------|-----------|----------|---------------|---------------|-------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | |
| Branch: | T02GB | | Name: | Taxiway 02 Gold Beach | | Use: | TAXIWAY | Area: | 5,678 SqFt | | |
| Section: | 02 | of | 2 | From: | T02GB-01 | | To: | A01GB-02 | | | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | Zone: | 4S1 | | Category: | D | | | |
| Area: | 4,042 SqFt | | Length: | 100 Ft | | Width: | 40 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | Ft | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False |
| Work Date: | 6/1/2011 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: 1 | | | | | |
| Conditions: | PCI: 55 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 4042.00 SqFt | | PCI: | 55 | | | |
| Sample Comments: | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | M | 4.00 | SqFt | | | | | | |
| 43 | BLOCK CR | | L | 480.00 | SqFt | | | | | | |
| 48 | L & T CR | | L | 428.00 | Ft | | | | | | |
| 48 | L & T CR | | L | 24.00 | Ft | | | | | | |
| 50 | PATCHING | | L | 146.00 | SqFt | | | | | | |
| 57 | WEATHERING | | L | 4042.00 | SqFt | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|------------------------------------|-----------------------|----------------------|-----------|-----------|------------|---------------|---------------|-----------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | |
| Branch: | T02GB | | Name: | Taxiway 02 Gold Beach | | Use: | TAXIWAY | | Area: | 5,678 SqFt | |
| Section: | 01 | of 2 | From: | Taxiway A | | | To: | Section 02 | | Last Const.: | 10/3/2012 |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 1,636 SqFt | | Length: | 40 Ft | | Width: | 15 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | Ft | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 10/3/2012 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 89 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 1636.00 SqFt | | PCI: | 89 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 24.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 1636.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|------------|------------|------------------------------------|-------------------------------|--|----------------------|--------------|-------|---------------|---------------|-------|---|
| Network: | | Gold Beach | | Name: | | Gold Beach Municipal | | | | | | |
| Branch: | TA1GB | | Name: | Taxiway A1 Gold Beach | | Use: | TAXIWAY | Area: | 4,568 SqFt | | | |
| Section: | 02 of 2 | | From: | Section 01 | | To: | Taxiway A | | Last Const.: | 10/3/2012 | | |
| Surface: | AC | | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D | Rank: | P |
| Area: | 1,890 SqFt | | Length: | 36 Ft | | Width: | 40 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False | |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False | |
| Work Date: | 10/3/2012 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: 90 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 01 | | Type: | R | | Area: | 1890.00 SqFt | | PCI: | 90 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 8.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 1890.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|--|-----------------------|----------------------|-----------|---------|-----------|---------------|---------------|-------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | |
| Branch: | TA1GB | | Name: | Taxiway A1 Gold Beach | | Use: | TAXIWAY | Area: | 4,568 SqFt | | |
| Section: | 01 | of | 2 | From: | Runway 34 End | | | To: | Section 02 | | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D | | |
| Area: | 2,678 SqFt | | Length: | 56 Ft | | Width: | 40 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | Ft | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2001 | | Work Type: Patching - AC Deep | | | | Code: | PA-AD | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2006 | | Work Type: Subgrade - Compacted | | | | Code: | SG-CO | | Is Major M&R: | False |
| Work Date: | 9/2/2006 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False |
| Work Date: | 9/3/2006 | | Work Type: Base Course - Crushed Aggregate | | | | Code: | BA-CA | | Is Major M&R: | False |
| Work Date: | 9/4/2006 | | Work Type: Complete Reconstruction - AC | | | | Code: | CR-AC | | Is Major M&R: | True |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | | 1 | | | |
| Conditions: | PCI: 90 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 2678.00 SqFt | | PCI: | 90 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 8.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 2678.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|------------|---------|-------------------------------|---------------------------------|--------------|-------------|---------|-----------|---------------|--------------|---------------|-------|
| Network: | Gold Beach | | Name: | Gold Beach Municipal | | | | | | | | |
| Branch: | TA2GB | | Name: | Taxiway A2 Gold Beach | | Use: | TAXIWAY | | Area: | 4,679 SqFt | | |
| Section: | 01 | of | 1 | From: | Runway 16/34 | | To: | Taxiway A | | Last Const.: | 9/4/2006 | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 4,679 SqFt | | Length: | 86 Ft | | Width: | 35 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: | Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 9/1/1963 | | Work Type: | New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 9/1/1995 | | Work Type: | Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: | Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False |
| Work Date: | 9/1/2006 | | Work Type: | Subgrade - Compacted | | | | Code: | SG-CO | | Is Major M&R: | False |
| Work Date: | 9/2/2006 | | Work Type: | Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False |
| Work Date: | 9/3/2006 | | Work Type: | Base Course - Crushed Aggregate | | | | Code: | BA-CA | | Is Major M&R: | False |
| Work Date: | 9/4/2006 | | Work Type: | Complete Reconstruction - AC | | | | Code: | CR-AC | | Is Major M&R: | True |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: 90 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 5536.00 SqFt | | PCI: | 90 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 30.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5536.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|------------------------------------|-------------------------------|----------------------|-----------|--------------|---------------|-----------|---------------|-----------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | |
| Branch: | TA3BG | | Name: | Taxiway A3 Gold Beach | | Use: | TAXIWAY | | Area: | 4,109 SqFt | |
| Section: | 02 of 2 | | From: | Section 01 | | | To: | Taxiway A | | Last Const.: | 10/2/2012 |
| Surface: | AC | | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D Rank: P | |
| Area: | 1,421 SqFt | | Length: | 40 Ft | | Width: | 40 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 10/2/2012 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 90 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | | Type: | R | | Area: | 1421.00 SqFt | | PCI: | 90 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 9.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 1421.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|--|-----------------------|----------------------|-----------|---------|-----------|---------------|---------------|-------|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | |
| Branch: | TA3BG | | Name: | Taxiway A3 Gold Beach | | Use: | TAXIWAY | | Area: | 4,109 SqFt | |
| Section: | 01 | of | 2 | From: | Runway 16 End | | | To: | Taxiway A | | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D | | |
| Area: | 2,688 SqFt | | Length: | 57 Ft | | Width: | 40 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | Ft | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2001 | | Work Type: Patching - AC Deep | | | | Code: | PA-AD | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False |
| Work Date: | 9/1/2006 | | Work Type: Subgrade - Compacted | | | | Code: | SG-CO | | Is Major M&R: | False |
| Work Date: | 9/2/2006 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False |
| Work Date: | 9/3/2006 | | Work Type: Base Course - Crushed Aggregate | | | | Code: | BA-CA | | Is Major M&R: | False |
| Work Date: | 9/4/2006 | | Work Type: Complete Reconstruction - AC | | | | Code: | CR-AC | | Is Major M&R: | True |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 90 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 2688.00 SqFt | | PCI: | 90 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 9.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 2688.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|---------|--|----------------------|----------------------|-----------|---------|---------------|-------|---------------|-----------|---|
| Network: | Gold Beach | | | Name: | Gold Beach Municipal | | | | | | | |
| Branch: | TAGB | | Name: | Taxiway A Gold Beach | | Use: | TAXIWAY | | Area: | 79,558 SqFt | | |
| Section: | 01 | of 1 | | From: | Taxiway A1 | | To: | Taxiway A3 | | Last Const.: | 10/3/2012 | |
| Surface: | AC | Family: | 2023_Region1_Cat4_Taxi way_AC | | Zone: | 4S1 | | Category: | D | | Rank: | P |
| Area: | 79,558 SqFt | | Length: | 3,175 Ft | | Width: | 25 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 9/1/1963 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | |
| Work Date: | 9/1/1963 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False | |
| Work Date: | 9/1/1995 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False | |
| Work Date: | 9/1/2001 | | Work Type: Patching - AC Deep | | | | Code: | PA-AD | | Is Major M&R: | False | |
| Work Date: | 9/1/2003 | | Work Type: Crack Sealing - AC | | | | Code: | CS-AC | | Is Major M&R: | False | |
| Work Date: | 9/1/2003 | | Work Type: Surface Treatment - Slurry Seal | | | | Code: | ST-SS | | Is Major M&R: | False | |
| Work Date: | 10/1/2012 | | Work Type: Subbase - Aggregate | | | | Code: | SB-AG | | Is Major M&R: | False | |
| Work Date: | 10/2/2012 | | Work Type: Base Course - Aggregate | | | | Code: | BA-AG | | Is Major M&R: | False | |
| Work Date: | 10/3/2012 | | Work Type: Complete Reconstruction - AC | | | | Code: | CR-AC | | Is Major M&R: | True | |
| Last Insp. Date: | 7/1/2023 | | TotalSamples: | 16 | | Surveyed: | 5 | | | | | |
| Conditions: | PCI: 93 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 01 | Type: | R | Area: | 4987.00 SqFt | | PCI: | 94 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 4987.00 SqFt | | | | | | | | |
| Sample Number: | 04 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 94 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 08 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 91 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 8.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 12 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 94 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 16 | Type: | R | Area: | 3866.00 SqFt | | PCI: | 94 | | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 3866.00 SqFt | | | | | | | | |

APPENDIX F

Work History Report

12/14/2023

Work History Report

Page 1 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-13-2023-5pm

| Network: Gold Beach Municipal | | Branch: A01GB | Apron 01 Gold Be | | Section: 01 | Surface: AC |
|--------------------------------------|-------------------|---------------------------------|----------------------------|---------------------------|-------------------------------------|------------------------------|
| L.C.D. 9/1/1984 | Use: APRON | Rank: P | Length: 625.00 (Ft) | Width: 200.00 (Ft) | True Area: | 117218 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 6/1/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | <input type="checkbox"/> | PMP 2011 1"-0 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/2003 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1984 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 9/1/1984 | BA-AG | Base Course - Aggregate | 0.00 | 2.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: A01GB | Apron 01 Gold Be | | Section: 02 | Surface: AC |
|--------------------------------------|-------------------|---------------------------------|----------------------------|---------------------------|-------------------------------------|------------------------------|
| L.C.D. 9/1/1963 | Use: APRON | Rank: P | Length: 265.00 (Ft) | Width: 120.00 (Ft) | True Area: | 31810 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 6/1/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | <input type="checkbox"/> | PMP 2011 1"-0 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: A01GB | Apron 01 Gold Be | | Section: 03 | Surface: AC |
|--------------------------------------|-------------------|---------------------------------|----------------------------|---------------------------|-------------------------------------|------------------------------|
| L.C.D. 9/1/1984 | Use: APRON | Rank: S | Length: 340.00 (Ft) | Width: 300.00 (Ft) | True Area: | 100647 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 6/1/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | <input type="checkbox"/> | PMP 2011 1"-0 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/2003 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1984 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 9/1/1984 | BA-AG | Base Course - Aggregate | 0.00 | 2.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: A01GB | Apron 01 Gold Be | | Section: 04 | Surface: AC |
|--------------------------------------|-------------------|-------------------------|----------------------------|--------------------------|-------------------------------------|--------------------|
| L.C.D. 10/3/2012 | Use: APRON | Rank: S | Length: 654.00 (Ft) | Width: 15.00 (Ft) | True Area: | 9698 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 10/3/2012 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: ASRUNUPGBSouth Run-Up Apr | Section: 01 | | Surface: AC | |
|--------------------------------------|-------------------|--|----------------------------|--------------------------|-------------------------------------|--------------|
| L.C.D. 10/3/2012 | Use: APRON | Rank: P | Length: 263.00 (Ft) | Width: 61.50 (Ft) | True Area: | 13318 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 10/3/2012 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |

12/14/2023

Work History Report

Page 2 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-13-2023-5pm

| Network: Gold Beach Municipal | | Branch: R16GB | Runway 16/34 Gol | Section: 01 | Surface:AC | |
|-------------------------------|-----------|---------------------------------|------------------|-----------------------|-------------------------------------|--------------------------|
| L.C.D. 9/4/2006 | | Use: RUNWAY | Rank: P | Length: 3,200.00 (Ft) | Width: 75.00 (Ft) | True Area: 240000 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 9/4/2006 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | p-403 |
| 9/3/2006 | BA-CA | Base Course - Crushed Aggregate | 0.00 | 3.00 | <input type="checkbox"/> | P-209 |
| 9/2/2006 | SB-AG | Subbase - Aggregate | 0.00 | 11.00 | <input type="checkbox"/> | P-154 |
| 9/1/2006 | SG-CO | Subgrade - Compacted | 0.00 | 12.00 | <input type="checkbox"/> | P-152 |
| 9/1/2003 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | <input type="checkbox"/> | circa 2003 |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/2/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: T01GB | | Taxiway 01 Gold | | Section: 01 | | Surface: AC | |
|-------------------------------|-----------|---------------------------------|------|-----------------|-------------------------------------|---------------------|--|--|--|
| L.C.D. 9/1/1963 | | Use: TAXIWAY | | Rank: P | | Length: 100.00 (Ft) | | Width: 40.00 (Ft) True Area: 4395 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | | | |
| 6/1/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | <input type="checkbox"/> | PMP 2011 | | | |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | | | | |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | | | | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | | | | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | | | | |

| Network: Gold Beach Municipal Branch: T02GB Taxiway 02 Gold Section: 01 Surface:AC | | | | | | |
|--|-----------|-------------------------|---------|--------------------|-------------------------------------|------------------------|
| L.C.D. 10/3/2012 | | Use: TAXIWAY | Rank: P | Length: 40.00 (Ft) | Width: 15.00 (Ft) | True Area: 1636 (SqFt) |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 10/3/2012 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |

| Network: Gold Beach Municipal | | Branch: T02GB | | Taxiway 02 Gold | | Section: 02 | | Surface: AC | | | |
|-------------------------------|-----------|---------------------------------|------|-----------------|-------------------------------------|---------------------|--|-------------------|--|------------------------|--|
| L.C.D. 9/1/1963 | | Use: TAXIWAY | | Rank: P | | Length: 100.00 (Ft) | | Width: 40.00 (Ft) | | True Area: 4042 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | | | | | |
| 6/1/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | <input type="checkbox"/> | PMP 2011 | | | | | |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | | | | | | |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | | | | | | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | | | | | | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | | | | | | |

12/14/2023

Work History Report

Page 3 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-13-2023-5pm

Network: Gold Beach Municipal Branch: TA1GB Taxiway A1 Gold Section: 01 Surface: AC
 L.C.D. 9/4/2006 Use: TAXIWAY Rank: P Length: 56.00 (Ft) Width: 40.00 (Ft) True Area: 2678 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|---------------------------------|------|----------------|-------------------------------------|------------|
| 9/4/2006 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | p-403 |
| 9/3/2006 | BA-CA | Base Course - Crushed Aggregate | 0.00 | 3.00 | <input type="checkbox"/> | P-209 |
| 9/2/2006 | SB-AG | Subbase - Aggregate | 0.00 | 11.00 | <input type="checkbox"/> | P-154 |
| 9/1/2006 | SG-CO | Subgrade - Compacted | 0.00 | 12.00 | <input type="checkbox"/> | P-152 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/2003 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/2001 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | <input type="checkbox"/> | circa 2001 |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

Network: Gold Beach Municipal Branch: TA1GB Taxiway A1 Gold Section: 02 Surface: AC
 L.C.D. 10/3/2012 Use: TAXIWAY Rank: P Length: 36.40 (Ft) Width: 40.00 (Ft) True Area: 1890 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|-------------------------|------|----------------|-------------------------------------|----------|
| 10/3/2012 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |

Network: Gold Beach Municipal Branch: TA2GB Taxiway A2 Gold Section: 01 Surface: AC
 L.C.D. 9/4/2006 Use: TAXIWAY Rank: P Length: 85.50 (Ft) Width: 35.00 (Ft) True Area: 4679 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|---------------------------------|------|----------------|-------------------------------------|----------|
| 9/4/2006 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | p-403 |
| 9/3/2006 | BA-CA | Base Course - Crushed Aggregate | 0.00 | 3.00 | <input type="checkbox"/> | P-209 |
| 9/2/2006 | SB-AG | Subbase - Aggregate | 0.00 | 11.00 | <input type="checkbox"/> | P-154 |
| 9/1/2006 | SG-CO | Subgrade - Compacted | 0.00 | 12.00 | <input type="checkbox"/> | P-152 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

12/14/2023

Work History Report

Page 4 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-13-2023-5pm

Network: Gold Beach Municipal Branch: TA3BG Taxiway A3 Gold Section: 01 Surface: AC
 L.C.D. 9/4/2006 Use: TAXIWAY Rank: P Length: 57.00 (Ft) Width: 40.00 (Ft) True Area: 2688 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|---------------------------------|------|----------------|-------------------------------------|------------|
| 9/4/2006 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | p-403 |
| 9/3/2006 | BA-CA | Base Course - Crushed Aggregate | 0.00 | 3.00 | <input type="checkbox"/> | P-209 |
| 9/2/2006 | SB-AG | Subbase - Aggregate | 0.00 | 11.00 | <input type="checkbox"/> | P-154 |
| 9/1/2006 | SG-CO | Subgrade - Compacted | 0.00 | 12.00 | <input type="checkbox"/> | P-152 |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/2003 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/2001 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | <input type="checkbox"/> | circa 2001 |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

Network: Gold Beach Municipal Branch: TA3BG Taxiway A3 Gold Section: 02 Surface: AC
 L.C.D. 10/2/2012 Use: TAXIWAY Rank: P Length: 40.00 (Ft) Width: 40.00 (Ft) True Area: 1421 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|-------------------------|------|----------------|-------------------------------------|----------|
| 10/2/2012 | NC-AC | New Construction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |

Network: Gold Beach Municipal Branch: TAGB Taxiway A Gold B Section: 01 Surface: AC
 L.C.D. 10/3/2012 Use: TAXIWAY Rank: P Length: 3,175.00 (Ft) Width: 25.00 (Ft) True Area: 79558 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|---------------------------------|------|----------------|-------------------------------------|------------|
| 10/3/2012 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | <input checked="" type="checkbox"/> | P401 |
| 10/2/2012 | BA-AG | Base Course - Aggregate | 0.00 | 4.00 | <input type="checkbox"/> | P209 |
| 10/1/2012 | SB-AG | Subbase - Aggregate | 0.00 | 10.00 | <input type="checkbox"/> | |
| 9/1/2003 | CS-AC | Crack Sealing - AC | 0.00 | 0.10 | <input type="checkbox"/> | |
| 9/1/2003 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/2001 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | <input type="checkbox"/> | circa 2001 |
| 9/1/1995 | ST-SS | Surface Treatment - Slurry Seal | 0.00 | 0.50 | <input type="checkbox"/> | |
| 9/1/1963 | NC-AC | New Construction - AC | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |
| 9/1/1963 | BA-AG | Base Course - Aggregate | 0.00 | 6.00 | <input type="checkbox"/> | |

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|---------------------------------|---------------|-------------------|--------------------|--------------------|
| Base Course - Aggregate | 16 | 695,236.00 | 4.75 | 1.39 |
| Base Course - Crushed Aggregate | 4 | 250,045.00 | 3.00 | 0.00 |
| Complete Reconstruction - AC | 5 | 329,603.00 | 2.00 | 0.00 |
| Crack Sealing - AC | 14 | 605,827.01 | 0.06 | 0.05 |
| New Construction - AC | 15 | 615,678.00 | 1.47 | 0.50 |
| Patching - AC Deep | 4 | 324,924.00 | 0.00 | 0.00 |
| Subbase - Aggregate | 10 | 357,566.00 | 10.40 | 0.49 |
| Subgrade - Compacted | 4 | 250,045.00 | 12.00 | 0.00 |
| Surface Treatment - Slurry Seal | 13 | 672,639.00 | 0.50 | 0.00 |