

2023 ODAV Pavement Evaluation Program Sportsman Airpark

Newberg, Oregon

December 29, 2023

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY	1
3	PAVEMENT CONDITION INSPECTION RESULTS.....	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results.....	5
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	8
	4.1 Introduction.....	8
	4.2 Future Condition Analysis.....	8
	4.3 Functional Remaining Life	8
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	10
	5.1 Introduction.....	10
	5.2 Recommended Localized Maintenance.....	10
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan	10
6	LIMITATIONS.....	12

TABLES

Table 3-1:	ASTM PCI Rating Scale.....	5
Table 5-1:	Localized Maintenance Quantities.....	10
Table 5-2:	Surface Treatment, Rehabilitation, And Reconstruction Quantities	10

FIGURES

Figure 2.1:	Sportsman Airpark Location Map
Figure 2.2:	Sportsman Airpark Pavement Area by Surface Type
Figure 2.3:	Sportsman Airpark Pavement Area by Branch Use
Figure 2.4:	Sportsman Airpark Pavement Inventory
Figure 3.1:	Sportsman Airpark 2023 PCI Survey Results
Figure 3.2:	Sportsman Airpark Pavement Condition Rating by Percent of Area
Figure 4.1:	Sportsman Airpark Future Pavement Condition
Figure 5.1:	Sportsman Airpark 5-Year Pavement Management Plan

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan
Appendix E:	Reinspection Report
Appendix F:	Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a five-year plan comprised of maintenance, surface treatment, rehabilitation, and reconstruction projects for the Sportsman Airpark in Newberg, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Sportsman Airpark in 2023 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Sportsman Airpark is located in Newberg, Oregon, and is owned and operated by Jerry and Lessie Dale. The airport consists of a single runway, a taxiway, two connector taxiways, and three aprons that serve a variety of general aviation aircraft. The general location of the airport is shown below on the Sportsman Airpark Location Map, Figure 2.1.



Figure 2.1: SPORTSMAN AIRPARK LOCATION MAP

The airside pavements at the Sportsman Airpark are comprised of asphalt concrete (AC) and AC overlaid with AC (AAC). The airport pavements, delineated by surface type and branch use, are shown on the Sportsman Airpark Percent of Pavement Area by Surface Type, Figure 2.2, and on the Sportsman Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on the Sportsman Airpark Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report, Table 1F.




Figure 2.2: SPORTSMAN AIRPARK PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3: SPORTSMAN AIRPARK PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Agg. = AGGREGATE



3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Sportsman Airpark in July 2023. The 2023 survey work was performed on sections last inspected in 2018 in order to update the Sportsman Airpark inspection data. GRI performed the 2023 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.


3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Sportsman Airpark is approximately 96. The section PCIs ranged from a low of 69 to a high of 100. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking and fatigue (alligator) cracking. Section PCIs following our pavement survey are displayed below spatially on the Sportsman Airpark 2023 PCI Survey Results, Figure 3.1.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



The condition distribution of the network by percent of total pavement area is provided on the Sportsman Airpark Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2023 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2: SPORTSMAN AIRPARK PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Sportsman Airpark are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 96 to a value of 91 in 2028 and 86 in 2033 if no maintenance or rehabilitation work is performed. The projected pavement condition in 5 years and 10 years for each pavement section at Sportsman Airpark is displayed spatially on the Sportsman Airpark Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Sportsman Airpark. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Sportsman Airpark are summarized in Table 2C in Appendix C.

PREDICTED CONDITION IN 2028




PREDICTED CONDITION IN 2033



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priority and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Quantity
Asphalt Concrete Crack Sealing	2,866 linear feet
Asphalt Concrete Full-Depth Patching	24 linear feet

5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan


To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the Sportsman Airpark 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

Treatment Type	Quantity, square feet
Reconstruction	0
Overlay	0
Fog Seal	31,364
Slurry Seal	5,885



ACTION TIMING		ACTION	
	2024		FOG SEAL
	2025		SLURRY SEAL
	2026		OVERLAY
	2027		RECONSTRUCTION
	2028		ROUTINE MAINTENANCE



6 LIMITATIONS

This report has been prepared to assist the Oregon Department of Aviation (ODAV) with pavement-related project planning for the Sportsman Airpark. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Sportsman Airpark would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025
Lindsi A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Engineering Staff

This document has been submitted electronically.

APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Sportsman Airpark is located in Newberg, Oregon, and is owned and operated by Jerry & Lessie Dale. The pavement network/facilities at Sportsman Airpark serve a variety of general aviation aircraft. Sportsman Airpark consists of a single runway, a taxiway, two taxiway connectors, and three aprons. The types of airside pavements include asphalt concrete (AC) and AC overlaid with AC (AAC).

The current airport pavement management system (APMS) network at Sportsman Airpark has an approximate area of 281,566 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Sportsman Airpark contains 10 branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as “*a contiguous pavement area having uniform construction, maintenance, usage history, and condition.*” All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Sportsman Airpark contains 14 sections that are managed by Jerry and Lessie Dale, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement’s prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2023 Sportsman Airpark PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Sportsman Airpark were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A: SPORTSMAN AIRPARK PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01SP	Apron 01 Sportsman	2	20,864
A02SP	Apron 02 Sportsman	1	10,500
A03SP	Apron 03 Sportsman	1	5,310
A04SP	Apron 04 Sportsman	1	9,250
A05SP	Apron 05 Sportsman	1	36,815
R17SP	Runway 17/35 Sportsman	4	147,079
T01SP	Taxiway 01 Sportsman	4	40,176
T02SP	Taxiway 02 Sportsman	2	3,702
T03SP	Taxiway 03 Sportsman	1	4,551
T04SP	Taxiway 04 Sportsman	1	3,319

Table 2A: SPORTSMAN AIRPARK CURRENT PAVEMENT INVENTORY

BranchID	Branch Name	Branch Use	SectionID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type
A01SP	Apron 01 Sportsman	APRON	01	Apron 02	FBO	P	168	32	5,321	8/1/1997	AC
A01SP	Apron 01 Sportsman	APRON	02	Section 01	Hangar	P	185	105	15,543	8/2/1997	AC
A02SP	Apron 02 Sportsman	APRON	01	Taxiway 02	Apron 01	P	150	70	10,500	8/1/1997	AAC
A03SP	Apron 03 Sportsman	APRON	01	Runway 17/35	End	P	140	50	5,310	9/1/2023	AC
A04SP	Apron 04 Sportsman	APRON	01	R17SP-03	R17SP-03	P	200	50	9,250	9/2/2023	AC
A05SP	Apron 05 Sportsman	APRON	01	T01SP-01	T01SP-02	P	185	135	36,815	9/2/2023	AC
R17SP	Runway 17/35 Sportsman	RUNWAY	01	Runway 17 End	Section 02	P	375	50	20,229	9/1/2023	AC
R17SP	Runway 17/35 Sportsman	RUNWAY	02	Section 01	Section 03	P	2,075	50	103,750	9/1/2023	AC
R17SP	Runway 17/35 Sportsman	RUNWAY	03	Section 02	Runway 35 End	P	295	50	14,750	9/1/2023	AC
R17SP	Runway 17/35 Sportsman	RUNWAY	04	R17SP-03	End	P	167	50	8,350	9/2/2023	AC
T01SP	Taxiway 01 Sportsman	TAXIWAY	01	Apron 01	T01SP-02	P	154	30	4,722	9/2/2023	AAC
T01SP	Taxiway 01 Sportsman	TAXIWAY	02	T01SP-01	T01SP-03	P	347	30	10,015	9/2/2023	AC
T01SP	Taxiway 01 Sportsman	TAXIWAY	03	T01SP-02	T01SP-04	P	1,165	20	23,302	9/2/2023	AC
T01SP	Taxiway 01 Sportsman	TAXIWAY	04	T01SP-03	Runway 35 End	P	30	100	2,137	9/2/2023	AC
T02SP	Taxiway 02 Sportsman	TAXIWAY	01	Runway 17/35	Section 02	P	70	30	2,368	9/2/2023	AC
T02SP	Taxiway 02 Sportsman	TAXIWAY	02	Section 01	Apron 02	P	40	30	1,334	8/1/1997	AAC
T03SP	Taxiway 03 Sportsman	TAXIWAY	01	Runway 17/35	Taxiway 01	P	168	25	4,551	8/2/1997	AC
T04SP	Taxiway 04 Sportsman	TAXIWAY	01	R17SP-03	T01SP-03	P	135	20	3,319	9/2/2023	AC

Abbreviations:

P = Primary pavement


LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)

AC = Asphalt Concrete, AAC = Asphalt overlaid Asphalt

Table 3A: EXAMPLE SAMPLE RATES FOR AC PAVEMENTS


AC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n
1	1
2-3	2
4-6	3
7-13	4
14-38	5
39+	6

Note: AC = Asphalt Concrete



LEGEND

- SECTION
- SAMPLE UNIT



**SPORTSMAN AIRPARK
SAMPLE UNIT LAYOUT**

APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC and AAC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE PAVEMENT

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load
42	Bleeding	Other
43	Block Cracking	Climate/ Durability
44	Corrugation	Other
45	Depression	Other
46	Jet Blast	Other
47	Joint Reflection Cracking	Climate/ Durability
48	Longitudinal & Transverse Cracking	Climate/ Durability
49	Oil Spillage	Other
50	Patching	Climate/ Durability
51	Polished Aggregate	Other
52	Raveling	Climate/ Durability
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional”– defined as nonrepresentative instead of random- are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

“The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.”

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling.
- **Other factors:** Includes oil spillage, bleeding, and patching.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Sportsman Airpark pavement network consists of 10 branches and 18 sections. A total of 37 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2023 PCI survey, the area-weighted average PCI for the entire pavement network at Sportsman Airpark is approximately 96, which corresponds to a PCI rating of Good.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2023 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Sportsman Airpark pavement sections is outlined in Table 4B in this appendix.

Table 2B: SPORTSMAN AIRPARK CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01SP	2	20,864	APRON	70	Fair
A02SP	1	10,500	APRON	70	Fair
A03SP	1	5,310	APRON	100	Good
A04SP	1	9,250	APRON	100	Good
A05SP	1	36,815	APRON	100	Good
R17SP	4	147,079	RUNWAY	100	Good
T01SP	4	40,176	TAXIWAY	100	Good
T02SP	2	3,702	TAXIWAY	89	Good
T03SP	1	4,551	TAXIWAY	75	Satisfactory
T04SP	1	3,319	TAXIWAY	100	Good

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	6	82,739	89
RUNWAY	4	147,079	100
TAXIWAY	8	51,748	97
ALL	18	281,566	96

Abbreviation: PCI = Pavement Condition Index

Table 3B: SPORTSMAN AIRPARK 2023 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01SP	01	8/1/1997	AC	APRON	11/28/2023	26	70	Fair	74	26	0
A01SP	02	8/2/1997	AC	APRON	11/28/2023	26	70	Fair	100	0	0
A02SP	01	8/1/1997	AAC	APRON	11/28/2023	26	70	Fair	100	0	0
A03SP	01	9/1/2023	AC	APRON	11/28/2023	0	100	Good	100	0	0
A04SP	01	9/2/2023	AC	APRON	11/28/2023	0	100	Good	0	0	0
A05SP	01	9/2/2023	AC	APRON	11/28/2023	0	100	Good	0	0	0
R17SP	01	9/1/2023	AC	RUNWAY	11/28/2023	0	100	Good	0	0	0
R17SP	02	9/1/2023	AC	RUNWAY	11/28/2023	0	100	Good	0	0	0
R17SP	03	9/1/2023	AC	RUNWAY	11/28/2023	0	100	Good	0	0	0
R17SP	04	9/2/2023	AC	RUNWAY	11/28/2023	0	100	Good	0	0	0
T01SP	01	9/2/2023	AAC	TAXIWAY	11/28/2023	0	100	Good	100	0	0
T01SP	02	9/2/2023	AC	TAXIWAY	11/28/2023	0	100	Good	100	0	0
T01SP	03	9/2/2023	AC	TAXIWAY	11/28/2023	0	100	Good	0	0	0
T01SP	04	9/2/2023	AC	TAXIWAY	11/28/2023	0	100	Good	0	0	0
T02SP	01	9/2/2023	AC	TAXIWAY	11/28/2023	0	100	Good	100	0	0
T02SP	02	8/1/1997	AAC	TAXIWAY	11/28/2023	26	69	Fair	100	0	0
T03SP	01	8/2/1997	AC	TAXIWAY	11/28/2023	26	75	Satisfactory	100	0	0
T04SP	01	9/2/2023	AC	TAXIWAY	11/28/2023	0	100	Good	0	0	0

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = Asphalt overlaid Asphalt

Table 4B: SPORTSMAN AIRPARK COMPARISON OF PREVIOUS INSPECTION AND 2023 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2018 Survey			2023 Survey			Age ⁴	Δ PCI/yr ⁵	Rate of Deterioration
					PCI ³	PCI Category	Inspection Date	PCI	PCI Category				
A01SP	01	AC	5,321	8/1/97	71	Satisfactory	5/10/2018	70	Fair	21	-0.19		NORMAL
A01SP	02	AC	15,543	8/2/97	92	Good	5/10/2018	70	Fair	21	-4		HIGH
A02SP	01	AAC	10,500	8/1/97	74	Satisfactory	5/10/2018	70	Fair	21	-0.78		NORMAL
A03SP	01	AC	5,310	9/1/23	32	Very Poor	5/10/2018	100	Good	-5	13		NONE
A04SP	01	AC	9,250	9/2/23	-	-	-	100	Good	-	-		N/A ⁶
A05SP	01	AC	36,815	9/2/23	-	-	-	100	Good	-	-		N/A
R17SP	01	AC	20,229	9/1/23	27	Very Poor	5/10/2018	100	Good	-5	14.19		NONE
R17SP	02	AC	103,750	9/1/23	36	Very Poor	5/10/2018	100	Good	-5	12		NONE
R17SP	03	AC	14,750	9/1/23	40	Very Poor	5/10/2018	100	Good	-5	11.66		NONE
R17SP	04	AC	8,350	9/2/23	-	-	-	100	Good	-	-		N/A
T01SP	01	AAC	4,722	9/2/23	67	Fair	5/10/2018	100	Good	-5	6.41		NONE
T01SP	02	AC	10,015	9/2/23	0	Failed	5/10/2018	100	Good	-5	19		NONE
T01SP	03	AC	23,302	9/2/23	62	Fair	5/10/2018	100	Good	-5	7.39		NONE
T01SP	04	AC	2,137	9/2/23	13	Serious	5/10/2018	100	Good	-5	17		NONE
T02SP	01	AC	2,368	9/2/23	25	Serious	5/10/2018	100	Good	-5	14.58		NONE
T02SP	02	AAC	1,334	8/1/97	77	Satisfactory	5/10/2018	69	Fair	21	-2		NORMAL
T03SP	01	AC	4,551	8/2/97	81	Satisfactory	5/10/2018	75	Satisfactory	21	-1.11		NORMAL
T04SP	01	AC	3,319	9/2/23	-	Good	-	100	Good	-	-		N/A

Abbreviations:

¹ AC = Asphalt Concrete, AAC = Asphalt overlaid Asphalt

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

³ PCI = Pavement Condition Index

⁴ Age = Pavement age in years at the time of the PCI survey in 2018

⁵ Δ PCI/yr = Change in PCI points per year between 2018 survey and 2023 survey

⁶ N/A =Not Applicable due to changes in sectioning

APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data-outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Sportsman Airpark. The delineation is based on branch use, surface type, section rank, and structural design life. We use three distinct models for the following “families” of pavements at Sportsman Airpark. For each model, we reviewed the data in order to filter out any inconsistent or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 3C below.




Figure 1C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC APRONS




Figure 2C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC RUNWAYS




Figure 3C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 4 AC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Sportsman Airpark:

- Runways – 60
- Taxiways/Taxilanes – 55
- Aprons – 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Sportsman Airpark, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition.

This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Sportsman Airpark: the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT AND FUTURE PCI

BranchID	SectionID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2018	2023	2028	2033
A01SP	01	71	70	64	59
A01SP	02	92	70	64	59
A02SP	01	74	70	64	59
A03SP	01	32	100	94	89
A04SP	01	-	100	95	89
A05SP	01	-	100	95	89
R17SP	01	27	100	94	91
R17SP	02	36	100	94	91
R17SP	03	40	100	94	91
R17SP	04	-	100	95	91
T01SP	01	67	100	96	90
T01SP	02	0	100	96	90
T01SP	03	62	100	96	90
T01SP	04	13	100	96	90
T02SP	01	25	100	96	90
T02SP	02	77	69	62	49
T03SP	01	81	75	73	70
T04SP	01	-	100	97	91

Abbreviation: PCI = Pavement Condition Index

Table 2C: SPORTSMAN AIRPARK FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service Life
A01SP	01	AC	70	16 - 20	50	> 20
A01SP	02	AC	70	16 - 20	50	> 20
A02SP	01	AAC	70	16 - 20	50	> 20
A03SP	01	AC	100	> 20	50	> 20
A04SP	01	AC	100	> 20	50	> 20
A05SP	01	AC	100	> 20	50	> 20
R17SP	01	AC	100	> 20	60	> 20
R17SP	02	AC	100	> 20	60	> 20
R17SP	03	AC	100	> 20	60	> 20
R17SP	04	AC	100	> 20	60	> 20
T01SP	01	AAC	100	> 20	55	> 20
T01SP	02	AC	100	> 20	55	> 20
T01SP	03	AC	100	> 20	55	> 20
T01SP	04	AC	100	> 20	55	> 20
T02SP	01	AC	100	> 20	55	> 20
T02SP	02	AAC	69	6 - 10	55	11 - 15
T03SP	01	AC	75.3	> 20	55	> 20
T04SP	01	AC	100	> 20	55	> 20

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = Asphalt overlaid Asphalt

¹ Major M&R (Maintenance and Rehabilitation) Trigger PCI = Critical PCI

APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Sportsman Airpark pavement network condition over time. We used PAVER v7.0.8 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2024. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction – Considered for pavements with a PCI less than 40.
- Rehabilitation (AC Overlay) – Considered for pavements between 40 PCI and the critical PCI and for pavements exhibiting significant load-related distresses.
- Surface Treatment – Treatments (fog seal, slurry seal, thin AC overlay) are applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance – Maintenance performed on a routine basis, such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use

to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2018 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Sportsman Airpark and information provided by the ODAV Pavement Maintenance Program (PMP) project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Sportsman Airpark. The costs represent the fully-loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: REGION 1 UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major M&R	Complete Reconstruction with AC	\$17.32	Sq Ft
	Cold Mill and Overlay – 2 Inches Thick	\$7.64	Sq Ft
Surface Treatment (Global) M&R	Surface Treatment - Slurry Seal	\$0.52	Sq Ft
	Surface Treatment - Fog Seal	\$0.31	Sq Ft
Localized Preventive M&R	Crack Sealing - AC	\$3.12	Ft
	Crack Sealing - PCC	\$23.4	Ft
	Crack Sealing – Wide Cracks	\$51.48	Ft
	Joint Sealing – PCC	\$7.80	Ft
	AC Patching – Full Depth	\$78.00	Sq Ft
	PCC Patching – Full Depth	\$156.00	Sq Ft

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: SPORTSMAN AIRPARK NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01SP	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	310	Ft	\$3.12	\$967	\$4,103
A02SP	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,005	Ft	\$3.12	\$3,136	
T03SP	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	80	Ft	\$3.12	\$250	
T03SP	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	157	Ft	\$3.12	\$490	\$739
A01SP	01	Alligator Cracking	Medium	Patching - AC Deep	24	SqFt	\$78.00	\$1,824	\$1,824
T02SP	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	114	Ft	\$3.12	\$356	\$356
T02SP	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	12	Ft	\$3.12	\$37	\$37
A01SP	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,122	Ft	\$3.12	\$3,500	
A01SP	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	66	Ft	\$3.12	\$205	\$3,706

Abbreviations:

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; Ft = Feet; SqFt = Square Feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2024	A01SP	01	APRON	AC	70	Fog Seal	5,321	\$0.31	\$1,650
	A01SP	02	APRON	AC	70	Fog Seal	15,543	\$0.31	\$4,818
	A02SP	01	APRON	AAC	70	Fog Seal	10,500	\$0.31	\$3,255
	T02SP	02	TAXIWAY	AAC	69	Slurry Seal	1,334	\$0.52	\$694
	T03SP	01	TAXIWAY	AC	75	Slurry Seal	4,551	\$0.52	\$2,367

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = Asphalt overlaid Asphalt

Cost Summary	
2024 Total Project Cost	\$12,783
2025 Total Project Cost	\$0
2026 Total Project Cost	\$0
2027 Total Project Cost	\$0
2028 Total Project Cost	\$0
Total 5-Year Project Cost	\$12,783

APPENDIX E

Reinspection Report

Re-Inspection Report

ODA_2023Survey_11-21-23

Generated Date 12/5/2023

Network:	Sportsman		Name:	Sportsman Airpark					
Branch:	A01SP	Name:	Apron 01 Sportsman		Use:	APRON	Area:	20,864 SqFt	
Section:	01	of	2	From:	Apron 02	To:	FBO	Last Const.:	8/1/1997
Surface:	AC	Family:	2023_Region1_Cat4_Apron_AC	Zone:	2S6	Category:	F	Rank:	P
Area:	5,321 SqFt	Length:	168 Ft	Width:	32 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	8/1/1965	Work Type:	Subbase - Aggregate			Code:	SB-AG	Is Major M&R:	False
Work Date:	8/2/1965	Work Type:	Base Course - Aggregate			Code:	BA-AG	Is Major M&R:	False
Work Date:	8/3/1965	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	8/1/1997	Work Type:	Overlay - Thin			Code:	OL-ACTH	Is Major M&R:	True
Work Date:	9/1/2009	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Last Insp. Date:	7/1/2023	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	70							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5321.00 SqFt	PCI:	70		
Sample Comments:									
41	ALLIGATOR CR	M	8.00	SqFt					
48	L & T CR	L	310.00	Ft					
57	WEATHERING	M	5321.00	SqFt					

Network:	Sportsman			Name:	Sportsman Airpark						
Branch:	A01SP		Name:	Apron 01 Sportsman		Use:	APRON	Area:	20,864 SqFt		
Section:	02	of	2	From:	Section 01			To:	Hangar		
Surface:	AC	Family:	2023_Region1_Cat4_Apron_AC	Zone:	2S6			Category:	F		
Area:	15,543 SqFt		Length:	185 Ft		Width:	105 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	8/1/1997		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	8/2/1997		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Work Date:	9/1/2009		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	4		Surveyed:	3				
Conditions:	PCI:	70									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	3128.00 SqFt		PCI:	73			
Sample Comments:											
48	L & T CR	L	185.00 Ft								
48	L & T CR	M	32.00 Ft								
57	WEATHERING	L	3128.00 SqFt								
Sample Number:	02	Type:	R	Area:	5250.00 SqFt		PCI:	66			
Sample Comments:											
48	L & T CR	L	391.00 Ft								
48	L & T CR	M	19.00 Ft								
52	RAVELING	M	24.00 SqFt								
57	WEATHERING	L	5250.00 SqFt								
Sample Number:	03	Type:	R	Area:	3675.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR	L	294.00 Ft								
57	WEATHERING	L	3675.00 SqFt								

Network:	Sportsman		Name:	Sportsman Airpark									
Branch:	A02SP		Name:	Apron 02 Sportsman		Use:	APRON		Area:	10,500 SqFt			
Section:	01	of	1	From:	Taxiway 02			To:	Apron 01		Last Const.:	8/1/1997	
Surface:	AAC		Family:	2023_Region1_Cat4_Apron_AC		Zone:	2S6		Category:	F		Rank:	P
Area:	10,500 SqFt		Length:	150 Ft		Width:	70 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	8/1/1976		Work Type: Base Course - Aggregate					Code:	BA-AG		Is Major M&R:	False	
Work Date:	8/2/1976		Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R:	True	
Work Date:	8/1/1997		Work Type: Overlay - AC Thin					Code:	OL-AT		Is Major M&R:	True	
Work Date:	9/1/2009		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2						
Conditions:	PCI: 70												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5250.00 SqFt		PCI:	73			
Sample Comments:													
48	L & T CR		L	461.00 Ft									
57	WEATHERING		L	5250.00 SqFt									
Sample Number:	02		Type:	R		Area:	5250.00 SqFt		PCI:	66			
Sample Comments:													
48	L & T CR		L	544.00 Ft									
57	WEATHERING		L	4250.00 SqFt									
57	WEATHERING		M	1000.00 SqFt									

Network:	Sportsman			Name:	Sportsman Airpark				
Branch:	A03SP		Name:	Apron 03 Sportsman		Use:	APRON	Area:	5,310 SqFt
Section:	01	of	1	From:	Runway 17/35		To:	End	Last Const.: 8/2/1980
Surface:	AC	Family:	2023_Region1_Cat4_Apron_AC	Zone:	2S6		Category:	F	Rank: P
Area:	5,310 SqFt		Length:	140 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0
Section Comments:									
Work Date:	8/1/1980		Work Type: Base Course - Aggregate			Code:	BA-AG		Is Major M&R: False
Work Date:	8/2/1980		Work Type: New Construction - AC			Code:	NC-AC		Is Major M&R: True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed: 1			
Conditions:	PCI:	100							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5310.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									

Network:	Sportsman			Name:	Sportsman Airpark							
Branch:	R17SP		Name:	Runway 17/35 Sportsman		Use:	RUNWAY		Area:	138,729 SqFt		
Section:	01	of	3	From:	Runway 17 End			To:	Section 02		Last Const.:	8/3/1965
Surface:	AC	Family:	2023_Region1_Cat4_Runway_AC		Zone:	2S6		Category:	F		Rank:	P
Area:	20,229 SqFt		Length:	375 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	8/1/1982		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	5		Surveyed:	3					
Conditions:	PCI: 100											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	6478.00 SqFt		PCI:	100				
Sample Comments:												
<No Distress>												
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	100				
Sample Comments:												
<No Distress>												
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	100				
Sample Comments:												
<No Distress>												

Network:	Sportsman			Name:	Sportsman Airpark						
Branch:	R17SP		Name:	Runway 17/35 Sportsman		Use:	RUNWAY		Area:	138,729 SqFt	
Section:	03 of 3		From:	Section 02			To:	Runway 35 End		Last Const.:	8/3/1965
Surface:	AC		Family:	2023_Region1_Cat4_Runway_AC		Zone:	2S6		Category:	F Rank: P	
Area:	14,750 SqFt		Length:	295 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: False	
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	8/1/1982		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Last Insp. Date:	7/1/2023		TotalSamples:	3		Surveyed: 2					
Conditions:	PCI: 100										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											

Network:	Sportsman			Name:	Sportsman Airpark						
Branch:	R17SP		Name:	Runway 17/35 Sportsman		Use:	RUNWAY		Area:	138,729 SqFt	
Section:	02 of 3		From:	Section 01			To:	Section 03		Last Const.:	8/3/1965
Surface:	AC		Family:	2023_Region1_Cat4_Runway_AC		Zone:	2S6		Category:	F Rank: P	
Area:	103,750 SqFt		Length:	2,075 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	8/1/1982		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	21		Surveyed:	5				
Conditions:	PCI: 100										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	07		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	10		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	14		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	20		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											

Network: Sportsman		Name: Sportsman Airpark	
Branch: T01SP	Name: Taxiway 01 Sportsman	Use: TAXIWAY	Area: 40,176 SqFt
Section: 04 of 4	From: T01SP-03	To: Runway 35 End	Last Const.: 8/3/1965
Surface: AC	Family: 2023_Region1_Cat4_Taxiway_AC	Zone: 2S6	Category: F Rank: P
Area: 2,137 SqFt	Length: 30 Ft	Width: 100 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 8/1/1965	Work Type: Subbase - Aggregate		Code: SB-AG Is Major M&R: False
Work Date: 8/2/1965	Work Type: Base Course - Aggregate		Code: BA-AG Is Major M&R: False
Work Date: 8/3/1965	Work Type: New Construction - AC		Code: NC-AC Is Major M&R: True
Last Insp. Date: 7/1/2023	TotalSamples: 1	Surveyed: 1	
Conditions: PCI: 100			
Inspection Comments:			
Sample Number: 01	Type: R	Area: 3538.00 SqFt	PCI: 100
Sample Comments:			
<No Distress>			

Network:	Sportsman			Name:	Sportsman Airpark						
Branch:	T01SP		Name:	Taxiway 01 Sportsman		Use:	TAXIWAY	Area:	40,176 SqFt		
Section:	02	of 4	From:	T01SP-01			To:	T01SP-03		Last Const.:	8/3/1965
Surface:	AC	Family:	2023_Region1_Cat4_Taxi way_AC	Zone:	2S6		Category:	F		Rank:	P
Area:	10,015 SqFt		Length:	347 Ft		Width:	30 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:			Grade:	0		Lanes:		0		
Section Comments:											
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2				
Conditions:	PCI:	100									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	4500.00 SqFt		PCI:	100			
Sample Comments:											
<No Distress>											
Sample Number:	02	Type:	R	Area:	5515.00 SqFt		PCI:	100			
Sample Comments:											
<No Distress>											

Network:	Sportsman			Name:	Sportsman Airpark								
Branch:	T01SP		Name:	Taxiway 01 Sportsman		Use:	TAXIWAY	Area:	40,176 SqFt				
Section:	01	of 4	From:	Apron 01			To:	T01SP-02		Last Const.:	8/1/1997		
Surface:	AAC		Family:	2023_Region1_Cat4_Taxi way_AC		Zone:	2S6		Category:	F		Rank:	P
Area:	4,722 SqFt		Length:	154 Ft		Width:	30 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False		
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False		
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	8/1/1997		Work Type: Overlay - AC Thin				Code:	OL-AT		Is Major M&R:	True		
Work Date:	9/1/2009		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False		
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 100												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	4722.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													

Network:	Sportsman			Name:	Sportsman Airpark							
Branch:	T01SP		Name:	Taxiway 01 Sportsman		Use:	TAXIWAY	Area:	40,176 SqFt			
Section:	03	of 4	From:	T01SP-02			To:	T01SP-04		Last Const.:	8/2/1980	
Surface:	AC	Family:	2023_Region1_Cat4_Taxi way_AC		Zone:	2S6		Category:	F		Rank:	P
Area:	23,302 SqFt		Length:	1,165 Ft		Width:	20 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	8/1/1980		Work Type:	Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	False	
Work Date:	8/2/1980		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2009		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	4		Surveyed:	3					
Conditions:	PCI:	100										
Inspection Comments:												
Sample Number:	02	Type:	R	Area:	6000.00 SqFt			PCI:	100			
Sample Comments:												
<No Distress>												
Sample Number:	03	Type:	R	Area:	6000.00 SqFt			PCI:	100			
Sample Comments:												
<No Distress>												
Sample Number:	04	Type:	R	Area:	5302.00 SqFt			PCI:	100			
Sample Comments:												
<No Distress>												

Network:	Sportsman			Name:	Sportsman Airpark				
Branch:	T02SP		Name:	Taxiway 02 Sportsman		Use:	TAXIWAY	Area:	3,702 SqFt
Section:	02	of	2	From:	Section 01		To:	Apron 02	Last Const.: 8/1/1997
Surface:	AAC	Family:	2023_Region1_Cat4_Taxi way_AC	Zone:	2S6		Category:	F	Rank: P
Area:	1,334 SqFt		Length:	40 Ft		Width:	30 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0
Section Comments:									
Work Date:	8/1/1965		Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	8/2/1965		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	8/3/1965		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True
Work Date:	8/1/1997		Work Type: Overlay - AC Thin				Code:	OL-AT	Is Major M&R: True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1		
Conditions:	PCI: 69								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	1334.00 SqFt		PCI:	69	
Sample Comments:									
48	L & T CR		L	114.00 Ft					
48	L & T CR		M	12.00 Ft					
57	WEATHERING		L	1334.00 SqFt					

Network: Sportsman		Name: Sportsman Airpark	
Branch: T02SP	Name: Taxiway 02 Sportsman	Use: TAXIWAY	Area: 3,702 SqFt
Section: 01 of 2	From: Runway 17/35	To: Section 02	Last Const.: 8/3/1965
Surface: AC	Family: 2023_Region1_Cat4_Taxi way_AC	Zone: 2S6	Category: F Rank: P
Area: 2,368 SqFt	Length: 70 Ft	Width: 30 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 8/1/1965	Work Type: Subbase - Aggregate		Code: SB-AG Is Major M&R: False
Work Date: 8/2/1965	Work Type: Base Course - Aggregate		Code: BA-AG Is Major M&R: False
Work Date: 8/3/1965	Work Type: New Construction - AC		Code: NC-AC Is Major M&R: True
Last Insp. Date: 7/1/2023	TotalSamples: 1	Surveyed: 1	
Conditions: PCI: 100			
Inspection Comments:			
Sample Number: 01	Type: R	Area: 2368.00 SqFt	PCI: 100
Sample Comments:			
<No Distress>			

Network:		Sportsman		Name:		Sportsman Airpark	
Branch:		T03SP		Name:		Taxiway 03 Sportsman	
Use:		TAXIWAY		Area:		4,551 SqFt	
Section:		01 of 1		From:		Runway 17/35	
To:		Taxiway 01		Last Const.:		8/2/1997	
Surface:		AC		Family:		2023_Region1_Cat4_Taxi way_AC	
Zone:		2S6		Category:		F	
Rank:		P		Area:		4,551 SqFt	
Length:		168 Ft		Width:		25 Ft	
Slabs:		Slab Length:		Ft		Slab Width:	
Ft		Joint Length:		Ft		Shoulder:	
Street Type:		Grade:		0		Lanes:	
0		Section Comments:		Work Date:		8/1/1997	
Work Type:		Base Course - Aggregate		Code:		BA-AG	
Is Major M&R:		False		Work Date:		8/2/1997	
Work Type:		New Construction - AC		Code:		NC-AC	
Is Major M&R:		True		Last Insp. Date:		7/1/2023	
TotalSamples:		1		Surveyed:		1	
Conditions:		PCI:		75		Inspection Comments:	
Sample Number:		01		Type:		R	
Area:		4551.00 SqFt		PCI:		75	
Sample Comments:		48		L & T CR		L	
157.00		Ft		48		L & T CR	
80.00		Ft		57		WEATHERING	
4551.00		SqFt					

APPENDIX F

Work History Report

12/13/2023

Work History Report

Page 1 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-12-2023-3pm

Network: Sportsman Airpark		Branch: A01SP		Apron 01 Sportsma		Section: 01	Surface: AC
L.C.D. 8/1/1997	Use: APRON	Rank: P	Length: 168.00 (Ft)	Width: 32.00 (Ft)	True Area: 5321 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2009	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/1997	OL- ACTH	Overlay - Thin	0.00	2.00	<input checked="" type="checkbox"/>		
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: A01SP		Apron 01 Sportsma		Section: 02	Surface: AC
L.C.D. 8/2/1997	Use: APRON	Rank: P	Length: 185.00 (Ft)	Width: 105.00 (Ft)	True Area: 15543 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2009	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/2/1997	CR-AC	Complete Reconstruction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/1/1997	BA-AG	Base Course - Aggregate	0.00	8.00	<input checked="" type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	7.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: A02SP		Apron 02 Sportsma		Section: 01	Surface: AAC
L.C.D. 8/1/1997	Use: APRON	Rank: P	Length: 150.00 (Ft)	Width: 70.00 (Ft)	True Area: 10500 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2009	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/1997	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1976	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/1/1976	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: A03SP		Apron 03 Sportsma		Section: 01	Surface: AC
L.C.D. 8/2/1980	Use: APRON	Rank: P	Length: 140.00 (Ft)	Width: 50.00 (Ft)	True Area: 5310 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/2/1980	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/1/1980	BA-AG	Base Course - Aggregate	0.00	12.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: A04SP		Apron 04 Sportsma		Section: 01	Surface: AC
L.C.D. 9/2/2023	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 50.00 (Ft)	True Area: 9250 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>		
9/1/2023	BA-AG	Base Course - Aggregate	0.00	12.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: A05SP		Apron 05 Sportsma		Section: 01	Surface: AC
L.C.D. 9/2/2023	Use: APRON	Rank: P	Length: 185.00 (Ft)	Width: 135.00 (Ft)	True Area: 36815 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2023	CR-AC	Complete Reconstruction - AC	184,075.00	3.00	<input checked="" type="checkbox"/>		
9/1/2023	BA-AG	Base Course - Aggregate	0.00	12.00	<input type="checkbox"/>		

12/13/2023

Work History Report

Page 2 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-12-2023-3pm

Network: Sportsman Airpark		Branch: R17SP	Runway 17/35 Spo		Section: 01	Surface: AC
L.C.D. 9/1/2023	Use: RUNWAY	Rank: P	Length: 375.00 (Ft)	Width: 50.00 (Ft)	True Area:	20229 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2023	MOL-3	Cold Mill and Overlay - 3 Inches	0.00	3.00	<input checked="" type="checkbox"/>	Extensive full-depth patching required during mill and inlay
8/1/1982	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>	

Network: Sportsman Airpark		Branch: R17SP	Runway 17/35 Spo		Section: 02	Surface: AC
L.C.D. 9/1/2023	Use: RUNWAY	Rank: P	Length: 2,075.00 (Ft)	Width: 50.00 (Ft)	True Area:	103750 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2023	MOL-3	Cold Mill and Overlay - 3 Inches	0.00	3.00	<input checked="" type="checkbox"/>	Extensive full-depth patching required during mill and inlay
8/1/1982	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>	

Network: Sportsman Airpark		Branch: R17SP	Runway 17/35 Spo		Section: 03	Surface: AC
L.C.D. 9/1/2023	Use: RUNWAY	Rank: P	Length: 295.00 (Ft)	Width: 50.00 (Ft)	True Area:	14750 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2023	MOL-3	Cold Mill and Overlay - 3 Inches	0.00	3.00	<input checked="" type="checkbox"/>	Extensive full-depth patching required during mill and inlay
8/1/1982	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>	

Network: Sportsman Airpark		Branch: R17SP	Runway 17/35 Spo		Section: 04	Surface: AC
L.C.D. 9/2/2023	Use: RUNWAY	Rank: P	Length: 167.00 (Ft)	Width: 50.00 (Ft)	True Area:	8350 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	
9/1/2023	BA-AG	Base Course - Aggregate	0.00	12.00	<input type="checkbox"/>	

Network: Sportsman Airpark		Branch: T01SP	Taxiway 01 Sports		Section: 01	Surface: AAC
L.C.D. 8/1/1997	Use: TAXIWAY	Rank: P	Length: 154.00 (Ft)	Width: 30.00 (Ft)	True Area:	4722 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2009	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/1/1997	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>	

12/13/2023

Work History Report

Page 3 of 5

Pavement Database: ODA_2023Survey_MASTER DB-12-12-2023-3pm

Network: Sportsman Airpark		Branch: T01SP		Taxiway 01 Sports		Section: 02	Surface: AC
L.C.D. 8/3/1965	Use: TAXIWAY	Rank: P	Length: 347.00 (Ft)	Width: 30.00 (Ft)	True Area: 10015 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: T01SP		Taxiway 01 Sports		Section: 03	Surface: AC
L.C.D. 9/2/2023	Use: TAXIWAY	Rank: P	Length: 1,165.00 (Ft)	Width: 20.00 (Ft)	True Area: 23302 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2023	CR-AC	Complete Reconstruction - AC	116,510.00	3.00	<input checked="" type="checkbox"/>		
9/1/2023	BA-CT	Base Course - Cement Treated	0.00	12.00	<input type="checkbox"/>		
9/1/2009	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/2/1980	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/1/1980	BA-AG	Base Course - Aggregate	0.00	12.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: T01SP		Taxiway 01 Sports		Section: 04	Surface: AC
L.C.D. 8/3/1965	Use: TAXIWAY	Rank: P	Length: 30.00 (Ft)	Width: 100.00 (Ft)	True Area: 2137 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: T02SP		Taxiway 02 Sports		Section: 01	Surface: AC
L.C.D. 8/3/1965	Use: TAXIWAY	Rank: P	Length: 70.00 (Ft)	Width: 30.00 (Ft)	True Area: 2368 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: T02SP		Taxiway 02 Sports		Section: 02	Surface: AAC
L.C.D. 8/1/1997	Use: TAXIWAY	Rank: P	Length: 40.00 (Ft)	Width: 30.00 (Ft)	True Area: 1334 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1997	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>		
8/3/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/1965	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>		
8/1/1965	SB-AG	Subbase - Aggregate	0.00	10.00	<input type="checkbox"/>		

Network: Sportsman Airpark		Branch: T03SP		Taxiway 03 Sports		Section: 01	Surface: AC
L.C.D. 8/2/1997	Use: TAXIWAY	Rank: P	Length: 168.00 (Ft)	Width: 25.00 (Ft)	True Area: 4551 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/2/1997	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>		
8/1/1997	BA-AG	Base Course - Aggregate	0.00	8.00	<input type="checkbox"/>		

12/13/2023

Work History Report

Page 4 of 5

*Pavement Database: ODA_2023Survey_MASTER DB-12-12-2023-3pm***Network:** Sportsman Airpark**Branch:** T04SP

Taxiway 04 Sports

Section: 01**Surface:** AC**L.C.D.** 9/2/2023**Use:** TAXIWAY**Rank:** P**Length:** 135.00 (Ft)**Width:** 20.00 (Ft)**True Area:** 3319 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	
9/1/2023	BA-CT	Base Course - Cement Treated	0.00	12.00	<input type="checkbox"/>	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	17	278,247.00	6.94	3.51
Base Course - Cement Treated	2	26,621.00	12.00	0.00
Cold Mill and Overlay - 3 Inches	3	138,729.00	3.00	0.00
Complete Reconstruction - AC	3	75,660.00	2.67	0.47
Crack Sealing - AC	8	198,117.00	0.00	0.00
New Construction - AC	16	229,208.00	2.25	0.43
Overlay - AC Thin	3	16,556.00	2.00	0.00
Overlay - Thin	1	5,321.00	2.00	0.00
Subbase - Aggregate	10	180,169.00	9.70	0.90