

2023 ODAV Pavement Evaluation Program Stark's Twin Oaks Airpark

Hillsboro, Oregon

December 29, 2023

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY	1
3	PAVEMENT CONDITION INSPECTION RESULTS.....	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results	5
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	8
	4.1 Introduction.....	8
	4.2 Future Condition Analysis	8
	4.3 Functional Remaining Life.....	8
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	10
	5.1 Introduction.....	10
	5.2 Recommended Localized Maintenance.....	10
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan.....	10
6	LIMITATIONS.....	12

TABLES

Table 3-1:	ASTM PCI Rating Scale.....	5
Table 5-1:	Localized Maintenance Quantities.....	10
Table 5-2:	Surface Treatment, Rehabilitation, And Reconstruction Quantities	10

FIGURES

Figure 2.1:	Starks's Twin Oaks Airpark Location Map
Figure 2.2:	Starks's Twin Oaks Airpark Pavement Area by Surface Type
Figure 2.3:	Starks's Twin Oaks Airpark Pavement Area by Branch Use
Figure 2.4:	Starks's Twin Oaks Airpark Pavement Inventory
Figure 3.1:	Starks's Twin Oaks Airpark 2023 PCI Survey Results
Figure 3.2:	Starks's Twin Oaks Airpark Pavement Condition Rating by Percent of Area
Figure 4.1:	Starks's Twin Oaks Airpark Future Pavement Condition
Figure 5.1:	Starks's Twin Oaks Airpark 5-Year Pavement Management Plan

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan
Appendix E:	Reinspection Report
Appendix F:	Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a five-year plan comprised of maintenance, surface treatment, rehabilitation, and reconstruction projects for Stark's Twin Oaks Airpark in Hillsboro, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Stark's Twin Oaks Airpark in 2023 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Stark's Twin Oaks Airpark is located in Hillsboro, Oregon, and is owned and operated by Robert C. and Betty Stark. The airport consists of a single runway, a taxiway, multiple connector taxiways, and aprons that serve a variety of general aviation aircraft. The general location of the airport is shown below on Stark's Twin Oaks Airpark Location Map, Figure 2.1.



Figure 2.1: STARK'S TWIN OAKS AIRPARK LOCATION MAP

The airside pavements at Stark's Twin Oaks Airpark are comprised of asphalt concrete (AC), AC overlaid with AC (AAC), and portland cement concrete (PCC). The airport pavements, delineated by surface type and branch use, are shown on the Stark's Twin Oaks Airpark Percent of Pavement Area by Surface Type, Figure 2.2, and on the Stark's Twin Oaks Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on Stark's Twin Oaks Airpark Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report, Table 1F.




Figure 2.2: STARK'S TWIN OAKS AIRPARK PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3: STARK'S TWIN OAKS AIRPARK PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; PCC = PORTLAND CEMENT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE



3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Stark's Twin Oaks Airpark in July 2023. The 2023 survey work was performed on sections last inspected in 2018 in order to update Stark's Twin Oaks Airpark inspection data. GRI performed the 2023 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible and rigid pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.


3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Stark's Twin Oaks Airpark is approximately 74. The section PCIs ranged from a low of 30 to a high of 100. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, and patching on AC-surfaced pavements, and joint seal damage on PCC pavements. Section PCIs following our pavement survey are displayed below spatially on the Stark's Twin Oaks Airpark 2023 PCI Survey Results, Figure 3.1.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



The condition distribution of the network by percent of total pavement area is provided on Stark's Twin Oaks Airpark Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2023 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2: STARK'S TWIN OAKS AIRPARK PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Stark's Twin Oaks Airpark are displayed on Figures 1C through 4C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 74 to a value of 68 in 2028 and 62 in 2033 if no maintenance or rehabilitation work is performed. The projected pavement condition in 5 years and 10 years for each pavement section at Stark's Twin Oaks Airpark is displayed spatially on the Stark's Twin Oaks Airpark Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Stark's Twin Oaks Airpark. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Stark's Twin Oaks Airpark are summarized in Table 2C in Appendix C.



PREDICTED CONDITION IN 2028



PREDICTED CONDITION IN 2033



SECTION PCI



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priority and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Quantity
Asphalt Concrete Crack Sealing	25,466 linear feet
Asphalt Concrete Wide Crack Sealing	11 linear feet
Portland Cement Concrete Crack Sealing	88 linear feet

5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan


To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the Stark's Twin Oaks Airpark 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES



Treatment Type	Quantity, square feet
Reconstruction	18,211
Overlay	70,478
Fog Seal	31,912
Slurry Seal	223,939



ACTION TIMING



ACTION



6 LIMITATIONS

This report has been prepared to assist the Oregon Department of Aviation (ODAV) with pavement-related project planning for Stark's Twin Oaks Airpark. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Stark's Twin Oaks Airpark would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025

Lindsy A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Engineering Staff

This document has been submitted electronically.

APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Stark's Twin Oaks Airpark is located in Hillsboro, Oregon, and is owned and operated by Robert C. and Betty Stark. The pavement network/facilities at Stark's Twin Oaks Airpark serve a variety of general aviation aircraft. Stark's Twin Oaks Airpark consists of a single runway, a taxiway, multiple connector taxiways, and aprons. The types of airside pavements include asphalt concrete (AC), AC overlaid with AC (AAC), and portland cement concrete (PCC).

The current airport pavement management system (APMS) network at Stark's Twin Oaks Airpark has an approximate area of 431,453 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Stark's Twin Oaks Airpark contains 20 branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as "*a contiguous pavement area having uniform construction, maintenance, usage history, and condition.*" All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Stark's Twin Oaks Airpark contains 39 sections that are managed by Robert C. and Betty Stark, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement's prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet and $20 \text{ slabs} \pm 8 \text{ slabs}$ for rigid pavements. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2023 Stark's Twin Oaks Airpark PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible and rigid pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Stark's Twin Oaks Airpark were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A: STARK'S TWIN OAKS AIRPARK PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01SK	Apron 01 Stark's	6	82,560
AHLD02SK	Hold Apron RW 02 Stark's	2	9,385
R02SK	Runway 02/20 Stark's	4	126,367
T01SK	Taxiway 01 Stark's	7	65,514
T02SK	Taxiway 02 Stark's	1	3,029
T03SK	Taxiway 03 Stark's	1	4,509
T04SK	Taxiway 04 Stark's	1	1,394
T05SK	Taxiway 05 Stark's	1	10,065
T06SK	Taxiway 06 Stark's	1	2,570
TH1SK	Hangar Taxiway 1 Stark's	1	12,593
TH2SK	Hangar Taxiway 2 Stark's	2	18,242
TH3SK	Hangar Taxiway 3 Stark's	2	17,966
TH4SK	Hangar Taxiway 4 Stark's	1	11,065
TH5SK	Hangar Taxiway 5 Stark's	2	11,217
TH6SK	Hangar Taxiway 6 Stark's	2	10,226
TH7SK	Hangar Taxiway 7 Stark's	1	6,744
TH8SK	Hangar Taxiway 8 Stark's	1	10,313
TH9SK	Hangar Taxiway 9 Stark's	1	2,541
TH10SK	Hangar Taxiway 10 Stark's	1	12,592
TH11SK	Hangar Taxiway 11 Stark's	1	12,561

Table 2A: STARK'S TWIN OAKS AIRPARK CURRENT PAVEMENT INVENTORY

BranchID	Branch Name	Branch Use	SectionID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type	Approximate Slab Length, feet	Approximate Slab Width, feet	Number of Slabs
A01SK	Apron 01 Stark's	APRON	01	Taxiway 01	Section 03	P	210	135	21,840	8/1/1985	AC	0	0	0
A01SK	Apron 01 Stark's	APRON	02	Taxiway 01	Section 01	P	160	40	6,617	8/1/1980	AC	0	0	0
A01SK	Apron 01 Stark's	APRON	03	Section 01	Hangar	P	227	60	16,016	8/2/2004	AC	0	0	0
A01SK	Apron 01 Stark's	APRON	04	Taxiway	A01SK-01	P	200	80	15,753	6/2/2023	AC	0	0	0
A01SK	Apron 01 Stark's	APRON	05	Taxiway	A01SK-06	P	270	52	14,753	9/2/2017	AC	0	0	0
A01SK	Apron 01 Stark's	APRON	06	A01SK-05	End	P	105	82	7,581	9/2/2017	PCC	11	11	73
AHLD02SK	Hold Apron RW 02 Stark's	APRON	01	Taxiway 06	End	P	70	25	1,143	9/1/2011	AC	0	0	0
AHLD02SK	Hold Apron RW 02 Stark's	APRON	02	AHLD02SK-01	Taxiway 02	P	270	35	8,242	4/2/2023	AC	0	0	0
R02SK	Runway 02/20 Stark's	RUNWAY	01	Runway 02 End	Section 02	P	75	50	3,750	9/1/2011	AC	0	0	0
R02SK	Runway 02/20 Stark's	RUNWAY	02	Section 01	Section 03	P	1,200	50	60,000	8/1/1992	AC	0	0	0
R02SK	Runway 02/20 Stark's	RUNWAY	03	Taxiway 02	Section 04	P	1,150	50	57,500	8/1/1996	AC	0	0	0
R02SK	Runway 02/20 Stark's	RUNWAY	04	Section 03	Runway 20 End	P	125	42	5,117	8/1/1994	AC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	01	Runway 02	Taxiway 02	P	654	20	15,358	9/1/2011	AC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	02	Taxiway 02	TH1	P	789	20	15,462	8/2/2004	AC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	03	Taxiway 03	Intersection	P	108	18	1,926	9/1/2017	AAC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	04	Taxiway 03	Taxiway 05	P	397	18	7,146	9/1/2017	AAC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	05	Taxiway 05	Intersection	P	260	18	4,680	9/1/2017	AAC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	06	Taxiway 06	Runway 20 End	P	446	18	14,845	8/1/1994	AC	0	0	0
T01SK	Taxiway 01 Stark's	TAXIWAY	07	Runway 02	Taxiway 02	P	67	95	6,097	4/2/2023	AC	0	0	0
T02SK	Taxiway 02 Stark's	TAXIWAY	01	Runway 02/20	Taxiway 06	P	90	50	3,029	8/2/2004	AC	0	0	0
T03SK	Taxiway 03 Stark's	TAXIWAY	01	Runway 02/20	Taxiway 01	P	144	20	4,509	8/1/1995	AC	0	0	0
T04SK	Taxiway 04 Stark's	TAXIWAY	01	Runway 02/20	Taxiway 01	P	67	20	1,394	8/1/1996	AC	0	0	0
T05SK	Taxiway 05 Stark's	TAXIWAY	01	Runway 02/20	Taxiway 01	P	67	120	10,065	8/1/1995	AC	0	0	0
T06SK	Taxiway 06 Stark's	TAXIWAY	01	Runway 02/20	Taxiway 01	P	123	18	2,570	8/1/1994	AC	0	0	0
TH10SK	Hangar Taxiway 10 Stark's	TAXIWAY	01	Taxiway 01	Hangars	P	530	25	12,592	9/1/2016	AC	0	0	0
TH11SK	Hangar Taxiway 11 Stark's	TAXIWAY	01	T01SK-02	End	P	530	25	12,561	9/1/2020	AC	0	0	0
TH1SK	Hangar Taxiway 1 Stark's	TAXIWAY	01	Taxiway 01 Stark's	East End	S	530	25	12,593	6/1/2009	AC	0	0	0
TH2SK	Hangar Taxiway 2 Stark's	TAXIWAY	01	TH2SK-01	Hangars	P	390	40	15,600	9/2/2003	AC	0	0	0
TH2SK	Hangar Taxiway 2 Stark's	TAXIWAY	02	T01SK-02	Hangars	P	130	20	2,642	8/2/2004	AC	0	0	0
TH3SK	Hangar Taxiway 3 Stark's	TAXIWAY	01	TH3SK-01	Hangars	P	380	40	15,200	9/2/2003	AC	0	0	0
TH3SK	Hangar Taxiway 3 Stark's	TAXIWAY	02	T01SK-02	Hangars	P	133	20	2,766	8/2/2004	AC	0	0	0
TH4SK	Hangar Taxiway 4 Stark's	TAXIWAY	01	Taxiway 01	Hangars	S	500	22	11,065	8/1/2000	AC	0	0	0
TH5SK	Hangar Taxiway 5 Stark's	TAXIWAY	01	Section 02	Hangars	S	395	13	4,937	8/1/2000	AC	0	0	0
TH5SK	Hangar Taxiway 5 Stark's	TAXIWAY	02	Taxiway 01	Hangars	S	500	13	6,280	8/1/1995	AC	0	0	0
TH6SK	Hangar Taxiway 6 Stark's	TAXIWAY	01	Taxiway 01	Hangars	S	460	10	4,621	8/1/1990	AC	0	0	0
TH6SK	Hangar Taxiway 6 Stark's	TAXIWAY	02	Taxiway 01	Hangars	S	460	12	5,605	8/1/1990	AC	0	0	0
TH7SK	Hangar Taxiway 7 Stark's	TAXIWAY	01	Taxiway 01	Hangars	S	480	14	6,744	8/1/1990	AC	0	0	0
TH8SK	Hangar Taxiway 8 Stark's	TAXIWAY	01	Taxiway 01	Hangars	S	470	14	10,313	8/1/1990	AC	0	0	0
TH9SK	Hangar Taxiway 9 Stark's	TAXIWAY	01	Apron 01	Hangars	S	210	12	2,541	8/1/1985	AC	0	0	0

Abbreviations:

P = Primary pavement, S = Secondary pavement

LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)


AC = Asphalt Concrete, AAC = AC overlaid AC, PCC = Portland Cement Concrete

Table 3A: EXAMPLE SAMPLE RATES FOR AC AND PCC PAVEMENTS

AC Sampling Rate		PCC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n	Total Number of Sample Units, N	Sample Units to Survey, n
1	1	1	1
2-3	2	2	2
4-6	3	3-4	3
7-13	4	5-6	4
14-38	5	7-8	5
39+	6	9-11	6
		12-14	7
		15-19	8
		20-27	9
		28-38	10
		39-58	11
		59-104	12
		105-313	13
		314+	14


Note: AC = Asphalt Concrete

PCC = Portland Cement Concrete



LEGEND

- SECTION
- SAMPLE UNIT



**STARK'S TWIN OAKS AIRPARK
SAMPLE UNIT LAYOUT**

DEC. 2023

JOB NO. 6593-E

FIG. 1A

APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC and AAC) and rigid pavement (e.g., PCC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE AND RIGID PAVEMENT

Flexible Pavement			Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause	PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load	61	Blow-Up	Load
42	Bleeding	Other	62	Corner Break	Load
43	Block Cracking	Climate/ Durability	63	Longitudinal, Transverse, & Diagonal Cracks	Climate/ Durability
44	Corrugation	Other	64	Durability Cracking	Climate/ Durability
45	Depression	Other	65	Joint Seal Damage	Other
46	Jet Blast	Other	66	Small Patch	Other
47	Joint Reflection Cracking	Climate/ Durability	67	Large Patch	Other
48	Longitudinal & Transverse Cracking	Climate/ Durability	68	Pop Outs	Other
49	Oil Spillage	Other	69	Pumping	Other
50	Patching	Climate/ Durability	70	Scaling	Other
51	Polished Aggregate	Other	71	Faulting	Other
52	Raveling	Climate/ Durability	72	Shattered Slab	Load

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause
73	Shrinkage Cracking	Other
74	Joint Spalls	Other
75	Corner Spalls	Other
76	Alkali-Silica Reactivity (ASR)	Other

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional”– defined as nonrepresentative instead of random- are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

“The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.”

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking. Rigid

pavement distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping, and joint spalling.

- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering. Rigid pavement distresses include blow-ups, durability cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling. Rigid pavement distresses include corner breaks, divided slabs, and pumping.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, patching, and concrete slab joint faulting.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Stark's Twin Oaks Airpark pavement network consists of 20 branches and 39 sections. A total of 69 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2023 PCI survey, the area-weighted average PCI for the entire pavement network at Stark's Twin Oaks Airpark is approximately 74, which corresponds to a PCI rating of Satisfactory.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2023 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Stark's Twin Oaks Airpark pavement sections is outlined in Table 4B in this appendix.

Table 2B: STARK'S TWIN OAKS AIRPARK CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01SK	6	82,560	APRON	78	Satisfactory
AHLD02SK	2	9,385	APRON	93	Good
R02SK	4	126,367	RUNWAY	72	Satisfactory
T01SK	7	65,514	TAXIWAY	73	Satisfactory
T02SK	1	3,029	TAXIWAY	76	Satisfactory
T03SK	1	4,509	TAXIWAY	69	Fair
T04SK	1	1,394	TAXIWAY	79	Satisfactory
T05SK	1	10,065	TAXIWAY	64	Fair
T06SK	1	2,570	TAXIWAY	68	Fair
TH1SK	1	12,593	TAXIWAY	77	Satisfactory
TH2SK	2	18,242	TAXIWAY	56	Fair
TH3SK	2	17,966	TAXIWAY	67	Fair
TH4SK	1	11,065	TAXIWAY	73	Satisfactory
TH5SK	2	11,217	TAXIWAY	94	Good
TH6SK	2	10,226	TAXIWAY	45	Poor
TH7SK	1	6,744	TAXIWAY	94	Good
TH8SK	1	10,313	TAXIWAY	63	Fair
TH9SK	1	2,541	TAXIWAY	30	Very Poor
TH10SK	1	12,592	TAXIWAY	88	Good
TH11SK	1	12,561	TAXIWAY	94	Good

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	8	91,945	80
RUNWAY	4	126,367	72
TAXIWAY	26	213,141	73
ALL	38	431,453	74

Table 3B: STARK'S TWIN OAKS AIRPARK 2023 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01SK	01	8/1/1985	AC	APRON	7/1/2023	38	63	Fair	36	64	0
A01SK	02	8/1/1980	AC	APRON	7/1/2023	43	56	Fair	72	28	0
A01SK	03	8/2/2004	AC	APRON	7/1/2023	19	75	Satisfactory	75	25	0
A01SK	04	6/2/2023	AC	APRON	7/1/2023	0	100	Good	0	0	0
A01SK	05	9/2/2017	AC	APRON	7/1/2023	6	84	Satisfactory	100	0	0
A01SK	06	9/2/2017	PCC	APRON	7/1/2023	6	90	Good	16	74	10
AHLD02SK	01	9/1/2011	AC	APRON	7/1/2023	12	86	Good	100	0	0
AHLD02SK	02	4/2/2023	AC	APRON	7/1/2023	0	94	Good	100	0	0
R02SK	01	9/1/2011	AC	RUNWAY	7/1/2023	12	83	Satisfactory	100	0	0
R02SK	02	8/1/1992	AC	RUNWAY	7/1/2023	31	67	Fair	69	31	0
R02SK	03	8/1/1996	AC	RUNWAY	7/1/2023	27	76	Satisfactory	100	0	0
R02SK	04	8/1/1994	AC	RUNWAY	7/1/2023	29	67	Fair	100	0	0
T01SK	01	9/1/2011	AC	TAXIWAY	7/1/2023	12	83	Satisfactory	98	0	2
T01SK	02	8/2/2004	AC	TAXIWAY	7/1/2023	19	47	Poor	43	57	0
T01SK	03	9/1/2017	AAC	TAXIWAY	7/1/2023	6	95	Good	100	0	0
T01SK	04	9/1/2017	AAC	TAXIWAY	7/1/2023	6	92	Good	100	0	0
T01SK	05	9/1/2017	AAC	TAXIWAY	7/1/2023	6	76	Satisfactory	67	33	0
T01SK	06	8/1/1994	AC	TAXIWAY	7/1/2023	29	70	Fair	66	34	0
T01SK	07	4/2/2023	AC	TAXIWAY	7/1/2023	0	94	Good	100	0	0
T02SK	01	8/2/2004	AC	TAXIWAY	7/1/2023	19	76	Satisfactory	100	0	0
T03SK	01	8/1/1995	AC	TAXIWAY	7/1/2023	28	69	Fair	100	0	0
T04SK	01	8/1/1996	AC	TAXIWAY	7/1/2023	27	79	Satisfactory	100	0	0
T05SK	01	8/1/1995	AC	TAXIWAY	7/1/2023	28	64	Fair	45	55	0
T06SK	01	8/1/1994	AC	TAXIWAY	7/1/2023	29	68	Fair	100	0	0
TH10SK	01	9/1/2016	AC	TAXIWAY	7/1/2023	7	88	Good	100	0	0
TH11SK	01	9/1/2020	AC	TAXIWAY	7/1/2023	3	94	Good	100	0	0
TH1SK	01	6/1/2009	AC	TAXIWAY	7/1/2023	14	77	Satisfactory	100	0	0
TH2SK	01	9/2/2003	AC	TAXIWAY	7/1/2023	20	58	Fair	50	50	0
TH2SK	02	8/2/2004	AC	TAXIWAY	7/1/2023	19	46	Poor	46	48	6
TH3SK	01	9/2/2003	AC	TAXIWAY	7/1/2023	20	68	Fair	76	24	0
TH3SK	02	8/2/2004	AC	TAXIWAY	7/1/2023	19	62	Fair	63	37	0
TH4SK	01	8/1/2000	AC	TAXIWAY	7/1/2023	23	73	Satisfactory	76	24	0
TH5SK	01	8/1/2000	AC	TAXIWAY	7/1/2023	23	94	Good	100	0	0
TH5SK	02	8/1/1995	AC	TAXIWAY	7/1/2023	28	94	Good	100	0	0
TH6SK	01	8/1/1990	AC	TAXIWAY	7/1/2023	33	55	Poor	51	49	0
TH6SK	02	8/1/1990	AC	TAXIWAY	7/1/2023	33	37	Very Poor	38	62	0
TH7SK	01	8/1/1990	AC	TAXIWAY	7/1/2023	33	94	Good	100	0	0
TH8SK	01	8/1/1990	AC	TAXIWAY	7/1/2023	33	63	Fair	31	69	0
TH9SK	01	8/1/1985	AC	TAXIWAY	7/1/2023	38	30	Very Poor	27	59	14

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC, PCC = Portland Cement Concrete

Table 4B: STARK'S TWIN OAKS AIRPARK COMPARISON OF PREVIOUS INSPECTION AND 2023 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2018 Survey			2023 Survey			Rate of Deterioration
					PCI	PCI Category	Inspection Date	PCI	PCI Category	Age ³	
A01SK	01	AC	21,840	8/1/85	90	Good	7/8/2018	63	Fair	33	HIGH
A01SK	02	AC	6,617	8/1/80	87	Good	7/8/2018	56	Fair	38	HIGH
A01SK	03	AC	16,016	8/2/04	84	Satisfactory	7/8/2018	75	Satisfactory	14	NORMAL
A01SK	04	AC	15,753	6/2/23	-	Good	-	100	Good	-	N/A
A01SK	05	AC	14,753	9/2/17	-	Good	-	84.1	Satisfactory	-	N/A
A01SK	06	PCC	7,581	9/2/17	-	Good	-	89.8	Good	-	N/A
AHLD02SK	01	AC	1,143	9/1/11	100	Good	7/8/2018	86	Good	7	NORMAL
AHLD02SK	02	AC	8,242	4/2/23	-	Good	-	94	Good	-	N/A
R02SK	01	AC	3,750	9/1/11	100	Good	7/8/2018	83	Satisfactory	7	NORMAL
R02SK	02	AC	60,000	8/1/92	82	Satisfactory	7/8/2018	67	Fair	26	NORMAL
R02SK	03	AC	57,500	8/1/96	90	Good	7/8/2018	76	Satisfactory	22	NORMAL
R02SK	04	AC	5,117	8/1/94	79	Satisfactory	7/8/2018	67	Fair	24	NORMAL
T01SK	01	AC	15,358	9/1/11	94	Good	7/8/2018	83	Satisfactory	7	NORMAL
T01SK	02	AC	15,462	8/2/04	88	Good	7/8/2018	47	Poor	14	HIGH
T01SK	03	AAC	1,926	9/1/17	100	Good	7/8/2018	94.5	Good	1	NORMAL
T01SK	04	AAC	7,146	9/1/17	100	Good	7/8/2018	92	Good	1	NORMAL
T01SK	05	AAC	4,680	9/1/17	100	Good	7/8/2018	76	Satisfactory	1	HIGH
T01SK	06	AC	14,845	8/1/94	86	Good	7/8/2018	70	Fair	24	NORMAL
T01SK	07	AC	6,097	4/2/23	-	Good	-	94	Good	-	N/A
T02SK	01	AC	3,029	8/2/04	90	Good	7/8/2018	76	Satisfactory	14	NORMAL
T03SK	01	AC	4,509	8/1/95	79	Satisfactory	7/8/2018	69.3	Fair	23	NORMAL
T04SK	01	AC	1,394	8/1/96	91	Good	7/8/2018	79	Satisfactory	22	NORMAL
T05SK	01	AC	10,065	8/1/95	89	Good	7/8/2018	64	Fair	23	HIGH
T06SK	01	AC	2,570	8/1/94	80	Satisfactory	7/8/2018	68	Fair	24	NORMAL
TH10SK	01	AC	12,592	9/1/16	100	Good	7/8/2018	88	Good	2	NORMAL
TH11SK	01	AC	12,561	9/1/20	-	Good	-	94	Good	-	N/A
TH1SK	01	AC	12,593	6/1/09	77	Satisfactory	7/8/2018	77	Satisfactory	9	NONE
TH2SK	01	AC	15,600	9/2/03	68	Fair	7/8/2018	58	Fair	15	NORMAL
TH2SK	02	AC	2,642	8/2/04	47	Poor	7/8/2018	46	Poor	14	NORMAL
TH3SK	01	AC	15,200	9/2/03	68	Fair	7/8/2018	68	Fair	15	NONE
TH3SK	02	AC	2,766	8/2/04	78	Satisfactory	7/8/2018	62	Fair	14	NORMAL
TH4SK	01	AC	11,065	8/1/00	81	Satisfactory	7/8/2018	73	Satisfactory	18	NORMAL
TH5SK	01	AC	4,937	8/1/00	51	Poor	7/8/2018	94	Good	18	NONE
TH5SK	02	AC	6,280	8/1/95	34	Very Poor	7/8/2018	94	Good	23	NONE
TH6SK	01	AC	4,621	8/1/90	64	Fair	7/8/2018	55	Poor	28	NORMAL
TH6SK	02	AC	5,605	8/1/90	54	Poor	7/8/2018	37	Very Poor	28	NORMAL
TH7SK	01	AC	6,744	8/1/90	17	Serious	7/8/2018	94	Good	28	NONE
TH8SK	01	AC	10,313	8/1/90	50	Poor	7/8/2018	63	Fair	28	NONE
TH9SK	01	AC	2,541	8/1/85	64	Fair	7/8/2018	30	Very Poor	33	HIGH

Abbreviations:

¹ AC = Asphalt Concrete, AAC = Asphalt Overlay AC, PCC = Portland Cement Concrete, PCI = Pavement Condition Index² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)³ Age = Pavement age in years at the time of the PCI survey in 2018⁴ Δ PCI/yr = Change in PCI points per year between 2018 survey and 2023 survey⁵ N/A = Not applicable due to changes in sectioning

APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data-outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Stark’s Twin Oaks Airpark. The delineation is based on branch use, surface type, section rank, and structural design life. We use four distinct models for the following “families” of pavements at Stark’s Twin Oaks Airpark. For each model, we reviewed the data in order to filter out any inconsistent or inaccurate data or any data that fell outside the boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 4C below.




Figure 1C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 PCC RUNWAYS, TAXIWAYS, AND APRONS




Figure 2C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC APRONS




Figure 3C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC RUNWAYS




Figure 4C - CONDITION PREDICTION MODEL FOR NORTHWESTERN CATEGORY 5 AC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during

budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Stark's Twin Oaks Airpark:

- Runways – 55
- Taxiways/Taxilanes – 50
- Aprons – 45

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Stark's Twin Oaks Airpark, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Stark's Twin Oaks Airpark: the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT AND FUTURE PCI

BranchID	SectionID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2018	2023	2028	2033
A01SK	01	90	63	58	54
A01SK	02	87	56	51	47
A01SK	03	84	75	70	66
A01SK	04	-	100	95	91
A01SK	05	-	84	79	75
A01SK	06	-	90	84	78
AHLD02SK	01	100	86	81	77
AHLD02SK	02	-	94	89	85
R02SK	01	100	83	78	73
R02SK	02	82	67	62	57
R02SK	03	90	76	71	66
R02SK	04	79	67	62	57
T01SK	01	94	83	76	69
T01SK	02	88	47	40	33
T01SK	03	100	95	87	81
T01SK	04	100	92	85	78
T01SK	05	100	76	69	62
T01SK	06	86	70	63	56
T01SK	07	-	94	87	80
T02SK	01	90	76	69	62
T03SK	01	79	69	62	55
T04SK	01	91	79	72	65
T05SK	01	89	64	57	50
T06SK	01	80	68	61	54
TH1SK	01	100	77	70	63
TH2SK	01	-	58	51	44
TH2SK	02	77	46	39	32
TH3SK	01	68	68	61	54
TH3SK	02	47	62	55	48
TH4SK	01	68	73	66	59
TH5SK	01	78	94	87	80
TH5SK	02	81	94	87	80
TH6SK	01	51	55	48	41
TH6SK	02	34	37	30	23
TH7SK	01	64	94	87	80
TH8SK	01	54	63	56	49
TH9SK	01	17	30	23	16
TH10SK	01	50	88	81	74
TH11SK	01	64	94	87	80

Abbreviation: PCI = Pavement Condition Index

Table 2C: STARK'S TWIN OAKS AIRPARK FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service Life
A01SK	01	AC	63	> 20	45	> 20
A01SK	02	AC	56	11 - 15	45	16 - 20
A01SK	03	AC	75	> 20	45	> 20
A01SK	04	AC	100	> 20	45	> 20
A01SK	05	AC	84	> 20	45	> 20
A01SK	06	PCC	90	> 20	45	> 20
AHLD02SK	01	AC	86	> 20	45	> 20
AHLD02SK	02	AC	94	> 20	45	> 20
R02SK	01	AC	83	> 20	55	> 20
R02SK	02	AC	67	11 - 15	55	> 20
R02SK	03	AC	76	> 20	55	> 20
R02SK	04	AC	67	11 - 15	55	> 20
T01SK	01	AC	83	> 20	50	> 20
T01SK	02	AC	47	0 - 5	50	0 - 5
T01SK	03	AAC	95	> 20	50	> 20
T01SK	04	AAC	92	> 20	50	> 20
T01SK	05	AAC	76	16 - 20	50	> 20
T01SK	06	AC	70	11 - 15	50	> 20
T01SK	07	AC	94	> 20	50	> 20
T02SK	01	AC	76	16 - 20	50	> 20
T03SK	01	AC	69	11 - 15	50	> 20
T04SK	01	AC	79	> 20	50	> 20
T05SK	01	AC	64	6 - 10	50	16 - 20
T06SK	01	AC	68	11 - 15	50	> 20
TH1SK	01	AC	46	> 20	50	> 20
TH2SK	01	AC	68	0 - 5	50	11 - 15
TH2SK	02	AC	62	0 - 5	50	0 - 5
TH3SK	01	AC	73	11 - 15	50	> 20
TH3SK	02	AC	94	6 - 10	50	16 - 20
TH4SK	01	AC	94	16 - 20	50	> 20
TH5SK	01	AC	55	> 20	50	> 20
TH5SK	02	AC	37	> 20	50	> 20
TH6SK	01	AC	94	0 - 5	50	6 - 10
TH6SK	02	AC	63	0 - 5	50	0 - 5
TH7SK	01	AC	30	> 20	50	> 20
TH8SK	01	AC	88	6 - 10	50	16 - 20
TH9SK	01	AC	94	0 - 5	50	0 - 5
TH10SK	01	AC	77	> 20	50	> 20
TH11SK	01	AC	58	> 20	50	> 20

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC,

PCC = Portland Cement Concrete

¹ Major M&R (Maintenance and Rehabilitation) Trigger PCI = Critical PCI

APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of Stark's Twin Oaks Airpark pavement network condition over time. We used PAVER v7.1.1 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2024. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction – Considered for pavements with a PCI less than 40.
- Rehabilitation (AC Overlay) – Considered for pavements between 40 PCI and the critical PCI, and for pavements exhibiting significant load-related distresses.
- Surface Treatment – Treatments (fog seal, slurry seal, thin AC overlay) applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance – Maintenance performed on a routine basis such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use

to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type costs to PCI. We reviewed the unit costs from the 2018 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Stark's Twin Oaks Airpark and information provided by the ODAV Pavement Maintenance Program (PMP) project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Stark's Twin Oaks Airpark. The costs represent the fully-loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: REGION 1 UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major M&R	Complete Reconstruction with AC	\$17.32	Sq Ft
	Cold Mill and Overlay – 2 Inches Thick	\$7.64	Sq Ft
Surface Treatment (Global) M&R	Surface Treatment - Slurry Seal	\$0.52	Sq Ft
	Surface Treatment - Fog Seal	\$0.31	Sq Ft
Localized Preventive M&R	Crack Sealing - AC	\$3.12	Ft
	Crack Sealing - PCC	\$23.4	Ft
	Crack Sealing – Wide Cracks	\$51.48	Ft
	Joint Sealing – PCC	\$7.80	Ft
	AC Patching – Full Depth	\$78.00	Sq Ft
	PCC Patching – Full Depth	\$156.00	Sq Ft

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: STARK'S TWIN OAKS AIRPARK NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,230	Ft	\$3.12	\$3,837	\$54,995
A01SK	01	Alligator Cracking	Medium	Patching - AC Deep	656	SqFt	\$78.00	\$51,158	
A01SK	02	Block Cracking	Low	Crack Sealing - AC	305	Ft	\$3.12	\$951	\$7,241
A01SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	823	Ft	\$3.12	\$2,568	
A01SK	02	Alligator Cracking	Medium	Patching - AC Deep	47	SqFt	\$78.00	\$3,722	
A01SK	03	Long. & Trans. Cracking	Medium	Crack Sealing - AC	71	Ft	\$3.12	\$221	\$3,818
A01SK	03	Long. & Trans. Cracking	Low	Crack Sealing - AC	672	Ft	\$3.12	\$2,097	
A01SK	03	Alligator Cracking	Medium	Patching - AC Deep	19	SqFt	\$78.00	\$1,500	
A01SK	05	Long. & Trans. Cracking	Low	Crack Sealing - AC	518	Ft	\$3.12	\$1,616	
A01SK	06	Linear Cracking	Low	Crack Sealing - PCC	88	Ft	\$23.40	\$2,059	\$2,059
AHLD02SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	31	Ft	\$3.12	\$97	\$97
R02SK	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	14	Ft	\$3.12	\$44	\$190
R02SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	47	Ft	\$3.12	\$147	
R02SK	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	246	Ft	\$3.12	\$768	\$21,121
R02SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	5,775	Ft	\$3.12	\$18,018	
R02SK	02	Alligator Cracking	High	Patching - AC Deep	30	SqFt	\$78.00	\$2,336	
R02SK	03	Long. & Trans. Cracking	High	Crack Seal - Wide Cracks	11	Ft	\$51.48	\$592	\$10,916
R02SK	03	Long. & Trans. Cracking	Medium	Crack Sealing - AC	115	Ft	\$3.12	\$359	
R02SK	03	Long. & Trans. Cracking	Low	Crack Sealing - AC	3,194	Ft	\$3.12	\$9,966	
R02SK	04	Long. & Trans. Cracking	Low	Crack Sealing - AC	519	Ft	\$3.12	\$1,619	\$1,675
R02SK	04	Long. & Trans. Cracking	Medium	Crack Sealing - AC	18	Ft	\$3.12	\$56	
T01SK	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	29	Ft	\$3.12	\$90	\$1,265
T01SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	377	Ft	\$3.12	\$1,176	
T01SK	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	74	Ft	\$3.12	\$231	\$80,009
T01SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,420	Ft	\$3.12	\$4,430	
T01SK	02	Alligator Cracking	Medium	Patching - AC Deep	966	SqFt	\$78.00	\$75,348	
T01SK	05	Long. & Trans. Cracking	Low	Crack Sealing - AC	225	Ft	\$3.12	\$702	\$1,792
T01SK	05	Alligator Cracking	Medium	Patching - AC Deep	14	SqFt	\$78.00	\$1,090	
T01SK	06	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,368	Ft	\$3.12	\$4,270	\$8,306
T01SK	06	Alligator Cracking	Medium	Patching - AC Deep	52	SqFt	\$78.00	\$4,037	
T02SK	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	27	Ft	\$3.12	\$84	\$530
T02SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	143	Ft	\$3.12	\$446	
T03SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	540	Ft	\$3.12	\$1,686	\$1,686
T04SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	20	Ft	\$3.12	\$62	\$62
T05SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	665	Ft	\$3.12	\$2,075	\$22,333
T05SK	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	27	Ft	\$3.12	\$84	
T05SK	01	Alligator Cracking	Medium	Patching - AC Deep	258	SqFt	\$78.00	\$20,174	
T06SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	340	Ft	\$3.12	\$1,061	\$1,061
TH10SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	214	Ft	\$3.12	\$668	\$668
TH1SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	832	Ft	\$3.12	\$2,596	\$2,596
TH2SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,953	Ft	\$3.12	\$6,092	\$6,092
TH2SK	01	Alligator Cracking	Medium	Patching - AC Deep	274	SqFt	\$78.00	\$21,410	\$21,410

Table 3D: STARK'S TWIN OAKS AIRPARK NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
TH2SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	162	Ft	\$3.12	\$505	\$6,197
TH2SK	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	22	Ft	\$3.12	\$69	
TH2SK	02	Alligator Cracking	Medium	Patching - AC Deep	72	SqFt	\$78.00	\$5,623	
TH3SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	1,220	Ft	\$3.12	\$3,806	\$6,223
TH3SK	01	Alligator Cracking	Medium	Patching - AC Deep	31	SqFt	\$78.00	\$2,417	
TH3SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	141	Ft	\$3.12	\$440	
TH3SK	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	22	Ft	\$3.12	\$69	\$2,593
TH3SK	02	Alligator Cracking	Medium	Patching - AC Deep	27	SqFt	\$78.00	\$2,085	
TH4SK	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	44	Ft	\$3.12	\$137	
TH4SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	606	Ft	\$3.12	\$1,891	\$3,577
TH4SK	01	Alligator Cracking	Medium	Patching - AC Deep	19	SqFt	\$78.00	\$1,549	
TH6SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	683	Ft	\$3.12	\$2,131	
TH6SK	01	Alligator Cracking	Medium	Patching - AC Deep	105	SqFt	\$78.00	\$8,205	\$10,336
TH6SK	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	344	Ft	\$3.12	\$1,073	
TH6SK	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	15	Ft	\$3.12	\$47	
TH6SK	02	Alligator Cracking	Medium	Patching - AC Deep	375	SqFt	\$78.00	\$29,237	\$30,357
TH8SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	188	Ft	\$3.12	\$587	
TH8SK	01	Alligator Cracking	High	Patching - AC Deep	539	SqFt	\$78.00	\$42,072	
TH9SK	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	187	Ft	\$3.12	\$583	\$24,479
TH9SK	01	Alligator Cracking	Medium	Patching - AC Deep	307	SqFt	\$78.00	\$23,896	

Abbreviations:

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; Ft = Feet; SqFt = Square Feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2024	T01SK	02	TAXIWAY	AC	47	Overlay	15,462	\$7.64	\$118,130
	T05SK	01	TAXIWAY	AC	64	Overlay	10,065	\$7.64	\$76,900
2025	A01SK	03	APRON	AC	74	Fog Seal	16,016	\$0.31	\$4,965
	A01SK	05	APRON	AC	83	Fog Seal	14,753	\$0.31	\$4,573
	AHLD02SK	01	APRON	AC	85	Fog Seal	1,143	\$0.31	\$354
	R02SK	01	RUNWAY	AC	82	Slurry Seal	3,750	\$0.52	\$1,950
	R02SK	02	RUNWAY	AC	66	Slurry Seal	60,000	\$0.52	\$31,200
	R02SK	03	RUNWAY	AC	75	Slurry Seal	57,500	\$0.52	\$29,900
	R02SK	04	RUNWAY	AC	66	Slurry Seal	5,117	\$0.52	\$2,661
	T01SK	01	TAXIWAY	AC	82	Slurry Seal	15,358	\$0.52	\$7,986
	T01SK	05	TAXIWAY	AAC	75	Slurry Seal	4,680	\$0.52	\$2,434
	T01SK	06	TAXIWAY	AC	69	Slurry Seal	14,845	\$0.52	\$7,719
	T03SK	01	TAXIWAY	AC	68	Slurry Seal	4,509	\$0.52	\$2,345
	T04SK	01	TAXIWAY	AC	78	Slurry Seal	1,394	\$0.52	\$725
	T06SK	01	TAXIWAY	AC	67	Slurry Seal	2,570	\$0.52	\$1,336
	TH10SK	01	TAXIWAY	AC	84	Slurry Seal	12,592	\$0.52	\$6,548
	TH1SK	01	TAXIWAY	AC	76	Slurry Seal	12,593	\$0.52	\$6,548
	TH3SK	01	TAXIWAY	AC	67	Slurry Seal	15,200	\$0.52	\$7,904
	TH3SK	02	TAXIWAY	AC	61	Slurry Seal	2,766	\$0.52	\$1,438
	TH4SK	01	TAXIWAY	AC	72	Slurry Seal	11,065	\$0.52	\$5,754
2026	A01SK	01	APRON	AC	63	Overlay	21,840	\$7.64	\$166,865
	TH8SK	01	TAXIWAY	AC	63	Overlay	10,313	\$7.64	\$78,795
	TH9SK	01	TAXIWAY	AC	30	Reconstruction	2,541	\$17.32	\$44,010
2027	TH2SK	01	TAXIWAY	AC	58	Overlay	15,600	\$7.64	\$119,189
	TH2SK	02	TAXIWAY	AC	46	Overlay	2,642	\$7.64	\$20,185
	TH6SK	01	TAXIWAY	AC	55	Overlay	4,621	\$7.64	\$35,306
	TH6SK	02	TAXIWAY	AC	37	Reconstruction	5,605	\$17.32	\$97,078

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC

Cost Summary	
2024 Total Project Cost	\$195,030
2025 Total Project Cost	\$126,340
2026 Total Project Cost	\$289,670
2027 Total Project Cost	\$271,758
2028 Total Project Cost	\$0
Total 5-Year Project Cost	\$882,798

APPENDIX E

Reinspection Report

Re-Inspection Report

ODA_2023Survey_11-21-23

Generated Date 12/5/2023

Page 1 of 39

Network:	Starks	Name:	Stark's Twin Oaks						
Branch:	A01SK	Name:	Apron 01 Stark's	Use:	APRON	Area:	82,560 SqFt		
Section:	01	of	6	From:	Taxiway 01	To:	Section 03	Last Const.:	8/1/1985
Surface:	AC	Family:	2023_Region1_Cat5_Apron_AC	Zone:	7S3	Category:	E	Rank:	P
Area:	21,840 SqFt	Length:	210 Ft	Width:	135 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	8/1/1985	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True		
Work Date:	9/1/2016	Work Type: Oregon Slurry Seal			Code:	OR-SS	Is Major M&R: False		
Last Insp. Date:	7/1/2023	TotalSamples:	4	Surveyed:		3			
Conditions:	PCI: 63								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5408.00 SqFt	PCI:	41		
Sample Comments:									
41	ALLIGATOR CR	M	314.00	SqFt					
48	L & T CR	L	428.00	Ft					
48	L & T CR	L	152.00	Ft					
57	WEATHERING	L	5408.00	SqFt					
Sample Number:	03	Type:	R	Area:	4589.00 SqFt	PCI:	52		
Sample Comments:									
41	ALLIGATOR CR	M	104.00	SqFt					
48	L & T CR	L	68.00	Ft					
48	L & T CR	L	231.00	Ft					
57	WEATHERING	L	4589.00	SqFt					
Sample Number:	04	Type:	R	Area:	6396.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	44.00	Ft					
57	WEATHERING	L	6396.00	SqFt					

Network:		Starks		Name:		Stark's Twin Oaks							
Branch:	A01SK		Name:	Apron 01 Stark's		Use:	APRON	Area:	82,560 SqFt				
Section:	02		of	6		From:	Taxiway 01		To:	Section 01	Last Const.:	8/1/1980	
Surface:	AC		Family:	2023_Region1_Cat5_Apron_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	6,617 SqFt		Length:	160 Ft		Width:	40 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	8/1/1980		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2016		Work Type:	Oregon Slurry Seal				Code:	OR-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 56												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	6617.00 SqFt		PCI:	56			
Sample Comments:													
41	ALLIGATOR CR		M	24.00 SqFt									
43	BLOCK CR		L	1000.00 SqFt									
48	L & T CR		L	823.00 Ft									
57	WEATHERING		L	6617.00 SqFt									

Network:	Starks			Name:	Stark's Twin Oaks						
Branch:	A01SK		Name:	Apron 01 Stark's		Use:	APRON	Area:	82,560 SqFt		
Section:	04	of 6	From:	Taxiway			To:	A01SK-01	Last Const.:	6/2/2023	
Surface:	AC	Family:	2023_Region1_Cat5_Apron_AC		Zone:	Category:			Rank:	P	
Area:	15,753 SqFt		Length:	200 Ft		Width:	80 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	6/1/2023		Work Type:	Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	False
Work Date:	6/2/2023		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2				
Conditions:	PCI:	100									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	7575.00 SqFt		PCI:	100			
Sample Comments:											
<No Distress>											
Sample Number:	02	Type:	R	Area:	8177.00 SqFt		PCI:	100			
Sample Comments:											
<No Distress>											

Network:		Starks		Name:		Stark's Twin Oaks						
Branch:	A01SK		Name:	Apron 01 Stark's		Use:	APRON	Area:	82,560 SqFt			
Section:	05		of	6		From:	Taxiway		To:	A01SK-06	Last Const.:	9/2/2017
Surface:	AC		Family:	2023_Region1_Cat5_Apron_AC		Zone:			Category:	Rank: P		
Area:	14,753 SqFt		Length:	270 Ft		Width:	52 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	9/1/2017		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	9/2/2017		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	3		Surveyed:	3					
Conditions:	PCI: 84											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	4815.00 SqFt		PCI:	87		
Sample Comments:												
48	L & T CR		L	105.00 Ft								
57	WEATHERING		L	4815.00 SqFt								
Sample Number:	02		Type:	R		Area:	5330.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	105.00 Ft								
57	WEATHERING		L	5330.00 SqFt								
Sample Number:	03		Type:	R		Area:	4608.00 SqFt		PCI:	77		
Sample Comments:												
48	L & T CR		L	308.00 Ft								
57	WEATHERING		L	4608.00 SqFt								

Network:	Starks		Name:		Stark's Twin Oaks							
Branch:	A01SK		Name:		Apron 01 Stark's		Use:	APRON	Area:	82,560 SqFt		
Section:	06	of 6		From:	A01SK-05			To:	End	Last Const.:	9/2/2017	
Surface:	PCC	Family:		2023_Region1_Cat3/4/5_AII		Zone:	PCC		Category:	Rank:	P	
Area:	7,581 SqFt		Length:		105 Ft		Width:		82 Ft			
Slabs:	73	Slab Length:		11 Ft		Slab Width:		11 Ft		Joint Length:	1,606 Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:		0			
Section Comments:												
Work Date:	9/1/2017		Work Type:				Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False
Work Date:	9/2/2017		Work Type:				Complete Reconstruction - PCC		Code:	CR-PC	Is Major M&R:	True
Last Insp. Date:	7/1/2023		Total Samples:		4		Surveyed:		4			
Conditions:	PCI: 90											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:		23.00 Slabs		PCI:		87		
Sample Comments:												
63	LINEAR CR		L	2.00 Slabs								
65	JT SEAL DMG		L	23.00 Slabs								
75	CORNER SPALL		L	2.00 Slabs								
Sample Number:	02	Type:	R	Area:		13.00 Slabs		PCI:		79		
Sample Comments:												
63	LINEAR CR		L	5.00 Slabs								
65	JT SEAL DMG		L	13.00 Slabs								
Sample Number:	03	Type:	R	Area:		19.00 Slabs		PCI:		93		
Sample Comments:												
63	LINEAR CR		L	1.00 Slabs								
65	JT SEAL DMG		L	19.00 Slabs								
Sample Number:	04	Type:	R	Area:		18.00 Slabs		PCI:		98		
Sample Comments:												
65	JT SEAL DMG		L	18.00 Slabs								

Network:		Starks		Name:		Stark's Twin Oaks				
Branch:	A01SK		Name:	Apron 01 Stark's		Use:	APRON	Area:	82,560 SqFt	
Section:	03	of	6	From:	Section 01		To:	Hangar	Last Const.:	8/2/2004
Surface:	AC	Family:	2023_Region1_Cat5_Apron_AC	Zone:	7S3		Category:	E	Rank:	P
Area:	16,016 SqFt		Length:	227 Ft		Width:	60 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:			Grade:		0	Lanes:		0	
Section Comments:										
Work Date:	8/1/2004		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R:	False
Work Date:	8/2/2004		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	3		Surveyed:	2			
Conditions:	PCI: 75									
Inspection Comments:										
Sample Number:	01	Type:	R	Area:	5474.00 SqFt		PCI:	79		
Sample Comments:										
48	L & T CR		L	162.00 Ft						
48	L & T CR		L	23.00 Ft						
48	L & T CR		M	50.00 Ft						
57	WEATHERING		L	5474.00 SqFt						
Sample Number:	02	Type:	R	Area:	5846.00 SqFt		PCI:	71		
Sample Comments:										
41	ALLIGATOR CR		M	4.00 SqFt						
48	L & T CR		L	204.00 Ft						
48	L & T CR		L	86.00 Ft						
52	RAVELING		M	4.00 SqFt						
57	WEATHERING		L	5846.00 SqFt						

Network:		Starks		Name:		Stark's Twin Oaks																		
Branch:		AHLD02SK		Name:		Hold Apron RW 02 Stark's		Use:		APRON		Area:		9,385 SqFt										
Section:		02		of		2		From:		AHLD02SK-01		To:		Taxiway 02		Last Const.:		4/2/2023						
Surface:		AC		Family:		2023_Region1_Cat5_Apron_AC		Zone:				Category:				Rank:		P						
Area:		8,242 SqFt		Length:		270 Ft		Width:		35 Ft														
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft										
Shoulder:				Street Type:				Grade:		0		Lanes:		0										
Section Comments:																								
Work Date:				4/1/2023				Work Type:				Base Course - Aggregate				Code:		BA-AG		Is Major M&R:			False	
Work Date:				4/2/2023				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:			True	
Last Insp. Date:				7/1/2023				TotalSamples:				1				Surveyed:				1				
Conditions:				PCI: 94																				
Inspection Comments:																								
Sample Number:				01				Type:		R		Area:		8242.00 SqFt				PCI:		94				
Sample Comments:																								
57		WEATHERING		L		8242.00 SqFt																		

Network:		Starks		Name:		Stark's Twin Oaks																									
Branch:		AHLD02SK		Name:		Hold Apron RW 02 Stark's		Use:		APRON		Area:		9,385 SqFt																	
Section:		01		of		2		From:		Taxiway 06		To:		End		Last Const.:		9/1/2011													
Surface:		AC		Family:		2023_Region1_Cat5_Apron_AC		Zone:		7S3		Category:		E		Rank:		P													
Area:		1,143 SqFt		Length:		70 Ft		Width:		25 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				9/1/2011				Work Type:				New Construction - Initial				Code:				NC-IN				Is Major M&R:				True			
Last Insp. Date:				7/1/2023				TotalSamples:				1				Surveyed:				1											
Conditions:				PCI:				86																							
Inspection Comments:																															
Sample Number:				01				Type:		R		Area:				1143.00 SqFt				PCI:				86							
Sample Comments:																															
48		L & T CR		L		31.00		Ft																							
57		WEATHERING		L		1143.00		SqFt																							

Network:	Starks			Name:	Stark's Twin Oaks								
Branch:	R02SK		Name:	Runway 02/20 Stark's		Use:	RUNWAY		Area:	126,367 SqFt			
Section:	02	of 4		From:	Section 01			To:	Section 03		Last Const.:	8/1/1992	
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC		Zone:	7S3		Category:	E		Rank:	P	
Area:	60,000 SqFt		Length:	1,200 Ft		Width:	50 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:		Grade:		0		Lanes:	0					
Section Comments:													
Work Date:	8/1/1992		Work Type:				New Construction - AC		Code:	NC-AC		Is Major M&R:	True
Work Date:	6/1/2010		Work Type:				Crack Sealing - AC		Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2016		Work Type:				Crack Sealing - AC		Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/2016		Work Type:				Patching - AC Full Depth		Code:	PA-AF		Is Major M&R:	False
Work Date:	9/3/2016		Work Type:				Oregon Slurry Seal		Code:	OR-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	12		Surveyed:	4						
Conditions:	PCI:		67										
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	72			
Sample Comments:													
48	L & T CR		L	238.00 Ft									
48	L & T CR		L	248.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	04		Type:	R		Area:	5000.00 SqFt		PCI:	68			
Sample Comments:													
48	L & T CR		L	170.00 Ft									
48	L & T CR		L	278.00 Ft									
48	L & T CR		M	15.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	08		Type:	R		Area:	5000.00 SqFt		PCI:	62			
Sample Comments:													
41	ALLIGATOR CR		H	4.00 SqFt									
48	L & T CR		L	230.00 Ft									
48	L & T CR		L	260.00 Ft									
48	L & T CR		M	8.00 Ft									
48	L & T CR		M	42.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	11		Type:	R		Area:	5000.00 SqFt		PCI:	67			
Sample Comments:													
48	L & T CR		L	229.00 Ft									
48	L & T CR		L	272.00 Ft									
48	L & T CR		M	4.00 Ft									
48	L & T CR		M	13.00 Ft									
57	WEATHERING		L	5000.00 SqFt									

Network:		Starks		Name:		Stark's Twin Oaks																	
Branch:		R02SK		Name:		Runway 02/20 Stark's		Use:		RUNWAY		Area:		126,367 SqFt									
Section:		03		of		4		From:		Taxiway 02		To:		Section 04		Last Const.:		8/1/1996					
Surface:		AC		Family:		2023_Region1_Cat5_Run way_AC		Zone:		7S3		Category:		E		Rank:		P					
Area:		57,500 SqFt		Length:		1,150 Ft		Width:		50 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				8/1/1996				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Work Date:				6/1/2010				Work Type:				Crack Sealing - AC				Code:		CS-AC		Is Major M&R:		False	
Work Date:				9/1/2016				Work Type:				Crack Sealing - AC				Code:		CS-AC		Is Major M&R:		False	
Work Date:				9/2/2016				Work Type:				Patching - AC Full Depth				Code:		PA-AF		Is Major M&R:		False	
Work Date:				9/3/2016				Work Type:				Oregon Slurry Seal				Code:		OR-SS		Is Major M&R:		False	
Last Insp. Date:				7/1/2023				TotalSamples:				12				Surveyed:		4					
Conditions:				PCI:				76															
Inspection Comments:																							
Sample Number:		01		Type:		R		Area:		5000.00 SqFt		PCI:		70									
Sample Comments:																							
48		L & T CR		L		397.00 Ft																	
48		L & T CR		M		32.00 Ft																	
48		L & T CR		H		4.00 Ft																	
57		WEATHERING		L		5000.00 SqFt																	
Sample Number:		04		Type:		R		Area:		5000.00 SqFt		PCI:		76									
Sample Comments:																							
48		L & T CR		L		167.00 Ft																	
48		L & T CR		L		61.00 Ft																	
50		PATCHING		L		240.00 SqFt																	
50		PATCHING		L		116.00 SqFt																	
57		WEATHERING		L		5000.00 SqFt																	
Sample Number:		08		Type:		R		Area:		5000.00 SqFt		PCI:		75									
Sample Comments:																							
48		L & T CR		L		267.00 Ft																	
48		L & T CR		M		8.00 Ft																	
57		WEATHERING		L		5000.00 SqFt																	
Sample Number:		11		Type:		R		Area:		5000.00 SqFt		PCI:		82									
Sample Comments:																							
48		L & T CR		L		219.00 Ft																	
57		WEATHERING		L		5000.00 SqFt																	

Network:		Starks		Name:		Stark's Twin Oaks							
Branch:	R02SK		Name:	Runway 02/20 Stark's		Use:	RUNWAY	Area:	126,367 SqFt				
Section:	04		of	4		From:	Section 03		To:	Runway 20 End	Last Const.:	8/1/1994	
Surface:	AC		Family:	2023_Region1_Cat5_Run way_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	5,117 SqFt		Length:	125 Ft		Width:	42 Ft						
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:				Grade:		0		Lanes:		0		
Section Comments:													
Work Date:	8/1/1994		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True			
Work Date:	6/1/2010		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False			
Work Date:	9/1/2016		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False			
Work Date:	9/2/2016		Work Type: Oregon Slurry Seal				Code:	OR-SS		Is Major M&R: False			
Last Insp. Date:	7/1/2023		TotalSamples:		1		Surveyed:		1				
Conditions:	PCI:		67										
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5117.00 SqFt		PCI:	67			
Sample Comments:													
48	L & T CR		L	519.00 Ft									
48	L & T CR		M	18.00 Ft									
57	WEATHERING		L	5117.00 SqFt									

Network:		Starks		Name:		Stark's Twin Oaks						
Branch:	R02SK		Name:	Runway 02/20 Stark's		Use:	RUNWAY	Area:	126,367 SqFt			
Section:	01	of 4		From:	Runway 02 End		To:	Section 02		Last Const.:	9/1/2011	
Surface:	AC	Family:	2023_Region1_Cat5_Run way_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	3,750 SqFt		Length:	75 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/2011		Work Type: New Construction - Initial				Code:	NC-IN		Is Major M&R:	True	
Work Date:	9/1/2016		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/2016		Work Type: Patching - AC Full Depth				Code:	PA-AF		Is Major M&R:	False	
Work Date:	9/3/2016		Work Type: Oregon Slurry Seal				Code:	OR-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 83											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	3750.00 SqFt		PCI:	83				
Sample Comments:												
48	L & T CR		L	47.00 Ft								
48	L & T CR		M	14.00 Ft								
57	WEATHERING		L	3750.00 SqFt								

Network:		Starks		Name:		Stark's Twin Oaks								
Branch:	T01SK		Name:	Taxiway 01 Stark's		Use:	TAXIWAY	Area:	65,514 SqFt					
Section:	05		of	7		From:	Taxiway 05		To:	Intersection		Last Const.:	9/1/2017	
Surface:	AAC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P	
Area:	4,680 SqFt		Length:	260 Ft		Width:	18 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	8/1/1995		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	9/1/2017		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True		
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1							
Conditions:	PCI: 76													
Inspection Comments:														
Sample Number:	01		Type:	R		Area:	4680.00 SqFt		PCI:	76				
Sample Comments:														
41	ALLIGATOR CR		M	3.00 SqFt										
48	L & T CR		L	127.00 Ft										
48	L & T CR		L	98.00 Ft										
57	WEATHERING		L	4680.00 SqFt										

Network:		Starks		Name:		Stark's Twin Oaks						
Branch:	T01SK		Name:	Taxiway 01 Stark's		Use:	TAXIWAY	Area:	65,514 SqFt			
Section:	06 of 7		From:	Taxiway 06			To:	Runway 20 End		Last Const.:	8/1/1994	
Surface:	AC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E Rank: P		
Area:	14,845 SqFt		Length:	446 Ft		Width:	18 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	8/1/1994		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2016		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/2016		Work Type:	Oregon Slurry Seal				Code:	OR-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	3		Surveyed:	2					
Conditions:	PCI: 70											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	6400.00 SqFt		PCI:	70		
Sample Comments:												
41	ALLIGATOR CR		M	21.00 SqFt								
48	L & T CR		L	452.00 Ft								
48	L & T CR		L	47.00 Ft								
57	WEATHERING		L	6400.00 SqFt								
Sample Number:	02		Type:	R		Area:	5196.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	570.00 Ft								
57	WEATHERING		L	5196.00 SqFt								

Network:		Starks		Name:		Stark's Twin Oaks							
Branch:	T01SK		Name:	Taxiway 01 Stark's		Use:	TAXIWAY	Area:	65,514 SqFt				
Section:	04		of	7		From:	Taxiway 03		To:	Taxiway 05	Last Const.:	9/1/2017	
Surface:	AAC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	7,146 SqFt		Length:	397 Ft		Width:	18 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	8/1/1995		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2017		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True	
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2						
Conditions:	PCI: 92												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	3600.00 SqFt		PCI:	89			
Sample Comments:													
50	PATCHING		L	75.00 SqFt									
57	WEATHERING		L	3600.00 SqFt									
Sample Number:	02		Type:	R		Area:	3978.00 SqFt		PCI:	94			
Sample Comments:													
57	WEATHERING		L	3978.00 SqFt									

Network:		Starks		Name:		Stark's Twin Oaks								
Branch:	T01SK		Name:	Taxiway 01 Stark's		Use:	TAXIWAY	Area:	65,514 SqFt					
Section:	03		of	7		From:	Taxiway 03		To:	Intersection		Last Const.:	9/1/2017	
Surface:	AAC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P	
Area:	1,926 SqFt		Length:	108 Ft		Width:	18 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	8/1/2000		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	9/1/2017		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True		
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1							
Conditions:	PCI: 95													
Inspection Comments:														
Sample Number:	01		Type:	R		Area:	2812.00 SqFt		PCI:	95				
Sample Comments:														
57	WEATHERING		L	1926.00 SqFt										

Network:		Starks		Name:		Stark's Twin Oaks								
Branch:	T01SK		Name:	Taxiway 01 Stark's		Use:	TAXIWAY	Area:	65,514 SqFt					
Section:	07		of	7		From:	Runway 02		To:	Taxiway 02		Last Const.:	4/2/2023	
Surface:	AC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:			Category:			Rank:	P	
Area:	6,097 SqFt		Length:	67 Ft		Width:	95 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	4/1/2022		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True		
Work Date:	4/1/2023		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False		
Work Date:	4/2/2023		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1							
Conditions:	PCI: 94													
Inspection Comments:														
Sample Number:	01		Type:	R		Area:	6097.00 SqFt		PCI:	94				
Sample Comments:														
57	WEATHERING		L	6097.00 SqFt										

Network:		Starks		Name:		Stark's Twin Oaks																	
Branch:		T01SK		Name:		Taxiway 01 Stark's		Use:		TAXIWAY		Area:		65,514 SqFt									
Section:		01		of		7		From:		Runway 02		To:		Taxiway 02		Last Const.:		9/1/2011					
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		P					
Area:		15,358 SqFt		Length:		654 Ft		Width:		20 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				9/1/2011				Work Type:				New Construction - Initial				Code:		NC-IN		Is Major M&R:		True	
Last Insp. Date:				7/1/2023				TotalSamples:				3				Surveyed:				2			
Conditions:				PCI:				83															
Inspection Comments:																							
Sample Number:		01		Type:		R		Area:		3618.00 SqFt		PCI:		89									
Sample Comments:																							
48		L & T CR		L		55.00 Ft																	
57		WEATHERING		L		3618.00 SqFt																	
Sample Number:		02		Type:		R		Area:		6000.00 SqFt		PCI:		80									
Sample Comments:																							
45		DEPRESSION		L		6.00 SqFt																	
48		L & T CR		L		181.00 Ft																	
48		L & T CR		M		18.00 Ft																	
57		WEATHERING		L		6000.00 SqFt																	

Network: Starks		Name: Stark's Twin Oaks	
Branch: T01SK	Name: Taxiway 01 Stark's		Use: TAXIWAY Area: 65,514 SqFt
Section: 02	of 7	From: Taxiway 02	To: TH1 Last Const.: 8/2/2004
Surface: AC	Family: 2023_Region1_Cat5_Taxi way_AC	Zone: 7S3	Category: E Rank: P
Area: 15,462 SqFt	Length: 789 Ft	Width: 20 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 8/1/2004		Work Type: Base Course - Aggregate	Code: BA-AG Is Major M&R: False
Work Date: 8/2/2004		Work Type: New Construction - AC	Code: NC-AC Is Major M&R: True
Work Date: 9/1/2016		Work Type: Oregon Slurry Seal	Code: OR-SS Is Major M&R: False
Last Insp. Date: 7/1/2023		TotalSamples: 3	Surveyed: 3
Conditions: PCI: 47			
Inspection Comments:			
Sample Number: 01	Type: R	Area: 5464.00 SqFt	PCI: 30
Sample Comments:			
41	ALLIGATOR CR	M	36.00 SqFt
41	ALLIGATOR CR	M	336.00 SqFt
41	ALLIGATOR CR	M	56.00 SqFt
41	ALLIGATOR CR	M	261.00 SqFt
41	ALLIGATOR CR	M	60.00 SqFt
48	L & T CR	L	272.00 Ft
48	L & T CR	L	185.00 Ft
57	WEATHERING	L	5464.00 SqFt
Sample Number: 02	Type: R	Area: 6000.00 SqFt	PCI: 54
Sample Comments:			
41	ALLIGATOR CR	M	60.00 SqFt
41	ALLIGATOR CR	M	12.00 SqFt
48	L & T CR	L	100.00 Ft
48	L & T CR	L	250.00 Ft
48	L & T CR	L	336.00 Ft
48	L & T CR	M	28.00 Ft
57	WEATHERING	L	6000.00 SqFt
Sample Number: 03	Type: R	Area: 3998.00 SqFt	PCI: 61
Sample Comments:			
41	ALLIGATOR CR	M	24.00 SqFt
48	L & T CR	L	97.00 Ft
48	L & T CR	L	18.00 Ft
48	L & T CR	L	162.00 Ft
48	L & T CR	M	18.00 Ft
48	L & T CR	M	28.00 Ft
57	WEATHERING	L	3998.00 SqFt

Network:	Starks		Name:		Stark's Twin Oaks							
Branch:	T02SK		Name:	Taxiway 02 Stark's		Use:	TAXIWAY	Area:	3,029 SqFt			
Section:	01	of	1	From:	Runway 02/20		To:	Taxiway 06		Last Const.:	8/2/2004	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	3,029 SqFt		Length:	90 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	8/1/2004		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False		
Work Date:	8/2/2004		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/2016		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/2/2016		Work Type: Oregon Slurry Seal				Code:	OR-SS		Is Major M&R: False		
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 76											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	3029.00 SqFt		PCI:	76				
Sample Comments:												
48	L & T CR		L	51.00 Ft								
48	L & T CR		L	92.00 Ft								
48	L & T CR		M	27.00 Ft								
57	WEATHERING		L	3029.00 SqFt								

Network:		Starks		Name:		Stark's Twin Oaks							
Branch:	T03SK		Name:	Taxiway 03 Stark's		Use:	TAXIWAY	Area:	4,509 SqFt				
Section:	01	of 1		From:	Runway 02/20		To:	Taxiway 01		Last Const.:	8/1/1995		
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P	
Area:	4,509 SqFt		Length:	144 Ft		Width:	20 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	8/1/1995		Work Type:				New Construction - AC		Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2016		Work Type:				Crack Sealing - AC		Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/2016		Work Type:				Oregon Slurry Seal		Code:	OR-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI:		69										
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	3622.00 SqFt		PCI:	69					
Sample Comments:													
48	L & T CR		L	434.00 Ft									
57	WEATHERING		L	3622.00 SqFt									

Network:		Starks		Name:		Stark's Twin Oaks							
Branch:	T04SK		Name:	Taxiway 04 Stark's		Use:	TAXIWAY	Area:	1,394 SqFt				
Section:	01		of	1		From:	Runway 02/20		To:	Taxiway 01	Last Const.:	8/1/1996	
Surface:	AC		Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E		Rank:	P
Area:	1,394 SqFt		Length:	67 Ft		Width:	20 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	8/1/1996		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2016		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/2016		Work Type:	Oregon Slurry Seal				Code:	OR-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 79												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	1394.00 SqFt		PCI:	79			
Sample Comments:													
48	L & T CR		L	20.00 Ft									
50	PATCHING		L	82.00 SqFt									
57	WEATHERING		L	1394.00 SqFt									

Network: Starks		Name: Stark's Twin Oaks	
Branch: T05SK	Name: Taxiway 05 Stark's		Use: TAXIWAY Area: 10,065 SqFt
Section: 01	of 1	From: Runway 02/20	To: Taxiway 01 Last Const.: 8/1/1995
Surface: AC	Family: 2023_Region1_Cat5_Taxi way_AC	Zone: 7S3	Category: E Rank: P
Area: 10,065 SqFt	Length: 67 Ft	Width: 120 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 8/1/1995		Work Type: New Construction - AC	Code: NC-AC Is Major M&R: True
Work Date: 9/1/2016		Work Type: Crack Sealing - AC	Code: CS-AC Is Major M&R: False
Work Date: 9/2/2016		Work Type: Oregon Slurry Seal	Code: OR-SS Is Major M&R: False
Last Insp. Date: 7/1/2023		TotalSamples: 2	Surveyed: 2
Conditions: PCI: 64			
Inspection Comments:			
Sample Number: 01	Type: R	Area: 5692.00 SqFt	PCI: 83
Sample Comments:			
48	L & T CR	L	210.00 Ft
57	WEATHERING	L	5692.00 SqFt
Sample Number: 02	Type: R	Area: 4373.00 SqFt	PCI: 39
Sample Comments:			
41	ALLIGATOR CR	M	18.00 SqFt
41	ALLIGATOR CR	M	110.00 SqFt
41	ALLIGATOR CR	M	16.00 SqFt
41	ALLIGATOR CR	M	54.00 SqFt
48	L & T CR	L	130.00 Ft
48	L & T CR	L	220.00 Ft
48	L & T CR	L	105.00 Ft
48	L & T CR	M	27.00 Ft
57	WEATHERING	L	4373.00 SqFt

Network:		Starks		Name:		Stark's Twin Oaks																	
Branch:		T06SK		Name:		Taxiway 06 Stark's		Use:		TAXIWAY		Area:		2,570 SqFt									
Section:		01		of		1		From:		Runway 02/20		To:		Taxiway 01		Last Const.:		8/1/1994					
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		P					
Area:		2,570 SqFt		Length:		123 Ft		Width:		18 Ft													
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft											
Shoulder:		Street Type:		Grade:		0		Lanes:		0													
Section Comments:																							
Work Date:				8/1/1994				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Work Date:				9/1/2016				Work Type:				Crack Sealing - AC				Code:		CS-AC		Is Major M&R:		False	
Last Insp. Date:				7/1/2023				TotalSamples:				1				Surveyed:				1			
Conditions:				PCI:				68															
Inspection Comments:																							
Sample Number:				01				Type:		R		Area:		2570.00 SqFt				PCI:		68			
Sample Comments:																							
48		L & T CR				L		340.00 Ft															
57		WEATHERING				L		2570.00 SqFt															

Network:		Starks		Name:		Stark's Twin Oaks																									
Branch:		TH10SK		Name:		Hangar Taxiway 10 Stark's		Use:		TAXIWAY		Area:		12,592 SqFt																	
Section:		01		of		1		From:		Taxiway 01		To:		Hangars		Last Const.:		9/1/2016													
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		P													
Area:		12,592 SqFt		Length:		530 Ft		Width:		25 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				9/1/2016				Work Type:				New Construction - AC				Code:				NC-AC				Is Major M&R:				True			
Last Insp. Date:				7/1/2023				TotalSamples:				2				Surveyed:				2											
Conditions:				PCI:				88																							
Inspection Comments:																															
Sample Number:				01				Type:				R				Area:				5592.00 SqFt				PCI:				89			
Sample Comments:																															
48				L & T CR				L				74.00				Ft															
57				WEATHERING				L				5592.00				SqFt															
Sample Number:				02				Type:				R				Area:				7000.00 SqFt				PCI:				88			
Sample Comments:																															
48				L & T CR				L				97.00				Ft															
48				L & T CR				L				43.00				Ft															
57				WEATHERING				L				7000.00				SqFt															

Network:	Starks		Name:	Stark's Twin Oaks							
Branch:	TH11SK		Name:	Hangar Taxiway 11 Stark's		Use:	TAXIWAY	Area:	12,561 SqFt		
Section:	01	of	1	From:	T01SK-02			To:	End	Last Const.:	9/1/2020
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:				Category:	Rank: P	
Area:	12,561 SqFt		Length:	530 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	9/1/2020		Work Type: New Construction - Initial				Code:	NC-IN		Is Major M&R: True	
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5584.00 SqFt			PCI:	94		
Sample Comments:											
57	WEATHERING		L	5584.00 SqFt							
Sample Number:	02	Type:	R	Area:	6977.00 SqFt			PCI:	94		
Sample Comments:											
57	WEATHERING		L	6977.00 SqFt							

Network:		Starks		Name:		Stark's Twin Oaks																									
Branch:		TH1SK		Name:		Hangar Taxiway 1 Stark's		Use:		TAXIWAY		Area:		12,593 SqFt																	
Section:		01		of		1		From:		Taxiway 01 Stark's		To:		East End		Last Const.:		6/1/2009													
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		S													
Area:		12,593 SqFt		Length:		530 Ft		Width:		25 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				6/1/2009				Work Type:				New Construction - Initial				Code:				NC-IN				Is Major M&R:				True			
Last Insp. Date:				7/1/2023				TotalSamples:				2				Surveyed:				2											
Conditions:				PCI:				77																							
Inspection Comments:																															
Sample Number:				01				Type:		R		Area:				5593.00 SqFt				PCI:				74							
Sample Comments:																															
48		L & T CR				L		264.00		Ft																					
48		L & T CR				L		192.00		Ft																					
57		WEATHERING				L		5593.00		SqFt																					
Sample Number:				02				Type:		R		Area:				7000.00 SqFt				PCI:				79							
Sample Comments:																															
48		L & T CR				L		70.00		Ft																					
48		L & T CR				L		306.00		Ft																					
57		WEATHERING				L		7000.00		SqFt																					

Network:		Starks		Name:		Stark's Twin Oaks					
Branch:	TH2SK		Name:	Hangar Taxiway 2 Stark's		Use:	TAXIWAY	Area:	18,242 SqFt		
Section:	02	of 2	From:	T01SK-02		To:	Hangars		Last Const.:	8/2/2004	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E	Rank:	P
Area:	2,642 SqFt		Length:	130 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	8/1/2004		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	8/2/2004		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 46										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	2642.00 SqFt		PCI:	46			
Sample Comments:											
41	ALLIGATOR CR		M	42.00	SqFt						
45	DEPRESSION		L	18.00	SqFt						
48	L & T CR		L	138.00	Ft						
48	L & T CR		L	24.00	Ft						
48	L & T CR		M	22.00	Ft						
57	WEATHERING		L	2642.00	SqFt						

Network:		Starks		Name:		Stark's Twin Oaks																	
Branch:		TH2SK		Name:		Hangar Taxiway 2 Stark's		Use:		TAXIWAY		Area:		18,242 SqFt									
Section:		01		of		2		From:		TH2SK-01		To:		Hangars		Last Const.:		9/2/2003					
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		P					
Area:		15,600 SqFt		Length:		390 Ft		Width:		40 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				9/1/2003				Work Type:				Base Course - Aggregate				Code:		BA-AG		Is Major M&R:		False	
Work Date:				9/2/2003				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Last Insp. Date:				7/1/2023				TotalSamples:				4				Surveyed:				3			
Conditions:				PCI: 58																			
Inspection Comments:																							
Sample Number:		01		Type:		R		Area:		4000.00 SqFt		PCI:		62									
Sample Comments:																							
41	ALLIGATOR CR			M	26.00 SqFt																		
48	L & T CR			L	378.00 Ft																		
48	L & T CR			L	150.00 Ft																		
57	WEATHERING			L	4000.00 SqFt																		
Sample Number:		02		Type:		R		Area:		4000.00 SqFt		PCI:		59									
Sample Comments:																							
41	ALLIGATOR CR			M	45.00 SqFt																		
48	L & T CR			L	356.00 Ft																		
48	L & T CR			L	137.00 Ft																		
57	WEATHERING			L	4000.00 SqFt																		
Sample Number:		03		Type:		R		Area:		4000.00 SqFt		PCI:		52									
Sample Comments:																							
41	ALLIGATOR CR			M	36.00 SqFt																		
41	ALLIGATOR CR			M	56.00 SqFt																		
48	L & T CR			L	368.00 Ft																		
48	L & T CR			L	68.00 Ft																		
48	L & T CR			L	45.00 Ft																		
57	WEATHERING			L	4000.00 SqFt																		

Network:		Starks		Name:		Stark's Twin Oaks					
Branch:	TH3SK		Name:	Hangar Taxiway 3 Stark's		Use:	TAXIWAY	Area:	17,966 SqFt		
Section:	02	of 2	From:	T01SK-02		To:	Hangars		Last Const.:	8/2/2004	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E	Rank:	P
Area:	2,766 SqFt		Length:	133 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	8/1/2004		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	8/2/2004		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 62										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	2766.00 SqFt		PCI:	62			
Sample Comments:											
41	ALLIGATOR CR		M	10.00 SqFt							
48	L & T CR		L	141.00 Ft							
48	L & T CR		M	22.00 Ft							
50	PATCHING		L	20.00 SqFt							
57	WEATHERING		L	2766.00 SqFt							

Network:	Starks		Name:	Stark's Twin Oaks					
Branch:	TH3SK		Name:	Hangar Taxiway 3 Stark's		Use:	TAXIWAY	Area:	17,966 SqFt
Section:	01	of	2	From:	TH3SK-01		To:	Hangars	Last Const.: 9/2/2003
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC	Zone:	7S3		Category:	E	Rank: P
Area:	15,200 SqFt		Length:	380 Ft		Width:	40 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade: 0				Lanes:	0	
Section Comments:									
Work Date:	9/1/2003		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	9/2/2003		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True
Last Insp. Date:	7/1/2023		TotalSamples:	4		Surveyed:	3		
Conditions:	PCI: 68								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	4000.00 SqFt		PCI:	66	
Sample Comments:									
48	L & T CR		L	407.00 Ft					
50	PATCHING		L	74.00 SqFt					
57	WEATHERING		L	4000.00 SqFt					
Sample Number:	03	Type:	R	Area:	4000.00 SqFt		PCI:	68	
Sample Comments:									
48	L & T CR		L	242.00 Ft					
48	L & T CR		L	115.00 Ft					
50	PATCHING		L	74.00 SqFt					
57	WEATHERING		L	4000.00 SqFt					
Sample Number:	04	Type:	R	Area:	4000.00 SqFt		PCI:	68	
Sample Comments:									
41	ALLIGATOR CR		M	10.00 SqFt					
48	L & T CR		L	199.00 Ft					
50	PATCHING		L	74.00 SqFt					
57	WEATHERING		L	4000.00 SqFt					

Network: Starks		Name: Stark's Twin Oaks	
Branch: TH4SK	Name: Hangar Taxiway 4 Stark's		Use: TAXIWAY Area: 11,065 SqFt
Section: 01	of 1	From: Taxiway 01	To: Hangars Last Const.: 8/1/2000
Surface: AC	Family: 2023_Region1_Cat5_Taxi way_AC	Zone: 7S3	Category: E Rank: S
Area:	11,065 SqFt	Length:	500 Ft Width: 22 Ft
Slabs:	Slab Length:	Ft	Slab Width: Ft Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 8/1/2000		Work Type: New Construction - AC	Code: NC-AC Is Major M&R: True
Work Date: 8/1/2000		Work Type: Base Course - Aggregate	Code: BA-AG Is Major M&R: False
Work Date: 9/1/2016		Work Type: Crack Sealing - AC	Code: CS-AC Is Major M&R: False
Work Date: 9/2/2016		Work Type: Patching - AC Deep	Code: PA-AD Is Major M&R: False
Last Insp. Date: 7/1/2023		TotalSamples: 2	Surveyed: 2
Conditions: PCI: 73			
Inspection Comments:			
Sample Number: 01	Type: R	Area: 4377.00 SqFt	PCI: 74
Sample Comments:			
41	ALLIGATOR CR	M	6.00 SqFt
48	L & T CR	L	78.00 Ft
48	L & T CR	L	106.00 Ft
50	PATCHING	L	42.00 SqFt
57	WEATHERING	L	4377.00 SqFt
Sample Number: 02	Type: R	Area: 6688.00 SqFt	PCI: 73
Sample Comments:			
48	L & T CR	L	131.00 Ft
48	L & T CR	L	254.00 Ft
48	L & T CR	L	37.00 Ft
48	L & T CR	M	14.00 Ft
48	L & T CR	M	30.00 Ft
57	WEATHERING	L	6688.00 SqFt

Network:		Starks		Name:		Stark's Twin Oaks																									
Branch:		TH5SK		Name:		Hangar Taxiway 5 Stark's		Use:		TAXIWAY		Area:		11,217 SqFt																	
Section:		02		of		2		From:		Taxiway 01		To:		Hangars		Last Const.:		8/1/1995													
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		S													
Area:		6,280 SqFt		Length:		500 Ft		Width:		13 Ft																					
Slabs:		Slab Length:				Ft		Slab Width:				Ft		Joint Length:				Ft													
Shoulder:		Street Type:						Grade:		0				Lanes:		0															
Section Comments:																															
Work Date:				8/1/1995				Work Type:				New Construction - AC				Code:				NC-AC				Is Major M&R:				True			
Last Insp. Date:				7/1/2023				TotalSamples:				2				Surveyed:				1											
Conditions:				PCI:				94																							
Inspection Comments:																															
Sample Number:				01				Type:		R		Area:				6280.00 SqFt				PCI:				94							
Sample Comments:																															
57		WEATHERING				L		6280.00 SqFt																							

Network:	Starks			Name:	Stark's Twin Oaks					
Branch:	TH5SK		Name:	Hangar Taxiway 5 Stark's		Use:	TAXIWAY	Area:	11,217 SqFt	
Section:	01	of	2	From:	Section 02			To:	Hangars	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC	Zone:	7S3			Category:	E	Last Const.: 8/1/2000
Area:	4,937 SqFt		Length:	395 Ft		Width:	13 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	8/1/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed: 1				
Conditions:	PCI: 94									
Inspection Comments:										
Sample Number:	01	Type:	R	Area:	4937.00 SqFt			PCI:	94	
Sample Comments:										
57	WEATHERING		L	4937.00 SqFt						

Network:		Starks		Name:		Stark's Twin Oaks					
Branch:	TH6SK		Name:	Hangar Taxiway 6 Stark's		Use:	TAXIWAY	Area:	10,226 SqFt		
Section:	02	of	2	From:	Taxiway 01		To:	Hangars	Last Const.:	8/1/1990	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3	Category:	E	Rank:	S	
Area:	5,605 SqFt		Length:	460 Ft		Width:	12 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	8/1/1990		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 37										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5605.00 SqFt		PCI:	37			
Sample Comments:											
41	ALLIGATOR CR		M	250.00	SqFt						
41	ALLIGATOR CR		M	26.00	SqFt						
41	ALLIGATOR CR		M	25.00	SqFt						
48	L & T CR		L	212.00	Ft						
48	L & T CR		L	132.00	Ft						
48	L & T CR		M	15.00	Ft						
57	WEATHERING		L	5605.00	SqFt						

Network:		Starks		Name:		Stark's Twin Oaks					
Branch:	TH6SK		Name:	Hangar Taxiway 6 Stark's		Use:	TAXIWAY	Area:	10,226 SqFt		
Section:	01	of	2	From:	Taxiway 01		To:	Hangars	Last Const.:	8/1/1990	
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3	Category:	E	Rank:	S	
Area:	4,621 SqFt		Length:	460 Ft		Width:	10 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	8/1/1990		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 55										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	4621.00 SqFt		PCI:	55			
Sample Comments:											
41	ALLIGATOR CR		M	56.00 SqFt							
41	ALLIGATOR CR		M	12.00 SqFt							
48	L & T CR		L	615.00 Ft							
48	L & T CR		L	68.00 Ft							
57	WEATHERING		L	4621.00 SqFt							

Network:	Starks			Name:	Stark's Twin Oaks						
Branch:	TH7SK		Name:	Hangar Taxiway 7 Stark's		Use:	TAXIWAY	Area:	6,744 SqFt		
Section:	01	of	1	From:	Taxiway 01			To:	Hangars		
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC		Zone:	7S3		Category:	E	Last Const.:	8/1/1990
Area:	6,744 SqFt		Length:	480 Ft		Width:	14 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	8/1/1990		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2023		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	6744.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	6744.00 SqFt							

Network:	Starks			Name:	Stark's Twin Oaks					
Branch:	TH8SK	Name:	Hangar Taxiway 8 Stark's		Use:	TAXIWAY	Area:	10,313 SqFt		
Section:	01	of	1	From:	Taxiway 01		To:	Hangars	Last Const.:	8/1/1990
Surface:	AC	Family:	2023_Region1_Cat5_Taxi way_AC	Zone:	7S3		Category:	E	Rank:	S
Area:	10,313 SqFt		Length:	470 Ft		Width:	14 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	8/1/1990		Work Type: New Construction - AC			Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	7/1/2023		TotalSamples:	2		Surveyed:	2			
Conditions:	PCI: 63									
Inspection Comments:										
Sample Number:	01	Type:	R	Area:	6128.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	6128.00 SqFt						
Sample Number:	02	Type:	R	Area:	4185.00 SqFt		PCI:	18		
Sample Comments:										
41	ALLIGATOR CR		H	450.00 SqFt						
48	L & T CR		L	188.00 Ft						
57	WEATHERING		M	4185.00 SqFt						

Network:		Starks		Name:		Stark's Twin Oaks																	
Branch:		TH9SK		Name:		Hangar Taxiway 9 Stark's		Use:		TAXIWAY		Area:		2,541 SqFt									
Section:		01		of		1		From:		Apron 01		To:		Hangars		Last Const.:		8/1/1985					
Surface:		AC		Family:		2023_Region1_Cat5_Taxi way_AC		Zone:		7S3		Category:		E		Rank:		S					
Area:		2,541 SqFt		Length:		210 Ft		Width:		12 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				8/1/1985				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Last Insp. Date:				7/1/2023				TotalSamples:				1				Surveyed:				1			
Conditions:				PCI:				30															
Inspection Comments:																							
Sample Number:		01		Type:		R		Area:		2541.00 SqFt		PCI:		30									
Sample Comments:																							
41		ALLIGATOR CR		M		240.00 SqFt																	
45		DEPRESSION		L		64.00 SqFt																	
48		L & T CR		L		187.00 Ft																	
57		WEATHERING		L		2541.00 SqFt																	

APPENDIX F

Work History Report

12/12/2023

Work History Report

Page 1 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 01 Surface: AC L.C.D. 8/1/1985 Use: APRON Rank: P Length: 210.00 (Ft) Width: 135.00 (Ft) True Area: 21840 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	
8/1/1985	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 02 Surface: AC L.C.D. 8/1/1980 Use: APRON Rank: P Length: 160.00 (Ft) Width: 40.00 (Ft) True Area: 6617 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	
8/1/1980	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 03 Surface: AC L.C.D. 8/2/2004 Use: APRON Rank: P Length: 227.00 (Ft) Width: 60.00 (Ft) True Area: 16016 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/2/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/1/2004	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 04 Surface: AC L.C.D. 6/2/2023 Use: APRON Rank: P Length: 200.00 (Ft) Width: 80.00 (Ft) True Area: 15753 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	
6/1/2023	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	9-12"AB

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 05 Surface: AC L.C.D. 9/2/2017 Use: APRON Rank: P Length: 270.00 (Ft) Width: 52.00 (Ft) True Area: 14753 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2017	CR-AC	Complete Reconstruction - AC	73,765.00	3.00	<input checked="" type="checkbox"/>	Thickness estimated based on sections
9/1/2017	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	Thickness estimated based on sections

Network: Stark's Twin Oaks Branch: A01SK Apron 01 Stark's Section: 06 Surface: PCC L.C.D. 9/2/2017 Use: APRON Rank: P Length: 105.00 (Ft) Width: 82.00 (Ft) True Area: 7581 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2017	CR-PC	Complete Reconstruction - PCC	75,810.00	0.00	<input checked="" type="checkbox"/>	Unknown Thickness
9/1/2017	BA-AG	Base Course - Aggregate	0.00	0.00	<input type="checkbox"/>	Unknown Thickness

Network: Stark's Twin Oaks Branch: AHLD02SK Hold Apron RW 0 Section: 01 Surface: AC L.C.D. 9/1/2011 Use: APRON Rank: P Length: 70.00 (Ft) Width: 25.00 (Ft) True Area: 1143 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2011	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

12/12/2023

Work History Report

Page 2 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks		Branch: AHLD02SK		Hold Apron RW 0		Section: 02	Surface: AC
L.C.D. 4/2/2023	Use: APRON	Rank: P	Length: 270.00 (Ft)	Width: 35.00 (Ft)	True Area: 8242 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
4/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	9-12" AB	
4/1/2023	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: R02SK		Runway 02/20 Star		Section: 01	Surface: AC
L.C.D. 9/1/2011	Use: RUNWAY	Rank: P	Length: 75.00 (Ft)	Width: 50.00 (Ft)	True Area: 3750 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/3/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>		
9/2/2016	PA-AF	Patching - AC Full Depth	0.00	0.00	<input type="checkbox"/>		
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/1/2011	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: R02SK		Runway 02/20 Star		Section: 02		Surface: AC	
L.C.D. 8/1/1992		Use: RUNWAY		Rank: P		Length: 1,200.00 (Ft)		Width: 50.00 (Ft) True Area: 60000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/3/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth			
9/2/2016	PA-AF	Patching - AC Full Depth	0.00	0.00	<input type="checkbox"/>				
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
6/1/2010	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
8/1/1992	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>				

Network: Stark's Twin Oaks		Branch: R02SK		Runway 02/20 Star		Section: 03		Surface: AC			
L.C.D. 8/1/1996		Use: RUNWAY		Rank: P		Length: 1,150.00 (Ft)		Width: 50.00 (Ft)		True Area: 57500 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
9/3/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth, date; circa 1995					
9/2/2016	PA-AF	Patching - AC Full Depth	0.00	0.00	<input type="checkbox"/>						
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>						
6/1/2010	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>						
8/1/1996	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>						

Network: Stark's Twin Oaks		Branch: R02SK		Runway 02/20 Star		Section: 04		Surface: AC	
L.C.D. 8/1/1994		Use: RUNWAY		Rank: P		Length: 125.00 (Ft)		Width: 42.00 (Ft) True Area: 5117 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth			
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
6/1/2010	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
8/1/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>				

12/12/2023

Work History Report

Page 3 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 01 Surface: AC L.C.D. 9/1/2011 Use: TAXIWAY Rank: P Length: 654.00 (Ft) Width: 20.00 (Ft) True Area: 15358 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2011	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 02 Surface: AC L.C.D. 8/2/2004 Use: TAXIWAY Rank: P Length: 789.00 (Ft) Width: 20.00 (Ft) True Area: 15462 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	
8/2/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/1/2004	BA-AG	Base Course - Aggregate	0.00	8.00	<input type="checkbox"/>	

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 03 Surface: AAC L.C.D. 9/1/2017 Use: TAXIWAY Rank: P Length: 108.00 (Ft) Width: 18.00 (Ft) True Area: 1926 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	OL-AS	Overlay - AC Structural	4,218.00	0.00	<input checked="" type="checkbox"/>	Unknown thickness and assumed date
8/1/2000	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 04 Surface: AAC L.C.D. 9/1/2017 Use: TAXIWAY Rank: P Length: 397.00 (Ft) Width: 18.00 (Ft) True Area: 7146 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	Unknown thickness and assumed date
8/1/1995	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth, date; circa 1995

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 05 Surface: AAC L.C.D. 9/1/2017 Use: TAXIWAY Rank: P Length: 260.00 (Ft) Width: 18.00 (Ft) True Area: 4680 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	Unknown thickness and assumed date
8/1/1995	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth, date; circa 1995

Network: Stark's Twin Oaks Branch: T01SK Taxiway 01 Stark's Section: 06 Surface: AC L.C.D. 8/1/1994 Use: TAXIWAY Rank: P Length: 446.00 (Ft) Width: 18.00 (Ft) True Area: 14845 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/1/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth

12/12/2023

Work History Report

Page 4 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks		Branch: T01SK		Taxiway 01 Stark's		Section: 07	Surface: AC
L.C.D. 4/2/2023	Use: TAXIWAY	Rank: P	Length: 67.00 (Ft)	Width: 95.00 (Ft)	True Area: 6097 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
4/2/2023	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	9-12" AB	
4/1/2023	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>		
4/1/2022	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: T02SK		Taxiway 02 Stark's		Section: 01	Surface: AC
L.C.D. 8/2/2004	Use: TAXIWAY	Rank: P	Length: 90.00 (Ft)	Width: 50.00 (Ft)	True Area: 3029 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>		
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/2/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/1/2004	BA-AG	Base Course - Aggregate	0.00	8.00	<input type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: T03SK		Taxiway 03 Stark's		Section: 01	Surface: AC
L.C.D. 8/1/1995	Use: TAXIWAY	Rank: P	Length: 144.00 (Ft)	Width: 20.00 (Ft)	True Area: 4509 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth, date; circa 1995	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/1995	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: T04SK		Taxiway 04 Stark's		Section: 01	Surface: AC
L.C.D. 8/1/1996	Use: TAXIWAY	Rank: P	Length: 67.00 (Ft)	Width: 20.00 (Ft)	True Area: 1394 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth, date; circa 1995	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/1996	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: T05SK		Taxiway 05 Stark's		Section: 01	Surface: AC
L.C.D. 8/1/1995	Use: TAXIWAY	Rank: P	Length: 67.00 (Ft)	Width: 120.00 (Ft)	True Area: 10065 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2016	OR-SS	Oregon Slurry Seal	0.00	0.00	<input type="checkbox"/>	Unknown depth, date; circa 1995	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/1995	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: T06SK		Taxiway 06 Stark's		Section: 01	Surface: AC
L.C.D. 8/1/1994	Use: TAXIWAY	Rank: P	Length: 123.00 (Ft)	Width: 18.00 (Ft)	True Area: 2570 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	Unknown depth	
8/1/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

12/12/2023

Work History Report

Page 5 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks Branch: TH10SK Hangar Taxiway 1 Section: 01 Surface: AC L.C.D. 9/1/2016 Use: TAXIWAY Rank: P Length: 530.00 (Ft) Width: 25.00 (Ft) True Area: 12592 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH11SK Hangar Taxiway 1 Section: 01 Surface: AC L.C.D. 9/1/2020 Use: TAXIWAY Rank: P Length: 530.00 (Ft) Width: 25.00 (Ft) True Area: 12561 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2020	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH1SK Hangar Taxiway 1 Section: 01 Surface: AC L.C.D. 6/1/2009 Use: TAXIWAY Rank: S Length: 530.00 (Ft) Width: 25.00 (Ft) True Area: 12593 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2009	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH2SK Hangar Taxiway 2 Section: 01 Surface: AC L.C.D. 9/2/2003 Use: TAXIWAY Rank: P Length: 390.00 (Ft) Width: 40.00 (Ft) True Area: 15600 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2003	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/2003	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH2SK Hangar Taxiway 2 Section: 02 Surface: AC L.C.D. 8/2/2004 Use: TAXIWAY Rank: P Length: 130.00 (Ft) Width: 20.00 (Ft) True Area: 2642 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/2/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/1/2004	BA-AG	Base Course - Aggregate	0.00	8.00	<input type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH3SK Hangar Taxiway 3 Section: 01 Surface: AC L.C.D. 9/2/2003 Use: TAXIWAY Rank: P Length: 380.00 (Ft) Width: 40.00 (Ft) True Area: 15200 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2003	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/2003	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Stark's Twin Oaks Branch: TH3SK Hangar Taxiway 3 Section: 02 Surface: AC L.C.D. 8/2/2004 Use: TAXIWAY Rank: P Length: 133.00 (Ft) Width: 20.00 (Ft) True Area: 2766 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/2/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
8/1/2004	BA-AG	Base Course - Aggregate	0.00	8.00	<input type="checkbox"/>	

12/12/2023

Work History Report

Page 6 of 8

Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm

Network: Stark's Twin Oaks		Branch: TH4SK		Hangar Taxiway 4		Section: 01	Surface: AC
L.C.D. 8/1/2000	Use: TAXIWAY	Rank: S	Length: 500.00 (Ft)	Width: 22.00 (Ft)	True Area: 11065 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/2/2016	PA-AD	Patching - AC Deep	0.00	0.00	<input type="checkbox"/>	unknown depth	
9/1/2016	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/2000	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		
8/1/2000	BA-AG	Base Course - Aggregate	0.00	0.00	<input type="checkbox"/>		

Network: Stark's Twin Oaks		Branch: TH5SK		Hangar Taxiway 5		Section: 01	Surface: AC
L.C.D. 8/1/2000	Use: TAXIWAY	Rank: S	Length: 395.00 (Ft)	Width: 12.50 (Ft)	True Area: 4937 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/2000	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown Depth	

Network: Stark's Twin Oaks		Branch: TH5SK		Hangar Taxiway 5		Section: 02	Surface: AC
L.C.D. 8/1/1995	Use: TAXIWAY	Rank: S	Length: 500.00 (Ft)	Width: 12.50 (Ft)	True Area: 6280 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1995	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth, date; circa 1995	

Network: Stark's Twin Oaks		Branch: TH6SK		Hangar Taxiway 6		Section: 01	Surface: AC
L.C.D. 8/1/1990	Use: TAXIWAY	Rank: S	Length: 460.00 (Ft)	Width: 10.00 (Ft)	True Area: 4621 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1990	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN	

Network: Stark's Twin Oaks		Branch: TH6SK		Hangar Taxiway 6		Section: 02	Surface: AC
L.C.D. 8/1/1990	Use: TAXIWAY	Rank: S	Length: 460.00 (Ft)	Width: 12.00 (Ft)	True Area: 5605 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1990	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN	

Network: Stark's Twin Oaks		Branch: TH7SK		Hangar Taxiway 7		Section: 01	Surface: AC
L.C.D. 8/1/1990	Use: TAXIWAY	Rank: S	Length: 480.00 (Ft)	Width: 14.00 (Ft)	True Area: 6744 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1990	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth, date; circa 1990	

Network: Stark's Twin Oaks		Branch: TH8SK		Hangar Taxiway 8		Section: 01	Surface: AC
L.C.D. 8/1/1990	Use: TAXIWAY	Rank: S	Length: 470.00 (Ft)	Width: 14.00 (Ft)	True Area: 10313 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/1/1990	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown depth, date; circa 1990	

12/12/2023

Work History Report

Page 7 of 8

*Pavement Database: ODA_2023Survey_MASTER DB-12-11-2023_4pm***Network:** Stark's Twin Oaks**Branch:** TH9SK

Hangar Taxiway 9

Section: 01**Surface:** AC**L.C.D.** 8/1/1985**Use:** TAXIWAY**Rank:** S**Length:** 210.00 (Ft)**Width:** 12.00 (Ft)**True Area:** 2541 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/1985	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	UNKNOWN

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	13	134,206.00	6.62	3.03
Complete Reconstruction - AC	1	14,753.00	3.00	0.00
Complete Reconstruction - PCC	1	7,581.00	0.00	0.00
Crack Sealing - AC	14	296,461.01	0.00	0.00
New Construction - AC	32	363,714.00	0.78	1.11
New Construction - Initial	6	51,502.00	0.00	0.00
Oregon Slurry Seal	12	204,128.00	0.00	0.00
Overlay - AC Structural	3	13,752.00	0.00	0.00
Patching - AC Deep	1	11,065.00	0.00	0.00
Patching - AC Full Depth	3	121,250.00	0.00	0.00