

2024 ODAV Pavement Evaluation Program Illinois Valley Airport

Cave Junction, Oregon

February 12, 2025

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY.....	1
3	PAVEMENT CONDITION INSPECTION RESULTS	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results.....	6
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	9
	4.1 Introduction.....	9
	4.2 Future Condition Analysis	9
	4.3 Functional Remaining Life	9
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	11
	5.1 Introduction.....	11
	5.2 Recommended Localized Maintenance.....	11
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan	11
6	LIMITATIONS	13

TABLES

Table 3-1:	ASTM PCI Rating Scale.....	5
Table 5-1:	Localized Maintenance Quantities.....	11
Table 5-2:	Surface Treatment, Rehabilitation, and Reconstruction Quantities	11

FIGURES

Figure 2.1:	Illinois Valley Airport Location Map	2
Figure 2.2:	Illinois Valley Airport Percent of Pavement Area by Surface Type.....	3
Figure 2.3:	Illinois Valley Airport Pavement Area by Branch Use	3
Figure 2.4:	Illinois Valley Airport Pavement Inventory	4
Figure 3.1:	Illinois Valley Airport 2024 PCI Survey Results.....	7
Figure 3.2:	Illinois Valley Airport Pavement Condition Rating by Percent of Area.....	8
Figure 4.1:	Illinois Valley Airport Future Pavement Condition	10
Figure 5.1:	Illinois Valley Airport 5-Year Pavement Management Plan	12

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan



APPENDICES (CONTINUED)

Appendix E: Reinspection Report

Appendix F: Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a 5-year plan comprising maintenance, surface treatment, rehabilitation, and reconstruction projects for the Illinois Valley Airport in Cave Junction, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Illinois Valley Airport in 2024 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the Pavement Condition Index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from 0 to 100, where 0 represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Illinois Valley Airport is in Cave Junction, Oregon, and is owned and operated by Josephine County. The airport consists of one runway, multiple connector taxiways, taxilanes, and aprons that serve a variety of general aviation aircraft. The general location of the airport is shown below on the Illinois Valley Airport Location Map, Figure 2.1.



Figure 2.1: ILLINOIS VALLEY AIRPORT LOCATION MAP

The airside pavements at the Illinois Valley Airport are composed of asphalt concrete (AC), AC overlaid with AC, and portland cement concrete (PCC). The airport pavements, delineated by surface type and branch use, are shown on the Illinois Valley Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on the Illinois Valley Airport Pavement Area by Branch Use, Figure 2.3, shown below. The pavement inventory, including work history for each pavement section, is displayed spatially on the Illinois Valley Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 2A and 3A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report, Table 1F.




Figure 2.2: ILLINOIS VALLEY AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE





Figure 2.3: ILLINOIS VALLEY AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE; BST = BITUMINOUS SURFACE TREATMENT; PCC = PORTLAND CEMENT CONCRETE



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

**ILLINOIS VALLEY AIRPORT
PAVEMENT INVENTORY**








3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Illinois Valley Airport in August 2024. The 2024 survey work was performed on sections last inspected in 2019 in order to update the Illinois Valley Airport inspection data. GRI performed the 2024 PCI survey in accordance with the methods described in FAA Advisory Circular No. 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1, below.


Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

Abbreviations: ASTM = ASTM International; PCI = Pavement Condition Index; M&R = maintenance and rehabilitation


3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Illinois Valley Airport is approximately 86. The section PCIs ranged from a low of 0 to a high of 94. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, block cracking, and depression on AC-surfaced pavements and patching, shattered slabs, and faulting on PCC surfaced pavements. Section PCIs following our pavement survey are displayed below spatially on the Illinois Valley Airport 2024 PCI Survey Results, Figure 3.1.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



**ILLINOIS VALLEY AIRPORT
2024 PCI SURVEY RESULTS**

The condition distribution of the network by percent of total pavement area is provided on the Illinois Valley Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2024 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2: ILLINOIS VALLEY AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Illinois Valley Airport are displayed on Figures 1C through 4C in Appendix C.

4.2 Future Condition Analysis


Using the condition prediction models discussed above, the projected condition of each pavement section was determined for five- and 10-year periods. Based on this analysis, we project the PCI will decrease from a current value of 86 to a value of 81 in 2029 and to 75 in 2034 if no maintenance or rehabilitation work is performed. The projected pavement condition in five years and 10 years for each pavement section at Illinois Valley Airport is displayed spatially on the Illinois Valley Airport Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.

4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and Falling Weight Deflectometer deflection tests.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Illinois Valley Airport. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Illinois Valley Airport are summarized in Table 2C in Appendix C.



FEB. 2025 JOB NO. 6593-WOC7 FIG. 4.1

5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated maintenance and rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priorities and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the 5-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1, below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES

Localized Maintenance Operation	Quantity, linear feet or square feet
Asphalt Concrete Crack Sealing	14,848
Asphalt Concrete Full-Depth Patching	1,320
Asphalt Concrete Patching Leveling	131
Portland Cement Concrete Full-Depth Patching	2,000


5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan

To develop the 5-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

Treatment Type	Quantity, square feet
Reconstruction	47,501
Overlay	11,911
Fog Seal	13,090
Slurry Seal	20,840

Maps of the project locations by year are shown on the Illinois Valley Airport 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is summarized in Table 4D in Appendix D.





ACTION TIMING

- 2025
- 2026
- 2027
- 2028
- 2029

ACTION

- FOG SEAL
- SLURRY SEAL
- OVERLAY
- RECONSTRUCTION
- ROUTINE MAINTENANCE



**ILLINOIS VALLEY AIRPORT
5-YEAR PAVEMENT MANAGEMENT PLAN**

6 LIMITATIONS

This report has been prepared to assist ODAV with pavement-related project planning for the Illinois Valley Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes and given the understanding that costs at the time of construction may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective M&R program should be reviewed and updated on a regular basis. The pavement condition should be regularly surveyed and updated, and completed construction activities should be tracked in the PAVER database. If Illinois Valley Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025

Lindsy A. Hammond, PE
Principal



Matthew A. Haynes, PE
Project Engineer



Ana Coca, PhD
Staff Engineer

This document has been submitted electronically.



APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Illinois Valley Airport is in Cave Junction, Oregon, and is owned and operated by Josephine County. The pavement network / facilities at Illinois Valley Airport serve a variety of general aviation aircraft. Illinois Valley Airport consists of one runway and multiple connector taxiways, taxilanes, and aprons. The types of airside pavements include asphalt concrete (AC), AC overlaid with AC, and portland cement concrete.

The current airport pavement management system (APMS) network at Illinois Valley Airport has an approximate area of 553,397 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 2A and 3A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Illinois Valley Airport contains nine branches, information about which is tabulated in Table 2A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as “a contiguous pavement area having uniform construction, maintenance, usage history, and condition.” All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Illinois Valley Airport contains 17 sections that are managed by Josephine County, information about which is summarized in Table 3A and the locations of which are shown spatially on Figure 1A.

PAVER assigns a rank to each pavement segment that designates the pavement segment’s prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked “Primary,” the surrounding aprons and shoulders are ranked “Secondary,” and low-use areas are ranked “Tertiary.” The ranks for all sections are shown on Table 3A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average Pavement Condition Index (PCI) values. To meet this criterion, the ASTM method recommends that sample units for flexible pavements be 5,000 ±2,000 square feet and 20 slabs ±eight slabs for rigid pavements. The delineation of sample units for each section is shown on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of 8 PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2024 Illinois Valley Airport PCI survey, Table 1A was used as a guideline in developing sampling rates for flexible and rigid pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of 8 PCI points.

Sample unit locations at Illinois Valley Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and the remaining sample units are systematically spaced throughout the section at equal distances apart.

Table 1A: EXAMPLE SAMPLE RATES FOR AC AND PCC PAVEMENTS

AC Sampling Rate		PCC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n	Total Number of Sample Units, N	Sample Units to Survey, n
1	1	1	1
2 – 3	2	2	2
4 – 6	3	3 – 4	3
7 – 13	4	5 – 6	4
14 – 38	5	7 – 8	5
39+	6	9 – 11	6
		12 – 14	7
		15 – 19	8
		20 – 27	9
		28 – 38	10
		39 – 58	11
		59 – 104	12
		105 – 313	13
		314+	14

Abbreviations: AC = asphalt concrete; PCC = portland cement concrete

Table 2A: ILLINOIS VALLEY AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01IV	Apron 01 Illinois Valley	4	47,501
A02IV	Apron 02 Illinois Valley	1	42,524
A03IV	Apron 03 Illinois Valley	2	25,001
ARUN	Apron RunUp	2	28,895
R18IV	Runway 18/36 Illinois Valley	2	367,773
T01IV-01	Taxiway 01	3	20,863
T02IV	Taxiway 02 Illinois Valley	1	2,868
T03IV	Taxiway 03 Illinois Valley	1	3,236
TEIV	Taxiway E Illinois Valley	1	14,736

Table 3A: ILLINOIS VALLEY AIRPORT CURRENT PAVEMENT INVENTORY


Branch ID	Branch Name	Branch Use	Section ID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type	Approximate Slab Length, feet	Approximate Slab Width, feet	Number of Slabs
A01IV	Apron 01 Illinois Valley	APRON	01	Runway 18/36	A01IV-02	P	230	85	25,651	9/1/1977	AAC	0	0	0
A01IV	Apron 01 Illinois Valley	APRON	02	A01IV-01	A01IV-03,04,05	P	205	120	18,850	9/2/1965	AC	0	0	0
A01IV	Apron 01 Illinois Valley	APRON	03	A01IV-02	A01IV-02	P	50	40	2,000	9/2/1965	PCC	10	13	16
A01IV	Apron 01 Illinois Valley	APRON	04	A01IV-01	A01IV-02	P	50	20	1,000	9/2/1965	PCC	25	20	2
A02IV	Apron 02 Illinois Valley	APRON	01	Runway 18/36	End	P	452	95	42,524	8/2/2017	AC	0	0.0	0
A03IV	Apron 03 Illinois Valley	APRON	01	Hangars	A03IV-02	S	210	82	11,911	9/2/1993	AC	0	0	0
A03IV	Apron 03 Illinois Valley	APRON	02	A03IV-01	Rwy18 End Turnabout	S	250	94	13,090	9/2/1991	AC	0	0	0
ARUN	Apron RunUp	APRON	01	T01IV-02	End	P	142	100	15,730	6/1/2023	AC	0	0	0
ARUN	Apron RunUp	APRON	02	R18IV-01	West End	P	115	117	13,165	6/1/2023	AC	0	0	0
R18IV	Runway 18/36 Illinois Valley	RUNWAY	01	Runway 36 End	R18IV-02	P	1,265	75	102,648	9/1/1977	AAC	0	0	0
R18IV	Runway 18/36 Illinois Valley	RUNWAY	02	R18IV-01	R18IV-03	P	3,535	75	265,125	1/1/1980	AAC	0	0	0
T01IV-01	Taxiway 01	TAXIWAY	01	R18IV-02	T01IV-02	P	86	32	2,745	6/1/2023	AC	0	0	0
T01IV-01	Taxiway 01	TAXIWAY	02	T01IV-01	T01IV-03	P	411	27	8,196	6/1/2023	AC	0	0	0
T01IV-01	Taxiway 01	TAXIWAY	03	T01IV-02	End	P	183	58	9,922	6/1/2023	AC	0	0	0
T02IV	Taxiway 02 Illinois Valley	TAXIWAY	01	Runway	Apron 02	P	89	25	2,868	8/2/2017	AC	0	0	0
T03IV	Taxiway 03 Illinois Valley	TAXIWAY	01	Runway	Apron 02	P	100	25	3,236	8/2/2017	AC	0	0	0
TEIV	Taxiway E Illinois Valley	TAXIWAY	01	Runway 18/36	End	P	537	25	14,736	7/3/2004	AC	0	0	0

Abbreviations:

P = primary pavement; S = secondary pavement


LCD = Last construction date. The date of the last major rehabilitation (e.g., overlay).

AC = asphalt concrete; AAC = AC overlaid with AC; PCC = portland cement concrete



LEGEND

- SECTIONS
- SAMPLE UNIT



**ILLINOIS VALLEY AIRPORT
SAMPLE UNIT LAYOUT**



APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the Pavement Condition Index (PCI) is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM International (ASTM) D5340. Flexible pavement (e.g., asphalt concrete [AC] and AC overlaid with AC) and rigid pavement (e.g., portland cement concrete) distress types are presented in Table 1B. The pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE AND RIGID PAVEMENT

Flexible Pavement			Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause	PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load	61	Blow-Up	Load
42	Bleeding	Other	62	Corner Break	Load
43	Block Cracking	Climate/ Durability	63	Longitudinal, Transverse, & Diagonal Cracks	Climate/ Durability
44	Corrugation	Other	64	Durability Cracking	Climate/ Durability
45	Depression	Other	65	Joint Seal Damage	Other
46	Jet Blast	Other	66	Small Patch	Other
47	Joint Reflection Cracking	Climate/ Durability	67	Large Patch	Other
48	Longitudinal & Transverse Cracking	Climate/ Durability	68	Pop Outs	Other
49	Oil Spillage	Other	69	Pumping	Other
50	Patching	Climate/ Durability	70	Scaling	Other
51	Polished Aggregate	Other	71	Faulting	Other

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
52	Raveling	Climate/ Durability
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause
72	Shattered Slab	Load
73	Shrinkage Cracking	Other
74	Joint Spalls	Other
75	Corner Spalls	Other
76	Alkali-Silica Reactivity (ASR)	Other

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional” (units defined as nonrepresentative instead of random) are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, which governs PCI surveys, offers this caution:

The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the present condition of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI cannot measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the maintenance and rehabilitation planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking. Rigid pavement distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping, and joint spalling.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse cracking, swelling, and raveling/weathering. Rigid pavement distresses include blow-ups, durability cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- **Moisture- and drainage-related:** Flexible pavement distress includes alligator/fatigue cracking, depressions, potholes, and swelling. Rigid pavement distresses include corner breaks, divided slabs, and pumping.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, patching, and concrete slab joint faulting.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Illinois Valley Airport pavement network consists of nine branches and 17 sections. Forty sample units were visually inspected in the field. Data from the inspected sample units were input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2024 PCI survey, the area-weighted average PCI for the entire pavement network at Illinois Valley Airport is approximately 86, which corresponds to a PCI rating of Good.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2024 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Illinois Valley Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B: ILLINOIS VALLEY AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01IV	4	47,501	APRON	34	Very Poor
A02IV	1	42,524	APRON	92	Good
A03IV	2	25,001	APRON	68	Fair
ARUN	2	28,895	APRON	94	Good
R18IV	2	367,773	RUNWAY	93	Good
T01IV	3	20,863	TAXIWAY	93	Good
T02IV	1	2,868	TAXIWAY	75	Satisfactory
T03IV	1	3,236	TAXIWAY	79	Satisfactory
TEIV	1	14,736	TAXIWAY	81	Satisfactory

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	9	143,921	69
RUNWAY	2	367,773	93
TAXIWAY	6	41,703	87
ALL	17	553,397	86

Abbreviations: PCI = Pavement Condition Index

Table 3B: ILLINOIS VALLEY AIRPORT 2024 PAVEMENT CONDITION INDEX SURVEY RESULTS

Branch ID	Section ID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01IV	01	9/1/1977	AAC	APRON	8/1/2024	47	42	Poor	100	0	0
A01IV	02	9/2/1965	AC	APRON	8/1/2024	59	28	Very Poor	61	39	0
A01IV	03	9/2/1965	PCC	APRON	8/1/2024	59	0	Failed	0	100	0
A01IV	04	9/2/1965	PCC	APRON	8/1/2024	59	10	Failed	0	0	100
A02IV	01	8/2/2017	AC	APRON	8/1/2024	7	92	Good	100	0	0
A03IV	01	9/2/1993	AC	APRON	8/1/2024	31	47	Poor	52	48	0
A03IV	02	9/2/1991	AC	APRON	8/1/2024	33	88	Good	100	0	0
ARUN	01	6/1/2023	AC	APRON	8/1/2024	1	94	Good	100	0	0
ARUN	02	6/1/2023	AC	APRON	8/1/2024	1	94	Good	100	0	0
R18IV	01	9/1/1977	AAC	RUNWAY	8/1/2024	47	94	Good	100	0	0
R18IV	02	1/1/1980	AAC	RUNWAY	8/1/2024	45	93	Good	100	0	0
T01IV-01	01	6/1/2023	AC	TAXIWAY	8/1/2024	1	94	Good	100	0	0
T01IV-01	02	6/1/2023	AC	TAXIWAY	8/1/2024	1	94	Good	100	0	0
T01IV-01	03	6/1/2023	AC	TAXIWAY	8/1/2024	1	92	Good	100	0	0
T02IV	01	8/2/2017	AC	TAXIWAY	8/1/2024	7	75	Satisfactory	100	0	0
T03IV	01	8/2/2017	AC	TAXIWAY	8/1/2024	7	79	Satisfactory	100	0	0
TEIV	01	7/3/2004	AC	TAXIWAY	8/1/2024	20	81	Satisfactory	100	0	0

Abbreviations:

PCI = Pavement Condition Index; AAC = AC overlaid with AC; AC = asphalt concrete; PCC = portland cement concrete

Table 4B: ILLINOIS VALLEY AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2024 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2019 Survey			2024 Survey			Rate of Deterioration	
					PCI ³	PCI Category	Inspection Date	PCI	PCI Category	Age ⁴		Δ PCI/yr ⁵
A01IV	01	AAC	25,651	9/1/77	37	Fair	5/13/2019	42	Poor	42	0.96	NONE
A01IV	02	AC	18,850	9/2/65	13	Satisfactory	5/13/2019	28	Very Poor	54	3	NONE
A01IV	03	PCC	2,000	9/2/65	0	Satisfactory	5/13/2019	0	Failed	54	0.00	NONE
A01IV	04	PCC	1,000	9/2/65	0	Satisfactory	5/13/2019	10	Failed	54	2	NONE
A02IV	01	AC	42,524	8/2/17	98	Satisfactory	5/13/2019	92	Good	2	-1.15	NORMAL
A03IV	01	AC	11,911	9/2/93	78	Satisfactory	5/13/2019	47	Poor	26	-6	HIGH
A03IV	02	AC	13,090	9/2/91	90	Satisfactory	5/13/2019	88	Good	28	-0.38	NORMAL
ARUN	01	AC	15,730	6/1/23	--	--	--	94	Good	--	--	NA ⁶
ARUN	02	AC	13,165	6/1/23	--	--	--	94	Good	--	--	NA
R18IV	01	AAC	102,648	9/1/77	59	Satisfactory	5/13/2019	94	Good	42	7	NONE
R18IV	02	AAC	265,125	1/1/80	62	Good	5/13/2019	93	Good	39	5.93	NONE
T01IV-01	01	AC	2,745	6/1/23	--	--	--	94	Good	--	--	NA
T01IV-01	02	AC	8,196	6/1/23	--	--	--	94	Good	--	--	NA
T01IV-01	03	AC	9,922	6/1/23	--	--	--	92	Good	--	--	NA
T02IV	01	AC	2,868	8/2/17	100	Fair	5/13/2019	75	Satisfactory	2	-4.79	HIGH
T03IV	01	AC	3,236	8/2/17	100	Very Poor	5/13/2019	79	Satisfactory	2	-4	HIGH
TEIV	01	AC	14,736	7/3/04	90	Fair	5/13/2019	81	Satisfactory	15	-1.72	NORMAL

Abbreviations:

- ¹ AC = asphalt concrete; AAC = AC overlaid with AC; PCC = portland cement concrete
² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g., AC overlay).
³ PCI = Pavement Condition Index
⁴ Age = Pavement age in years at the time of the PCI survey in 2019
⁵ Δ PCI/yr = Change in PCI points per year between 2019 survey and 2024 survey
⁶ NA = Not applicable due to changes in sectioning
 -- = no value



APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan, this is done with the aid of a prediction model. When an airport pavement management system is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after Pavement Condition Index (PCI) surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is as follows:

1. Define the pavement families.
2. Review the data.
3. Conduct a data-outlier analysis.
4. Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Illinois Valley Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use four distinct models for the following “families” of pavements at Illinois Valley Airport. For each model, we reviewed the data to filter out any inconsistent or inaccurate data or any data outside the boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 4C below.




Figure 1C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 3/4 ASPHALT CONCRETE APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 3/4 ASPHALT CONCRETE RUNWAYS




Figure 3C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 3 ASPHALT CONCRETE TAXIWAYS




Figure 4C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 2/3/4 PORTLAND CEMENT CONCRETE RUNWAYS, TAXIWAYS, AND APRONS

C.3 CRITICAL PCI

Each condition-prediction model has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major maintenance and rehabilitation (M&R) (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Illinois Valley Airport:

- Runways: 60
- Taxiways/Taxilanes: 55
- Aprons: 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for five- and 10-year periods. The projected pavement conditions in five years and 10 years for each pavement section at Illinois Valley Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Illinois Valley Airport: the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (i.e., PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT, AND FUTURE PCI

Branch ID	Section ID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2019	2024	2029	2034
NETWORK	--	64	86	81	75
A01IV	01	37	42	37	31
A01IV	02	13	28	22	17
A01IV	03	0	0	0	0
A01IV	04	0	10	7	4
A02IV	01	98	92	87	81
A03IV	01	78	47	42	36
A03IV	02	90	88	83	77
ARUN	01	--	94	89	83
ARUN	02	--	94	89	83
R18IV	01	59	94	88	83
R18IV	02	62	93	87	82
T01IV-01	01	--	94	88	83
T01IV-01	02	--	94	88	83
T01IV-01	03	--	92	86	81
T02IV	01	100	75	69	64
T03IV	01	100	79	73	68
TEIV	01	90	81	75	70

Abbreviations: PCI = Pavement Condition Index; -- = no value

Table 2C: ILLINOIS VALLEY AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service Life
A01IV	01	AAC	42	0 – 5	50	0 – 5
A01IV	02	AC	28	0 – 5	50	0 – 5
A01IV	03	PCC	0	0 – 5	50	0 – 5
A01IV	04	PCC	10	0 – 5	50	0 – 5
A02IV	01	AC	92	> 20	50	> 20
A03IV	01	AC	47	– 5	50	6 – 10
A03IV	02	AC	88	> 20	50	> 20
ARUN	01	AC	94	> 20	50	> 20
ARUN	02	AC	94	> 20	50	> 20
R18IV	01	AAC	94	> 20	60	> 20
R18IV	02	AAC	93	> 20	60	> 20
T01IV-01	01	AC	94	> 20	55	> 20
T01IV-01	02	AC	94	> 20	55	> 20
T01IV-01	03	AC	92	> 20	55	> 20
T02IV	01	AC	75	16 – 20	55	> 20
T03IV	01	AC	79	> 20	55	> 20
TEIV	01	AC	81	> 20	55	> 20

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; PCC = portland cement concrete; M&R = maintenance and rehabilitation

¹ Major M&R Trigger PCI = Critical PCI



APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the maintenance and rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Illinois Valley Airport pavement network condition over time. We used PAVER v7.1.2 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2025. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- **Reconstruction:** Considered for pavements with a Pavement Condition Index (PCI) less than 40.
- **Rehabilitation (Asphalt Concrete [AC] Overlay):** Considered for pavements between 40 PCI and the critical PCI and for pavements exhibiting significant load-related distresses.
- **Surface Treatment:** Treatments (fog seal, slurry seal, thin AC overlay) are applied to an entire pavement section with the intent of slowing the rate of deterioration.
- **Localized Maintenance:** Maintenance performed on a routine basis, such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the 5-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, and Runway). The PAVER analysis uses the combination of the section rank and the branch use to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: MAINTENANCE AND REHABILITATION WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
Runway	1	3	6
Taxiway	2	5	8
Apron	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM International D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2019 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Illinois Valley Airport and information provided by the Oregon Department of Aviation Pavement Maintenance Program project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Illinois Valley Airport. The costs represent the fully loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D, below.

Table 2D: REGION 2 UNIT COST DATA

Type of M&R	Work Type	Unit Cost per Square Foot
Major M&R	Complete Reconstruction with AC	\$19.05
	Cold Mill and Overlay—2 Inches Thick	\$8.41
Surface Treatment (Global) M&R	Surface Treatment—Slurry Seal	\$0.50
	Surface Treatment—Fog Seal	\$0.33
Localized Preventive M&R	Crack Sealing—AC	\$2.75
	Crack Sealing—PCC	\$17.00
	Wide Crack Repair	\$75.00
	Joint Sealing—PCC	\$12.00
	AC Patching—Full Depth	\$75.00
	PCC Patching—Full Depth	\$140.00

Abbreviations: M&R = maintenance and rehabilitation; AC = asphalt concrete; PCC = portland cement concrete

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal / fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: ILLINOIS VALLEY AIRPORT NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01IV	01	Block Cracking	Medium	Crack Sealing—AC	7,819	Ft	\$2.75	\$21,501	\$21,501
A01IV	02	Block Cracking	Medium	Crack Sealing—AC	5,503	Ft	\$2.75	\$15,132	\$85,271
A01IV	02	Alligator Cracking	Medium	Patching—AC Deep	935	SqFt	\$75.00	\$70,139	
A01IV	03	Shattered Slab	High	Patching—PCC Full Depth	2,000	SqFt	\$200.00	\$400,000	\$400,000
A01IV	04	Faulting	High	Patching—AC Leveling	131	SqFt	\$75.00	\$9,843	\$9,843
A03IV	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	613	Ft	\$2.75	\$1,686	\$31,484
A03IV	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	369	Ft	\$2.75	\$1,015	
A03IV	01	Alligator Cracking	Medium	Patching—AC Deep	384	SqFt	\$75.00	\$28,784	
A03IV	02	Long. & Trans. Cracking	Low	Crack Sealing—AC	198	Ft	\$2.75	\$545	\$545
R18IV	02	Long. & Trans. Cracking	Low	Crack Sealing—AC	239	Ft	\$2.75	\$655	\$655
T02IV	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	29	Ft	\$2.75	\$80	\$80
T03IV	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	40	Ft	\$2.75	\$110	\$110
TEIV	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	39	Ft	\$2.75	\$108	\$108

Abbreviations:

Long. = longitudinal; Trans. = transverse; AC = asphalt concrete; PCC = portland cement concrete; Ft = feet; SqFt = square feet

Table 4D: 5-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2025	A03IV	01	APRON	AC	48	Overlay	11,911	\$13.73	\$163,538
2026	A01IV	02	APRON	AC	28	Reconstruction	18,850	\$19.05	\$359,088
	A01IV	03	APRON	PCC	0	Reconstruction	2,000	\$19.05	\$38,100
	A01IV	04	APRON	PCC	10	Reconstruction	1,000	\$19.05	\$19,050
2027	T02IV	01	TAXIWAY	AC	75	Slurry Seal	2,868	\$0.50	\$1,434
	T03IV	01	TAXIWAY	AC	79	Slurry Seal	3,236	\$0.50	\$1,618
	TEIV	01	TAXIWAY	AC	81	Slurry Seal	14,736	\$0.50	\$7,368
2028	A01IV	01	APRON	AAC	42	Reconstruction	25,651	\$19.05	\$488,646
2029	A03IV	02	APRON	AC	88	Fog Seal	13,090	\$0.33	\$4,320

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; PCC = portland cement concrete

Cost Summary	
2025 Total Project Cost	\$163,538
2026 Total Project Cost	\$416,237
2027 Total Project Cost	\$10,420
2028 Total Project Cost	\$488,646
2029 Total Project Cost	\$4,320
Total Five-Year Project Cost	\$1,083,161



APPENDIX E

Reinspection Report

Inspection Report

ODAV_2024_12-11-24_4pm_amc

Generated Date12/13/2024

Page 1 of 18

Network:	Illinois			Name:	Illinois Valley						
Branch:	A01IV		Name:	Apron 01 Illinois Valley		Use:	APRON		Area:	47,501 SqFt	
Section:	01		of	4		From:	Runway 18/36		To:	A01IV-02	
Surface:	AAC		Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	3S4		Category:	J	
Area:	25,651 SqFt		Length:	230 Ft		Width:	85 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:	0	

Section Comments:

Work Date:	9/1/1953	Work Type:	Subbase - Aggregate	Code:	SB-AG	Is Major M&R:	False
Work Date:	9/2/1953	Work Type:	Base Course - Aggregate	Code:	BA-AG	Is Major M&R:	False
Work Date:	9/3/1953	Work Type:	Surface Course - BST	Code:	SU-SB	Is Major M&R:	True
Work Date:	9/1/1977	Work Type:	Overlay - AC Thin	Code:	OL-AT	Is Major M&R:	True

Last Insp. Date:	8/1/2024	TotalSamples:	6	Surveyed:	3
Conditions:	PCI: 42				
Inspection Comments:					

Sample Number:	01	Type:	R	Area:	4100.00 SqFt	PCI:	42
----------------	----	-------	---	-------	--------------	------	----

Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
43	BLOCK CR	M	4100.00 SqFt	100.0	53.0	
57	WEATHERING	M	4100.00 SqFt	100.0	20.3	

Sample Number:	03	Type:	R	Area:	4250.00 SqFt	PCI:	42
----------------	----	-------	---	-------	--------------	------	----

Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
43	BLOCK CR	M	4250.00 SqFt	100.0	53.0	
57	WEATHERING	M	4250.00 SqFt	100.0	20.3	

Sample Number:	04	Type:	R	Area:	4250.00 SqFt	PCI:	42
----------------	----	-------	---	-------	--------------	------	----

Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
43	BLOCK CR	M	4250.00 SqFt	100.0	53.0	
57	WEATHERING	M	4250.00 SqFt	100.0	20.3	

Network:	Illinois			Name:	Illinois Valley						
Branch:	A01IV		Name:	Apron 01 Illinois Valley		Use:	APRON	Area:	47,501 SqFt		
Section:	02	of	4	From:	A01IV-01		To:	A01IV-03,04,05		Last Const.:	9/2/1965
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	3S4	Category:	J	Rank:	P	
Area:	18,850 SqFt		Length:	205 Ft		Width:	120 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0	Lanes:		0			
Section Comments:											

Work Date: 9/1/1965	Work Type: Base Course - Unknown (Major MR)	Code: BA-UN	Is Major M&R: True
Work Date: 9/2/1965	Work Type: New Construction - AC	Code: NC-AC	Is Major M&R: True
Last Insp. Date: 8/1/2024	TotalSamples: 3	Surveyed: 2	
Conditions: PCI: 28			
Inspection Comments:			

Sample Number:	01	Type:	R	Area:	6400.00 SqFt	PCI:	29
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	236.00 SqFt	3.7	43.5	
43	BLOCK CR	M	6164.00 SqFt	96.3	52.3	
57	WEATHERING	M	6400.00 SqFt	100.0	20.3	

Sample Number:	03	Type:	R	Area:	6510.00 SqFt	PCI:	27
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	323.00 SqFt	5.0	47.1	
43	BLOCK CR	M	6200.00 SqFt	95.2	52.0	
57	WEATHERING	M	6510.00 SqFt	100.0	20.3	

Network:	Illinois			Name:	Illinois Valley							
Branch:	A01IV		Name:	Apron 01 Illinois Valley			Use:	APRON		Area:	47,501 SqFt	
Section:	03	of	4	From:	A01IV-02			To:	A01IV-02		Last Const.:	9/2/1965
Surface:	PCC	Family:	2024_Region2_Cat 2/3/4_Apron_PCC		Zone:	3S4		Category:	J		Rank:	P
Area:	2,000 SqFt		Length:	50 Ft		Width:	40 Ft					
Slabs:	16	Slab Length:	10 Ft		Slab Width:	13 Ft		Joint Length:	270 Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1965		Work Type: Subbase - Unknown (Major MR)					Code:	SB-UN		Is Major M&R: True	
Work Date:	9/2/1965		Work Type: New Construction - PCC					Code:	NC-PC		Is Major M&R: True	
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 0											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	16.00 Slabs		PCI:	0				
Sample Comments:												
Distress	Description		Severity	Quantity	Density	Deduct	Comments					
72	SHAT. SLAB		H	16.00 Slabs	100.0	99.9						

Network:	Illinois			Name:	Illinois Valley							
Branch:	A01IV		Name:	Apron 01 Illinois Valley			Use:	APRON		Area:	47,501 SqFt	
Section:	04	of	4	From:	A01IV-01			To:	A01IV-02		Last Const.:	9/2/1965
Surface:	PCC	Family:	2024_Region2_Cat 2/3/4_Apron_PCC		Zone:	3S4		Category:	J		Rank:	P
Area:	1,000 SqFt		Length:	50 Ft		Width:	20 Ft					
Slabs:	2	Slab Length:	25 Ft		Slab Width:	20 Ft		Joint Length:	20 Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1965		Work Type: Subbase - Unknown (Major MR)					Code:	SB-UN		Is Major M&R:	True
Work Date:	9/2/1965		Work Type: New Construction - PCC					Code:	NC-PC		Is Major M&R:	True
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 10											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	2.00 Slabs		PCI:	10				
Sample Comments:												
Distress	Description		Severity	Quantity	Density	Deduct	Comments					
71	FAULTING		H	2.00 Slabs	100.0	90.0						

Network:	Illinois			Name:	Illinois Valley							
Branch:	A02IV		Name:	Apron 02 Illinois Valley		Use:	APRON		Area:	42,524 SqFt		
Section:	01	of	1	From:	Runway 18/36			To:	End		Last Const.:	8/2/2017
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	3S4		Category:	J		Rank:	P
Area:	42,524 SqFt		Length:	452 Ft		Width:	95 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1965		Work Type: Base Course - Unknown (Major MR)				Code:	BA-UN		Is Major M&R: True		
Work Date:	9/2/1965		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/1977		Work Type: Overlay - AC Thin				Code:	OL-AT		Is Major M&R: True		
Work Date:	7/31/2017		Work Type: Geotextile				Code:	FB-TX		Is Major M&R: False		
Work Date:	8/1/2017		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False		
Work Date:	8/2/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Work Date:	9/1/2017		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Last Insp. Date:	8/1/2024		TotalSamples:	8		Surveyed: 4						
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
57	WEATHERING	L	5000.00 SqFt	100.0	6.0							
Sample Number:	03	Type:	R	Area:	3764.00 SqFt		PCI:	94				
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
57	WEATHERING	L	3764.00 SqFt	100.0	6.0							
Sample Number:	06	Type:	R	Area:	5099.00 SqFt		PCI:	88				
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
50	PATCHING	L	160.00 SqFt	3.1	7.4							
57	WEATHERING	L	5099.00 SqFt	100.0	6.0							
Sample Number:	08	Type:	R	Area:	6054.00 SqFt		PCI:	94				
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
57	WEATHERING	L	6054.00 SqFt	100.0	6.0							

Network:	Illinois			Name:	Illinois Valley						
Branch:	A03IV		Name:	Apron 03 Illinois Valley		Use:	APRON		Area:	25,001 SqFt	
Section:	01 of 2		From:	Hangars			To:	A03IV-02		Last Const.:	9/2/1993
Surface:	AC		Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	3S4		Category:	J Rank: S	
Area:	11,911 SqFt		Length:	210 Ft		Width:	82 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	9/1/1993		Work Type: Base Course - Unknown (Major MR)				Code:	BA-UN		Is Major M&R: True	
Work Date:	9/2/1993		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	9/1/2003		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/2/2003		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Work Date:	6/1/2011		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/1/2017		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Last Insp. Date:	8/1/2024		TotalSamples:	2		Surveyed:	2				
Conditions:	PCI: 48										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	5916.00 SqFt		PCI:	59	
Sample Comments:											
Distress	Description		Severity	Quantity		Density	Deduct	Comments			
41	ALLIGATOR CR		M	12.00	SqFt	0.2	15.6				
48	L & T CR		L	121.00	Ft	2.0	7.5				
48	L & T CR		M	302.00	Ft	5.1	26.0				
57	WEATHERING		L	5916.00	SqFt	100.0	6.0				
Sample Number:	02		Type:	R		Area:	5994.00 SqFt		PCI:	38	
Sample Comments:											
Distress	Description		Severity	Quantity		Density	Deduct	Comments			
41	ALLIGATOR CR		M	297.00	SqFt	5.0	47.1				
48	L & T CR		L	492.00	Ft	8.2	20.7				
48	L & T CR		M	67.00	Ft	1.1	11.8				
50	PATCHING		L	44.00	SqFt	0.7	3.0				
57	WEATHERING		L	5994.00	SqFt	100.0	6.0				

Network:	Illinois			Name:	Illinois Valley						
Branch:	A03IV		Name:	Apron 03 Illinois Valley		Use:	APRON	Area:	25,001 SqFt		
Section:	02	of	2	From:	A03IV-01		To:	Rwy18 End Turnabout			
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	3S4	Category:	J	Rank:	S	
Area:	13,090 SqFt		Length:	250 Ft		Width:	94 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1991		Work Type: Base Course - Unknown (Major MR)				Code:	BA-UN		Is Major M&R:	True
Work Date:	9/2/1991		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2003		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	6/1/2011		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2017		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	8/1/2024		TotalSamples:	2		Surveyed: 2					
Conditions:	PCI: 88										
Inspection Comments:											
Sample Number:	01		Type:	R	Area:	6576.00 SqFt		PCI:	90		
Sample Comments:											
Distress	Description		Severity	Quantity	Density	Deduct	Comments				
48	L & T CR		L	33.00 Ft	0.5	4.1					
57	WEATHERING		L	6576.00 SqFt	100.0	6.0					
Sample Number:	02		Type:	R	Area:	6513.00 SqFt		PCI:	86		
Sample Comments:											
Distress	Description		Severity	Quantity	Density	Deduct	Comments				
48	L & T CR		L	165.00 Ft	2.5	8.8					
57	WEATHERING		L	6513.00 SqFt	100.0	6.0					

Network:	Illinois			Name:	Illinois Valley								
Branch:	ARUN		Name:	Apron RunUp			Use:	APRON		Area:	28,895 SqFt		
Section:	01	of	2	From:	T01IV-02				To:	End		Last Const.:	6/1/2023
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:					Category:	Rank: P		
Area:	15,730 SqFt		Length:	142 Ft		Width:	100 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:	Construction date estimated based on available historical imagery												
Work Date:	6/1/2023		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True	
Last Insp. Date:	8/1/2024		TotalSamples:	3		Surveyed:	2						
Conditions:	PCI:	94											
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	5244.00 SqFt			PCI:	94				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5244.00 SqFt		100.0	6.0						
Sample Number:	03	Type:	R	Area:	5244.00 SqFt			PCI:	94				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5244.00 SqFt		100.0	6.0						

Network:	Illinois			Name:	Illinois Valley							
Branch:	ARUN		Name:	Apron RunUp		Use:	APRON		Area:	28,895 SqFt		
Section:	02	of	2	From:	R18IV-01			To:	West End		Last Const.:	6/1/2023
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:				Category:	Rank: P		
Area:	13,165 SqFt		Length:	115 Ft		Width:	117 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												

Work Date:	6/1/2023	Work Type:	New Construction - Initial	Code:	NC-IN	Is Major M&R:	True
Last Insp. Date:	8/1/2024	TotalSamples:	3	Surveyed:	2		
Conditions:	PCI:	94					
Inspection Comments:							

Sample Number:	01	Type:	R	Area:	4388.00 SqFt	PCI:	94
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	4388.00 SqFt	100.0	6.0	

Sample Number:	03	Type:	R	Area:	4388.00 SqFt	PCI:	94
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	4388.00 SqFt	100.0	6.0	

Network:	Illinois			Name:	Illinois Valley								
Branch:	R18IV		Name:	Runway 18/36 Illinois Valley		Use:	RUNWAY		Area:	405,546 SqFt			
Section:	01	of	3	From:	Runway 36 End			To:	R18IV-02		Last Const.:	9/1/1977	
Surface:	AAC		Family:	2024_Region2_Cat 3/4_Runway_AC		Zone:	3S4		Category:	J		Rank:	P
Area:	102,648 SqFt		Length:	1,265 Ft		Width:	75 Ft						
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:				Grade:		0		Lanes:		0		
Section Comments:	The area section was reduced after improvements performed in 2023 (See project number JCOTO-05 "Runway 18-36 Rehabilitation and Aligned Taxiway Removal")												
Work Date:	9/1/1965		Work Type: Base Course - Unknown (Major MR)					Code:	BA-UN		Is Major M&R: True		
Work Date:	9/2/1965		Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/1977		Work Type: Overlay - AC Thin					Code:	OL-AT		Is Major M&R: True		
Work Date:	9/1/1980		Work Type: Surface Seal - Fog Seal					Code:	SS-FS		Is Major M&R: False		
Work Date:	9/1/2003		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R: False		
Work Date:	9/2/2003		Work Type: Surface Treatment - Slurry Seal					Code:	ST-SS		Is Major M&R: False		
Work Date:	6/1/2011		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2014		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2017		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R: False		
Last Insp. Date:	8/1/2024		TotalSamples:	19		Surveyed:		5					
Conditions:	PCI: 94												
Inspection Comments:													
Sample Number:	03		Type:	R		Area:	5625.00 SqFt		PCI:		94		
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0						
Sample Number:	06		Type:	R		Area:	5625.00 SqFt		PCI:		94		
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0						
Sample Number:	10		Type:	R		Area:	5625.00 SqFt		PCI:		94		
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0						
Sample Number:	14		Type:	R		Area:	5625.00 SqFt		PCI:		94		
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0						
Sample Number:	15		Type:	R		Area:	5625.00 SqFt		PCI:		94		
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0						

Network:	Illinois			Name:	Illinois Valley							
Branch:	R18IV		Name:	Runway 18/36 Illinois Valley		Use:	RUNWAY		Area:	405,546 SqFt		
Section:	02 of 3		From:	R18IV-01			To:	R18IV-03		Last Const.:	1/1/1980	
Surface:	ABR		Family:	2024_Region2_Cat 3/4_Runway_AC		Zone:	3S4		Category:	J Rank: P		
Area:	265,125 SqFt		Length:	3,535 Ft		Width:	75 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	9/1/1953		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	9/2/1953		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	9/3/1953		Work Type:	Surface Course - Double Bitum.				Code:	SU-DB		Is Major M&R:	True
Work Date:	9/1/1977		Work Type:	Overlay - AC Thin				Code:	OL-AT		Is Major M&R:	True
Work Date:	1/1/1980		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True
Work Date:	9/1/1980		Work Type:	Surface Seal - Fog Seal				Code:	SS-FS		Is Major M&R:	False
Work Date:	9/1/1994		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	7/1/2004		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	6/1/2011		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2014		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2017		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	8/1/2024		TotalSamples:	47		Surveyed:	7					
Conditions:	PCI: 93											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	5625.00 SqFt		PCI:	92		
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
48	L & T CR		L	4.00 Ft		0.1	2.5					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0					
Sample Number:	10		Type:	R		Area:	5625.00 SqFt		PCI:	90		
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
48	L & T CR		L	27.00 Ft		0.5	4.0					
57	WEATHERING		L	5625.00 SqFt		100.0	6.0					
Sample Number:	19		Type:	R		Area:	5625.00 SqFt		PCI:	94		
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
57	WEATHERING		L	5625.00 SqFt		100.0	6.0					
Sample Number:	27		Type:	A		Area:	5625.00 SqFt		PCI:	94		
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
57	WEATHERING		L	5625.00 SqFt		100.0	6.0					
Sample Number:	28		Type:	R		Area:	5625.00 SqFt		PCI:	94		
Sample Comments:												

Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	5625.00 SqFt	100.0	6.0	
<div>Sample Number: 37</div> <div>Type: R</div> <div>Area:</div> <div>5625.00 SqFt</div> <div>PCI: 94</div> <div>Sample Comments:</div>						
Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	5625.00 SqFt	100.0	6.0	
<div>Sample Number: 46</div> <div>Type: R</div> <div>Area:</div> <div>5625.00 SqFt</div> <div>PCI: 94</div> <div>Sample Comments:</div>						
Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	5625.00 SqFt	100.0	6.0	

Network:	Illinois	Name:	Illinois Valley						
Branch:	T01IV-01	Name:	Taxiway 01	Use:	TAXIWAY	Area:	20,863 SqFt		
Section:	01	of	3	From:	R18V-02	To:	T01IV-02	Last Const.:	6/1/2023
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC	Zone:		Category:		Rank:	P
Area:	2,745 SqFt	Length:	86 Ft	Width:	32 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/2023	Work Type:	New Construction - Initial	Code:	NC-IN	Is Major M&R:	True		
Last Insp. Date:	8/1/2024	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 94								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	2745.00 SqFt	PCI:	94		
Sample Comments:									
Distress	Description	Severity	Quantity	Density	Deduct	Comments			
57	WEATHERING	L	2745.00 SqFt	100.0	6.0				

Network:	Illinois	Name:	Illinois Valley						
Branch:	T01IV-01	Name:	Taxiway 01	Use:	TAXIWAY	Area:	20,863 SqFt		
Section:	02	of	3	From:	T01IV-01	To:	T01IV-03	Last Const.:	6/1/2023
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC	Zone:		Category:		Rank:	P
Area:	8,196 SqFt	Length:	411 Ft	Width:	27 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/2023	Work Type:	New Construction - Initial	Code:	NC-IN	Is Major M&R:	True		

Last Insp. Date:	8/1/2024	TotalSamples:	2	Surveyed:	2
Conditions:	PCI:	94			
Inspection Comments:					

Sample Number:	01	Type:	R	Area:	4097.00 SqFt	PCI:	94
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	4097.00 SqFt	100.0	6.0	

Sample Number:	02	Type:	R	Area:	4099.00 SqFt	PCI:	94
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
57	WEATHERING	L	4099.00 SqFt	100.0	6.0	

Network:	Illinois			Name:	Illinois Valley							
Branch:	T01IV-01		Name:	Taxiway 01		Use:	TAXIWAY		Area:	20,863 SqFt		
Section:	03	of	3	From:	T01IV-02			To:	End		Last Const.:	6/1/2023
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:				Category:	Rank: P		
Area:	9,922 SqFt		Length:	183 Ft		Width:	58 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	6/1/2023		Work Type:	New Construction - Initial				Code:	NC-IN		Is Major M&R:	True
Last Insp. Date:	8/1/2024		TotalSamples:	2		Surveyed:	2					
Conditions:	PCI:	92										
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	4916.00 SqFt			PCI:	91			
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
48	L & T CR		L	12.00 Ft		0.2	3.4					
57	WEATHERING		L	4916.00 SqFt		100.0	6.0					
Sample Number:	02	Type:	R	Area:	5006.00 SqFt			PCI:	94			
Sample Comments:												
Distress	Description		Severity	Quantity		Density	Deduct	Comments				
57	WEATHERING		L	5006.00 SqFt		100.0	6.0					

Network:	Illinois			Name:	Illinois Valley								
Branch:	T02IV			Name:	Taxiway 02 Illinois Valley			Use:	TAXIWAY		Area:	2,868 SqFt	
Section:	01	of 1		From:	Runway				To:	Apron 02		Last Const.:	8/2/2017
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	3S4			Category:	J		Rank:	P
Area:	2,868 SqFt			Length:	89 Ft		Width:	25 Ft					
Slabs:	Slab Length:			Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:					Grade:		0		Lanes:		0	
Section Comments:													
Work Date:	7/31/2017			Work Type: Geotextile					Code:	FB-TX		Is Major M&R: False	
Work Date:	8/1/2017			Work Type: Base Course - Aggregate					Code:	BA-AG		Is Major M&R: False	
Work Date:	8/2/2017			Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	8/1/2024			TotalSamples:	1			Surveyed:	1				
Conditions:	PCI:	75											
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	2868.00 SqFt			PCI:	75				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
48	L & T CR		L	29.00	Ft	1.0	5.0						
57	WEATHERING		L	1434.00	SqFt	50.0	4.8						
57	WEATHERING		M	1434.00	SqFt	50.0	15.3						

Network:	Illinois			Name:	Illinois Valley									
Branch:	T03IV			Name:	Taxiway 03 Illinois Valley			Use:	TAXIWAY		Area:	3,236 SqFt		
Section:	01	of 1		From:	Runway				To:	Apron 02		Last Const.:	8/2/2017	
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	3S4			Category:	J		Rank:	P	
Area:	3,236 SqFt			Length:	100 Ft			Width:	25 Ft					
Slabs:	Slab Length:			Ft		Slab Width:			Ft		Joint Length:			Ft
Shoulder:	Street Type:			Grade:			0		Lanes:			0		
Section Comments:														
Work Date:	7/31/2017			Work Type: Geotextile					Code:	FB-TX		Is Major M&R: False		
Work Date:	8/1/2017			Work Type: Base Course - Aggregate					Code:	BA-AG		Is Major M&R: False		
Work Date:	8/2/2017			Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R: True		
Last Insp. Date:	8/1/2024			TotalSamples:	1			Surveyed: 1						
Conditions:	PCI: 79													
Inspection Comments:														
Sample Number:	01	Type:	R	Area:			3226.00 SqFt		PCI: 79					
Sample Comments:														
Distress	Description		Severity	Quantity		Density	Deduct	Comments						
48	L & T CR		L	40.00 Ft		1.2	5.5							
57	WEATHERING		L	2362.00 SqFt		73.2	5.6							
57	WEATHERING		M	864.00 SqFt		26.8	10.6							

Network:	Illinois			Name:	Illinois Valley					
Branch:	TEIV		Name:	Taxiway E Illinois Valley		Use:	TAXIWAY	Area:	14,736 SqFt	
Section:	01	of	1	From:	Runway 18/36		To:	End	Last Const.:	7/3/2004
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	3S4	Category:	J	Rank:	P
Area:	14,736 SqFt		Length:	537 Ft		Width:	25 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	7/1/2004		Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False	
Work Date:	7/2/2004		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False	
Work Date:	7/3/2004		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True	
Last Insp. Date:	8/1/2024		TotalSamples:	3		Surveyed:		2		
Conditions:	PCI:	81								
Inspection Comments:										
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	71		
Sample Comments:										
Distress	Description	Severity	Quantity	Density	Deduct	Comments				
48	L & T CR	L	23.00 Ft	0.5	4.0					
50	PATCHING	L	75.00 SqFt	1.5	4.6					
57	WEATHERING	L	2500.00 SqFt	50.0	4.8					
57	WEATHERING	M	2500.00 SqFt	50.0	15.3					
Sample Number:	03	Type:	R	Area:	4735.00 SqFt		PCI:	92		
Sample Comments:										
Distress	Description	Severity	Quantity	Density	Deduct	Comments				
48	L & T CR	L	3.00 Ft	0.1	2.5					
57	WEATHERING	L	4735.00 SqFt	100.0	6.0					



APPENDIX F

Work History Report

12/16/2024

Table 1F: Work History Report

Page 1 of 6

Pavement Database: ODAV_2024_12-13-24_5pm_amc

Network: Illinois Valley		Branch: A01IV		Apron 01 Illinois		Section: 01		Surface: AAC	
L.C.D. 9/1/1977		Use: APRON		Rank: P		Length: 230.00 (Ft)		Width: 85.00 (Ft) True Area: 25651 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/1/1977	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>				
9/3/1953	SU-SB	Surface Course - BST	0.00	0.75	<input checked="" type="checkbox"/>				
9/2/1953	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>				
9/1/1953	SB-AG	Subbase - Aggregate	0.00	6.00	<input type="checkbox"/>				

Network: Illinois Valley		Branch: A01IV		Apron 01 Illinois		Section: 02		Surface: AC	
L.C.D. 9/2/1965		Use: APRON		Rank: P		Length: 205.00 (Ft)		Width: 120.00 (Ft) True Area: 18850 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/2/1965	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	unk. thickness			
9/1/1965	BA-UN	Base Course - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>				

Network: Illinois Valley		Branch: A01IV		Apron 01 Illinois		Section: 03		Surface: PCC	
L.C.D. 9/2/1965		Use: APRON		Rank: P		Length: 50.00 (Ft)		Width: 40.00 (Ft) True Area: 2000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/2/1965	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN			
9/1/1965	SB-UN	Subbase - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>				

Network: Illinois Valley		Branch: A01IV		Apron 01 Illinois		Section: 04		Surface: PCC	
L.C.D. 9/2/1965		Use: APRON		Rank: P		Length: 50.00 (Ft)		Width: 20.00 (Ft) True Area: 1000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/2/1965	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	unk. thickness			
9/1/1965	SB-UN	Subbase - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>				

Network: Illinois Valley		Branch: A02IV		Apron 02 Illinois		Section: 01		Surface: AC	
L.C.D. 8/2/2017		Use: APRON		Rank: P		Length: 452.00 (Ft)		Width: 95.00 (Ft) True Area: 42524 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	, P403 P208 circa 1965 circa 1965			
8/2/2017	CR-AC	Complete Reconstruction - AC	212,620.00	3.00	<input checked="" type="checkbox"/>				
8/1/2017	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>				
7/31/2017	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>				
9/1/1977	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>				
9/2/1965	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>				
9/1/1965	BA-UN	Base Course - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>				

12/16/2024

Work History Report

Page 2 of 6

Pavement Database: ODAV_2024_12-13-24_5pm_ama

Network: Illinois Valley		Branch: A03IV	Apron 03 Illinois		Section: 01	Surface: AC
L.C.D. 9/2/1993	Use: APRON	Rank: S	Length: 210.00 (Ft)	Width: 82.00 (Ft)	True Area:	11911 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011 UNKNOWN X-SECTION
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2003	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/2003	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1993	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1993	BA-UN	Base Course - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Illinois Valley		Branch: A03IV	Apron 03 Illinois		Section: 02	Surface: AC
L.C.D. 9/2/1991	Use: APRON	Rank: S	Length: 250.00 (Ft)	Width: 94.00 (Ft)	True Area:	13090 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011 UNKNOWN X-SECTION
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/1/2003	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1991	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1991	BA-UN	Base Course - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Illinois Valley		Branch: ARUN	Apron RunUp		Section: 01	Surface: AC
L.C.D. 6/1/2022	Use: APRON	Rank: P	Length: 142.00 (Ft)	Width: 100.00 (Ft)	True Area:	15730 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2022	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	Construction date estimated from histo
6/1/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>	

Network: Illinois Valley		Branch: ARUN	Apron RunUp		Section: 02	Surface: AC
L.C.D. 6/1/2022	Use: APRON	Rank: P	Length: 115.00 (Ft)	Width: 117.00 (Ft)	True Area:	13165 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/2/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	Construction date estimated from histo
6/1/2022	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>	

12/16/2024

Work History Report

Page 3 of 6

Pavement Database: ODAV_2024_12-13-24_5pm_ama

Network: Illinois Valley

Branch: R18IV

Runway 18/36 Illin

Section: 01

Surface: AAC

L.C.D. 6/1/2022

Use: RUNWAY

Rank: P

Length: 1,265.00 (Ft)

Width: 75.00 (Ft)

True Area: 102648 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2022	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	Full-depth repairs were performed as n , PMP 2011 circa 1965 circa 1965
6/1/2022	OL-AS	Overlay - AC Structural	0.00	4.00	<input checked="" type="checkbox"/>	
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2003	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/2003	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1980	SS-FS	Surface Seal - Fog Seal	0.00	0.10	<input type="checkbox"/>	
9/1/1977	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>	
9/2/1965	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	
9/1/1965	BA-UN	Base Course - Unknown (Major MR)	0.00	0.00	<input checked="" type="checkbox"/>	

Network: Illinois Valley

Branch: R18IV

Runway 18/36 Illin

Section: 02

Surface: ABR

L.C.D. 6/1/2022

Use: RUNWAY

Rank: P

Length: 3,535.00 (Ft)

Width: 75.00 (Ft)

True Area: 265125 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2022	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	Full-depth repairs were performed as n , PMP 2011
6/1/2022	OL-AS	Overlay - AC Structural	0.00	4.00	<input checked="" type="checkbox"/>	
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
7/1/2004	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	
9/1/1994	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1980	SS-FS	Surface Seal - Fog Seal	0.00	0.10	<input type="checkbox"/>	
1/1/1980	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1977	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>	
9/3/1953	SU-DB	Surface Course - Double Bitum.	0.00	0.00	<input checked="" type="checkbox"/>	
9/2/1953	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
9/1/1953	SB-AG	Subbase - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Illinois Valley

Branch: R18IV

Runway 18/36 Illin

Section: x03

Surface: AC

L.C.D. 9/1/1977

Use: RUNWAY

Rank: P

Length: 400.00 (Ft)

Width: 75.00 (Ft)

True Area: 37773 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
7/1/2004	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	
9/1/1994	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1980	SS-FS	Surface Seal - Fog Seal	0.00	0.10	<input type="checkbox"/>	
9/1/1977	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>	
9/3/1953	SU-SB	Surface Course - BST	0.00	0.75	<input checked="" type="checkbox"/>	
9/2/1953	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>	
9/1/1953	SB-AG	Subbase - Aggregate	0.00	6.00	<input type="checkbox"/>	

12/16/2024

Work History Report

Page 4 of 6

Pavement Database: ODAV_2024_12-13-24_5pm_ama

Network: Illinois Valley		Branch: T01IV		Taxiway 01		Section: 01		Surface: AC			
L.C.D. 6/1/2022		Use: TAXIWAY		Rank: P		Length: 86.00 (Ft)		Width: 32.00 (Ft)		True Area: 2745 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
6/1/2022	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	Construction date estimated from histo					
6/1/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>						
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>						

Network: Illinois Valley		Branch: T01IV		Taxiway 01		Section: 02		Surface: AC			
L.C.D. 6/1/2022		Use: TAXIWAY		Rank: P		Length: 411.00 (Ft)		Width: 27.00 (Ft)		True Area: 8196 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
6/1/2022	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	Construction date estimated from histo					
6/1/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>						
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>						

Network: Illinois Valley		Branch: T01IV		Taxiway 01		Section: 03		Surface: AC			
L.C.D. 6/1/2022		Use: TAXIWAY		Rank: P		Length: 183.00 (Ft)		Width: 58.00 (Ft)		True Area: 9922 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
6/1/2022	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	Construction date estimated from histo					
6/1/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>						
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>						

Network: Illinois Valley		Branch: T02IV		Taxiway 02 Illinois		Section: 01		Surface: AC			
L.C.D. 8/2/2017		Use: TAXIWAY		Rank: P		Length: 89.00 (Ft)		Width: 25.00 (Ft)		True Area: 2868 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
6/1/2022	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P403 P208					
6/1/2022	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>						
8/2/2017	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>						
8/1/2017	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>						
7/31/2017	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>						

Network: Illinois Valley		Branch: T03IV		Taxiway 03 Illinois		Section: 01		Surface: AC			
L.C.D. 8/2/2017		Use: TAXIWAY		Rank: P		Length: 100.00 (Ft)		Width: 25.00 (Ft)		True Area: 3236 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
8/2/2017	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	P403					
8/1/2017	BA-AG	Base Course - Aggregate	0.00	9.00	<input type="checkbox"/>	P208					
7/31/2017	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>						

Network: Illinois Valley		Branch: TEIV		Taxiway E Illinois		Section: 01		Surface: AC			
L.C.D. 7/3/2004		Use: TAXIWAY		Rank: P		Length: 537.00 (Ft)		Width: 25.00 (Ft)		True Area: 14736 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments					
7/3/2004	NC-AC	New Construction - AC	0.00	2.50	<input checked="" type="checkbox"/>						
7/2/2004	BA-AG	Base Course - Aggregate	0.00	4.00	<input type="checkbox"/>						
7/1/2004	SB-AG	Subbase - Aggregate	0.00	5.00	<input type="checkbox"/>						

12/16/2024

Work History Report

Page 5 of 6

*Pavement Database: ODAV_2024_12-13-24_5pm_amc***Network:** Illinois Valley**Branch:** x_T01IV

Taxiway 01 Illinois

Section: 01**Surface:** AC**L.C.D.** 1/1/1991**Use:** TAXIWAY**Rank:** S**Length:** 276.00 (Ft)**Width:** 15.00 (Ft)**True Area:** 5192 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1991	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Unknown (Major MR)	5	189,023.00	0.00	0.00
Base Course - Aggregate	13	444,539.00	6.08	1.82
Complete Reconstruction - AC	1	42,524.00	3.00	0.00
Crack Sealing - AC	25	2,142,869.02	0.02	0.04
Geotextile	3	48,628.00	0.00	0.00
New Construction - AC	13	259,621.00	2.65	1.54
New Construction - Initial	2	270,317.00	0.00	0.00
New Construction - PCC	2	3,000.00	0.00	0.00
Overlay - AC Structural	2	367,773.00	4.00	0.00
Overlay - AC Thin	5	473,721.00	2.00	0.00
Subbase - Aggregate	10	395,911.00	4.70	0.90
Subbase - Unknown (Major MR)	2	3,000.00	0.00	0.00
Surface Course - BST	2	63,424.00	0.75	0.00
Surface Course - Double Bitum.	1	265,125.00	0.00	0.00
Surface Seal - Fog Seal	3	405,546.00	0.10	0.00
Surface Treatment - Slurry Seal	4	417,457.00	0.30	0.20