

2024 ODAV Pavement Evaluation Program Myrtle Creek Municipal Airport

Myrtle Creek, Oregon

February 12, 2025

Prepared for
State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY.....	1
3	PAVEMENT CONDITION INSPECTION RESULTS	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results.....	6
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	8
	4.1 Introduction.....	8
	4.2 Future Condition Analysis.....	9
	4.3 Functional Remaining Life	9
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	11
	5.1 Introduction.....	11
	5.2 Recommended Localized Maintenance.....	11
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan	11
6	LIMITATIONS.....	13

TABLES

Table 3-1: ASTM PCI RATING SCALE	5
Table 5-1: LOCALIZED MAINTENANCE QUANTITIES	11
Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES	11

FIGURES

Figure 2.1: Myrtle Creek Municipal Airport Location Map	2
Figure 2.2: Myrtle Creek Municipal Airport Percent of Pavement Area by Surface Type	3
Figure 2.3: Myrtle Creek Municipal Airport Pavement Area by Branch Use	3
Figure 2.4: Myrtle Creek Municipal Airport Pavement Inventory.....	4
Figure 3.1: Myrtle Creek Municipal Airport 2024 Survey Results.....	7
Figure 3.2: Myrtle Creek Municipal Airport Pavement Condition Rating by Percent of Area	8
Figure 4.1: Myrtle Creek Municipal Airport Future Pavement Condition.....	10
Figure 5.1: Myrtle Creek Municipal Airport 5-Year Pavement Management Plan.....	12

APPENDICES

Appendix A: Pavement Inventory Reports and Maps
Appendix B: Pavement Condition Index Survey Results
Appendix C: Future Pavement Condition Analysis
Appendix D: Unit Cost Data and Maintenance and Rehabilitation Plan



APPENDICES (CONTINUED)

Appendix E: Reinspection Report

Appendix F: Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a five-year plan comprising maintenance, surface treatment, rehabilitation, and reconstruction projects for the Myrtle Creek Municipal Airport in Myrtle Creek, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Myrtle Creek Municipal Airport in 2024 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the Pavement Condition Index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from 0 to 100, where 0 represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Myrtle Creek Municipal Airport is located in Myrtle Creek, Oregon, and is owned and operated by the City of Myrtle Creek. The airport consists of one runway, one parallel taxiway, and multiple connector taxiways, taxilanes, and aprons that serve a variety of general aviation aircraft. The general location of the airport is shown below on the Myrtle Creek Municipal Airport Location Map, Figure 2.1.



Figure 2.1: MYRTLE CREEK MUNICIPAL AIRPORT LOCATION MAP

The airside pavements at the Myrtle Creek Municipal Airport are composed of asphalt concrete (AC) and AC overlaid with AC. The airport pavements, delineated by surface type and branch use, are shown on the Myrtle Creek Municipal Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on the Myrtle Creek Municipal Airport Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on the Myrtle Creek Municipal Airport Pavement Inventory, Figure 2.4. We used the sampling rates outlined in Table 1A of Appendix A in our survey. The sample unit layout for each section is shown on Figure 1A in Appendix A. The pavement facilities summarized by branch and section are listed in Tables 2A and 3A, respectively, in Appendix A. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report presented in Appendix F.




Figure 2.2: MYRTLE CREEK MUNICIPAL AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3: MYRTLE CREEK MUNICIPAL AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE



OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

MYRTLE CREEK MUNICIPAL AIRPORT PAVEMENT INVENTORY








3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Myrtle Creek Municipal Airport in August 2024. The 2024 survey work was performed on sections last inspected in 2019 in order to update the Myrtle Creek Municipal Airport inspection data. GRI performed the 2024 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1, below.


Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

Abbreviations: ASTM = ASTM International; PCI = Pavement Condition Index; M&R = maintenance and rehabilitation

3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Myrtle Creek Municipal Airport is approximately 74. The section PCIs ranged from a low of 39 to a high of 90. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, block cracking, depression, and raveling on AC-surfaced pavements. Section PCIs following our pavement survey are displayed below spatially on the Myrtle Creek Municipal Airport 2024 PCI Survey Results, Figure 3.1.



- SECTION PCI**
- (86 - 100) GOOD
 - (71 - 85) SATISFACTORY
 - (56 - 70) FAIR
 - (41 - 55) POOR
 - (26 - 40) VERY POOR
 - (11 - 25) SERIOUS
 - (0 - 10) FAILED



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

**MYRTLE CREEK MUNICIPAL AIRPORT
2024 SURVEY RESULTS**

The condition distribution of the network by percent of total pavement area is provided on the Myrtle Creek Municipal Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2024 inspection is provided in Table 4B in Appendix B. The reinspection report that includes inspection details for individual sample units is presented in Appendix E.




Figure 3.2: MYRTLE CREEK MUNICIPAL AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Myrtle Creek Municipal Airport are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for five- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 74 to a value of 68 in 2029 and 63 in 2034 if no maintenance or rehabilitation work is performed. The projected pavement condition in five years and 10 years for each pavement section at Myrtle Creek Municipal Airport is displayed spatially on the Myrtle Creek Municipal Airport Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and, typically, a field exploration and testing program that includes core explorations and Falling Weight Deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Myrtle Creek Municipal Airport. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Myrtle Creek Municipal Airport are summarized in Table 2C in Appendix C.

PREDICTED CONDITION IN 2029



PREDICTED CONDITION IN 2034



- SECTION PCI
- (86 - 100) GOOD
 - (71 - 85) SATISFACTORY
 - (56 - 70) FAIR
 - (41 - 55) POOR
 - (26 - 40) VERY POOR
 - (11 - 25) SERIOUS
 - (0 - 10) FAILED

0 300 600

1 INCH = 300 FEET

GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

MYRTLE CREEK MUNICIPAL AIRPORT
FUTURE PAVEMENT CONDITION

5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. Details of our M&R work priorities and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1, below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Quantity
Asphalt Concrete Crack Sealing	26,246 linear feet
Asphalt Concrete Full-Depth Patching	2,181 square feet

5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan

To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2, below, and maps of the project locations by year are shown on the Myrtle Creek Municipal Airport 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

Treatment Type	Quantity, square feet
Reconstruction	29,900
Overlay	12,351
Fog Seal	34,778
Slurry Seal	274,138




ACTION TIMING

2025	2026	2027	2028	2029
------	------	------	------	------

ACTION

FOG SEAL	SLURRY SEAL	OVERLAY	RECONSTRUCTION	ROUTINE MAINTENANCE
----------	-------------	---------	----------------	---------------------



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

MYRTLE CREEK MUNICIPAL AIRPORT 5-YEAR PAVEMENT MANAGEMENT PLAN

6 LIMITATIONS

This report has been prepared to assist ODAV with pavement-related project planning for the Myrtle Creek Municipal Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Myrtle Creek Municipal Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025

Lindsy A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Staff Engineer

This document has been submitted electronically.



APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Myrtle Creek Municipal Airport is located in Myrtle Creek, Oregon, and is owned and operated by the City of Myrtle Creek. The pavement network/facilities at Myrtle Creek Municipal Airport serve a variety of general aviation aircraft. Myrtle Creek Municipal Airport consists of one runway, one parallel taxiway, and multiple connector taxiways, taxilanes, and aprons. The types of airside pavements include asphalt concrete (AC) and AC overlaid with AC.

The current airport pavement management system (APMS) network at Myrtle Creek Municipal Airport has an approximate area of 351,167 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 2A and 3A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Myrtle Creek Municipal Airport contains 10 branches, which are tabulated in Table 2A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as “a contiguous pavement area having uniform construction, maintenance, usage history, and condition.” All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Myrtle Creek Municipal Airport contains 17 sections that are managed by the City of Myrtle Creek, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement’s prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are

ranked *Secondary*, and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 3A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements to be 5,000 ±2,000 square feet. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2024 Myrtle Creek Municipal Airport PCI survey, Table 1A was used as a guideline in developing sampling rates for flexible pavement to reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Myrtle Creek Municipal Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A: EXAMPLE SAMPLE RATES FOR AC PAVEMENTS

AC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n
1	1
2 – 3	2
4 – 6	3
7 – 13	4
14 – 38	5
39+	6

Abbreviation: AC = asphalt concrete

Table 2A: MYRTLE CREEK MUNICIPAL AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
T02MC	Taxiway 02 Myrtle Creek	2	8,709
R03MC	Runway 03/21 Myrtle Creek	1	156,000
A01MC	Apron 01 Myrtle Creek	2	59,020
T01MC	Taxiway 01 Myrtle Creek	6	77,613
T03MC	Taxiway 03 Myrtle Creek	1	18,928
T07MC	Taxiway 07 Myrtle Creek	1	5,907
T04MC	Taxiway 04 Myrtle Creek	1	6,444
T06MC	Taxiway 06 Myrtle Creek	1	6,444
T05MC	Taxiway 05 Myrtle Creek	1	6,444
AHOLDMC	Hold Apron Myrtle Creek	1	5,658

Table 3A: MYRTLE CREEK MUNICIPAL AIRPORT CURRENT PAVEMENT INVENTORY


Branch ID	Branch Name	Branch Use	Section ID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type
A01MC	Apron 01 Myrtle Creek	APRON	01	Taxiway 04	A01MC-02	P	224	130	29,120	9/2/2000	AC
A01MC	Apron 01 Myrtle Creek	APRON	02	A01MC-01	Taxiway 02	P	230	130	29,900	9/2/1970	AC
AHOLDMC	Hold Apron Myrtle Creek	APRON	01	T03	End	S	72	72	5,658	9/2/2000	AC
R03MC	Runway 03/21 Myrtle Creek	RUNWAY	01	Runway 21 End	Runway 03 End	P	2,600	60	156,000	9/4/2007	AC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	01	R03MC-01	T01MC-02	P	20	30	1,112	9/4/2007	AC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	02	T01MC-01	T01MC-03	P	156	30	4,830	8/2/2002	AAC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	03	T01MC-02	T02MC-01	P	1,285	25	34,209	8/3/2002	AC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	04	T02MC-01	T01MC-05	P	1,098	25	31,989	8/3/2004	AC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	05	T01MC-04	T01MC-06	P	133	30	3,974	8/1/2004	AC
T01MC	Taxiway 01 Myrtle Creek	TAXIWAY	06	T01MC-05	R03MC-01	P	30	30	1,499	9/4/2007	AC
T02MC	Taxiway 02 Myrtle Creek	TAXIWAY	01	T02MC-02	A01MC-02	P	200	30	7,231	8/3/2004	AC
T02MC	Taxiway 02 Myrtle Creek	TAXIWAY	02	T02MC-01	R03MC-01	P	20	30	1,478	9/4/2007	AC
T03MC	Taxiway 03 Myrtle Creek	TAXIWAY	01	Apron 01	Taxiway 07	P	750	25	18,928	9/2/2000	AC
T04MC	Taxiway 04 Myrtle Creek	TAXIWAY	01	Taxiway 03	End	P	268	20	6,444	9/2/2000	AC
T05MC	Taxiway 05 Myrtle Creek	TAXIWAY	01	Taxiway 03	End	P	268	20	6,444	9/2/2000	AC
T06MC	Taxiway 06 Myrtle Creek	TAXIWAY	01	Taxiway 03	End	P	268	20	6,444	9/2/2000	AC
T07MC	Taxiway 07 Myrtle Creek	TAXIWAY	01	Taxiway 03	End	P	268	20	5,907	9/2/2000	AC

Abbreviations:

P = Primary pavement, S = Secondary pavement


LCD = Last Construction Date. The date of the last major rehabilitation (e.g., overlay).

AC = asphalt concrete, AAC = AC overlaid with AC



LEGEND

- SECTIONS
- SAMPLE UNIT



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

MYRTLE CREEK MUNICIPAL AIRPORT SAMPLE UNIT LAYOUT



APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM International (ASTM) D5340. Flexible pavement (e.g., asphalt concrete [AC] and AC overlaid with AC) distress types are presented in Table 1B, below. The pavement condition results by branch and section are summarized in Tables 2B and 3B of this appendix, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE PAVEMENT

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load
42	Bleeding	Other
43	Block Cracking	Climate/Durability
44	Corrugation	Other
45	Depression	Other
46	Jet Blast	Other
47	Joint Reflection Cracking	Climate/Durability
48	Longitudinal & Transverse Cracking	Climate/Durability
49	Oil Spillage	Other
50	Patching	Climate/Durability
51	Polished Aggregate	Other
52	Raveling	Climate/Durability
53	Rutting	Load
54	Shoving	Other

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional” (i.e., defined as nonrepresentative instead of random) are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering.

- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, and patching.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Myrtle Creek Municipal Airport pavement network consists of 10 branches and 17 sections. A total of 35 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the reinspection report presented in Appendix E. Based on the 2024 PCI survey, the area-weighted average PCI for the entire pavement network at Myrtle Creek Municipal Airport is approximately 74, which corresponds to a PCI rating of Satisfactory.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2024 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Myrtle Creek Municipal Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B: MYRTLE CREEK MUNICIPAL AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01MC	2	59,020	APRON	50	Poor
AHOLDMC	1	5,658	APRON	58	Fair
R03MC	1	156,000	RUNWAY	87	Good
T01MC	6	77,613	TAXIWAY	75	Satisfactory
T02MC	2	8,709	TAXIWAY	68	Fair
T03MC	1	18,928	TAXIWAY	58	Fair
T04MC	1	6,444	TAXIWAY	64	Fair
T05MC	1	6,444	TAXIWAY	54	Poor
T06MC	1	6,444	TAXIWAY	75	Satisfactory
T07MC	1	5,907	TAXIWAY	43	Poor

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	3	64,678	51
RUNWAY	1	156,000	87
TAXIWAY	13	130,489	69
ALL	17	351,167	74

Abbreviation: PCI = Pavement Condition Index

Table 3B: MYRTLE CREEK MUNICIPAL AIRPORT 2024 PAVEMENT CONDITION INDEX SURVEY RESULTS

Branch ID	Section ID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01MC	01	9/2/2000	AC	APRON	8/1/2024	24	62	Fair	100	0	0
A01MC	02	9/2/1970	AC	APRON	8/1/2024	54	39	Very Poor	57	43	0
AHOLDMC	01	9/2/2000	AC	APRON	8/1/2024	24	58	Fair	75	25	0
R03MC	01	9/4/2007	AC	RUNWAY	8/1/2024	17	87	Good	100	0	0
T01MC	01	9/4/2007	AC	TAXIWAY	8/1/2024	17	90	Good	100	0	0
T01MC	02	8/2/2002	AAC	TAXIWAY	8/1/2024	22	75	Satisfactory	100	0	0
T01MC	03	8/3/2002	AC	TAXIWAY	8/1/2024	22	75	Satisfactory	100	0	0
T01MC	04	8/3/2004	AC	TAXIWAY	8/1/2024	20	74	Satisfactory	100	0	0
T01MC	05	8/1/2004	AC	TAXIWAY	8/1/2024	20	68	Fair	100	0	0
T01MC	06	9/4/2007	AC	TAXIWAY	8/1/2024	17	87	Good	100	0	0
T02MC	01	8/3/2004	AC	TAXIWAY	8/1/2024	20	64	Fair	100	0	0
T02MC	02	9/4/2007	AC	TAXIWAY	8/1/2024	17	87	Good	100	0	0
T03MC	01	9/2/2000	AC	TAXIWAY	8/1/2024	24	58	Fair	88	12	0
T04MC	01	9/2/2000	AC	TAXIWAY	8/1/2024	24	64	Fair	93	0	7
T05MC	01	9/2/2000	AC	TAXIWAY	8/1/2024	24	54	Poor	100	0	0
T06MC	01	9/2/2000	AC	TAXIWAY	8/1/2024	24	75	Satisfactory	100	0	0
T07MC	01	9/2/2000	AC	TAXIWAY	8/1/2024	24	43	Poor	100	0	0

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC

Table 4B: MYRTLE CREEK MUNICIPAL AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2024 RESULTS

			Approximate Area, square feet	LCD ²	2019 Survey			2024 Survey			Rate of Deterioration	
Branch ID	Section ID	Surface Type ¹			PCI ³	PCI Category	Inspection Date	PCI	PCI Category	Age ⁴		Δ PCI/yr ⁵
A01MC	01	AC	29,120	9/2/2000	68	Fair	5/13/2019	62	Fair	19	-1.15	NORMAL
A01MC	02	AC	29,900	9/2/1970	49	Poor	5/13/2019	39	Very Poor	49	-2	NORMAL
AHOLDMC	01	AC	5,658	9/2/2000	67	Fair	5/13/2019	58	Fair	19	-1.72	NORMAL
R03MC	01	AC	156,000	9/4/2007	96	Good	5/13/2019	87	Good	12	-2	NORMAL
T01MC	01	AC	1,112	9/4/2007	100	Good	5/13/2019	90	Good	12	-1.91	NORMAL
T01MC	02	AAC	4,830	8/2/2002	74	Satisfactory	5/13/2019	75	Satisfactory	17	0	NONE
T01MC	03	AC	34,209	8/3/2002	93	Good	5/13/2019	75	Satisfactory	17	-3.45	NORMAL
T01MC	04	AC	31,989	8/3/2004	68	Fair	5/13/2019	74	Satisfactory	15	1	NONE
T01MC	05	AC	3,974	8/1/2004	62	Fair	5/13/2019	68	Fair	15	1.15	NONE
T01MC	06	AC	1,499	9/4/2007	100	Good	5/13/2019	87	Good	12	-2	NORMAL
T02MC	01	AC	7,231	8/3/2004	66	Fair	5/13/2019	64	Fair	15	-0.38	NORMAL
T02MC	02	AC	1,478	9/4/2007	91	Good	5/13/2019	87	Good	12	-1	NORMAL
T03MC	01	AC	18,928	9/2/2000	70	Fair	5/13/2019	58	Fair	19	-2.30	NORMAL
T04MC	01	AC	6,444	9/2/2000	73	Satisfactory	5/13/2019	64	Fair	19	-2	NORMAL
T05MC	01	AC	6,444	9/2/2000	75	Satisfactory	5/13/2019	54	Poor	19	-4.02	HIGH
T06MC	01	AC	6,444	9/2/2000	75	Satisfactory	5/13/2019	75	Satisfactory	19	0	NONE
T07MC	01	AC	5,907	9/2/2000	65	Fair	5/13/2019	43	Poor	19	-4.21	HIGH

Abbreviations:¹ AC = asphalt concrete; AAC = AC overlaid with AC² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g., AC overlay).³ PCI = Pavement Condition Index⁴ Age = Pavement age in years at the time of the PCI survey in 2019⁵ Δ PCI/yr = Change in PCI points per year between 2019 survey and 2024 survey



APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

FUTURE PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan, this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after Pavement Condition Index (PCI) surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The following procedure is used for developing the prediction models:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data-outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Myrtle Creek Municipal Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use four distinct models for the following “families” of pavements at Myrtle Creek Municipal Airport. For each model, we reviewed the data to filter out any inconsistent or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 3C, below.




Figure 1C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 3/4 ASPHALT CONCRETE APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 3/4 ASPHALT CONCRETE RUNWAYS




Figure 3C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 4 ASPHALT CONCRETE TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R (rehabilitation/reconstruction) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Myrtle Creek Municipal Airport:

- Runways: 60
- Taxiways/Taxilanes: 55
- Aprons: 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for five- and 10-year periods. The projected pavement conditions in five years and 10 years for each pavement section at Myrtle Creek Municipal Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition.

This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Myrtle Creek Municipal Airport: the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT, AND FUTURE PCI

Branch ID	Section ID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2019	2024	2029	2034
NETWORK	--	82	74	68	63
A01MC	01	68	62	57	53
A01MC	02	49	39	29	19
AHOLDMC	01	67	58	54	52
R03MC	01	96	87	80	75
T01MC	01	100	90	81	74
T01MC	02	74	75	70	67
T01MC	03	93	75	70	67
T01MC	04	68	74	69	67
T01MC	05	62	68	66	66
T01MC	06	100	87	79	72
T02MC	01	66	64	62	61
T02MC	02	91	87	79	72
T03MC	01	70	58	56	55
T04MC	01	73	64	62	61
T05MC	01	75	54	52	51
T06MC	01	75	75	70	67
T07MC	01	65	43	41	40

Abbreviation: PCI = Pavement Condition Index; -- = no value

Table 2C: MYRTLE CREEK MUNICIPAL AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI	Years to End of Functional Service Life
A01MC	01	AC	62	16 - 20	50	> 20
A01MC	02	AC	39	0 - 5	50	0 - 5
AHOLDMC	01	AC	58	11 - 15	50	> 20
R03MC	01	AC	87	> 20	60	> 20
T01MC	01	AC	90	> 20	55	> 20
T01MC	02	AAC	75	> 20	55	> 20
T01MC	03	AC	75	> 20	55	> 20
T01MC	04	AC	74	> 20	55	> 20
T01MC	05	AC	68	> 20	55	> 20
T01MC	06	AC	87	> 20	55	> 20
T02MC	01	AC	64	> 20	55	> 20
T02MC	02	AC	87	> 20	55	> 20
T03MC	01	AC	58	6 - 10	55	> 20
T04MC	01	AC	64	> 20	55	> 20
T05MC	01	AC	54	0 - 5	55	> 20
T06MC	01	AC	75	> 20	55	> 20
T07MC	01	AC	43	0 - 5	55	6 - 10

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; M&R = maintenance and rehabilitation; Trigger PCI = Critical PCI



APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the maintenance and rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Myrtle Creek Municipal Airport pavement network condition over time. We used PAVER v7.1.1 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2025. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction: Considered for pavements with a Pavement Condition Index (PCI) less than 40.
- Rehabilitation (AC Overlay): Considered for pavements with PCI between 40 and the critical PCI and for pavements exhibiting significant load-related distresses.
- Surface Treatment: Treatments (fog seal, slurry seal, thin AC overlay) are applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance: Maintenance performed on a routine basis, such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron,

Runway). The PAVER analysis uses the combination of the section rank and the branch use to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM International D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2018 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Myrtle Creek Municipal Airport and information provided by the ODAV Pavement Maintenance Program project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Myrtle Creek Municipal Airport. The costs represent the fully loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D, below.

Table 2D: REGION 1 UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major M&R	Complete Reconstruction with AC	\$19.05	Sq Ft
	Cold Mill and Overlay—2 Inches Thick	\$8.41	Sq Ft
Surface Treatment (Global) M&R	Surface Treatment—Slurry Seal	\$0.50	Sq Ft
	Surface Treatment—Fog Seal	\$0.33	Sq Ft
Localized Preventive M&R	Crack Sealing—AC	\$2.75	Ft
	Crack Sealing—PCC	\$17.00	Ft
	Crack Sealing—Wide Cracks	\$3.00	Ft
	Joint Sealing—PCC	\$12.00	Ft
	AC Patching—Full Depth	\$75.00	Sq Ft
	PCC Patching—Full Depth	\$140.00	Sq Ft

Abbreviations: M&R = maintenance and rehabilitation; AC = asphalt concrete; PCC = portland cement concrete; Sq Ft = square foot; Ft = foot

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommendations for the projects is provided in Table 4D of this appendix.

Table 3D: MYRTLE CREEK MUNICIPAL AIRPORT NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	3,729	Ft	\$2.75	\$10,254	\$11,273
A01MC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	371	Ft	\$2.75	\$1,020	
A01MC	02	Alligator Cracking	Medium	Patching - AC Deep	2,114	SqFt	\$75.00	\$158,563	\$181,676
A01MC	02	Block Cracking	Low	Crack Sealing - AC	8,405	Ft	\$2.75	\$23,113	
AHOLDMC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	26	Ft	\$2.75	\$72	\$4,646
AHOLDMC	01	Alligator Cracking	Medium	Patching - AC Deep	36	SqFt	\$75.00	\$2,707	
AHOLDMC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	679	Ft	\$2.75	\$1,867	
R03MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	3,120	Ft	\$2.75	\$8,580	\$8,580
T01MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	6	Ft	\$2.75	\$17	\$17
T01MC	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	318	Ft	\$2.75	\$875	\$875
T01MC	03	Long. & Trans. Cracking	Low	Crack Sealing - AC	901	Ft	\$2.75	\$2,477	\$2,477
T01MC	04	Long. & Trans. Cracking	Low	Crack Sealing - AC	2,722	Ft	\$2.75	\$7,485	\$7,485
T01MC	05	Long. & Trans. Cracking	Low	Crack Sealing - AC	504	Ft	\$2.75	\$1,386	\$1,386
T01MC	06	Long. & Trans. Cracking	Low	Crack Sealing - AC	35	Ft	\$2.75	\$96	\$96
T02MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	784	Ft	\$2.75	\$2,156	\$2,646
T02MC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	178	Ft	\$2.75	\$490	
T02MC	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	32	Ft	\$2.75	\$88	\$88
T03MC	01	Alligator Cracking	Medium	Patching - AC Deep	31	SqFt	\$75.00	\$2,295	\$8,563
T03MC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	274	Ft	\$2.75	\$755	
T03MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	2,005	Ft	\$2.75	\$5,513	
T04MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	599	Ft	\$2.75	\$1,647	\$1,647
T05MC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	55	Ft	\$2.75	\$151	\$151
T05MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	496	Ft	\$2.75	\$1,364	\$1,364
T06MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	369	Ft	\$2.75	\$1,015	\$1,015
T07MC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	64	Ft	\$2.75	\$176	\$1,757
T07MC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	575	Ft	\$2.75	\$1,581	

Abbreviations:

Long. = longitudinal; Trans. = transverse; AC = asphalt concrete; Ft = feet; SqFt = square feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per Square Foot	Total Cost
2025	A01MC	01	APRON	AC	62	Fog Seal	29,120	\$0.33	\$9,610
	AHOLDMC	01	APRON	AC	58	Fog Seal	5,658	\$0.33	\$1,867
	T01MC	01	TAXIWAY	AC	90	Slurry Seal	1,112	\$0.50	\$556
	T01MC	02	TAXIWAY	AAC	75	Slurry Seal	4,830	\$0.50	\$2,415
	T01MC	03	TAXIWAY	AC	75	Slurry Seal	34,209	\$0.50	\$17,105
	T01MC	04	TAXIWAY	AC	74	Slurry Seal	31,989	\$0.50	\$15,995
	T01MC	05	TAXIWAY	AC	69	Slurry Seal	3,974	\$0.50	\$1,987
	T01MC	06	TAXIWAY	AC	87	Slurry Seal	1,499	\$0.50	\$750
	T02MC	01	TAXIWAY	AC	64	Slurry Seal	7,231	\$0.50	\$3,616
	T02MC	02	TAXIWAY	AC	87	Slurry Seal	1,478	\$0.50	\$739
	T03MC	01	TAXIWAY	AC	58	Slurry Seal	18,928	\$0.50	\$9,464
	T04MC	01	TAXIWAY	AC	64	Slurry Seal	6,444	\$0.50	\$3,222
	T06MC	01	TAXIWAY	AC	75	Slurry Seal	6,444	\$0.50	\$3,222
2027	T05MC	01	TAXIWAY	AC	54	Overlay	6,444	\$8.41	\$54,191
	T07MC	01	TAXIWAY	AC	43	Overlay	5,907	\$17.48	\$103,225
2028	A01MC	02	APRON	AC	39	Reconstruction	29,900	\$19.05	\$569,588
2029	R03MC	01	RUNWAY	AC	87	Slurry Seal	156,000	\$0.50	\$78,001

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC

Cost Summary	
2025 Total Project Cost	\$70,546
2026 Total Project Cost	\$0
2027 Total Project Cost	\$157,416
2028 Total Project Cost	\$569,588
2029 Total Project Cost	\$78,001
Total Five-Year Project Cost	\$875,551



APPENDIX E

Reinspection Report

Re-Inspection Report

ODAV_2024_12-19-24_9am_MAH

Generated Date 12/23/2024

Network:	Myrtle	Name:	Myrtle Creek Municipal						
Branch:	A01MC	Name:	Apron 01 Myrtle Creek	Use:	APRON	Area:	59,020 SqFt		
Section:	02	of	2	From:	A01MC-01	To:	Taxiway 02	Last Const.:	9/2/1970
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC	Zone:	16S	Category:	I	Rank:	P
Area:	29,900 SqFt	Length:	230 Ft	Width:	130 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	9/1/1970	Work Type: Base Course - Aggregate			Code:	BA-AG	Is Major M&R: False		
Work Date:	9/2/1970	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True		
Work Date:	9/1/1980	Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS	Is Major M&R: False		
Work Date:	9/1/1995	Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R: False		
Work Date:	9/1/2000	Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R: False		
Last Insp. Date: 8/1/2024									
		TotalSamples:	6	Surveyed:		4			
Conditions:	PCI:	39							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5000.00 SqFt	PCI:	33		
Sample Comments:									
41	ALLIGATOR CR	M	416.00	SqFt					
43	BLOCK CR	L	4584.00	SqFt					
57	WEATHERING	M	5000.00	SqFt					
Sample Number:	03	Type:	R	Area:	5000.00 SqFt	PCI:	35		
Sample Comments:									
41	ALLIGATOR CR	M	205.00	SqFt					
43	BLOCK CR	L	4603.00	SqFt					
50	PATCHING	M	192.00	SqFt					
57	WEATHERING	M	5000.00	SqFt					
Sample Number:	05	Type:	R	Area:	3000.00 SqFt	PCI:	19		
Sample Comments:									
41	ALLIGATOR CR	M	665.00	SqFt					
43	BLOCK CR	L	2335.00	SqFt					
50	PATCHING	L	40.00	SqFt					
57	WEATHERING	M	3000.00	SqFt					
Sample Number:	06	Type:	R	Area:	6890.00 SqFt	PCI:	55		
Sample Comments:									
43	BLOCK CR	L	6821.00	SqFt					
50	PATCHING	M	69.00	SqFt					
57	WEATHERING	M	6890.00	SqFt					

Network:	Myrtle		Name:	Myrtle Creek Municipal								
Branch:	A01MC		Name:	Apron 01 Myrtle Creek		Use:	APRON	Area:	59,020 SqFt			
Section:	01	of 2	From:	Taxiway 04			To:	A01MC-02		Last Const.:	9/2/2000	
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	16S		Category:	I		Rank:	P
Area:	29,120 SqFt		Length:	224 Ft		Width:	130 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	8/1/2024		TotalSamples:	6		Surveyed:	4					
Conditions:	PCI: 62											
Inspection Comments:												
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	67		
Sample Comments:												
48	L & T CR		L	688.00 Ft								
57	WEATHERING		M	5000.00 SqFt								
Sample Number:	03		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	708.00 Ft								
48	L & T CR		M	80.00 Ft								
57	WEATHERING		M	5000.00 SqFt								
Sample Number:	05		Type:	R		Area:	3879.00 SqFt		PCI:	55		
Sample Comments:												
48	L & T CR		L	651.00 Ft								
48	L & T CR		M	48.00 Ft								
52	RAVELING		M	192.00 SqFt								
57	WEATHERING		M	3700.00 SqFt								
Sample Number:	06		Type:	R		Area:	6700.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	588.00 Ft								
48	L & T CR		M	134.00 Ft								
52	RAVELING		M	32.00 SqFt								
57	WEATHERING		M	6680.00 SqFt								

Network:	Myrtle			Name:	Myrtle Creek Municipal						
Branch:	AHOLDMC		Name:	Hold Apron Myrtle Creek		Use:	APRON		Area:	5,658 SqFt	
Section:	01	of	1	From:	T03		To:	--		Last Const.:	9/2/2000
Surface:	AC	Family:	2024_Region2_Cat 3/4_Apron_AC		Zone:	16S		Category:	I	Rank:	S
Area:	5,658 SqFt		Length:	72 Ft		Width:	72 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True	
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:		1			
Conditions:	PCI: 58										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5658.00 SqFt		PCI: 58				
Sample Comments:											
41	ALLIGATOR CR		M	16.00 SqFt							
48	L & T CR		L	150.00 Ft							
48	L & T CR		L	529.00 Ft							
48	L & T CR		M	26.00 Ft							
57	WEATHERING		M	5658.00 SqFt							

Network:	Myrtle			Name:	Myrtle Creek Municipal							
Branch:	R03MC		Name:	Runway 03/21 Myrtle Creek		Use:	RUNWAY		Area:	156,000 SqFt		
Section:	01	of 1		From:	Runway 21 End		To:	Runway 03 End		Last Const.:	9/4/2007	
Surface:	AC	Family:	2024_Region2_Cat 3/4_Runway_AC		Zone:	16S		Category:	I		Rank:	P
Area:	156,000 SqFt		Length:	2,600 Ft		Width:	60 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1970		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/2/1970		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1980		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1995		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2007		Work Type: Subbase - Geotextlile				Code:	SB-TX		Is Major M&R:	False	
Work Date:	9/2/2007		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	9/3/2007		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/4/2007		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True	
Last Insp. Date:	8/1/2024		TotalSamples:	26		Surveyed:	5					
Conditions:	PCI:	87										
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	6000.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	107.00 Ft								
57	WEATHERING		L	6000.00 SqFt								
Sample Number:	08		Type:	R		Area:	6000.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	119.00 Ft								
57	WEATHERING		L	6000.00 SqFt								
Sample Number:	15		Type:	R		Area:	6000.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	13.00 Ft								
48	L & T CR		L	32.00 Ft								
57	WEATHERING		L	6000.00 SqFt								
Sample Number:	20		Type:	R		Area:	6000.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	104.00 Ft								
57	WEATHERING		L	6000.00 SqFt								
Sample Number:	26		Type:	R		Area:	6000.00 SqFt		PCI:	83		
Sample Comments:												
48	L & T CR		L	25.00 Ft								
48	L & T CR		L	200.00 Ft								
57	WEATHERING		L	6000.00 SqFt								

Network:	Myrtle			Name:	Myrtle Creek Municipal									
Branch:	T01MC			Name:	Taxiway 01 Myrtle Creek			Use:	TAXIWAY		Area:	77,613 SqFt		
Section:	05		of	6	From:	T01MC-04			To:	T01MC-06		Last Const.:	8/1/2004	
Surface:	AC		Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P	
Area:	3,974 SqFt			Length:	133 Ft		Width:	30 Ft						
Slabs:	Slab Length:			Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:			Grade:		0		Lanes:	0					
Section Comments:														
Work Date:	9/1/1970			Work Type: Base Course - Aggregate					Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/2/1970			Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1980			Work Type: Surface Treatment - Slurry Seal					Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1995			Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R:	False	
Work Date:	8/1/2004			Work Type: Overlay - Thin					Code:	OL-ACTH		Is Major M&R:	True	
Work Date:	9/1/2014			Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	8/1/2024			TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 69													
Inspection Comments:														
Sample Number:	01		Type:	R		Area:	3974.00 SqFt			PCI:	68			
Sample Comments:														
48	L & T CR		L	504.00 Ft										
57	WEATHERING		M	3974.00 SqFt										

Network:	Myrtle			Name:	Myrtle Creek Municipal							
Branch:	T01MC		Name:	Taxiway 01 Myrtle Creek		Use:	TAXIWAY	Area:	77,613 SqFt			
Section:	02	of	6	From:	T01MC-01		To:	T01MC-03		Last Const.:	8/2/2002	
Surface:	AAC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P
Area:	4,830 SqFt		Length:	156 Ft		Width:	30 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1970		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/2/1970		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1995		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2000		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	8/1/2002		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	8/2/2002		Work Type: Overlay - AC Fabric				Code:	OL-AF		Is Major M&R:	True	
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI:	75										
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	4830.00 SqFt		PCI:	75				
Sample Comments:												
48	L & T CR		L	318.00 Ft								
57	WEATHERING		M	4830.00 SqFt								

Network:	Myrtle		Name:	Myrtle Creek Municipal									
Branch:	T01MC		Name:	Taxiway 01 Myrtle Creek		Use:	TAXIWAY	Area:	77,613 SqFt				
Section:	03	of 6	From:	T01MC-02			To:	T02MC-01		Last Const.:	8/3/2002		
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P	
Area:	34,209 SqFt		Length:	1,285 Ft		Width:	25 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	8/1/2002		Work Type:				Subgrade-Geotextile		Code:	SG-GE		Is Major M&R:	True
Work Date:	8/2/2002		Work Type:				Base Course - Aggregate		Code:	BA-AG		Is Major M&R:	False
Work Date:	8/3/2002		Work Type:				New Construction - AC		Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	8/1/2024		TotalSamples:	7		Surveyed:	4						
Conditions:	PCI: 75												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5125.00 SqFt		PCI:	75			
Sample Comments:													
48	L & T CR		L	136.00 Ft									
57	WEATHERING		M	5125.00 SqFt									
Sample Number:	03		Type:	R		Area:	5000.00 SqFt		PCI:	75			
Sample Comments:													
48	L & T CR		L	76.00 Ft									
57	WEATHERING		M	5000.00 SqFt									
Sample Number:	05		Type:	R		Area:	5000.00 SqFt		PCI:	75			
Sample Comments:													
48	L & T CR		L	181.00 Ft									
57	WEATHERING		M	5000.00 SqFt									
Sample Number:	06		Type:	R		Area:	3750.00 SqFt		PCI:	75			
Sample Comments:													
48	L & T CR		L	104.00 Ft									
57	WEATHERING		M	3750.00 SqFt									

Network:	Myrtle			Name:	Myrtle Creek Municipal				
Branch:	T01MC		Name:	Taxiway 01 Myrtle Creek		Use:	TAXIWAY	Area:	77,613 SqFt
Section:	06	of 6	From:	T01MC-05			To:	R03MC-01	Last Const.: 9/4/2007
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S	Category:	I	Rank: P
Area:	1,499 SqFt		Length:	30 Ft		Width:	30 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade: 0		Lanes: 0				
Section Comments:									
Work Date:	9/1/2007		Work Type: Subbase - Geotextlile				Code:	SB-TX	Is Major M&R: False
Work Date:	9/2/2007		Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	9/3/2007		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	9/4/2007		Work Type: Complete Reconstruction - AC				Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1		
Conditions:	PCI: 87								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	1499.00 SqFt		PCI:	87	
Sample Comments:									
48	L & T CR		L	35.00 Ft					
57	WEATHERING		L	1499.00 SqFt					

Network:	Myrtle		Name:	Myrtle Creek Municipal								
Branch:	T01MC		Name:	Taxiway 01 Myrtle Creek		Use:	TAXIWAY	Area:	77,613 SqFt			
Section:	04	of 6	From:	T02MC-01			To:	T01MC-05		Last Const.:	8/3/2004	
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P
Area:	31,989 SqFt		Length:	1,098 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	8/1/2004		Work Type: Subgrade-Geotextile				Code:	SG-GE		Is Major M&R:	True	
Work Date:	8/2/2004		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	8/3/2004		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	8/1/2024		TotalSamples:	6		Surveyed:	3					
Conditions:	PCI: 74											
Inspection Comments:												
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	75		
Sample Comments:												
48	L & T CR		L	399.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	04		Type:	R		Area:	5000.00 SqFt		PCI:	75		
Sample Comments:												
48	L & T CR		L	404.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	05		Type:	R		Area:	3750.00 SqFt		PCI:	72		
Sample Comments:												
48	L & T CR		L	76.00 Ft								
48	L & T CR		L	291.00 Ft								
57	WEATHERING		L	3750.00 SqFt								

Network:		Myrtle		Name:		Myrtle Creek Municipal							
Branch:	T01MC		Name:	Taxiway 01 Myrtle Creek		Use:	TAXIWAY	Area:	77,613 SqFt				
Section:	01	of	6	From:	R03MC-01		To:	T01MC-02		Last Const.:	9/4/2007		
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P	
Area:	1,112 SqFt		Length:	20 Ft		Width:	30 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	9/1/2007		Work Type:				Subbase - Geotextlile		Code:	SB-TX		Is Major M&R:	False
Work Date:	9/2/2007		Work Type:				Subbase - Aggregate		Code:	SB-AG		Is Major M&R:	False
Work Date:	9/3/2007		Work Type:				Base Course - Aggregate		Code:	BA-AG		Is Major M&R:	False
Work Date:	9/4/2007		Work Type:				Complete Reconstruction - AC		Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 90												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	1111.00 SqFt		PCI:	90					
Sample Comments:													
48	L & T CR		L	6.00 Ft									
57	WEATHERING		L	1111.00 SqFt									

Network:	Myrtle			Name:	Myrtle Creek Municipal				
Branch:	T02MC		Name:	Taxiway 02 Myrtle Creek		Use:	TAXIWAY	Area:	8,709 SqFt
Section:	01	of 2	From:	T02MC-02			To:	A01MC-02	Last Const.: 8/3/2004
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S	Category:	I	Rank: P
Area:	7,231 SqFt		Length:	200 Ft		Width:	30 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade: 0		Lanes:		0		
Section Comments:									
Work Date:	8/1/2004		Work Type: Subgrade-Geotextile				Code:	SG-GE	Is Major M&R: True
Work Date:	8/2/2004		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	8/3/2004		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Last Insp. Date:	8/1/2024		TotalSamples:	2		Surveyed: 2			
Conditions:	PCI: 64								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	4061.00 SqFt		PCI:	71	
Sample Comments:									
48	L & T CR	L	272.00 Ft						
48	L & T CR	L	164.00 Ft						
57	WEATHERING	M	4061.00 SqFt						
Sample Number:	02	Type:	R	Area:	3160.00 SqFt		PCI:	55	
Sample Comments:									
48	L & T CR	L	347.00 Ft						
48	L & T CR	M	178.00 Ft						
57	WEATHERING	M	3160.00 SqFt						

Network:	Myrtle		Name:	Myrtle Creek Municipal			
Branch:	T02MC	Name:	Taxiway 02 Myrtle Creek		Use:	TAXIWAY	Area: 8,709 SqFt
Section:	02	of 2	From:	T02MC-01	To:	R03MC-01	Last Const.: 9/4/2007
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC	Zone:	16S	Category:	I Rank: P
Area:	1,478 SqFt	Length:	20 Ft	Width:	30 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	9/1/2007	Work Type:	Subbase - Geotextlile		Code:	SB-TX	Is Major M&R: False
Work Date:	9/2/2007	Work Type:	Subbase - Aggregate		Code:	SB-AG	Is Major M&R: False
Work Date:	9/3/2007	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R: False
Work Date:	9/4/2007	Work Type:	Complete Reconstruction - AC		Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	8/1/2024	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 87						
Inspection Comments:							
Sample Number:	01	Type:	R	Area:	1478.00 SqFt	PCI:	87
Sample Comments:							
48	L & T CR	L	32.00 Ft				
57	WEATHERING	L	1478.00 SqFt				

Network:	Myrtle			Name:	Myrtle Creek Municipal				
Branch:	T03MC		Name:	Taxiway 03 Myrtle Creek		Use:	TAXIWAY	Area:	18,928 SqFt
Section:	01	of	1	From:	Apron 01		To:	Taxiway 07	
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S	Category:	I	Rank: P
Area:	18,928 SqFt		Length:	750 Ft		Width:	25 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade:		0		Lanes: 0		
Section Comments:									
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG	
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC	
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC	
Last Insp. Date:	8/1/2024		TotalSamples:	4		Surveyed:	3		
Conditions:	PCI: 58								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5240.00 SqFt		PCI:	60	
Sample Comments:									
48	L & T CR		L	382.00 Ft					
48	L & T CR		M	180.00 Ft					
52	RAVELING		M	40.00 SqFt					
57	WEATHERING		M	5200.00 SqFt					
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	57	
Sample Comments:									
41	ALLIGATOR CR		M	10.00 SqFt					
48	L & T CR		L	681.00 Ft					
48	L & T CR		M	41.00 Ft					
57	WEATHERING		M	5000.00 SqFt					
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	55	
Sample Comments:									
48	L & T CR		L	48.00 Ft					
48	L & T CR		L	503.00 Ft					
50	PATCHING		L	112.00 SqFt					
52	RAVELING		M	700.00 SqFt					
57	WEATHERING		M	4300.00 SqFt					

Network:	Myrtle			Name:	Myrtle Creek Municipal							
Branch:	T04MC		Name:	Taxiway 04 Myrtle Creek		Use:	TAXIWAY		Area:	6,444 SqFt		
Section:	01	of	1	From:	Taxiway 03			To:	End		Last Const.:	9/2/2000
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P
Area:	6,444 SqFt		Length:	268 Ft		Width:	20 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:		0		
Section Comments:												
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True		
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 64											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	6444.00 SqFt			PCI:	64			
Sample Comments:												
45	DEPRESSION		L	36.00 SqFt								
48	L & T CR		L	599.00 Ft								
52	RAVELING		M	48.00 SqFt								
52	RAVELING		M	64.00 SqFt								
57	WEATHERING		M	6334.00 SqFt								

Network:	Myrtle			Name:	Myrtle Creek Municipal						
Branch:	T05MC		Name:	Taxiway 05 Myrtle Creek		Use:	TAXIWAY	Area:	6,444 SqFt		
Section:	01	of	1	From:	Taxiway 03			To:	End		
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		
Area:	6,444 SqFt		Length:	268 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 54										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	6444.00 SqFt			PCI:	54		
Sample Comments:											
48	L & T CR		L	496.00 Ft							
48	L & T CR		M	55.00 Ft							
57	WEATHERING		M	5000.00 SqFt							
57	WEATHERING		H	1444.00 SqFt							

Network:	Myrtle			Name:	Myrtle Creek Municipal							
Branch:	T06MC		Name:	Taxiway 06 Myrtle Creek		Use:	TAXIWAY	Area:	6,444 SqFt			
Section:	01	of	1	From:	Taxiway 03		To:	End		Last Const.:	9/2/2000	
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P
Area:	6,444 SqFt		Length:	268 Ft		Width:	20 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/2000		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True		
Work Date:	9/2/2000		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/2014		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 75											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	6444.00 SqFt		PCI:	75				
Sample Comments:												
48	L & T CR		L	369.00 Ft								
57	WEATHERING		M	6444.00 SqFt								

Network:	Myrtle			Name:	Myrtle Creek Municipal								
Branch:	T07MC		Name:	Taxiway 07 Myrtle Creek		Use:	TAXIWAY	Area:	5,907 SqFt				
Section:	01	of	1	From:	Taxiway 03			To:	End		Last Const.:	9/2/2000	
Surface:	AC	Family:	2024_Region2_Cat 4_Taxiway_AC		Zone:	16S		Category:	I		Rank:	P	
Area:	5,907 SqFt		Length:	268 Ft		Width:	20 Ft						
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	9/1/2000		Work Type:				Base Course - Aggregate		Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/2000		Work Type:				New Construction - AC		Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2014		Work Type:				Crack Sealing - AC		Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 43												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	5907.00 SqFt		PCI:	43					
Sample Comments:													
48	L & T CR		L	575.00 Ft									
48	L & T CR		M	64.00 Ft									
57	WEATHERING		M	2990.00 SqFt									
57	WEATHERING		H	2600.00 SqFt									
57	WEATHERING		H	317.00 SqFt									



APPENDIX F

Work History Report

2/17/2025

Work History Report

Page 1 of 5

Pavement Database: ODAV_2024_02-05-25_2pm_AMC

Network: Myrtle Creek Municip		Branch: A01MC	Apron 01 Myrtle C		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: APRON	Rank: P	Length: 224.00 (Ft)	Width: 130.00 (Ft)	True Area:	29120 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Myrtle Creek Municip		Branch: A01MC	Apron 01 Myrtle C		Section: 02	Surface: AC
L.C.D. 9/2/1970	Use: APRON	Rank: P	Length: 230.00 (Ft)	Width: 130.00 (Ft)	True Area:	29900 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2000	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	DATE UNKNOWN
9/1/1995	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1980	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>	
9/1/1970	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Myrtle Creek Municip		Branch: AHOLDMC	Hold Apron Myrtle		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: APRON	Rank: S	Length: 72.00 (Ft)	Width: 72.00 (Ft)	True Area:	5658 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Myrtle Creek Municip		Branch: R03MC	Runway 03/21 Myr		Section: 01	Surface: AC
L.C.D. 9/4/2007	Use: RUNWAY	Rank: P	Length: 2,600.00 (Ft)	Width: 60.00 (Ft)	True Area:	156000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/4/2007	CR-AC	Complete Reconstruction - AC	0.00	2.00	<input checked="" type="checkbox"/>	P-403
9/3/2007	BA-AG	Base Course - Aggregate	0.00	7.00	<input type="checkbox"/>	P-208
9/2/2007	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>	P-154
9/1/2007	SB-TX	Subbase - Geotextlile	0.00	0.00	<input type="checkbox"/>	DATE UNKNOWN, Partial
9/1/1995	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1980	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>	
9/1/1970	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Myrtle Creek Municip		Branch: T01MC	Taxiway 01 Myrtle		Section: 01	Surface: AC
L.C.D. 9/4/2007	Use: TAXIWAY	Rank: P	Length: 20.00 (Ft)	Width: 30.00 (Ft)	True Area:	1112 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/4/2007	CR-AC	Complete Reconstruction - AC	0.00	2.00	<input checked="" type="checkbox"/>	P-403
9/3/2007	BA-AG	Base Course - Aggregate	0.00	7.00	<input type="checkbox"/>	P-208
9/2/2007	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>	P-154
9/1/2007	SB-TX	Subbase - Geotextlile	0.00	0.00	<input type="checkbox"/>	

2/17/2025

Work History Report

Page 2 of 5

Pavement Database: ODAV_2024_02-05-25_2pm_AMC

Network: Myrtle Creek Municip		Branch: T01MC		Taxiway 01 Myrtle		Section: 02	Surface: AAC
L.C.D. 8/2/2002	Use: TAXIWAY	Rank: P	Length: 156.00 (Ft)	Width: 30.00 (Ft)	True Area: 4830 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/2/2002	OL-AF	Overlay - AC Fabric	0.00	2.00	<input checked="" type="checkbox"/>	P-401 + Fabric	
8/1/2002	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/2000	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1995	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/2/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>		
9/1/1970	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T01MC		Taxiway 01 Myrtle		Section: 03	Surface: AC
L.C.D. 8/3/2002	Use: TAXIWAY	Rank: P	Length: 1,285.00 (Ft)	Width: 25.00 (Ft)	True Area: 34209 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
8/3/2002	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	P-401 P-209	
8/2/2002	BA-AG	Base Course - Aggregate	0.00	10.00	<input type="checkbox"/>		
8/1/2002	SG-GE	Subgrade-Geotextile	0.00	0.50	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T01MC		Taxiway 01 Myrtle		Section: 04	Surface: AC
L.C.D. 8/3/2004	Use: TAXIWAY	Rank: P	Length: 1,098.00 (Ft)	Width: 25.00 (Ft)	True Area: 31989 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/3/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/2004	BA-AG	Base Course - Aggregate	0.00	10.00	<input type="checkbox"/>		
8/1/2004	SG-GE	Subgrade-Geotextile	0.00	0.50	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T01MC		Taxiway 01 Myrtle		Section: 05	Surface: AC
L.C.D. 8/1/2004	Use: TAXIWAY	Rank: P	Length: 133.00 (Ft)	Width: 30.00 (Ft)	True Area: 3974 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	DATE UNKNOWN, Partial	
8/1/2004	OL- ACTH	Overlay - Thin	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/1995	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1980	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/2/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>		
9/1/1970	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T01MC		Taxiway 01 Myrtle		Section: 06	Surface: AC
L.C.D. 9/4/2007	Use: TAXIWAY	Rank: P	Length: 30.00 (Ft)	Width: 30.00 (Ft)	True Area: 1499 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/4/2007	CR-AC	Complete Reconstruction - AC	0.00	2.00	<input checked="" type="checkbox"/>	P-403 P-208 P-154	
9/3/2007	BA-AG	Base Course - Aggregate	0.00	7.00	<input type="checkbox"/>		
9/2/2007	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>		
9/1/2007	SB-TX	Subbase - Geotextile	0.00	0.00	<input type="checkbox"/>		

2/17/2025

Work History Report

Page 3 of 5

Pavement Database: ODAV_2024_02-05-25_2pm_AMC

Network: Myrtle Creek Municip		Branch: T02MC		Taxiway 02 Myrtle		Section: 01	Surface: AC
L.C.D. 8/3/2004	Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 30.00 (Ft)	True Area: 7231 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/3/2004	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
8/2/2004	BA-AG	Base Course - Aggregate	0.00	10.00	<input type="checkbox"/>		
8/1/2004	SG-GE	Subgrade-Geotextile	0.00	0.50	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T02MC		Taxiway 02 Myrtle		Section: 02	Surface: AC
L.C.D. 9/4/2007	Use: TAXIWAY	Rank: P	Length: 20.00 (Ft)	Width: 30.00 (Ft)	True Area: 1478 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/4/2007	CR-AC	Complete Reconstruction - AC	0.00	2.00	<input checked="" type="checkbox"/>	P-403	
9/3/2007	BA-AG	Base Course - Aggregate	0.00	7.00	<input type="checkbox"/>	P-208	
9/2/2007	SB-AG	Subbase - Aggregate	0.00	4.00	<input type="checkbox"/>	P-154	
9/1/2007	SB-TX	Subbase - Geotextile	0.00	0.00	<input type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T03MC		Taxiway 03 Myrtle		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: TAXIWAY	Rank: P	Length: 750.00 (Ft)	Width: 25.00 (Ft)	True Area: 18928 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T04MC		Taxiway 04 Myrtle		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: TAXIWAY	Rank: P	Length: 268.00 (Ft)	Width: 20.00 (Ft)	True Area: 6444 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T05MC		Taxiway 05 Myrtle		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: TAXIWAY	Rank: P	Length: 268.00 (Ft)	Width: 20.00 (Ft)	True Area: 6444 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Myrtle Creek Municip		Branch: T06MC		Taxiway 06 Myrtle		Section: 01	Surface: AC
L.C.D. 9/2/2000	Use: TAXIWAY	Rank: P	Length: 268.00 (Ft)	Width: 20.00 (Ft)	True Area: 6444 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

2/17/2025

Work History Report

Page 4 of 5

*Pavement Database: ODAV_2024_02-05-25_2pm_AMC***Network:** Myrtle Creek Municip**Branch:** T07MC

Taxiway 07 Myrtle

Section: 01**Surface:**AC**L.C.D.** 9/2/2000**Use:** TAXIWAY**Rank:** P**Length:** 268.00 (Ft)**Width:** 20.00 (Ft)**True Area:** 5907 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/2000	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/2000	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	18	507,167.00	6.89	1.45
Complete Reconstruction - AC	4	160,089.00	2.00	0.00
Crack Sealing - AC	17	356,403.00	0.04	0.05
New Construction - AC	14	347,078.00	1.86	0.23
Overlay - AC Fabric	1	4,830.00	2.00	0.00
Overlay - Thin	1	3,974.00	2.00	0.00
Subbase - Aggregate	4	160,089.00	4.00	0.00
Subbase - Geotextile	4	160,089.00	0.00	0.00
Subgrade-Geotextile	3	73,429.00	0.50	0.00
Surface Treatment - Slurry Seal	3	189,874.00	0.50	0.00