

2024 ODAV Pavement Evaluation Program Prospect State Airport

Prospect, Oregon

February 12, 2025

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97302-2595

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW	1
2	PAVEMENT INVENTORY	1
3	PAVEMENT CONDITION INSPECTION RESULTS	5
	3.1 Introduction.....	5
	3.2 Pavement Condition Index Survey Results.....	6
4	FUTURE PAVEMENT CONDITION ANALYSIS	8
	4.1 Introduction.....	8
	4.2 Future Condition Analysis	8
	4.3 Functional Remaining Life	9
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	11
	5.1 Introduction.....	11
	5.2 Recommended Localized Maintenance.....	11
	5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan	11
6	LIMITATIONS	13

TABLES

Table 3-1:	ASTM PCI Rating Scale	5
Table 5-1:	Localized Maintenance Quantities.....	11
Table 5-2:	Surface Treatment, Rehabilitation, and Reconstruction Quantities	11

FIGURES

Figure 2.1:	Prospect State Airport Location Map	2
Figure 2.2:	Prospect State Airport Percent of Pavement Area by Surface Type	3
Figure 2.3:	Prospect State Airport Pavement Area by Branch Use	3
Figure 2.4:	Prospect State Airport Pavement Inventory	4
Figure 3.1:	Prospect State Airport 2024 PCI Survey Results.....	7
Figure 3.2:	Prospect State Airport Pavement Condition Rating by Percent of Area	8
Figure 4.1:	Prospect State Airport Future Pavement Condition	10
Figure 5.1:	Prospect State Airport 5-Year Pavement Management Plan	12

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan



APPENDICES (CONTINUED)

Appendix E: Reinspection Report

Appendix F: Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODAV) airport pavement management system and developing a 5-year plan comprising maintenance, surface treatment, rehabilitation, and reconstruction projects for the Prospect State Airport in Prospect, Oregon. This project was implemented as part of the ODAV and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, and repair of airport pavements.

GRI conducted surveys of the airside pavement at Prospect State Airport in 2024 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the Pavement Condition Index (PCI) rating. PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from 0 to 100, where 0 represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Prospect State Airport is in Prospect, Oregon, and is owned and operated by ODAV. The airport consists of one runway, two connector taxiways, and one main apron that serve a variety of general aviation aircraft. The general location of the airport is shown below, on the Prospect State Airport Location Map, Figure 2.1.



Figure 2.1: PROSPECT STATE AIRPORT LOCATION MAP

The airside pavements at the Prospect State Airport are composed of asphalt concrete (AC), AC overlaid with AC, and surface-treated pavements. The airport pavements, delineated by surface type and branch use, are shown on the Prospect State Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on the Prospect State Airport Pavement Area by Branch Use, Figure 2.3, shown below. The pavement inventory, including the work history for each pavement section, is displayed spatially on the Prospect State Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are summarized in Tables 2A and 3A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 1A of Appendix A in our survey. The pavement inventory, including the work history for individual airport pavement sections, is provided in the work history report presented in Appendix F.




Figure 2.2: PROSPECT STATE AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE








Figure 2.3: PROSPECT STATE AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE; BST = BITUMINOUS SURFACE TREATMENT



1 INCH = 300 FEET



OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

PROSPECT STATE AIRPORT
PAVEMENT INVENTORY








3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Prospect State Airport in August 2024. The 2024 survey work was performed on sections last inspected in 2019 in order to update the Prospect State Airport inspection data. GRI performed the 2024 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340 and further discussed in Appendix B of this report.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1, below.


Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

Abbreviations: ASTM = ASTM International; PCI = Pavement Condition Index; M&R = maintenance and rehabilitation



3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Prospect State Airport is approximately 54. The section PCIs ranged from a low of 0 to a high of 61. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, block cracking, patching, and raveling on AC-surfaced pavements. Section PCIs following our pavement survey are displayed spatially on the Prospect State Airport 2024 PCI Survey Results, Figure 3.1, below.



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



**PROSPECT STATE AIRPORT
2024 PCI SURVEY RESULTS**

The condition distribution of the network by percent of total pavement area is provided on the Prospect State Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2024 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is presented in Appendix E.




Figure 3.2: PROSPECT STATE AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Prospect State Airport are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for five- and 10-year periods. Based on this analysis, we project the PCI to decrease from its current value of 54 to values of 45 in 2029 and 37 in

2034 if no maintenance or rehabilitation work is performed. The projected pavement condition in five years and 10 years for each pavement section at Prospect State Airport is displayed spatially on the Prospect State Airport Future Pavement Condition, Figure 4.1, and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

Functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and Falling Weight Deflectometer deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Prospect State Airport. The first type of functional remaining life is the time until rehabilitation, such as an overlay, is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining-life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at Prospect State Airport are summarized in Table 2C in Appendix C.

PREDICTED CONDITION IN 2029




PREDICTED CONDITION IN 2034



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

PROSPECT STATE AIRPORT
FUTURE PAVEMENT CONDITION

5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated maintenance and rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop localized maintenance, surface treatment, rehabilitation, and reconstruction needs. The details of our M&R work priorities and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is summarized in Table 3D in Appendix D and is independent of the surface treatments, rehabilitation, and reconstruction projects associated with the five-year surface treatment and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1, below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES

Localized Maintenance Operation	Quantity, linear feet or square feet
Asphalt Concrete Crack Sealing	22,393
Asphalt Concrete Full-Depth Patching	4,584


5.3 Surface Treatment, Rehabilitation, and Reconstruction Plan

To develop the 5-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of surface treatment, rehabilitation, and reconstruction projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of surface treatment, rehabilitation, and reconstruction quantities is provided in Table 5-2.

Table 5-2: SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION QUANTITIES

Treatment Type	Quantity, square feet
Reconstruction	10,358
Overlay	265,975
Fog Seal	9,268
Slurry Seal	0

Maps of the project locations by year are shown on the Prospect State Airport 5-Year Pavement Management Plan, Figure 5.1. The complete list of recommended surface treatment, rehabilitation, and reconstruction projects is presented in Table 4D in Appendix D.




ACTION TIMING

- 2025
- 2026
- 2027
- 2028
- 2029

ACTION

- FOG SEAL
- SLURRY SEAL
- OVERLAY
- RECONSTRUCTION
- ROUTINE MAINTENANCE



GRI OREGON DEPARTMENT OF AVIATION
STATEWIDE PAVEMENT EVALUATION
PROGRAM

**PROSPECT STATE AIRPORT
5-YEAR PAVEMENT MANAGEMENT PLAN**

6 LIMITATIONS

This report has been prepared to assist ODAV with pavement-related project planning for the Prospect State Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODAV, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The surface treatment, rehabilitation, and reconstruction recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective M&R program should be reviewed and updated on a regular basis. The pavement condition should be regularly surveyed and updated, and completed construction activities should be tracked in the PAVER database. If Prospect State Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2025

Lindsay A. Hammond, PE
Principal



Matthew A. Haynes, PE
Project Engineer



Ana Coca, PhD
Staff Engineer

This document has been submitted electronically.



APPENDIX A

Pavement Inventory Reports and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Prospect State Airport is located in Prospect, Oregon, and is owned and operated by the Oregon Department of Aviation (ODAV). The pavement network / facilities at Prospect State Airport serve a variety of general aviation aircraft. Prospect State Airport consists of one runway, two connector taxiways, and one main apron. The types of airside pavements include asphalt concrete (AC), AC overlaid with AC, and surface-treated pavements.

The current airport pavement management system (APMS) network at Prospect State Airport has an approximate area of 285,601 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities are summarized by branch and section in Tables 2A and 3A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Prospect State Airport contains six branches, information about which are tabulated in Table 2A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as "a contiguous pavement area having uniform construction, maintenance, usage history, and condition." All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Prospect State Airport contains six sections that are managed by ODAV, information about which is tabulated in Table 3A and the locations of which are shown spatially on Figure 1A.

PAVER assigns a rank that designates a pavement's prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked "Primary," the surrounding aprons and shoulders are ranked "Secondary," and low-use areas are ranked "Tertiary." The ranks for all sections are shown on Table 3A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average Pavement Condition Index (PCI) values. To meet this criterion, the ASTM method recommends that sample units for flexible pavements be 5,000 ±2,000 square feet. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of 8 PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad \text{(Equation 1)}$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2024 Prospect State Airport PCI survey, Table 1A was used as a guideline in developing sampling rates for flexible pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Prospect State Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section, and then the remaining sample units are systematically spaced throughout the section at equal distances apart.

Table 1A: EXAMPLE SAMPLE RATES FOR ASPHALT CONCRETE PAVEMENTS

Total Number of Sample Units, N	Sample Units to Survey, n
1	1
2 – 3	2
4 – 6	3
7 – 13	4
14 – 38	5
39+	6

Table 2A: PROSPECT STATE AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01PO	Apron 01 Prospect	1	9,268
A02PO	Apron 02 Prospect	1	64,225
A03PO	Apron 03 Prospect	1	7,918
R02PO	Runway 2/20 Prospect	1	201,750
T01PO	Taxiway 01 Prospect	1	1,047
T02PO	Taxiway 02 Prospect	1	1,393

Table 3A: PROSPECT STATE AIRPORT CURRENT PAVEMENT INVENTORY

Branch ID	Branch Name	Branch Use	Section ID	From	To	Rank	Length, feet	Width, feet	Approximate Area, square feet	LCD	Surface Type
A01PO	Apron 01 Prospect	APRON	01	Runway 02 End	--	P	200	70	9,268	9/1/1988	AC
A02PO	Apron 02 Prospect	APRON	01	Taxiway 01, 02	Fence	P	635	115	64,225	8/1/2001	AC
A03PO	Apron 03 Prospect	APRON	01	Runway 20 End	--	P	200	60	7,918	1/1/1988	ST
R02PO	Runway 2/20 Prospect	RUNWAY	01	Runway 02 End	Runway 20 End	P	4,035	50	201,750	9/1/1995	AAC
T01PO	Taxiway 01 Prospect	TAXIWAY	01	Runway 2/20	Apron 02	P	25	35	1,047	8/1/2001	AC
T02PO	Taxiway 02 Prospect	TAXIWAY	01	Runway 2/20	Apron 02	P	25	45	1,393	9/1/1999	ST


Abbreviations:

-- = no value

P = Primary pavement


LCD = Last construction date. The date of the last major rehabilitation (e.g., overlay).

AC = asphalt concrete, AAC = AC overlaid with AC, ST = surface treated



LEGEND

- SECTIONS
- SAMPLE UNIT



**PROSPECT STATE AIRPORT
SAMPLE UNIT LAYOUT**



APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the Pavement Condition Index (PCI) is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM International (ASTM) D5340. Flexible pavement (e.g., asphalt concrete [AC] and AC overlaid with AC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE PAVEMENT

PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load
42	Bleeding	Other
43	Block Cracking	Climate/Durability
44	Corrugation	Other
45	Depression	Other
46	Jet Blast	Other
47	Joint Reflection Cracking	Climate/Durability
48	Longitudinal & Transverse Cracking	Climate/Durability
49	Oil Spillage	Other
50	Patching	Climate/Durability
51	Polished Aggregate	Other
52	Raveling	Climate/Durability
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/Durability

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional” (i.e., defined as nonrepresentative instead of random) are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented in Table 3-1 of Section 3.1 is based on ASTM D5340.

Section 4.1 of ASTM D5340, which governs PCI surveys, offers this caution:

The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the present condition of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI cannot measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the maintenance and rehabilitation planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking.
- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, and patching.

As described above, distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Prospect State Airport pavement network consists of six branches and six sections. A total of 17 sample units were visually inspected in the field. Data from the inspected sample units was input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report presented in Appendix E. Based on the 2024 PCI survey, the area-weighted average PCI for the entire pavement network at Prospect State Airport is approximately 54, which corresponds to a PCI rating of Poor.

To investigate the rate of deterioration of each pavement section, we compared the PCI results from the 2024 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Prospect State Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B: PROSPECT STATE AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01PO	1	9,268	APRON	61	Fair
A02PO	1	64,225	APRON	54	Poor
A03PO	1	7,918	APRON	26	Serious
R02PO	1	201,750	RUNWAY	55	Poor
T01PO	1	1,047	TAXIWAY	28	Very Poor
T02PO	1	1,393	TAXIWAY	0	Failed

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	3	81,411	52
RUNWAY	1	201,750	55
TAXIWAY	2	2,440	12
ALL	6	285,601	54

Abbreviation: PCI = Pavement Condition Index

Table 3B: PROSPECT STATE AIRPORT 2024 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01PO	01	9/1/1988	AC	APRON	8/1/2024	36	61	Fair	100	0	0
A02PO	01	8/1/2001	AC	APRON	8/1/2024	23	54	Poor	71	29	0
A03PO	01	1/1/1988	ST	APRON	8/1/2024	37	26	Very Poor	50	45	5
R02PO	01	9/1/1995	AAC	RUNWAY	8/1/2024	29	55	Poor	70	30	0
T01PO	01	8/1/2001	AC	TAXIWAY	8/1/2024	23	28	Very Poor	74	26	0
T02PO	01	9/1/1999	ST	TAXIWAY	8/1/2024	25	0	Failed	6	94	0

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; ST = surface treated

Table 4B: PROSPECT STATE AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2024 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	2019 Survey				2024 Survey				Rate of Deterioration
				LCD ²	PCI ³	PCI Category	Inspection Date	PCI	PCI Category	Age ⁴	Δ PCI/yr ⁵	
A01PO	01	AC	9,268	9/1/88	53	Poor	5/13/2019	61	Fair	31	1.47	NONE
A02PO	01	AC	64,225	8/1/01	57	Fair	5/13/2019	54	Poor	18	-1	NORMAL
A03PO	01	ST	7,918	1/1/88	23	Serious	5/13/2019	26	Very Poor	31	0.48	NONE
R02PO	01	AAC	201,750	9/1/95	46	Poor	5/13/2019	55	Poor	24	2	NONE
T01PO	01	AC	1,047	8/1/01	50	Poor	5/13/2019	28	Very Poor	18	-4.23	HIGH
T02PO	01	ST	1,393	9/1/99	27	Very Poor	5/13/2019	0	Failed	20	-5	HIGH

Abbreviations:

¹ AC = asphalt concrete; AAC = AC overlaid with AC; ST = surface treatment

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g., AC overlay).

³ PCI = Pavement Condition Index

⁴ Age = Pavement age in years at the time of the PCI survey in 2019

⁵ Δ PCI/yr = Change in PCI points per year between 2019 survey and 2024 survey



APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

FUTURE PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan, this is done with the aid of a prediction model. When an airport pavement management system is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after Pavement Condition Index (PCI) surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing prediction models is as follows:

1. Define the pavement families.
2. Review the data.
3. Conduct a data-outlier analysis.
4. Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at Prospect State Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use four distinct models for the following “families” of pavements at Prospect State Airport. For each model, we reviewed the data to filter out any inconsistent or inaccurate data or any data that falls outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 3C, below.




Figure 1C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 5 ASPHALT CONCRETE APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 5 ASPHALT CONCRETE RUNWAYS




Figure 3C: CONDITION PREDICTION MODEL FOR REGION 2 CATEGORY 5 ASPHALT CONCRETE TAXIWAYS

C.3 CRITICAL PAVEMENT CONDITION INDEX

Each condition-prediction model has an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major maintenance and rehabilitation (M&R) is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Prospect State Airport:

- Runways: 55
- Taxiways/Taxilanes: 50
- Aprons: 45

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for five- and 10-year periods. The projected pavement conditions in five years and 10 years for each pavement section at Prospect State Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition.

This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Prospect State Airport: the time until rehabilitation and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (i.e., a PCI of less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C: PAST, PRESENT, AND FUTURE PCI

Branch ID	Section ID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2019	2024	2029	2034
NETWORK	--	48	54	45	37
A01PO	01	53	61	50	39
A02PO	01	57	54	43	32
A03PO	01	23	26	15	4
R02PO	01	46	55	48	40
T01PO	01	50	28	19	11
T02PO	01	27	0	0	0

Abbreviations: PCI = Pavement Condition Index; -- = no value

Table 2C: PROSPECT STATE AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service Life
A01PO	01	AC	61	6 - 10	45	6 - 10
A02PO	01	AC	54	0 - 5	45	6 - 10
A03PO	01	ST	26	0 - 5	45	0 - 5
R02PO	01	AAC	55	0 - 5	55	6 - 10
T01PO	01	AC	28	0 - 5	50	0 - 5
T02PO	01	ST	0	0 - 5	50	0 - 5

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; ST = surface treatment; M&R = maintenance and rehabilitation

¹ Major M&R Trigger PCI = Critical PCI



APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the maintenance and rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Prospect State Airport pavement network condition over time. We used PAVER v7.1.2 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2025. A backlog elimination analysis scenario was selected to generate a list of surface treatment, rehabilitation, and reconstruction projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- **Reconstruction:** Considered for pavements with a Pavement Condition Index (PCI) less than 40.
- **Rehabilitation (Asphalt Concrete [AC] Overlay):** Considered for pavements between 40 PCI and the critical PCI and for pavements exhibiting significant load-related distresses.
- **Surface Treatment:** Treatments (fog seal, slurry seal, thin AC overlay) are applied to an entire pavement section with the intent of slowing the rate of deterioration.
- **Localized Maintenance:** Maintenance performed on a routine basis, such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the 5-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: MAINTENANCE AND REHABILITATION WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

Distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM International D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in costs for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2019 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Prospect State Airport and information provided by the Oregon Department of Aviation Pavement Maintenance Program project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Prospect State Airport. The costs represent the fully loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D, below.

Table 2D: REGION 2 UNIT COST DATA

Type of M&R	Work Type	Unit Cost per Square Foot
Major M&R	Complete Reconstruction with AC	\$19.05
	Cold Mill and Overlay—2 Inches Thick	\$8.41
Surface Treatment (Global) M&R	Surface Treatment—Slurry Seal	\$0.50
	Surface Treatment—Fog Seal	\$0.33
Localized Preventive M&R	Crack Sealing—AC	\$2.75
	Crack Sealing—PCC	\$17.00
	Wide Crack Repair	\$75.00
	Joint Sealing—PCC	\$12.00
	AC Patching—Full Depth	\$75.00
	PCC Patching—Full Depth	\$140.00

Abbreviations: M&R = Maintenance and Rehabilitation; AC = asphalt concrete; PCC = portland cement concrete

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED SURFACE TREATMENT, REHABILITATION, AND RECONSTRUCTION PROJECTS

Surface treatment, rehabilitation, and reconstruction projects refer to activities such as slurry seal/fog seals, AC overlays, and reconstruction. A list of recommended projects is provided in Table 4D of this appendix.

Table 3D: PROSPECT STATE AIRPORT NETWORK MAINTENANCE REPORT

Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
A01PO	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	33	Ft	\$2.75	\$91	\$1,139
A01PO	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	381	Ft	\$2.75	\$1,048	
A02PO	01	Block Cracking	Medium	Crack Sealing—AC	2,193	Ft	\$2.75	\$6,031	\$67,445
A02PO	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	270	Ft	\$2.75	\$742	
A02PO	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	4,381	Ft	\$2.75	\$12,049	
A02PO	01	Alligator Cracking	Medium	Patching—AC Deep	648	SqFt	\$75.00	\$48,623	
A03PO	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	726	Ft	\$2.75	\$1,997	\$73,190
A03PO	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	39	Ft	\$2.75	\$107	
A03PO	01	Alligator Cracking	Medium	Patching—AC Deep	948	SqFt	\$75.00	\$71,086	
R02PO	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	12,482	Ft	\$2.75	\$34,324	\$144,730
R02PO	01	Long. & Trans. Cracking	Low	Crack Sealing—AC	1,654	Ft	\$2.75	\$4,549	
R02PO	01	Alligator Cracking	Medium	Patching—AC Deep	1,411	SqFt	\$75.00	\$105,856	
T01PO	01	Long. & Trans. Cracking	Medium	Crack Sealing—AC	234	Ft	\$2.75	\$644	\$2,889
T01PO	01	Alligator Cracking	Medium	Patching—AC Deep	30	SqFt	\$75.00	\$2,246	
T02PO	01	Alligator Cracking	High	Patching—AC Deep	1,547	SqFt	\$75.00	\$116,042	\$116,042

Abbreviations:

Long. = longitudinal; Trans. = transverse; AC = asphalt concrete; AAC = AC overlaid with AC; ST = surface treated; Ft = feet; SqFt = square feet

Table 4D: FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2025	T01PO	01	TAXIWAY	AC	28	Reconstruction	1,047	\$19.05	\$19,945
	T02PO	01	TAXIWAY	ST	0	Reconstruction	1,393	\$19.05	\$26,536
2026	R02PO	01	RUNWAY	AAC	55	Overlay	201,750	\$8.41	\$1,696,633
2027	A03PO	01	APRON	ST	26	Reconstruction	7,918	\$19.05	\$150,836
2028	A02PO	01	APRON	AC	54	Overlay	64,225	\$8.41	\$540,105
2029	A01PO	01	APRON	AC	61	Fog Seal	9,268	\$0.33	\$3,058

Abbreviations:

PCI = Pavement Condition Index; AC = asphalt concrete; AAC = AC overlaid with AC; ST = surface treated

Cost Summary	
2025 Total Project Cost	\$46,481
2026 Total Project Cost	\$1,696,633
2027 Total Project Cost	\$150,836
2028 Total Project Cost	\$540,105
2029 Total Project Cost	\$3,058
Total Five-Year Project Cost	\$2,437,115



APPENDIX E

Reinspection Report

Inspection Report

ODAV_2024_12-24-24_10am_AMC

Generated Date12/24/2024

Page 1 of 8

Network:	Prospect			Name:	Prospect State				
Branch:	A01PO		Name:	Apron 01 Prospect		Use:	APRON	Area:	9,268 SqFt
Section:	01	of	1	From:	Runway 02 End		To:	-	Last Const.: 9/1/1988
Surface:	AC	Family:	2024_Region2_Cat 5_Apron_AC		Zone:	64S	Category:	J	Rank: P
Area:	9,268 SqFt		Length:	200 Ft		Width:	70 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	

Section Comments:

Work Date:	9/1/1962	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False
Work Date:	9/1/1962	Work Type:	Surface Course - BST		Code:	SU-SB	Is Major M&R:	True
Work Date:	8/1/1988	Work Type:	New Construction - Initial		Code:	NC-IN	Is Major M&R:	True
Work Date:	9/1/1988	Work Type:	Overlay - AC Thin		Code:	OL-AT	Is Major M&R:	True
Work Date:	9/1/1999	Work Type:	Surface Treatment - Slurry Seal		Code:	ST-SS	Is Major M&R:	False
Work Date:	9/1/1999	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2001	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2006	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False

Last Insp. Date:8/1/2024

TotalSamples:2

Surveyed:2

Conditions: PCI: 61

Inspection Comments:

Sample Number:	01	Type:	R	Area:	5911.00 SqFt	PCI:	68
----------------	----	-------	---	-------	--------------	------	----

Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
48	L & T CR	L	6.00 Ft	0.1	2.5	
48	L & T CR	M	62.00 Ft	1.0	11.5	
50	PATCHING	M	372.00 SqFt	6.3	21.9	
57	WEATHERING	L	5911.00 SqFt	100.0	6.0	

Sample Number:	02	Type:	R	Area:	3357.00 SqFt	PCI:	49
----------------	----	-------	---	-------	--------------	------	----

Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
48	L & T CR	L	27.00 Ft	0.8	4.6	
48	L & T CR	M	246.00 Ft	7.3	31.4	
48	L & T CR	M	73.00 Ft	2.2	16.4	
50	PATCHING	M	486.00 SqFt	14.5	32.8	
57	WEATHERING	L	3357.00 SqFt	100.0	6.0	

Network:	Prospect			Name:	Prospect State							
Branch:	A02PO		Name:	Apron 02 Prospect		Use:	APRON		Area:	64,225 SqFt		
Section:	01	of	1	From:	Taxiway 01, 02			To:	Fence		Last Const.:	8/1/2001
Surface:	AC	Family:	2024_Region2_Cat_5_Apron_AC		Zone:	64S		Category:	J		Rank:	P
Area:	64,225 SqFt		Length:	635 Ft		Width:	115 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1962		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	8/1/2001		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/2006		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/2006		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	6/1/2011		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	6/2/2011		Work Type: Patching - AC Deep				Code:	PA-AD		Is Major M&R:	False	
Last Insp. Date:	8/1/2024		Total Samples:	13		Surveyed:	5					
Conditions:	PCI: 54											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	4993.00 SqFt			PCI:	66			
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
48	L & T CR	L	25.00 Ft	0.5	4.1							
48	L & T CR	M	295.00 Ft	5.9	28.1							
57	WEATHERING	L	4993.00 SqFt	100.0	6.0							
Sample Number:	03	Type:	R	Area:	5000.00 SqFt			PCI:	63			
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
48	L & T CR	M	390.00 Ft	7.8	32.4							
57	WEATHERING	L	5000.00 SqFt	100.0	6.0							
Sample Number:	04	Type:	R	Area:	5000.00 SqFt			PCI:	61			
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
48	L & T CR	L	44.00 Ft	0.9	4.7							
48	L & T CR	M	398.00 Ft	8.0	32.7							
57	WEATHERING	L	5000.00 SqFt	100.0	6.0							
Sample Number:	07	Type:	R	Area:	5000.00 SqFt			PCI:	42			
Sample Comments:												
Distress	Description	Severity	Quantity	Density	Deduct	Comments						
41	ALLIGATOR CR	M	164.00 SqFt	3.3	42.0							
48	L & T CR	L	36.00 Ft	0.7	4.4							
48	L & T CR	M	384.00 Ft	7.7	32.1							
50	PATCHING	L	37.00 SqFt	0.7	3.0							
57	WEATHERING	L	5000.00 SqFt	100.0	6.0							

Sample Number: 08		Type: R	Area: 5000.00 SqFt		PCI: 37	
Sample Comments:						
Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	50.00 SqFt	1.0	29.2	
43	BLOCK CR	M	2800.00 SqFt	56.0	42.6	
48	L & T CR	M	238.00 Ft	4.8	25.0	
57	WEATHERING	L	5000.00 SqFt	100.0	6.0	

Network:	Prospect			Name:	Prospect State						
Branch:	A03PO		Name:	Apron 03 Prospect		Use:	APRON	Area:	7,918 SqFt		
Section:	01	of	1	From:	Runway 20 End			To:	-	Last Const.:	1/1/1988
Surface:	ST	Family:	2024_Region2_Cat 5_Apron_AC		Zone:	64S		Category:	J	Rank:	P
Area:	7,918 SqFt		Length:	200 Ft		Width:	60 Ft				
Slabs:	Slab Length:			Ft	Slab Width:			Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:		0		Lanes:		0	
Section Comments:											
Work Date:	9/1/1962		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	9/2/1962		Work Type: Surface Course - BST				Code:	SU-SB		Is Major M&R: True	
Work Date:	1/1/1988		Work Type: New Construction - Initial				Code:	NC-IN		Is Major M&R: True	
Work Date:	9/1/1999		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/2/1999		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Work Date:	9/1/2006		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	

Last Insp. Date: 8/1/2024		TotalSamples: 2		Surveyed: 2	
Conditions: PCI: 26					
Inspection Comments:					

Sample Number:	01	Type:	R	Area:	4191.00 SqFt	PCI:	29
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	408.00 SqFt	9.7	55.9	
48	L & T CR	L	39.00 Ft	0.9	4.8	
48	L & T CR	M	298.00 Ft	7.1	30.9	
48	L & T CR	M	108.00 Ft	2.6	18.0	
50	PATCHING	M	132.00 SqFt	3.1	15.4	
57	WEATHERING	L	4191.00 SqFt	100.0	6.0	

Sample Number:	02	Type:	R	Area:	3727.00 SqFt	PCI:	22
Sample Comments:							

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	420.00 SqFt	11.3	57.8	
45	DEPRESSION	L	80.00 SqFt	2.1	11.8	
48	L & T CR	M	320.00 Ft	8.6	33.9	
50	PATCHING	M	170.00 SqFt	4.6	18.6	
57	WEATHERING	L	3727.00 SqFt	100.0	6.0	

Network:	Prospect			Name:	Prospect State								
Branch:	R02PO		Name:	Runway 2/20 Prospect		Use:	RUNWAY	Area:	201,750 SqFt				
Section:	01	of	1	From:	Runway 02 End			To:	Runway 20 End		Last Const.:	9/1/1995	
Surface:	AAC		Family:	2024_Region2_Cat 5_Runway_AC		Zone:	64S		Category:	J		Rank:	P
Area:	201,750 SqFt		Length:	4,035 Ft		Width:	50 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	9/1/1962		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False			
Work Date:	9/1/1962		Work Type: Surface Course - BST				Code:	SU-SB		Is Major M&R: True			
Work Date:	9/1/1970		Work Type: Surface Treatment - Chip				Code:	ST-CS		Is Major M&R: True			
Work Date:	9/1/1988		Work Type: Overlay - AC Thin				Code:	OL-AT		Is Major M&R: True			
Work Date:	9/1/1995		Work Type: Overlay - AC Thin				Code:	OL-AT		Is Major M&R: True			
Work Date:	9/1/1999		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False			
Work Date:	9/1/1999		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False			
Work Date:	9/1/2001		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False			
Work Date:	9/1/2006		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False			
Last Insp. Date:	8/1/2024		TotalSamples:	40		Surveyed:		6					
Conditions:	PCI: 55												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	5000.00 SqFt			PCI:	61				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
41	ALLIGATOR CR		M	6.00	SqFt	0.1	11.5						
48	L & T CR		L	30.00	Ft	0.6	4.2						
48	L & T CR		M	110.00	Ft	2.2	16.5						
50	PATCHING		M	380.00	SqFt	7.6	24.1						
57	WEATHERING		L	5000.00	SqFt	100.0	6.0						
Sample Number:	08	Type:	R	Area:	5000.00 SqFt			PCI:	61				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
48	L & T CR		L	26.00	Ft	0.5	4.1						
48	L & T CR		L	98.00	Ft	2.0	7.3						
48	L & T CR		M	113.00	Ft	2.3	16.7						
48	L & T CR		M	100.00	Ft	2.0	15.7						
50	PATCHING		M	266.00	SqFt	5.3	20.1						
57	WEATHERING		L	5000.00	SqFt	100.0	6.0						
Sample Number:	15	Type:	R	Area:	5000.00 SqFt			PCI:	55				
Sample Comments:													
Distress	Description		Severity	Quantity		Density	Deduct	Comments					
48	L & T CR		L	26.00	Ft	0.5	4.1						
48	L & T CR		M	240.00	Ft	4.8	25.1						

48	L & T CR	M	205.00	Ft	4.1	23.1
50	PATCHING	M	90.00	SqFt	1.8	11.8
57	WEATHERING	L	5000.00	SqFt	100.0	6.0

Sample Number: 22 **Type:** R **Area:** 5000.00 SqFt **PCI:** 58
Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
48	L & T CR	L	54.00	Ft	1.1	5.1
48	L & T CR	M	114.00	Ft	2.3	16.8
48	L & T CR	M	221.00	Ft	4.4	24.0
50	PATCHING	M	208.00	SqFt	4.2	17.8
57	WEATHERING	L	5000.00	SqFt	100.0	6.0

Sample Number: 29 **Type:** R **Area:** 5000.00 SqFt **PCI:** 41
Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	170.00	SqFt	3.4	42.5
41	ALLIGATOR CR	M	12.00	SqFt	0.2	16.9
48	L & T CR	L	12.00	Ft	0.2	3.3
48	L & T CR	M	234.00	Ft	4.7	24.8
48	L & T CR	M	113.00	Ft	2.3	16.7
50	PATCHING	M	136.00	SqFt	2.7	14.4
57	WEATHERING	L	5000.00	SqFt	100.0	6.0

Sample Number: 36 **Type:** R **Area:** 5000.00 SqFt **PCI:** 57
Sample Comments:

Distress	Description	Severity	Quantity	Density	Deduct	Comments
48	L & T CR	M	178.00	Ft	3.6	21.4
48	L & T CR	M	228.00	Ft	4.6	24.5
50	PATCHING	M	148.00	SqFt	3.0	15.0
57	WEATHERING	L	5000.00	SqFt	100.0	6.0

Network:	Prospect			Name:	Prospect State						
Branch:	T01PO		Name:	Taxiway 01 Prospect		Use:	TAXIWAY	Area:	1,047 SqFt		
Section:	01	of	1	From:	Runway 2/20		To:	Apron 02	Last Const.:	8/1/2001	
Surface:	AC	Family:	2024_Region2_Cat 5_Taxiway_AC		Zone:	64S	Category:	J	Rank:	P	
Area:	1,047 SqFt		Length:	25 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	9/1/1962		Work Type:	Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	False
Work Date:	8/1/2001		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/2006		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/2006		Work Type:	Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False
Work Date:	6/1/2011		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	8/1/2024		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 28										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	1047.00 SqFt		PCI:	28			
Sample Comments:											

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	M	12.00 SqFt	1.1	30.5	
48	L & T CR	M	234.00 Ft	22.3	51.0	
50	PATCHING	M	136.00 SqFt	13.0	31.2	
57	WEATHERING	L	1047.00 SqFt	100.0	6.0	

Network:	Prospect			Name:	Prospect State							
Branch:	T02PO		Name:	Taxiway 02 Prospect		Use:	TAXIWAY	Area:	1,393 SqFt			
Section:	01	of	1	From:	Runway 2/20		To:	Apron 02	Last Const.:	9/1/1999		
Surface:	ST	Family:	2024_Region2_Cat 5_Taxiway_AC		Zone:	64S	Category:	J	Rank:	P		
Area:	1,393 SqFt		Length:	25 Ft		Width:	45 Ft					
Slabs:	Slab Length:			Ft	Slab Width:			Ft	Joint Length:	Ft		
Shoulder:	Street Type:			Grade:			0	Lanes:	0			
Section Comments:												
Work Date:	9/1/1962		Work Type:				Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False
Work Date:	9/1/1999		Work Type:				Surface Course - BST		Code:	SU-SB	Is Major M&R:	True
Last Insp. Date:	8/1/2024		TotalSamples:		1		Surveyed:		1			
Conditions:	PCI:		0									
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	1393.00 SqFt		PCI:	0		
Sample Comments:												

Distress	Description	Severity	Quantity	Density	Deduct	Comments
41	ALLIGATOR CR	H	1393.00 SqFt	100.0	100.0	
57	WEATHERING	L	1393.00 SqFt	100.0	6.0	



APPENDIX F

Work History Report

12/24/2024

Work History Report

Page 1 of 3

Pavement Database: ODAV_2024_12-24-24_10am_AMC

Network: Prospect State		Branch: A01PO	Apron 01 Prospect	Section: 01	Surface: AC	
L.C.D. 9/1/1988	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 70.00 (Ft)	True Area:	9268 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	circa 2001
9/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1999	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1988	OL-AT	Overlay - AC Thin	0.00	1.00	<input checked="" type="checkbox"/>	
8/1/1988	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1962	SU-SB	Surface Course - BST	0.00	0.75	<input checked="" type="checkbox"/>	
9/1/1962	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Prospect State		Branch: A02PO	Apron 02 Prospect	Section: 01	Surface: AC	
L.C.D. 8/1/2001	Use: APRON	Rank: P	Length: 635.00 (Ft)	Width: 115.00 (Ft)	True Area:	64225 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/2/2011	PA-AD	Patching - AC Deep	0.00	0.00	<input type="checkbox"/>	PMP 2011
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011
9/2/2006	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
8/1/2001	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/1962	BA-AG	Base Course - Aggregate	0.00	0.00	<input type="checkbox"/>	
						Existing gravel apron

Network: Prospect State		Branch: A03PO	Apron 03 Prospect	Section: 01	Surface: ST	
L.C.D. 1/1/1988	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 60.00 (Ft)	True Area:	7918 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/2/1999	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
1/1/1988	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
9/2/1962	SU-SB	Surface Course - BST	0.00	0.75	<input checked="" type="checkbox"/>	
9/1/1962	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

Network: Prospect State		Branch: R02PO	Runway 2/20 Pros	Section: 01	Surface: AAC	
L.C.D. 9/1/1995	Use: RUNWAY	Rank: P	Length: 4,035.00 (Ft)	Width: 50.00 (Ft)	True Area:	201750 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	circa 2001
9/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1999	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1995	OL-AT	Overlay - AC Thin	0.00	1.00	<input checked="" type="checkbox"/>	
9/1/1988	OL-AT	Overlay - AC Thin	0.00	1.00	<input checked="" type="checkbox"/>	
9/1/1970	ST-CS	Surface Treatment - Chip	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1962	SU-SB	Surface Course - BST	0.00	0.75	<input checked="" type="checkbox"/>	
9/1/1962	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	

12/24/2024

Work History Report

Page 2 of 3

Pavement Database: ODAV_2024_12-24-24_10am_AMC

Network: Prospect State		Branch: T01PO		Taxiway 01 Prospe		Section: 01	Surface: AC
L.C.D. 8/1/2001	Use: TAXIWAY	Rank: P	Length: 25.00 (Ft)	Width: 35.00 (Ft)	True Area: 1047 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2011	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2011 Existing gravel apron	
9/2/2006	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>		
9/1/2006	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
8/1/2001	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/1962	BA-AG	Base Course - Aggregate	0.00	0.00	<input type="checkbox"/>		

Network: Prospect State		Branch: T02PO		Taxiway 02 Prospe		Section: 01	Surface: ST
L.C.D. 9/1/1999	Use: TAXIWAY	Rank: P	Length: 25.00 (Ft)	Width: 45.00 (Ft)	True Area: 1393 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/1999	SU-SB	Surface Course - BST	0.00	0.00	<input checked="" type="checkbox"/>	Slurry seal on existing gravel	
9/1/1962	BA-AG	Base Course - Aggregate	0.00	0.00	<input type="checkbox"/>	Existing gravel apron	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	6	285,601.00	3.00	3.00
Crack Sealing - AC	12	779,434.01	0.04	0.05
New Construction - AC	2	65,272.00	2.00	0.00
New Construction - Initial	2	17,186.00	0.00	0.00
Overlay - AC Thin	3	412,768.00	1.00	0.00
Patching - AC Deep	1	64,225.00	0.00	0.00
Surface Course - BST	4	220,329.00	0.56	0.32
Surface Treatment - Chip	1	201,750.00	0.00	0.00
Surface Treatment - Slurry Seal	5	284,208.00	0.30	0.24