2022 ODA Pavement Evaluation Program Lake Billy Chinook State Airport

Culver, Oregon

December 30, 2022 (REVISED: 01/24/2023)

Prepared for

State of Oregon Department of Aviation 3040 25th Street SE Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100 Tigard, OR 97224-7661 (503) 641-3478 | www.gri.com



TABLE OF CONTENTS

1 OV	OVERVIEW						
2 PA	VEMENT INVENTORY						
3 PA	VEMENT CONDITION INSPECTION RESULTS						
3.1 Inti	roduction						
3.2 Pa\	vement Condition Index Survey Results						
	TURE PAVEMENT CONDITION ANALYSIS						
4.1 Inti	roduction						
	1.2 Future Condition Analysis						
	nctional Remaining Life						
	AINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS						
	5.1 Introduction						
	commended Localized Maintenance						
	bbal Maintenance and Rehabilitation Plan						
	AITATIONS						
6 LIN	////TATIONS						
TABLES							
Table 3-1:	ASTM PCI Rating Scale						
Table 5-1:	•						
Table 5-2:	Global Maintenance and Rehabilitation Quantities						
FIGURES							
Figure 2.1:	, , ,						
Figure 2.2:							
Figure 2.3:	·						
Figure 2.4: Figure 3.1:	·						
Figure 3.1:	,						
	Area						
Figure 4.1	Future Pavement Condition						
Figure 5.1:	· · · · · · · · · · · · · · · · · · ·						
	Distribution Based on PCI						
Figure 5.2:	5-Year Pavement Management Plan						
APPENDI	CES						
Appendix A	A: Pavement Inventory Report and Maps						
Appendix I	B: Pavement Condition Index Survey Results						
Appendix (C: Future Pavement Condition Analysis						
Appendix I	D: Unit Cost Data and Maintenance and Rehabilitation Plan						



APPENDICES (continued)

Appendix E: Re-inspection Report
Appendix F: Work History Report



1 **OVERVIEW**

GRI assisted with updating the Oregon Department of Aviation (ODA) airport pavement management system and developing a five-year plan for global maintenance and rehabilitation (M&R) and preservation work for the Lake Billy Chinook State Airport in Culver, Oregon. This project was implemented as a part of the ODA and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Lake Billy Chinook Airport in 2022 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Lake Billy Chinook Airport is located in Culver, Oregon, and is owned and operated by Lake Billy Chinook Airport Development Corporation. The airport consists of one runway that serves a variety of general aviation aircraft. The general location of the airport is shown below on the Lake Billy Chinook Airport Location Map, Figure 2.1.



Figure 2.1 – LAKE BILLY CHINOOK AIRPORT LOCATION MAP



Lake Billy Chinook Airport contains one runway and two aprons. The airside pavements at Lake Billy Chinook Airport are surfaced with asphalt concrete (AC). The airport pavements, delineated by surface type and branch use, are shown on the Lake Billy Chinook Airport Percent of Pavement Area by Surface Type, Figure 2.2 and the Lake Billy Chinook Airport Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on the Lake Billy Chinook Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the Work History Report, Appendix F.




Figure 2.2 – LAKE BILLY CHINOOK AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE








Figure 2.3 – LAKE BILLY CHINOOK AIRPORT PAVEMENT AREA BY BRANCH USE







LAKE BILLY CHINOOK AIRPORT PAVEMENT INVENTORY

DEC. 2022 JOB NO. 6593-B FIG. 2.4



3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Lake Billy Chinook Airport in March 2022. The 2022 survey work was performed on sections that had not been previously inspected. GRI performed the 2022 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340, and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

PCI Color **PCI** Legend **PCI Rating and Definition** Range 86 -GOOD: Pavement has minor or no distresses and should require only routine maintenance. 100 SATISFACTORY: Pavement has scattered low-severity distresses that should require only 71 - 85routine maintenance. FAIR: Pavement has a combination of generally low- and medium-severity distresses. 56 - 70Maintenance and repair needs may range from routine to major. POOR: Pavement has low-, medium-, and high-severity distresses that probably cause 41 - 55some operational problems. M&R needs will be major. VERY POOR: Pavement has predominantly medium- and high-severity distresses that 26 - 40cause considerable maintenance and operational problems. M&R needs will be major. SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; 11 - 25immediate repairs are needed. FAILED: Pavement deterioration has progressed to the point that safe aircraft operations 0 - 10are no longer possible; complete reconstruction is required.

Table 3-1: ASTM PCI RATING SCALE

3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Lake Billy Chinook Airport is approximately 96. The section PCIs ranged from a low of 86 to a high of 97. The primary distresses observed during the inspection were longitudinal and transverse cracking. Section PCIs following our pavement survey are displayed below spatially on the 2022 PCI Survey Results, Figure 3.1.



(11 - 25) SERIOUS

(0 - 10) FAILED

DEC. 2022

JOB NO. 6593-B

FIG. 3.1



The condition distribution of the network by the percent of total pavement area is provided on the Lake Billy Chinook Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively. The Re-Inspection Report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2 – LAKE BILLY CHINOOK AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA



4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Lake Billy Chinook Airport are displayed on Figures 1C and 2C in Appendix C.

4.2 Future Condition Analysis


Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 96 to a value of 85 in the year 2027 and 73 in year the 2032 if no maintenance or rehabilitation work is performed. The projected pavement condition in five years and ten years for each pavement section at Lake Billy Chinook Airport is displayed spatially on the Future Pavement Condition, Figure 4.1 and listed in Table 1C in Appendix C, along with the present PCI values for the pavement network.

4.3 Functional Remaining Life

The functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Lake Billy Chinook Airport. The first type of functional remaining life is the time until rehabilitation such as an overlay is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.


The two types of functional remaining life for each section at Lake Billy Chinook Airport are summarized in Table 2C in Appendix C.



(86 - 100) GOOD (71 - 85) SATISFACTORY (56 - 70) FAIR (41 - 55) POOR (26 - 40) VERY POOR

(11 - 25) SERIOUS

(0 - 10) FAILED





FUTURE PAVEMENT CONDITION LAKE BILLY CHINOOK AIRPORT

FIG. 4.1

DEC. 2022 JOB NO. 6593-B



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, global maintenance, and rehabilitation needs. Details of our M&R work priority and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

Based on the 2022 PCI-survey results, the Lake Billy Chinook Airport Pavement Network General Treatment Type Distribution Based on PCI, Figure 5.1 displays a breakdown of the Lake Billy Chinook Airport network pavement condition by percent of area and general M&R treatment categories. Approximately 100% of the area requires preservation treatments with no sections requiring rehabilitation or reconstruction.




Figure 5.1 – LAKE BILLY CHINOOK AIRPORT PAVEMENT NETWORK GENERAL TREATMENT TYPE DISTRIBUTION BASED ON PCI

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the global maintenance and rehabilitation projects associated with the five-year global



maintenance and rehabilitation work plan. A summary of the approximate total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance	Approximate
Operation	Quantity
Asphalt Concrete Crack Sealing	249 linear feet

5.3 Global Maintenance and Rehabilitation Plan


To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of global M&R projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of global M&R quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the 5-Year Pavement Management Plan Lake Billy Chinook Airport, Figure 5.2. The complete list of recommended global M&R projects is presented in Table 4D in Appendix D.

Table 5-2: GLOBAL MAINTENANCE AND REHABILITATION QUANTITIES

Global Maintenance or Rehabilitation Operation	Quantity, square feet
Fog Seal	7,866
Slurry Seal	83,068







LAKE BILLY CHINOOK AIRPORT

DEC. 2022 JOB NO. 6593-B

FIG. 5.2



6 LIMITATIONS

This report has been prepared to assist the ODA with pavement-related project planning for the Lake Billy Chinook Airport. The scope is limited to the specific pavement areas described herein. The conclusions and recommendations provided in this report are based on information provided by ODA, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The global maintenance and rehabilitation recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given within this report. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Lake Billy Chinook Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,

PROFF

RENEWS: 06/2023

Lindsi A. Hammond, PE

Principal

Matthew A. Haynes, PE

Project Engineer

This document has been submitted electronically.



APPENDIX A

Pavement Inventory Reports and Maps



APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Lake Billy Chinook Airport is located in Culver, Oregon, and is owned and operated by the Lake Billy Chinook Airport Development Corporation. The pavement network/facilities at Lake Billy Chinook Airport serve a variety of general aviation aircraft. Lake Billy Chinook Airport consists of one runway and two aprons. The airside pavements at Lake Billy Chinook Airport are comprised of asphalt concrete (AC).

The current airport pavement management system (APMS) network at Lake Billy Chinook Airport has an approximate area of 91,000 square feet of paved airside facilities. Since no previous inspection had been conducted at Lake Billy Chinook Airport, we divided the pavement network into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of a pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Lake Billy Chinook Airport contains three branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as "a contiguous pavement area having uniform construction, maintenance, usage history, and condition." All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Lake Billy Chinook Airport contains 3 sections that are managed by the Lake Billy Chinook Airport Development Corporation, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement's prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are



ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet and 20 slabs \pm 8 slabs for rigid pavements. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(e^2/4\right)(N-1)+s^2}$$
 (Equation 1)

where:

n = number of sample units to be inspected

N = total number of samples in the pavement sections

e = allowable error

s = section standard deviation

For the 2022 Lake Billy Chinook Airport PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Lake Billy Chinook Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A – LAKE BILLY CHINOOK AIRPORT PAVEMENT BRANCHES

Facility Designation			Approximate Area,
(Branch ID)	Branch Name	Number of Sections	square feet
A01BC	Apron 01	1	3,950
A02BC	Apron 02	1	3,916
R16BC	Runway 16/34	1	83,068



Table 2A - LAKE BILLY CHINOOK AIRPORT CURRENT PAVEMENT INVENTORY

	Approximate Area, square										
BranchID	Branch Name	Branch Use	SectionID	From	То	Rank	Length, feet	Width, feet	feet	LCD ¹	Surface Type
A01BC	Apron 01	APRON	01	R16BC	End	S	45	100	3,950	Unknown	AC
A02BC	Apron 02	APRON	01	R16BC	End	S	40	100	3,916	Unknown	AC
R16BC	Runway 16/34	RUNWAY	01	A01BC-01	A02BC-01	Р	2,600	32	83,068	Unknown	AC

Abbreviations:

P = Primary pavement, S = Secondary pavement, AC = Asphalt Concrete

Notes:

¹ LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)






Table 3A: EXAMPLE SAMPLE RATES FOR AC PAVEMENTS


AC Sampling Rate							
Total Number of Sample Units, N	Sample Units to Survey, n						
1	1						
2-3	2						
4-6	3						
7-13	4						
14-38	5						
39+	6						

Note: AC = Asphalt Concrete











SAMPLE UNIT LAYOUT LAKE BILLY CHINOOK AIRPORT

DEC. 2022

JOB NO. 6593-B



APPENDIX B

Pavement Condition Index Survey Results



APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE PAVEMENT

	Flexible Pavement	
PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load
42	Bleeding	Other
43	Block Cracking	Climate/ Durability
44	Corrugation	Other
45	Depression	Other
46	Jet Blast	Other
47	Joint Reflection Cracking	Climate/ Durability
48	Longitudinal & Transverse Cracking	Climate/ Durability
49	Oil Spillage	Other
50	Patching	Climate/ Durability
51	Polished Aggregate	Other
52	Raveling	Climate/ Durability
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability



To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as "additional"— defined as nonrepresentative instead of random— are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 and are based on ASTM D5340.

Section 4.1 of ASTM D5340 governing PCI surveys offers this caution:

"The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure the structural capacity; neither does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures."

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- Load-related: Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking. Rigid pavement distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping, and joint spalling.
- Climate- and durability-related: Flexible pavement distresses include bleeding, block
 cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling,
 and raveling/weathering. Rigid pavement distresses include blow-ups, durability
 cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint
 and corner spalling.



- Moisture- and drainage-related: Flexible pavement distresses include alligator/ fatigue cracking, depressions, potholes, and swelling. Rigid pavement distresses include corner breaks, divided slabs, and pumping.
- Other factors: Oil spillage, jet blast erosion, bleeding, patching, and concrete slab joint faulting.

As described above, a distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, a distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Lake Billy Chinook Airport pavement network consists of 3 branches and 3 sections. A total of 7 sample units were visually inspected in the field. Data from the inspected sample units were input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2022 PCI survey, the area-weighted average PCI for the entire pavement network at Lake Billy Chinook Airport is approximately 96, which corresponds to a PCI rating of Good.

Table 2B - LAKE BILLY CHINOOK AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01BC	1	3,950	APRON	96	Good
A02BC	1	3,916	APRON	86	Good
R16BC	1	83,068	RUNWAY	97	Good

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	2	7,866	91
RUNWAY	1	83,068	97
ALL	3	90,934	96



Table 3B - LAKE BILLY CHINOOK AIRPORT 2022 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01BC	01	Unknown	AC	APRON	3/1/2022	Unknown	96	Good	100	0	0
A02BC	01	Unknown	AC	APRON	3/1/2022	Unknown	86	Good	100	0	0
R16BC	01	Unknown	AC	RUNWAY	3/1/2022	Unknown	97	Good	100	0	0

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete





APPENDIX C

Future Pavement Condition Analysis



APPENDIX C

FUTURE PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the "family" model procedure. A pavement "family" is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1. Define the pavement families.
- 2. Review the data.
- 3. Conduct a data outlier analysis.
- 4. Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement "family" at Lake Billy Chinook Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use two distinct models for the following "families" of pavements at Lake Billy Chinook Airport. For each model, we reviewed the data in order to filter out any suspicious or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a fourth-order, polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each "family." Our condition prediction models for each "family" are provided on Figures 1C and 2C below.






Figure 1C – CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 5 AC APRONS




Figure 2C – CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 5 AC RUNWAYS



C.3 CRITICAL PCI

Each of the condition-prediction models have an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Lake Billy Chinook Airport:

- Runways 55
- Taxiways/Taxilanes 50
- Aprons 45

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Lake Billy Chinook Airport are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Lake Billy Chinook Airport, the time until rehabilitation, and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C - PRESENT AND FUTURE PCI

		Current PCI	<u>Predicted</u>	Future PCI
BranchID	SectionID	2022	2027	2032
A01BC	01	96	84	72
A02BC	01	86	74	62
R16BC	01	97	85	73

Abbreviations:

PCI = Pavement Condition Index



Table 2C - LAKE BILLY CHINOOK AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

		Surface	Current	Years to Major	Major M&R	Years to End of
Branch ID	Section ID	Туре	PCI	M&R	Trigger PCI ¹	Functional Service
A01BC	01	AC	96	> 20	45	> 20
A02BC	01	AC	86	16 - 20	45	> 20
R16BC	01	AC	97	16 - 20	55	> 20

Abbreviations:

M&R = Maintenance and Rehabilitation, AC = Asphalt Concrete



¹ Major M&R Trigger PCI = Critical PCI



APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan



APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Lake Billy Chinook Airport pavement network condition over time. We used PAVER v7 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2023. A backlog elimination analysis scenario was selected to generate a list of global maintenance and rehabilitation projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction Considered for pavements with a PCI less than 40.
- Flexible Overlay Considered for pavements between 40 PCI and the critical PCI, and for pavements exhibiting significant load-related distresses.
- Global Maintenance Treatments (fog seal, slurry seal, thin AC overlay) applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance Maintenance performed on a routine basis such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use



to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

	Section Rank							
Branch Use	Primary	Secondary	Tertiary					
RUNWAY	1	3	6					
TAXIWAY	2	5	8					
APRON	4	7	9					

D.2 MAINTENANCE POLICIES AND UNIT COSTS

The distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in cost for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the bid tabulations for recent projects within the vicinity of Lake Billy Chinook Airport and information provided by the project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Lake Billy Chinook Airport. The costs represent the fully-loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: LAKE BILLY CHINOOK AIRPORT UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Maior MARID	Complete Reconstruction with AC	\$11.10	Sq Ft
Major M&R	Cold Mill and Overlay – 3 Inches Thick	\$4.90	Sq Ft
Clabal MOD	Surface Treatment - Slurry Seal	\$0.33	Sq Ft
Global M&R	Surface Treatment - Fog Seal	\$0.20	Sq Ft
	Crack Sealing - AC	\$2.00	Ft
	Crack Sealing - PCC	\$15.00	Ft
Localized Preventive M&R	Crack Sealing – Wide Cracks	\$33.00	Ft
Fieventive Mak	AC Patching – Full Depth	\$50.00	Sq Ft
	PCC Patching – Full Depth	\$100.00	Sq Ft



D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED GLOBAL MAINTENANCE AND REHABILITATION PROJECTS

Global maintenance and rehabilitation projects refer to activities such as slurry seal and thin AC overlays, as well as thick AC overlays and reconstruction. A list of recommended global M&R activities is provided in Table 4D of this appendix.

Table 3D - LAKE BILLY CHINOOK AIRPORT NETWORK MAINTENANCE REPORT

Network	Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
LakeBilly	A01BC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	14	Ft	\$2.00	\$28	\$28
LakeBilly	A02BC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	60	Ft	\$2.00	\$120	\$120
LakeBilly	R16BC	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	19	Ft	\$2.00	\$37	- \$349
LakeBilly	R16BC	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	156	Ft	\$2.00	\$312	\$549

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; Ft = Feet



Table 4D - FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2025	A01BC	01	APRON	AC	96	Fog Seal	3,950	\$0.20	\$790
2025	A02BC	01	APRON	AC	86	Fog Seal	3,916	\$0.20	\$783
2027	R16BC	01	RUNWAY	AC	97	Slurry Seal	83,068	\$0.33	\$27,413

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

Cost Summary	
2023 Total Project Cost	\$0
2024 Total Project Cost	\$0
2025 Total Project Cost	\$1,573
2026 Total Project Cost	\$0
2027 Total Project Cost	\$27,413
Total 5-Year Project Cost	\$28,986





APPENDIX E

Re-Inspection Report

Re-Inspection Report

ODA_WOC3_9-1-2022_PostBendAnalysis

Generated Date 9/30/2022

Generated Date		9/30/2022						
Network: LakeBil	ly			Name:	Lake Billy Chino	ok State Airport		
Branch: A01BC		Name:	Apron 0	1	Use:	APRON	Area:	3,950 SqFt
Section: 01	0:	f 1 Fro	m: R	16BC		To: End		Last Const.: 1/1/1900
Surface: AC	Family:	2022_Mountain_C pron_AC/AAC	Cat4/5_A	Zone:		Category:		Rank: S
Area:	3,950 SqFt	Length:		45 Ft	Width:	100 Ft		
Slabs:	Slab Len	igth:	Ft	Slab Wid	th:	Ft	Joint Length:	Ft
Shoulder:	Street T	ype:		Grade:	0		Lanes: 0	
Section Comments:								
Work Date: 1/1/1900	W	ork Type: New Co	nstruction	- Initial	Co	ode: NU-IN	Is Major	M&R: True
Last Insp. Date: 3/1/	2022	TotalSam	ples: 1		Surveyed	d: 1		
Conditions: PCI:	96							

Conditions: PCI: 96 **Inspection Comments:**

Sample Number: 01 Type: R Area: 3950.00 SqFt PCI: 96

Sample Comments:

48 L & T CR L 14.00 Ft

Lake Billy Chinook State Airport Network: LakeBilly Name: **Branch:** A02BC Name: Apron 02 Use: APRON 3,916 SqFt Area: Section: 01 of 1 From: R16BC To: End **Last Const.:** 1/1/1900 Surface: ACFamily: 2022_Mountain_Cat4/5_A Zone: Category: Rank: S pron_AC/AAC Width: 100 Ft 3,916 SqFt Length: 40 Ft Area: Ft Ft Slabs: Slab Length: Slab Width: Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Type: New Construction - Initial Work Date: 1/1/1900 Code: NU-IN Is Major M&R: True **Last Insp. Date:** 3/1/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 01 Type: R Area: 3916.00 SqFt **PCI:** 86 **Sample Comments:** 48 L & T CR M 44.00 Ft 48 L & T CR M 16.00 Ft

Network: LakeBilly		Name	: Lake Billy Chino	ok State Airport		
Branch: R16BC	Name	: Runway 16/34	Use:	RUNWAY	Area:	83,068 SqFt
Section: 01	of 1	From: A01BC-0	1	To: A02BC-01		Last Const.: 1/1/1900
Surface: AC	Family: 2022_Mot W_AC/A	untain_Cat4/5_R Zone: AC		Category:		Rank: P
Area: 83,00	68 SqFt Leng	9th: 2,600 Ft	Width:	32 Ft		
Slabs:	Slab Length:	Ft S	Slab Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	(Grade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1900	Work Type: 1	New Construction - Initia	Co	ode: NU-IN	Is Major I	M&R: True
Last Insp. Date: 3/1/2022	To	talSamples: 18	Surveye	d: 5		
Conditions: PCI: 97						
Inspection Comments:						
Sample Number: 01	Type: R	Area:	4800.00 SqFt	PCI: 100		
Sample Comments:						
<no distress=""></no>						
Sample Number: 05	Type: R	Area:	4800.00 SqFt	PCI: 96		
Sample Comments:						
48 L & T CR	L	24.00 Ft				
Sample Number: 09	Type: R	Area:	4800.00 SqFt	PCI: 100		
Sample Comments:						
<no distress=""></no>						
Sample Number: 13	Type: R	Area:	4800.00 SqFt	PCI: 92		
Sample Comments:						
48 L & T CR 48 L & T CR	M L	5.00 Ft 18.00 Ft				
Sample Number: 17	Type: R	Area:	3200.00 SqFt	PCI: 100		
Sample Comments:	- -		<u>*</u>			

<No Distress>



APPENDIX F

Work History Report

Work History Report

Page 1 of 2

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network: Lake Billy Chinook St			Branch: A01BC Apron 01			Section: 01		Surface:AC		
L.C.D. 1/1/1900 Use: APRON			Rank: S	Length:	45.00 (F	t) Wi	dth: 100.0	0 (Ft)	True Area: 3950.000001 (SqFt	
Work D	ate	Vork Code	Work l	Description	Cost		ckness (in)	Major M&R	Comments	
1/1/1900	N	U-IN	New Construc	ction - Initial	(0.00	0.00	>		

Network: Lake Billy Chinook St				Branch: A02BC	Apron	02	Section:	01 Surface:AC
L.C.D. 1/1/1900 Use: APRON				Rank: S L	ength: 40	.00 (Ft) W	idth: 100.0	00 (Ft) True Area: 3916.000001 (SqFt
	Work Date	Work Code	Work 1	Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/1900	NU-IN	New Construc	ction - Initial	0.00	0.00	V :	

	Network:	Lake Billy	Chinook St	Branch: R16BC	Runwa	ay 16/34	Section:	01	Surface:AC
l	L.C.D. 1/1/1900 Use: RUNWAY Rank: P Length: 2,600.00 (Ft) Width: 32.00 (Ft) True Area: 83068.00002 (SqFt								
	Work Date	te Work Code Work		Description	Cost	Thickness (in)	Major M&R		Comments
	1/1/1900	NU-IN	New Construc	tion - Initial	0.00	0.00	.		

Pavement Management System PAVER 7.0 TM

Page 2 of 2

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
New Construction - Initial	3	90,934.00	0.00	0.00

Pavement Management System PAVER 7.0 TM