2022 ODA Pavement Evaluation Program Sunriver Airport

Sunriver, Oregon

December 30, 2022 (REVISED: 01/24/2023)

Prepared for

State of Oregon Department of Aviation 3040 25th Street SE Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100 Tigard, OR 97224-7661 (503) 641-3478 | www.gri.com



TABLE OF CONTENTS

1	OVER	VIEW	1
2	PAVE	MENT INVENTORY	1
3	PAVE	MENT CONDITION INSPECTION RESULTS	4
	3.1 Introd	uction	4
	3.2 Pavem	ent Condition Index Survey Results	5
4	FUTUI	RE PAVEMENT CONDITION ANALYSIS	6
	4.1 Introd	uction	6
	4.2 Future	Condition Analysis	6
	4.3 Functi	onal Remaining Life	7
5	MAIN	TENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	8
	5.1 Introd	uction	8
	5.2 Recom	nmended Localized Maintenance	8
	5.3 Global	Maintenance and Rehabilitation Plan	9
6	LIMIT	ATIONS	10
Tak Tak Fig Fig Fig Fig Fig Fig Fig	SURES OURES OURES OURES OURE 2.1: OURE 2.2: OURE 2.3: OURE 2.4: OURE 3.1: OURE 3.1: OURE 3.1: OURE 3.1: OURE 3.2: OURE 3.1: OURE 5.1: OURE 5.1:	ASTM PCI Rating Scale Localized Maintenance Quantities Global Maintenance and Rehabilitation Quantities Sunriver Airport Location Map Sunriver Airport Pavement Area by Surface Type Sunriver Airport Pavement Area by Branch Use Sunriver Airport Pavement Inventory 2022 PCI Survey Results Sunriver Airport Pavement Condition Rating by Percent of Pavement Area Future Pavement Condition Sunriver Airport Pavement Network General Treatment Type Distribution Based on PCI 5-Year Pavement Management Plan	Ł
ΑP	PENDICE	S	
Ар Ар Ар Ар	pendix A: pendix B: pendix C: pendix D: pendix E:	Pavement Inventory Report and Maps Pavement Condition Index Survey Results Future Pavement Condition Analysis Unit Cost Data and Maintenance and Rehabilitation Plan Re-Inspection Report	



APPENDICES (continued)

Appendix F: Work History Report



1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODA) airport pavement management system and developing a five-year plan for global maintenance and rehabilitation (M&R) and preservation work for the Sunriver Airport in Sunriver, Oregon. This project was implemented as a part of the ODA and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at Sunriver Airport in 2022 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

Sunriver Airport is located in Sunriver, Oregon, and is owned and operated by Sunriver Resort. The airport consists of one runway that serves a variety of general aviation and air taxi aircraft. The general location of the airport is shown on the Sunriver Airport Location Map, Figure 2.1.





Figure 2.1 - SUNRIVER AIRPORT LOCATION MAP

Sunriver Airport contains one runway, one primary parallel taxiway, and multiple connector taxiways and aprons. The airside pavements at Sunriver Airport are comprised of asphalt concrete (AC) and portland cement concrete (PCC) pavements. The airport pavements, delineated by surface type and branch use, are shown on the Sunriver Airport Pavement Area by Surface Type, Figure 2.2 and the Sunriver Airport Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on the Sunriver Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the Work History Report, Appendix F.






Figure 2.2 – SUNRIVER AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE






Figure 2.3 – SUNRIVER AIRPORT PAVEMENT AREA BY BRANCH USE



Abbreviations: AC = Asphalt Concrete; PCC = Portland Cement Concrete; Cr. = Crushed; Agg. = Aggregate; est. = Estimated





SUNRIVER AIRPORT PAVEMENT INVENTORY

DEC. 2022 JOB NO. 6593-B FIG. 2.4



3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at Sunriver Airport in March 2022. The 2022 survey work was performed on sections last inspected in 2017 in order to update the Sunriver Airport inspection data. GRI performed the 2022 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340, and further discussed in Appendix B of this report.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible and rigid pavement is provided in Appendix B and summarized in Table 1B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.


Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.




3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at Sunriver Airport is approximately 84. The section PCIs ranged from a low of 57 to a high of 100. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, and patching for AC-surfaced pavements, and spalling, linear cracking, shrinkage cracking, and faulting for PCC-surfaced pavements. Section PCIs following our pavement survey are displayed below spatially on the 2022 PCI Survey Results, Figure 3.1. Section A01SU-05 was not surveyed due to obstructions.





(0 - 10) FAILED



2022 PCI SURVEY RESULTS SUNRIVER AIRPORT

DEC. 2022 JOB NO. 6593-E

JOB NO. 6593-B FIG. 3.1



The condition distribution of the network by the percent of total pavement area is provided on the Sunriver Airport Pavement Condition Rating by Percent of Pavement Area, Figure 3.2. A summary of the pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2022 inspection is provided in Table 4B in Appendix B. The reinspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2 – SUNRIVER AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF PAVEMENT AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for Sunriver Airport are displayed on Figures 1C through 3C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we project the PCI to decrease from a current value of 84 to a value of 72 in the year 2027




and 61 in the year 2032, if no maintenance or rehabilitation work is performed. The projected pavement condition in 5 years and 10 years for each pavement section at Sunriver Airport is displayed spatially on the Future Pavement Condition, Figure 4.1 and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.

4.3 Functional Remaining Life

The functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Sunriver Airport. The first type of functional remaining life is the time until rehabilitation such as an overlay is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.


The two types of functional remaining life for each section at Sunriver Airport are summarized in Table 2C in Appendix C.



SECTION PCI







FUTURE PAVEMENT CONDITION SUNRIVER AIRPORT

DEC. 2022 JOB NO. 6593-B FIG. 4.1



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated Maintenance and Rehabilitation (M&R) needs, as determined from the PAVER analysis results, in order to develop localized maintenance, global maintenance, and rehabilitation needs. Details of our M&R work priority and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

Based on the 2022 PCI-survey results, the Sunriver Airport Pavement Network General Treatment Type Distribution Based on PCI, Figure 5.1 displays a breakdown of the Sunriver Airport network pavement condition by percent of pavement area and general M&R treatment categories. Approximately 65%, 35%, and 0% of the area require preservation treatments, rehabilitation, and reconstruction, respectively.




Figure 5.1 – SUNRIVER AIRPORT PAVEMENT NETWORK GENERAL TREATMENT TYPE DISTRIBUTION BASED ON PCI

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the global maintenance and rehabilitation projects associated with the five-year global



maintenance and rehabilitation work plan. A summary of the approximate total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Approximate Quantity	
Asphalt Concrete Crack Sealing	21,218 linear feet	
Portland Cement Concrete Crack Sealing	150 linear feet	
Asphalt Concrete Full-Depth Patching	6,805 square feet	

5.3 Global Maintenance and Rehabilitation Plan

To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of global M&R projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of global M&R quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the 5-Year Pavement Management Plan, Figure 5.2. The complete list of recommended global M&R projects is presented in Table 4D in Appendix D.

Table 5-2: GLOBAL MAINTENANCE AND REHABILITATION (M&R) QUANTITIES

Global Maintenance or Rehabilitation Operation	Quantity, square feet
Overlay	409,820
Fog Seal	7,016
Slurry Seal	80,173





ROUTINE MAINTENANCE

5-YEAR PAVEMENT MANAGEMENT PLAN SUNRIVER AIRPORT

DEC. 2022 JOB NO. 6593-B

FIG. 5.2



6 LIMITATIONS

This report has been prepared to assist the Oregon Department of Aviation (ODA) with pavement-related project planning for the Sunriver Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODA, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The global maintenance and rehabilitation recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given herein. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If Sunriver Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,

PROFE

RENEWS: 06/2023

Lindsi A. Hammond, PE

Principal

Matthew A. Haynes, PE Project Engineer

This document has been submitted electronically.



APPENDIX A

Pavement Inventory Reports and Maps



APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

Sunriver Airport is located in Sunriver, Oregon, and is owned and operated by Sunriver Resort. The pavement network/facilities at Sunriver Airport serve a variety of general aviation and air taxi aircraft. Sunriver Airport consists of one runway, one primary parallel taxiway, and multiple connector taxiways and aprons. The airside pavements at Sunriver Airport are comprised of asphalt concrete (AC) and portland cement concrete (PCC) pavements.

The current airport pavement management system (APMS) network at Sunriver Airport has an approximate area of 1,280,000 square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of a pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for Sunriver Airport contains 11 branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as "a contiguous pavement area having uniform construction, maintenance, usage history, and condition." All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for Sunriver Airport contains 24 sections that are managed by Sunriver Resort, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement's prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are



ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet and 20 slabs ± 8 slabs for rigid pavements. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(e^2/4\right)(N-1)+s^2}$$
 (Equation 1)

where:

n = number of sample units to be inspected

N = total number of samples in the pavement sections

e = allowable error

s = section standard deviation

For the 2022 Sunriver Airport PCI survey, Table 3A on the next page was used as a guideline in developing sampling rates for flexible and rigid pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at Sunriver Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A – SUNRIVER AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01SU	Apron 01 Sunriver	6	488,849
A02SU	Apron 02 Sunriver	1	7,016
R18SU	Runway 18/36 Sunriver	1	409,820
T01SU	Taxiway 01 Sunriver	2	217,530
T02SU	Taxiway 02 Sunriver	1	11,900
T03SU	Taxiway 03 Sunriver	1	14,230
T04SU	Taxiway 04 Sunriver	4	19,210
T05SU	Taxiway 05 Sunriver	1	13,690
T06SU	Taxiway 06 Sunriver	1	13,970
T07SU	Taxiway 07 Sunriver	1	7,431
THANGARSU	T-Hangar Taxiways Sunriver	5	76,038



Table 2A - SUNRIVER AIRPORT CURRENT PAVEMENT INVENTORY

									Approximate Area, square		
BranchID	Branch Name	Branch Use	SectionID	From	То	Rank	Length, feet	Width, feet	feet	LCD	Surface Type
A01SU	Apron 01 Sunriver	APRON	01	T04SU-01	A01SU-03	Р	625	175	76,472	7/1/2020	AC
A01SU	Apron 01 Sunriver	APRON	02	A01SU-01	A01SU-01	Р	300	67	20,575	7/1/2020	PCC
A01SU	Apron 01 Sunriver	APRON	03	A01SU-01	T01SU-02	Р	925	400	349,900	7/1/2020	AC
A01SU	Apron 01 Sunriver	APRON	04	A01SU-03	W. Edge	Р	130	150	19,409	7/1/2020	PCC
A01SU	Apron 01 Sunriver	APRON	05	A01SU-04	East edge of PCC	Р	275	75	20,625	7/1/2020	PCC
A01SU	Apron 01 Sunriver	APRON	06	A01SU-04	End	Р	90	20	1,868	7/1/2020	PCC
A02SU	Apron 02 Sunriver	APRON	01	T07SU-01	R18SU-01	Р	100	70	7,016	7/1/2019	AC
R18SU	Runway 18/36 Sunriver	RUNWAY	01	R36 End	R18SU-02	Р	5,460	75	409,820	9/2/2009	AC
T01SU	Taxiway 01 Sunriver	TAXIWAY	01	R36 End	T03SU-01	Р	1,880	35	76,490	7/1/2019	AC
T01SU	Taxiway 01 Sunriver	TAXIWAY	02	T03SU-01	R18 End	Р	3,590	35	141,040	7/1/2019	AC
T02SU	Taxiway 02 Sunriver	TAXIWAY	01	T01SU-01	R18SU-01	Р	160	75	11,900	7/1/2019	AC
T03SU	Taxiway 03 Sunriver	TAXIWAY	01	T01SU-02	R18SU-01	Р	160	75	14,230	7/1/2019	AC
T04SU	Taxiway 04 Sunriver	TAXIWAY	01	T04SU-02	T01SU-02	S	190	35	6,361	7/1/2020	AC
T04SU	Taxiway 04 Sunriver	TAXIWAY	02	T04SU-01	SU-01	S	120	35	4,135	1/1/1970	AC
T04SU	Taxiway 04 Sunriver	TAXIWAY	03	T04SU-01	End	S	115	25	3,980	7/1/2020	AC
T04SU	Taxiway 04 Sunriver	TAXIWAY	04	T04SU-01	End	S	135	25	4,734	7/1/2020	AC
T05SU	Taxiway 05 Sunriver	TAXIWAY	01	T01SU-02	R18SU-01	Р	160	75	13,690	7/1/2019	AC
T06SU	Taxiway 06 Sunriver	TAXIWAY	01	T01SU-02	R18SU-01	Р	160	75	13,970	7/1/2019	AC
T07SU	Taxiway 07 Sunriver	TAXIWAY	01	T01SU-01	R18SU-01	Р	130	45	7,431	7/1/2019	AC
THANGARSU	T-Hangar Taxiways Sunriver	TAXIWAY	01	T04	End	S	388	45	17,460	1/1/1970	AC
THANGARSU	T-Hangar Taxiways Sunriver	TAXIWAY	02	THANGAR-01	End	S	260	70	18,181	1/1/1970	AC
THANGARSU	T-Hangar Taxiways Sunriver	TAXIWAY	03	THANGAR-01	End	S	260	60	15,584	1/1/1970	AC
THANGARSU	T-Hangar Taxiways Sunriver	TAXIWAY	04	THANGAR-01	End	S	260	60	15,584	1/1/1970	AC
THANGARSU	T-Hangar Taxiways Sunriver	TAXIWAY	05	THANGAR-01	End	S	260	35	9,229	1/1/1970	AC

P = Primary pavement, S = Secondary pavement



LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)

AC = Asphalt Concrete, PCC = Portland Cement Concrete




Table 3A: EXAMPLE SAMPLE RATES FOR AC AND PCC PAVEMENTS

AC Sampling Rate				
Total Number of Sample Units, N	Sample Units to Survey, n			
1	1			
2-3	2			
4-6	3			
7-13	4			
14-38	5			
39+	6			


Note: AC = Asphalt Concrete

PCC = Portland Cement Concrete

PCC Sampling Rate				
Total Number of Sample Units, N	Sample Units to Survey, n			
1	1			
2	2			
3-4	3			
5-6	4			
7-8	5			
9-11	6			
12-14	7			
15-19	8			
20-27	9			
28-38	10			
39-58	11			
59-104	12			
105-313	13			
314+	14			











APPENDIX B

Pavement Condition Index Survey Results



APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC and AAC) and rigid pavement (e.g., PCC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE AND RIGID PAVEMENT

Flexible Pavement					
PAVER Code	Pavement Distress	Related Cause			
41	Alligator Cracking	Load			
42	Bleeding	Other			
43	Block Cracking	Climate/ Durability			
44	Corrugation	Other			
45	Depression	Other			
46	Jet Blast	Other			
47	Joint Reflection Cracking	Climate/ Durability			
48	Longitudinal & Transverse Cracking	Climate/ Durability			
49	Oil Spillage	Other			
50	Patching	Climate/ Durability			
51	Polished Aggregate	Other			
52	Raveling	Climate/ Durability			

Rigid Pavement					
PAVER Code	Pavement Distress	Related Cause			
61	Blow-Up	Load			
62	Corner Break	Load			
63	Longitudinal, Transverse, & Diagonal Cracks	Climate/ Durability			
64	Durability Cracking	Climate/ Durability			
65	Joint Seal Damage	Other			
66	Small Patch	Other			
67	Large Patch	Other			
68	Pop Outs	Other			
69	Pumping	Other			
70	Scaling	Other			
71	Faulting	Other			
72	Shattered Slab	Load			



Flexible Pavement					
PAVER Code	Pavement Distress	Related Cause			
53	Rutting	Load			
54	Shoving	Other			
55	Slippage Cracking	Other			
56	Swelling	Other			
57	Weathering	Climate/ Durability			

Rigid Pavement						
PAVER Code	Pavement Distress	Related Cause				
73	Shrinkage Cracking	Other				
74	Joint Spalls	Other				
75	Corner Spalls	Other				
76	Alkali-Silica Reactivity (ASR)	Other				

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as "additional" – defined as nonrepresentative instead of random - are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 and are based on ASTM D5340.

Section 4.1 of ASTM D5340 governing PCI surveys offers this caution:

"The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure the structural capacity; neither does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures."

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

 Load-related: Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking. Rigid



pavement distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping, and joint spalling.

- Climate- and durability-related: Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering. Rigid pavement distresses include blow-ups, durability cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- Moisture- and drainage-related: Flexible pavement distresses include alligator/ fatigue cracking, depressions, potholes, and swelling. Rigid pavement distresses include corner breaks, divided slabs, and pumping.
- Other factors: Oil spillage, jet blast erosion, bleeding, patching, and concrete slab joint faulting.

As described above, a distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, a distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated Sunriver Airport pavement network consists of 11 branches and 24 sections. A total of 71 sample units were visually inspected in the field. Data from the inspected sample units were input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the Re-Inspection Report, in Appendix E. Based on the 2022 PCI survey, the area-weighted average PCI for the entire pavement network at Sunriver Airport is approximately 84, which corresponds to a PCI rating of Satisfactory.

To investigate the rate of deterioration of each pavement section we compared the PCI results from the 2022 survey to the PCI results from the previous inspection. The variation in PCI between inspections for Sunriver Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B - SUNRIVER AIRPORT CURRENT BRANCH CONDITION REPORT

Number of		Approximate Area,	Area Weighted					
Branch ID	Sections	square feet	Use	Average Branch PCI	PCI Category			
A01SU	6	488,849	APRON	99	Good			
A02SU	1	7,016	APRON	67	Good			
R18SU	1	409,820	RUNWAY	57	Good			
T01SU	2	217,530	TAXIWAY	99	Satisfactory			
T02SU	1	11,900	TAXIWAY	100	Good			
T03SU	1	14,230	TAXIWAY	100	Satisfactory			
T04SU	4	19,210	TAXIWAY	94	Fair			
T05SU	1	13,690	TAXIWAY	100	Fair			
T06SU	1	13,970	TAXIWAY	100	Good			
T07SU	1	7,431	TAXIWAY	100	Good			
THANGARSU	5	76.038	TAXIWAY	71	Good			

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	7	495,865	99
RUNWAY	1	409,820	57
TAXIWAY	16	373,999	93
ALL	24	1,279,684	84



Table 3B - SUNRIVER AIRPORT 2022 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01SU	01	7/1/2020	AC	APRON	3/1/2022	2	100	Good	100	0	0
A01SU	02	7/1/2020	PCC	APRON	3/1/2022	2	100	Good	0	0	0
A01SU	03	7/1/2020	AC	APRON	3/1/2022	2	100	Good	100	0	0
A01SU	04	7/1/2020	PCC	APRON	3/1/2022	2	85	Satisfactory	0	44	56
A01SU	05	7/1/2020	PCC	APRON	3/1/2022	2					
A01SU	06	7/1/2020	PCC	APRON	3/1/2022	2	77	Satisfactory	0	70	30
A02SU	01	7/1/2019	AC	APRON	3/1/2022	3	67	Fair	64	36	0
R18SU	01	9/2/2009	AC	RUNWAY	3/1/2022	12	57	Fair	46	54	0
T01SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	100	0	0
T01SU	02	7/1/2019	AC	TAXIWAY	3/1/2022	3	99	Good	100	0	0
T02SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	100	0	0
T03SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	100	0	0
T04SU	01	7/1/2020	AC	TAXIWAY	3/1/2022	2	100	Good	100	0	0
T04SU	02	1/1/1970	AC	TAXIWAY	3/1/2022	52	70	Fair	56	44	0
T04SU	03	7/1/2020	AC	TAXIWAY	3/1/2022	2	100	Good	100	0	0
T04SU	04	7/1/2020	AC	TAXIWAY	3/1/2022	2	100	Good	100	0	0
T05SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	56	44	0
T06SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	100	0	0
T07SU	01	7/1/2019	AC	TAXIWAY	3/1/2022	3	100	Good	100	0	0
THANGARSU	01	1/1/1970	AC	TAXIWAY	3/1/2022	52	65	Fair	100	0	0
THANGARSU	02	1/1/1970	AC	TAXIWAY	3/1/2022	52	72	Satisfactory	100	0	0
THANGARSU	03	1/1/1970	AC	TAXIWAY	3/1/2022	52	71	Satisfactory	100	0	0
THANGARSU	04	1/1/1970	AC	TAXIWAY	3/1/2022	52	74	Satisfactory	100	0	0
THANGARSU	05	1/1/1970	AC	TAXIWAY	3/1/2022	52	75	Satisfactory	100	0	0

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, PCC = Portland Cement Concrete

Note: Unable to inspect A01SU-05 due to obstruction



Table 4B - SUNRIVER AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2022 RESULTS

			Approximate Area, square			2017 Surve	≥V	20)22 Survey			Rate of
Branch ID	Section ID	Surface Type ¹	feet	LCD ²	PCI	PCI Category	Insp. Date	PCI	PCI Category	Age ³	Δ PCI/yr ⁴	Deterioration
A01SU	01	AC	76,472	7/1/2020	64	Fair	6/17/2017	100	Good	-3	7.65	NONE
A01SU	02	PCC	20,575	7/1/2020	11	Serious	6/17/2017	100	Good	-3	18.91	NONE
A01SU	03	AC	349,900	7/1/2020	37	Very Poor	6/17/2017	100	Good	-3	13.38	NONE
A01SU	04	PCC	19,409	7/1/2020	11	Serious	6/17/2017	85	Satisfactory	-3	15.72	NONE
A01SU	05	PCC	20,625	7/1/2020	-	-	-			-	-	-
A01SU	06	PCC	1,868	7/1/2020	-	-	-	77	Satisfactory	-	-	-
A02SU	01	AC	7,016	7/1/2019	-	-	-	67	Fair	-	-	-
R18SU	01	AC	409,820	9/2/2009	83	Satisfactory	6/17/2017	57	Fair	8	-5.52	HIGH
T01SU	01	AC	76,490	7/1/2019	17	Serious	6/17/2017	100	Good	-2	17.63	NONE
T01SU	02	AC	141,040	7/1/2019	52	Poor	6/17/2017	99	Good	-2	9.99	NONE
T02SU	01	AC	11,900	7/1/2019	-	-	-	100	Good	-	-	-
T03SU	01	AC	14,230	7/1/2019	63	Fair	6/17/2017	100	Good	-2	7.86	NONE
T04SU	01	AC	6,361	7/1/2020	-	-	-	100	Good	-	-	-
T04SU	02	AC	4,135	1/1/1970	73	Satisfactory	6/17/2017	70	Fair	47	-0.64	NORMAL
T04SU	03	AC	3,980	7/1/2020	-	-	-	100	Good	-	-	-
T04SU	04	AC	4,734	7/1/2020	-	-	-	100	Good	-	-	-
T05SU	01	AC	13,690	7/1/2019	84	Satisfactory	6/17/2017	100	Good	-2	3.40	NONE
T06SU	01	AC	13,970	7/1/2019	-	-	-	100	Good	-	-	-
T07SU	01	AC	7,431	7/1/2019	-	-	-	100	Good	-	-	-
THANGARSU	01	AC	17,460	1/1/1970	72	Satisfactory	6/17/2017	65	Fair	47	-1.49	NORMAL
THANGARSU	02	AC	18,181	1/1/1970	74	Satisfactory	6/17/2017	72	Satisfactory	47	-0.42	NORMAL
THANGARSU	03	AC	15,584	1/1/1970	77	Satisfactory	6/17/2017	71	Satisfactory	47	-1.27	NORMAL
THANGARSU	04	AC	15,584	1/1/1970	82	Satisfactory	6/17/2017	74	Satisfactory	47	-1.70	NORMAL
THANGARSU	05	AC	9,229	1/1/1970	82	Satisfactory	6/17/2017	75	Satisfactory	47	-1.49	NORMAL

Abbreviations:

Note: Unable to inspect A01SU-05 due to obstruction



¹ AC = Asphalt Concrete, PCC = Portland Cement Concrete

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

³ Age = Pavement age in years at the time of the PCI survey in 2017

 $^{^4}$ Δ PCI/yr = Change in PCI points per year between 2017 survey and 2022 survey



APPENDIX C

Future Pavement Condition Analysis



APPENDIX C

FUTURE PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the "family" model procedure. A pavement "family" is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1. Define the pavement families.
- 2. Review the data.
- 3. Conduct a data outlier analysis.
- 4. Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement "family" at Sunriver Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use three distinct models for the following "families" of pavements at Sunriver Airport. For each model, we reviewed the data in order to filter out any suspicious or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a fourth-order, polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each "family." Our condition prediction models for each "family" are provided on Figures 1C through 4C below.






Figure 1C – CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 4/5 PCC (ALL USES)




Figure 2C - CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 4 AC AND AAC APRONS






Figure 3C - CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 4 AC AND AAC RUNWAYS




Figure 4C - CONDITION PREDICTION MODEL FOR CENTRAL CATEGORY 4 AC AND AAC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models have an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to



prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at Sunriver Airport:

- Runways 60
- Taxiways/Taxilanes 55
- Aprons 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5-year and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at Sunriver Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at Sunriver Airport, the time until rehabilitation, and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C - PAST, PRESENT, AND FUTURE PCI

		Past Inspection PCI	Current PCI	Predicted F	uture PCI
BranchID	SectionID	2017	2022	2027	2032
A01SU	01	64	100	91	82
A01SU	02	11	100	89	77
A01SU	03	37	100	91	82
A01SU	04	11	85	74	62
A01SU	05	-	-	-	-
A01SU	06	-	77	66	54
A02SU	01	-	67	58	49
R18SU	01	83	57	41	24
T01SU	01	17	100	92	83
T01SU	02	52	99	91	82
T02SU	01	-	100	92	83
T03SU	01	63	100	92	83
T04SU	01	-	100	92	83
T04SU	02	73	70	62	53
T04SU	03	-	100	92	83
T04SU	04	-	100	92	83
T05SU	01	84	100	92	83
T06SU	01	-	100	92	83
T07SU	01	-	100	92	83
THANGARSU	01	72	65	57	48
THANGARSU	02	74	72	64	55
THANGARSU	03	77	71	63	54
THANGARSU	04	82	74	66	57
THANGARSU	05	82	75	67	58

Abbreviations:

PCI = Pavement Condition Index

Note: Unable to inspect A01SU-05 due to obstruction



Table 2C - SUNRIVER AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

		Surface	Current	Years to Major	Major M&R	Years to End of
Branch ID	Section ID	Туре	PCI	M&R	Trigger PCI ¹	Functional Service
A01SU	01	AC	100	> 20	50	> 20
A01SU	02	PCC	100	> 20	50	> 20
A01SU	03	AC	100	> 20	50	> 20
A01SU	04	PCC	85	11 - 15	50	> 20
A01SU	05	PCC			50	
A01SU	06	PCC	77	11 - 15	50	16 - 20
A02SU	01	AC	67	6 - 10	50	11 - 15
R18SU	01	AC	57	0 - 5	60	0 - 5
T01SU	01	AC	100	> 20	55	> 20
T01SU	02	AC	99	> 20	55	> 20
T02SU	01	AC	100	> 20	55	> 20
T03SU	01	AC	100	> 20	55	> 20
T04SU	01	AC	100	> 20	55	> 20
T04SU	02	AC	70	6 - 10	55	16 - 20
T04SU	03	AC	100	> 20	55	> 20
T04SU	04	AC	100	> 20	55	> 20
T05SU	01	AC	100	> 20	55	> 20
T06SU	01	AC	100	> 20	55	> 20
T07SU	01	AC	100	> 20	55	> 20
THANGARSU	01	AC	65	6 - 10	55	11 - 15
THANGARSU	02	AC	72	6 - 10	55	> 20
THANGARSU	03	AC	71	6 - 10	55	16 - 20
THANGARSU	04	AC	74	11 - 15	55	> 20
THANGARSU	05	AC	75	11 - 15	55	> 20

Abbreviations:

M&R = Maintenacne and Rehabilitation, AC = Asphalt Concrete, PCC = Portland Cement Concrete

¹ Major M&R Trigger PCI = Critical PCI

Note: Unable to inspect A01SU-05 due to obstruction





APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan



APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of the Sunriver Airport pavement network condition over time. We used PAVER v7 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2023. A backlog elimination analysis scenario was selected to generate a list of global maintenance and rehabilitation projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction Considered for pavements with a PCI less than 40.
- Flexible Overlay Considered for pavements between 40 PCI and the critical PCI, and for pavements exhibiting significant load-related distresses.
- Global Maintenance Treatments (fog seal, slurry seal, thin AC overlay) applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance Maintenance performed on a routine basis such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use



to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

		Section Rank	
Branch Use	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

The distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in cost for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type cost to PCI. We reviewed the unit costs from the 2017 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of Sunriver Airport and information provided by the project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at Sunriver Airport. The costs represent the fully-loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.



Table 2D: SUNRIVER AIRPORT UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major MARD	Complete Reconstruction with AC	\$11.10	Sq Ft
Major M&R	Cold Mill and Overlay – 3 Inches Thick	\$4.90	Sq Ft
Clabal MOD	Surface Treatment - Slurry Seal	\$0.33	Sq Ft
Global M&R	Surface Treatment - Fog Seal	\$0.20	Sq Ft
	Crack Sealing - AC	\$2.00	Ft
	Crack Sealing - PCC	\$15.00	Ft
Localized Preventive M&R	Crack Sealing – Wide Cracks	\$33.00	Ft
r revenuve MCK	AC Patching – Full Depth	\$50.00	Sq Ft
	PCC Patching – Full Depth	\$100.00	Sq Ft

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED GLOBAL MAINTENANCE AND REHABILITATION PROJECTS

Global maintenance and rehabilitation projects refer to activities such as slurry seal and thin AC overlays, as well as thick AC overlays and reconstruction. A list of recommended global M&R activities is provided in Table 4D of this appendix.

Table 3D - SUNRIVER AIRPORT NETWORK MAINTENANCE REPORT

Network	Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
Sunriver	A01SU	04	Linear Cracking	Low	Crack Sealing - PCC	130	Ft	\$15.00	\$1,949	\$1,949
Sunriver	A01SU	06	Linear Cracking	Low	Crack Sealing - PCC	10	Ft	\$15.00	\$146	- \$293
Sunriver	A01SU	06	Linear Cracking	Medium	Crack Sealing - PCC	10	Ft	\$15.00	\$146	- φ293
Sunriver	A02SU	01	Alligator Cracking	Medium	Patching - AC Deep	42	SqFt	\$50.00	\$2,100	
Sunriver	A02SU	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	185	Ft	\$2.00	\$370	\$2,824
Sunriver	A02SU	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	177	Ft	\$2.00	\$354	
Sunriver	R18SU	01	Alligator Cracking	Low	Crack Sealing - AC	176	Ft	\$2.00	\$353	_
Sunriver	R18SU	01	Alligator Cracking	Medium	Patching - AC Deep	6,763	SqFt	\$50.00	\$338,129	- \$374,376
Sunriver	R18SU	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	5,100	Ft	\$2.00	\$10,200	- \$374,370
Sunriver	R18SU	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	12,847	Ft	\$2.00	\$25,694	
Sunriver	T01SU	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	104	Ft	\$2.00	\$208	\$208
Sunriver	T04SU	02	Alligator Cracking	Low	Crack Sealing - AC	20	Ft	\$2.00	\$41	- \$279
Sunriver	T04SU	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	119	Ft	\$2.00	\$238	- \$279
Sunriver	THANGARSU	01	Long. & Trans. Cracking	Low	Crack Sealing - AC	79	Ft	\$2.00	\$158	- \$1,899
Sunriver	THANGARSU	01	Long. & Trans. Cracking	Medium	Crack Sealing - AC	870	Ft	\$2.00	\$1,741	- \$1,099
Sunriver	THANGARSU	02	Long. & Trans. Cracking	Low	Crack Sealing - AC	18	Ft	\$2.00	\$36	- \$1,029
Sunriver	THANGARSU	02	Long. & Trans. Cracking	Medium	Crack Sealing - AC	496	Ft	\$2.00	\$992	- \$1,029
Sunriver	THANGARSU	03	Long. & Trans. Cracking	Low	Crack Sealing - AC	39	Ft	\$2.00	\$78	- \$878
Sunriver	THANGARSU	03	Long. & Trans. Cracking	Medium	Crack Sealing - AC	400	Ft	\$2.00	\$800	- 40 70
Sunriver	THANGARSU	04	Long. & Trans. Cracking	Medium	Crack Sealing - AC	362	Ft	\$2.00	\$725	\$725
Sunriver	THANGARSU	05	Long. & Trans. Cracking	Low	Crack Sealing - AC	13	Ft	\$2.00	\$26	- \$449
Sunriver	THANGARSU	05	Long. & Trans. Cracking	Medium	Crack Sealing - AC	211	Ft	\$2.00	\$423	ş449

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; PCC = Portland Cement Concrete; Ft = Feet; SqFt = Square Feet



Table 4D - FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2024	R18SU	01	RUNWAY	AC	57	Overlay	409,820	\$4.90	\$2,007,998
	T04SU	02	TAXIWAY	AC	70	Slurry Seal	4,135	\$0.33	\$1,365
	THANGARSU	01	TAXIWAY	AC	65	Slurry Seal	17,460	\$0.33	\$5,762
2025	THANGARSU	02	TAXIWAY	AC	72	Slurry Seal	18,181	\$0.33	\$6,000
2023	THANGARSU	03	TAXIWAY	AC	71	Slurry Seal	15,584	\$0.33	\$5,143
	THANGARSU	04	TAXIWAY	AC	74	Slurry Seal	15,584	\$0.33	\$5,143
	THANGARSU	05	TAXIWAY	AC	75	Slurry Seal	9,229	\$0.33	\$3,046
2026	A02SU	01	APRON	AC	67	Fog Seal	7,016	\$0.20	\$1,403

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete

Cost Summary	
2023 Total Project Cost	\$0
2024 Total Project Cost	\$2,007,998
2025 Total Project Cost	\$26,457
2026 Total Project Cost	\$1,403
2027 Total Project Cost	\$0
Total 5-Year Project Cost	\$2,035,858





APPENDIX E

Re-Inspection Report

Re-Inspection Report

 $ODA_WOC3_9-1-2022_PostBendAnalysis$

<No Distress>

Generated Date 9/30/2022
Page 1 of 25

Generated Date	9/:	30/2022								rage 1 01 2.
Network: Sunriver			Name:	Sunriver						
Branch: A01SU		Name:	Apron 01 Sunriver	U	se: Al	PRON	Area:	488,	849 SqFt	
Section: 01	of 6	Fro	m: T04SU-01			To: A018	SU-03	I	ast Const.:	7/1/2020
Surface: AC	Family: 200 on	22_Central_Cat _AC/AAC	t4/5_Apr Zone:	S21		Category:	L	I	Rank: P	
Area:	76,472 SqFt	Length:	625 Ft	Width:		175 Ft	t			
Slabs:	Slab Length:		Ft Slab	Width:		Ft		Joint Length:	F	t
Shoulder:	Street Type:		Grad	le: 0]	Lanes: 0		
Section Comments:	Twin/Jet Ramp									
Work Date: 9/1/1985	Work '	Type: Base Co	ourse - Aggregate		Code:	BA-AG		Is Major M&	R: False	
Work Date: 9/2/1985	Work '	Type: New Co	nstruction - AC		Code:	NC-AC		Is Major M&	R: True	
Work Date: 9/1/1997	Work '	Type: Overlay	- AC Thin		Code:	OL-AT		Is Major M&	R: True	
Work Date: 9/1/1997	Work '	Type: Crack S	ealing - AC		Code:	CS-AC		Is Major M&	R: False	
Work Date: 9/1/1999	Work '	Type: Surface	Treatment - Seal Coat	(Global MR)	Code:	ST-SC		Is Major M&	R: False	
Work Date: 9/1/2003	Work '	Type: Crack S	ealing - AC		Code:	CS-AC		Is Major M&	R: False	
Work Date: 9/1/2012	Work '	Type: Crack S	ealing - AC		Code:	CS-AC		Is Major M&	R: False	
Work Date: 9/2/2012	Work '	Type: Patching	g - AC Deep		Code:	PA-AD		Is Major M&	R: False	
Work Date: 9/1/2015	Work '	Type: Crack S	ealing - AC		Code:	CS-AC		Is Major M&	R: False	
Work Date: 9/2/2015	Work '	Type: Patching	g - AC Deep		Code:	PA-AD		Is Major M&	R: False	
Work Date: 7/1/2020	Work	Type: Comple	te Reconstruction - AC	C	Code:	CR-AC		Is Major M&	R: True	
Work Date: 7/1/2020	Work	Type: Subbase	- Aggregate		Code:	SB-AG		Is Major M&	R: False	
Last Insp. Date: 3/1/2	022	TotalSam	ples: 17	Sur	veyed:	5				
Conditions: PCI:	100									
Inspection Comments:										
Sample Number: 01	Type:	R	Area:	4038.00 SqF	t	PCI:	100			
Sample Comments:										
<no distress=""></no>										
Sample Number: 05	Type:	R	Area:	4156.00 SqF	t	PCI:	100			
Sample Comments:										
<no distress=""></no>										
Sample Number: 11	Туре:	R	Area:	4590.00 SqF	t	PCI:	100			
Sample Comments:										
<no distress=""></no>										
Sample Number: 13	Type:	R	Area:	4740.00 SqF	t	PCI:	100			
Sample Comments:										
<no distress=""></no>										
Sample Number: 16	Type:	R	Area:	5154.00 SqF	t	PCI:	100			
Sample Comments:										

Network:	Sunriver				Name:	Sun	river						
Branch:	A01SU		Name:	Apron	01 Sunriver		Use	: AP	RON	Are	a: 488,8	349 SqFt	
	02 PCC	o Family:	f 6 2022_Central Uses_PCC		A01SU-01 Zone:	S21			To: A01 Category:			ast Const.:	7/1/2020
Area:	20	,575 SqFt	Length:		300 Ft		Width:		67 F	t			
Slabs:	120	Slab Len		12 Ft	Slal	b Width:		12	Ft		Joint Length:	2,916 Ft	
Shoulder:		Street T	ype:		Gra	ide: 0					Lanes: 0		
Section Co	mments:												
Work Date	e: 9/1/1970	W	ork Type: Base	e Course - Ag	ggregate			Code:	BA-AG		Is Major M&	R: False	
Work Date	e: 9/2/1970	W	ork Type: Surf	face Course -	Double Bitt	um.		Code:	SU-DB		Is Major M&	R: True	
Work Date	e: 9/3/1970	W	ork Type: Surf	face Treatmen	nt - Seal Coa	at (Global	MR)	Code:	ST-SC		Is Major M&	R: False	
Work Date	e: 9/1/1997	W	ork Type: Crac	ck Sealing - A	AC			Code:	CS-AC		Is Major M&	R: False	
Work Date	e: 7/1/2020	W	ork Type: Con	nplete Recons	struction - P	CC		Code:	CR-PC		Is Major M&	R: True	
Work Date	e: 7/1/2020	W	ork Type: Sub	base - Aggre	gate			Code:	SB-AG		Is Major M&	R: False	
Last Insp. 1	Date: 3/1/202	22	Totals	Samples: (5		Surve	yed: 4	1				
Conditions	: PCI : 1	00											
Inspection	Comments:												
Sample Nu	mber: 01	Typ	pe: R	A	rea:	20	0.00 Slabs		PCI:	100			
Sample Co	mments:												
<no distres<="" td=""><td>ss></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></no>	ss>												
Sample Nu	mber: 02	Туј	pe: R	A	rea:	20	0.00 Slabs		PCI:	100			
Sample Co	mments:												
<no distres<="" td=""><td>ss></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></no>	ss>												
Sample Nu	mber: 04	Тур	pe: R	A	rea:	20	0.00 Slabs		PCI:	100			
Sample Co	mments:												
<no distres<="" td=""><td>ss></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></no>	ss>												
Sample Nu	mber: 05	Тур	pe: R	A	rea:	20	0.00 Slabs		PCI:	100			

Sample Comments:

Network: Sunriver			Name:	Sunriver						
Branch: A01SU		Name:	Apron 01 Sunriver	Use	: APRC	N	Area:	488,849	SqFt	
Section: 03	of 6	Fr	om: A01SU-01		To	: T01SU-0	2	Last	Const.:	7/1/2020
Surface: AC		_Central_C AC/AAC	at4/5_Apr Zone:	S21	Ca	tegory: L		Ran	k: P	
Area: 349,9	000 SqFt	Length:	925 Ft	Width:		400 Ft				
Slabs:	Slab Length:		Ft Slat	Width:	Ft		Jo	int Length:	Ft	-
Shoulder:	Street Type:		Gra	de: 0			La	nes: 0		
Section Comments:										
Work Date: 9/1/1970	Work T	ype: Base C	ourse - Aggregate		Code: B	A-AG		Is Major M&R:	False	
Work Date: 9/2/1970	Work T	ype: Surface	e Course - Double Bitu	ım.	Code: S	U-DB		Is Major M&R:	True	
Work Date: 9/1/1999	Work T	ype: Overla	y - AC Thin		Code: O	L-AT		Is Major M&R:	True	
Work Date: 9/1/2003	Work T	ype: Crack	Sealing - AC		Code: C	S-AC		Is Major M&R:	False	
Work Date: 7/1/2020	Work T	ype: Compl	ete Reconstruction - A	С	Code: C	R-AC		Is Major M&R:	True	
Work Date: 7/1/2020	Work T	y pe: Subbas	e - Aggregate		Code: S	B-AG		Is Major M&R:	False	
Last Insp. Date: 3/1/2022	2	TotalSar	nples: 73	Surve	eyed: 7					
Conditions: PCI: 100	0									
Inspection Comments:										
Sample Number: 01	Type:	R	Area:	5000.00 SqFt		PCI: 10	0			
Sample Comments:										
<no distress=""></no>										
Sample Number: 16	Type:	R	Area:	5000.00 SqFt		PCI: 10	0			
Sample Comments:										
<no distress=""></no>										
Sample Number: 20	Type:	R	Area:	5000.00 SqFt		PCI: 10	0			
Sample Comments:										
<no distress=""></no>										
Sample Number: 30	Type:	R	Area:	5000.00 SqFt		PCI: 10	0			
Sample Comments:				•						
<no distress=""></no>										
Sample Number: 48	Type:	R	Area:	5000.00 SqFt		PCI: 10	0			
Sample Comments:	V F			. 1						
<no distress=""></no>										
Sample Number: 60	Type:	R	Area:	5357.00 SqFt		PCI: 10	0			
Sample Comments:	• •			1						
<no distress=""></no>										
Sample Number: 68	Туре:	R	Area:	6019.00 SqFt		PCI: 10	0			
Sample Comments:	ı, pe.			0015.00 Dq1 t		1 0 2 . 10	-			

Network: Sunriver		Name:				
Branch: A01SU	Name:	Apron 01 Sunriver	Use: A	PRON	Area: 48	38,849 SqFt
ection: 04	of 6	rom: A01SU-03		To: W. Edge		Last Const.: 7/1/202
Surface: PCC F	Tamily: 2022_Central_C Uses_PCC	Cat4/5_All Zone: S2	1	Category: L		Rank: P
Area: 19,409	SqFt Length:	130 Ft	Width:	150 Ft		
Slabs: 110	Slab Length:	14 Ft Slab Wid	lth: 12	2 Ft	Joint Length:	2,613 Ft
Shoulder:	Street Type:	Grade:	0		Lanes: 0	
Section Comments:						
Vork Date: 9/1/1970	Work Type: Base	Course - Aggregate	Code:	BA-AG	Is Major N	1&R: False
Vork Date: 9/2/1970	Work Type: Surfa	ce Course - Double Bitum.	Code	SU-DB	Is Major N	1&R: True
Vork Date: 9/1/1982	Work Type: Overl	ay - AC Thin	Code	OL-AT	Is Major N	1&R: True
Work Date: 9/1/1997	Work Type: Crack	Sealing - AC	Code	CS-AC	Is Major N	1&R: False
Work Date: 9/1/1999	Work Type: Surfa	ce Treatment - Seal Coat (Glo	obal MR) Code:	ST-SC	Is Major N	1&R: False
Work Date: 7/1/2020	Work Type: Comp	elete Reconstruction - PCC	Code	CR-PC	Is Major N	1&R: True
Last Insp. Date: 3/1/2022 Conditions: PCI: 85	TotalSa	amples: 6	Surveyed:	4		
Conditions: PCI: 85	TotalSz	amples: 6	Surveyed:	4		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01	TotalSa	Area:	Surveyed: 20.00 Slabs	PCI: 76		
Conditions: PCI: 85 nspection Comments: Sample Number: 01						
Conditions: PCI: 85 Inspection Comments: Cample Number: 01 Cample Comments: 4 JOINT SPALL	Type: R	Area: 3.00 Slabs				
Conditions: PCI: 85 nspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 3 LINEAR CR	Type: R L L	Area: 3.00 Slabs 2.00 Slabs				
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 3 LINEAR CR 11 FAULTING	Type: R L L L L	Area: 3.00 Slabs	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 nspection Comments: Cample Number: 01 Cample Comments: 4 JOINT SPALL 3 LINEAR CR 1 FAULTING Cample Number: 02	Type: R L L	Area: 3.00 Slabs 2.00 Slabs				
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 3 LINEAR CR 1 FAULTING Sample Number: 02 Sample Comments:	Type: R L L L L	Area: 3.00 Slabs 2.00 Slabs 4.00 Slabs	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 74 JOINT SPALL 75 LINEAR CR 71 FAULTING Sample Number: 02 Sample Comments: 75 LINEAR CR	Type: R L L L L Type: R	Area: 3.00 Slabs 2.00 Slabs 4.00 Slabs Area:	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 53 LINEAR CR 71 FAULTING Sample Number: 02 Sample Comments: 53 LINEAR CR 55 CORNER SPALL	Type: R L L L L Type: R	Area: 3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 nspection Comments: Gample Number: 01 Gample Comments: 4 JOINT SPALL 3 LINEAR CR 1 FAULTING Gample Number: 02 Gample Comments: 3 LINEAR CR 5 CORNER SPALL 4 JOINT SPALL	Type: R L L L L Type: R	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 3 LINEAR CR 1 FAULTING Sample Number: 02 Sample Comments: 3 LINEAR CR 5 CORNER SPALL 4 JOINT SPALL 63 SHRINKAGE CR	Type: R L L L Type: R L L L N	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 76		
conditions: PCI: 85 nspection Comments: ample Number: 01 ample Comments: 4 JOINT SPALL 3 LINEAR CR 1 FAULTING ample Number: 02 ample Comments: 3 LINEAR CR 5 CORNER SPALL 4 JOINT SPALL 3 SHRINKAGE CR	Type: R L L L L Type: R	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs	20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 4 JOINT SPALL 53 LINEAR CR 71 FAULTING Sample Number: 02 Sample Comments: 53 LINEAR CR 75 CORNER SPALL 74 JOINT SPALL 75 SHRINKAGE CR 76 Sample Number: 03	Type: R L L L Type: R L L L N	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Cample Number: 01 Cample Comments: Cample Comments: Cample Comments: Cample Number: 02 Cample Number: 02 Cample Comments: Cample Comments: Cample Comments: Cample Comments: Cample Number: 03 Cample Number: 03 Cample Comments:	Type: R L L L Type: R L L L N	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Sample Number: 01 Sample Comments: 74 JOINT SPALL 63 LINEAR CR 71 FAULTING Sample Number: 02 Sample Comments: 63 LINEAR CR 75 CORNER SPALL 64 JOINT SPALL 673 SHRINKAGE CR 65 Sample Number: 03 65 Sample Comments: 64 JOINT SPALL	Type: R L L L Type: R L L L N Type: R	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs Area: 2.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Cample Number: 01 Cample Comments: Cample Comments: Cample Comments: Cample Number: 02 Cample Number: 02 Cample Comments: Cample Comments: Cample Comments: Cample Number: 03 Cample Number: 03 Cample Comments:	Type: R L L L L Type: R Type: R Type: R L L L L L L L L L L L L L L L L L L	Area: 3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs Area:	20.00 Slabs 20.00 Slabs	PCI: 76		
Conditions: PCI: 85 Inspection Comments: Comple Number: 01 Comple Comments: Comple Comments: Comple Comments: Comple Number: 02 Comple Number: 02 Comple Comments: Comple	Type: R L L L L Type: R Type: R L L L L L L L L L L L L L L L L L L	3.00 Slabs 2.00 Slabs 4.00 Slabs Area: 1.00 Slabs 1.00 Slabs 2.00 Slabs 1.00 Slabs Area: 2.00 Slabs 3.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 76		

L L 1.00 Slabs

1.00 Slabs

63

74

LINEAR CR

JOINT SPALL

Network: Sunriver Name: Sunriver Apron 01 Sunriver A01SU Use: APRON 488,849 SqFt Branch: Name: Area: 05 A01SU-04 To: East edge of PCC Section: of 6 From: Last Const.: 7/1/2020 PCC Family: DEFAULT Zone: Rank: P Surface: Category: Area: 20,625 SqFt Length: 275 Ft Width: 75 Ft Slab Width: Slab Length: 12 Ft Slabs: 127 13 Ft Joint Length: 2,887 Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 7/1/2020 Code: SB-AG Is Major M&R: False Work Type: Subbase - Aggregate Work Date: 7/1/2020 Work Type: New Construction - PCC Code: NC-PC Is Major M&R: True **Last Insp. Date:** 3/1/2022 **TotalSamples:** 5 Surveyed: 3 **Conditions:** PCI: **Inspection Comments: PCI:** 100 Sample Number: 01 Type: R Area: 20.00 Slabs **Sample Comments:** Could not survey due to snow covering PCC slabs <No Distress> Sample Number: 03 Type: R 20.00 Slabs **PCI:** 100 Area: **Sample Comments:** Could not survey due to snow covering PCC slabs <No Distress>

20.00 Slabs

PCI: 100

Type: **Sample Comments:** Could not survey due to snow covering PCC slabs

R

Area:

<No Distress>

Sample Number: 04

Network: Sunriver Name: Sunriver **Branch:** A01SU Apron 01 Sunriver Use: APRON 488,849 SqFt Name: Area: **Section:** 06 of 6 A01SU-04 To: End Last Const.: 7/1/2020 From: Surface: PCC Family: 2022_Central_Cat4/5_All Zone: Category: Rank: P Uses PCC Width: 1,868 SqFt Length: 90 Ft 20 Ft Area: Slabs: 20 Slab Length: 10 Ft Slab Width: 9 Ft Joint Length: 261 Ft **Street Type:** Grade: 0 Lanes: 0 Shoulder: **Section Comments:** Code: NU-IN Work Date: 7/1/2020 Work Type: New Construction - Initial Is Major M&R: True **Last Insp. Date:** 3/1/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 01 Type: R Area: 20.00 Slabs **PCI:** 77 **Sample Comments:** LINEAR CR M 1.00 Slabs 63 JOINT SPALL 74 L 1.00 Slabs LINEAR CR L 63 1.00 Slabs

CORNER SPALL

SHRINKAGE CR

75

73

L

N

Slabs

1.00 Slabs

2.00

Network: S	Sunriver				Nan	ne:	Sunriver								
Branch: A	A02SU		Name:	Apror	02 Sun	river		Use:	AP	RON	A	Area:	7,0	16 SqFt	
Section: 01		of	1	From:	T07SU-	-01			,	To: R	18SU-01		L	ast Const.:	7/1/2019
Surface: AC			2022_Centra on_AC/AAC	al_Cat4/5_Ap	r Zon	e:			•	Catego	ry:		R	ank: P	
Area:	7,0	16 SqFt	Length	ı:	100 F		Wio	lth:		7	0 Ft				
Slabs:		Slab Lengt	th:	Ft		Slab Widt	th:]	Ft		Joint L	ength:	F	t
Shoulder:		Street Typ	e:			Grade:	0					Lanes:	0		
Section Comme	ents:														
Work Date: 7/	/1/2019	Wor	k Type: Ne	w Constructi	on - AC	!		Co	ode:	NC-A	C	Is N	Major M&l	R: True	
Work Date: 7/	/1/2019	Wor	k Type: Su	bbase - Crusł	ned Agg	regate		Co	ode:	SU-CA	A	Is N	Major M&l	R: False	
Work Date: 7/	/1/2019	Wor	k Type: Ba	se Course - A	ggregat	te		Co	ode:	BA-A	G	Is N	Major M&l	R: False	
Last Insp. Date	e: 3/1/2022	2	Tota	lSamples:	2			Surveye	d: 2	!					
Conditions:	PCI: 67														
Inspection Com	nments:														
Sample Numbe	er: 01	Туре	: R	1	Area:	5	5126.00	SqFt		PO	CI: 64				
Sample Commo	ents:														
48 L & T C			M	147.00											
57 WEATH48 L & T C			L L	5126.00 140.00	-										
	ATOR CR		M		SqFt										
Sample Numbe	er: 02	Туре	: R	1	Area:	1	1890.00	SqFt		PO	CI: 76				
Sample Commo	ents:														
57 WEATH	HERING		L	945.00	SqFt										
48 L & T C			L	45.00											
48 L & T C	CR		M	30.00	Ft										

Netwo	ork: Sunriver		Nan	ne: Sunrive	or		
Branc	h: R18SU	Name:	Runway 18/36	5 Sunriver	Use: R	UNWAY A	rea: 409,820 SqFt
Section	n: 01	of 1 F	rom: R36 En	d		To: R18SU-02	Last Const.: 9/2/2009
Surfac	ce: AC	Family: 2022_Central_C _AC/AAC	Cat4/5_RW Zon	e: S21		Category: L	Rank: P
Area:	409,8	20 SqFt Length:	5,460 F	t V	Vidth:	75 Ft	
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length: Ft
Should	der:	Street Type:		Grade: 0			Lanes: 0
Section	n Comments:						
Work	Date: 9/1/1970	Work Type: Base	Course - Aggregat	re	Code:	BA-AG	Is Major M&R: False
Work	Date: 9/1/1985	Work Type: Overl	ay - AC Thin		Code:	OL-AT	Is Major M&R: True
Work	Date: 9/1/2009	Work Type: Base	Course - Pulverize	ed AC	Code:	BA-PA	Is Major M&R: False
Work	Date: 9/2/2009	Work Type: Comp	elete Reconstruction	on - AC	Code:	CR-AC	Is Major M&R: True
Work	Date: 9/1/2012	Work Type: Crack	Sealing - AC		Code:	CS-AC	Is Major M&R: False
	Date: 9/1/2015	Work Type: Crack	Sealing - AC			CS-AC	Is Major M&R: False
Last I	nsp. Date: 3/1/2022	TotalSa	imples: 73		Surveyed:	6	
Condi	tions: PCI: 57						
Inspec	ction Comments:						
Sampl	le Number: 01	Type: R	Area:	5625.00	0 SaFt	PCI: 53	
_		reated by Inspection Schedule			· -1		
•							
41	ALLIGATOR CR	M	30.00 SqFt				
48 48	L & T CR L & T CR	M L	212.00 Ft 32.00 Ft				
41	ALLIGATOR CR	M	90.00 SqFt				
57	WEATHERING	L	5625.00 SqFt				
	le Number: 24	Type: R	Area:	5625.00	0 SaFt	PCI: 70	
_		reated by Inspection Schedule	111011	3023.00	o sqrt	101. 70	
48	L & T CR	M	48.00 Ft				
50	PATCHING	L	58.00 SqFt				
57	WEATHERING	L	5625.00 SqFt				
48	L & T CR	L	8.00 Ft				
48	L & T CR	M	75.00 Ft				
48	L & T CR	M	40.00 Ft				
48	L & T CR	L	30.00 Ft				
_	le Number: 34 le Comments: Cr	Type: R reated by Inspection Schedule	Area:	5625.00	0 SqFt	PCI : 69	
57	WEATHERING	L	5625.00 SqFt				
48	L & T CR	M	118.00 Ft				
48	L&TCR	L	38.00 Ft				
48	L & T CR	L	30.00 Ft				
48	L & T CR	M	105.00 Ft				
Sampl	le Number: 46	Type: R	Area:	5625.00	0 SqFt	PCI: 42	
Sampl	le Comments: Ci	reated by Inspection Schedule					
48	L & T CR	L	75.00 Ft				
41	ALLIGATOR CR	L	40.00 SqFt				
57	WEATHERING	L	5625.00 SqFt				
48	L & T CR	M	50.00 Ft				
41	ALLIGATOR CR	M	160.00 SqFt				
48 48	L & T CR L & T CR	L M	12.00 Ft 75.00 Ft				
				F CO F O	0 CaEt	DCI. 25	
_	le Number: 58	Type: R	Area:	5625.00	o Sqrt	PCI: 35	
Sampl		eated by Inspection Schedule					
48	L & T CR	L	120.00 Ft				

50	PATCHING	L	75.00 SqFt			
48	L & T CR	L	75.00 Ft			
48	L & T CR	M	150.00 Ft			
57	WEATHERING	L	5625.00 SqFt			
41	ALLIGATOR CR	M	250.00 SqFt			
Samı	ole Number: 68	Type: R	Area:	5625.00 SqFt	PCI: 75	
Samp	ole Comments: Creat	ed by Inspection Schedu	10			
	,	ed by hispection selledu	iic			
50	PATCHING	L	42.00 SqFt			
50 48		-				
	PATCHING	L	42.00 SqFt			
48	PATCHING L & T CR	L M	42.00 SqFt 75.00 Ft			

Network: Sunriver		Name:	Sunriver		
Branch: T01SU	Name:	Taxiway 01 Sunriver	Use:	TAXIWAY	Area: 217,530 SqFt
Section: 01	of 2	From: R36 End		To: T03SU-01	Last Const.: 7/1/2019
Surface: AC	Family: 2022_Central_way_AC/AAC		521	Category: L	Rank: P
Area: 76,490	SqFt Length:	1,880 Ft	Width:	35 Ft	
Slabs:	Slab Length:	Ft Slab W	idth:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade	0		Lanes: 0
Section Comments:					
Work Date: 9/1/1970	Work Type: Base	Course - Aggregate	ı	Code: BA-AG	Is Major M&R: False
Work Date: 9/2/1970	Work Type: Surfa	ce Course - Double Bitum.		Code: SU-DB	Is Major M&R: True
Work Date: 9/1/1990	Work Type: Over	lay - AC Thin		Code: OL-AT	Is Major M&R: True
Work Date: 9/1/1997	Work Type: Crac	k Sealing - AC		Code: CS-AC	Is Major M&R: False
Work Date: 9/1/2008	Work Type: Crac	s Seal - Wide Cracks		Code: CS-WD	Is Major M&R: False
Work Date: 9/2/2008	Work Type: Patcl	ning - AC Deep		Code: PA-AD	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Base	Course - Aggregate		Code: BA-AG	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Com	plete Reconstruction - AC		Code: CR-AC	Is Major M&R: True
Work Date: 7/1/2019	Work Type: Subb	ase - Aggregate	ı	Code: SB-AG	Is Major M&R: False
Last Insp. Date: 3/1/2022	TotalS	amples: 14	Surve	yed: 5	
Conditions: PCI: 100					
Inspection Comments:					
Sample Number: 01	Type: R	Area:	6378.00 SqFt	PCI: 100	
Sample Comments:					
<no distress=""></no>					
Sample Number: 04	Type: R	Area:	5270.00 SqFt	PCI: 100	
Sample Comments:					
<no distress=""></no>					
Sample Number: 07	Type: R	Area:	5260.00 SqFt	PCI: 100	
Sample Comments: <no distress=""></no>					
Sample Number: 10	Type: R	Area:	5255.00 SqFt	PCI: 100	
Sample Comments:	Type. R	ma.	5255.00 5qrt	101. 100	
<no distress=""></no>					
Sample Number: 13	Type: R	Area:	5852.00 SqFt	PCI: 100	
Sample Humbel. 13	Type.	mica.	5052.00 5qrt	1 (1, 100	

Sample Comments:

Network: Sunriver		Name: S	unriver	
Branch: T01SU	Name:	Taxiway 01 Sunriver	Use: TAXIWAY	Area: 217,530 SqFt
Section: 02	of 2 From	n: T03SU-01	To: R18 End	Last Const.: 7/1/2019
Surface: AC Fan	way_AC/AAC	/5_Taxi Zone: S21	Category: L	Rank: P
Area: 141,040 Sql	Ft Length:	3,590 Ft	Width: 35 Ft	
	ab Length:	Ft Slab Widt		Joint Length: Ft
	reet Type:	Grade:	0	Lanes: 0
Section Comments:				
Work Date: 9/1/1985	Work Type: Base Cou	rse - Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 9/2/1985	Work Type: New Con	struction - AC	Code: NC-AC	Is Major M&R: True
Work Date: 9/1/1997	Work Type: Overlay -	AC Thin	Code: OL-AT	Is Major M&R: True
Work Date: 9/1/1999	Work Type: Surface T	reatment - Seal Coat (Glob	al MR) Code: ST-SC	Is Major M&R: False
Work Date: 9/1/2003	Work Type: Crack Se	aling - AC	Code: CS-AC	Is Major M&R: False
Work Date: 9/1/2008	Work Type: Crack Se	al - Wide Cracks	Code: CS-WD	Is Major M&R: False
Work Date: 9/2/2008	Work Type: Patching	- AC Deep	Code: PA-AD	Is Major M&R: False
Work Date: 9/1/2012	Work Type: Crack Se	aling - AC	Code: CS-AC	Is Major M&R: False
Work Date: 9/1/2015	Work Type: Crack Se	aling - AC	Code: CS-AC	Is Major M&R: False
Work Date: 9/2/2015	Work Type: Patching	- AC Deep	Code: PA-AD	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Subbase	Aggregate	Code: SB-AG	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Base Cou	rse - Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Complete	Reconstruction - AC	Code: CR-AC	Is Major M&R: True
Last Insp. Date: 3/1/2022	TotalSamp	les: 36	Surveyed: 5	
Conditions: PCI: 99				
Inspection Comments:				
Sample Number: 01	Type: R	Area: 3	886.00 SqFt PCI: 96	
Sample Comments:				
48 L & T CR	L	15.00 Ft		
Sample Number: 13	Type: R	Area: 3:	546.00 SqFt PCI: 10	0
Sample Comments:				
<no distress=""></no>				
Sample Number: 19 Sample Comments:	Type: R	Area: 3.	525.00 SqFt PCI: 10	0
<no distress=""></no>				
Sample Number: 25	Type: R	Area: 5	865.00 SqFt PCI: 10	0
Sample Comments:	rjpo.	ziiva J	101, 10	~
<no distress=""></no>				
Sample Number: 31	Type: R	Area: 3:	525.00 SqFt PCI: 10	0
Sample Comments:	-JPC- IC	zarome J.	-20.00 Sqrt 101. 10	•
F				

Network: Sunriver		Name:	Sunriver		
Branch: T02SU	Name:	Taxiway 02 Sunriver	Use: TA	AXIWAY	Area: 11,900 SqFt
Section: 01 Surface: AC		om: T01SU-01 at4/5_Taxi Zone: S21	l	To: R18SU-01 Category: L	Last Const.: 7/1/2019 Rank: P
Area: 11,90	00 SqFt Length:	160 Ft	Width:	75 Ft	
Slabs:	Slab Length:	Ft Slab Wid	th:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade:	0		Lanes: 0
Section Comments:					
Work Date: 9/1/1970	Work Type: Base C	ourse - Aggregate	Code:	BA-AG	Is Major M&R: False
Work Date: 9/2/1970	Work Type: Surface	Course - Double Bitum.	Code:	SU-DB	Is Major M&R: True
Work Date: 9/1/1997	Work Type: Overla	y - AC Thin	Code:	OL-AT	Is Major M&R: True
Work Date: 9/1/1999	Work Type: Surface	Treatment - Seal Coat (Glo	obal MR) Code:	ST-SC	Is Major M&R: False
Work Date: 9/1/2008	Work Type: Crack	Seal - Wide Cracks	Code:	CS-WD	Is Major M&R: False
Work Date: 9/2/2008	Work Type: Patchir	g - AC Deep	Code:	PA-AD	Is Major M&R: False
Work Date: 9/1/2012	Work Type: Crack	Sealing - AC	Code:	CS-AC	Is Major M&R: False
Work Date: 9/1/2015	Work Type: Crack	Sealing - AC	Code:	CS-AC	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Base C	ourse - Aggregate	Code:	BA-AG	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Comple	ete Reconstruction - AC	Code:	CR-AC	Is Major M&R: True
Work Date: 7/1/2019	Work Type: Subbas	e - Aggregate	Code:	SB-AG	Is Major M&R: False
Last Insp. Date: 3/1/2022	TotalSar	nples: 2	Surveyed:	2	
Conditions: PCI: 100					
Inspection Comments:					
Sample Number: 01	Type: R	Area:	5657.00 SqFt	PCI: 100	
Sample Comments:					
<no distress=""></no>					
Sample Number: 02	Type: R	Area:	6243.00 SqFt	PCI: 100	

Sample Comments:

Network: Sunriver		Name: Sun	nriver	
Branch: T03SU	Name: Tax	iway 03 Sunriver	Use: TAXIWAY	Area: 14,230 SqFt
Section: 01	of 1 From:	T01SU-02	To: R18SU	J-01 Last Const.: 7/1/201
Surface: AC	Family: 2022_Central_Cat4/5_7 way_AC/AAC	Taxi Zone: S21	Category: L	Rank: P
Area: 14,23	30 SqFt Length:	160 Ft	Width: 75 Ft	
Slabs:		Slab Width:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0		Lanes: 0
Section Comments:				
Work Date: 9/1/1970	Work Type: Base Course	Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 9/2/1970	Work Type: Surface Cours	se - Double Bitum.	Code: SU-DB	Is Major M&R: True
Work Date: 9/1/1985	Work Type: Overlay - AC	Thin	Code: OL-AT	Is Major M&R: True
Work Date: 9/1/1997	Work Type: Crack Sealing	g - AC	Code: CS-AC	Is Major M&R: False
Work Date: 9/1/2008	Work Type: Crack Seal - V	Wide Cracks	Code: CS-WD	Is Major M&R: False
Work Date: 9/2/2008	Work Type: Patching - AC	Deep	Code: PA-AD	Is Major M&R: False
Work Date: 9/1/2012	Work Type: Crack Sealing	g - AC	Code: CS-AC	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Base Course	Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 7/1/2019	Work Type: Complete Red	construction - AC	Code: CR-AC	Is Major M&R: True
Work Date: 7/1/2019	Work Type: Subbase - Ag	gregate	Code: SB-AG	Is Major M&R: False
Last Insp. Date: 3/1/2022	TotalSamples:	4	Surveyed: 3	
Conditions: PCI: 100 Inspection Comments:				
Sample Number: 01	Type: R	Area: 3430	6.00 SqFt PCI:	100
Sample Comments:	••		•	
No Distress>				
Sample Number: 02 Sample Comments:	Type: R	Area: 356.	5.00 SqFt PCI:	100
<no distress=""></no>				
Sample Number: 03	Type: R	Area: 370	3.00 SqFt PCI:	100

Sample Comments:

Network: Sunriver Name: Sunriver **Branch:** T04SU Taxiway 04 Sunriver Use: TAXIWAY 19,210 SqFt Name: Area: **Section:** 01 of 4 T04SU-02 T01SU-02 Last Const.: 7/1/2020 From: To: Surface: ACFamily: 2022_Central_Cat4/5_Taxi Zone: Rank: S Category: way_AC/AAC Width: 6,361 SqFt Length: 190 Ft 35 Ft Area: Ft Slabs: Slab Length: Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: Grade: **Section Comments:** Work Type: Subbase - Aggregate Work Date: 7/1/2020 Code: SB-AG Is Major M&R: False Code: CR-AC Work Date: 7/1/2020 Work Type: Complete Reconstruction - AC Is Major M&R: True **Last Insp. Date:** 3/1/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:**

6361.00 SqFt

PCI: 100

Sample Number: 01 **Sample Comments:**

R

Area:

Type:

Network: Sunriver Name: Sunriver **Branch:** T04SU Taxiway 04 Sunriver Use: TAXIWAY 19,210 SqFt Name: Area: **Section:** 04 of 4 T04SU-01 Last Const.: 7/1/2020 From: To: End Surface: ACFamily: 2022_Central_Cat4/5_Taxi Zone: Rank: S Category: way_AC/AAC Width: 4,734 SqFt Length: 135 Ft 25 Ft Area: Ft Slabs: Slab Length: Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: Grade: **Section Comments:** Work Date: 7/1/2020 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True Code: SB-AG Work Date: 7/1/2020 Work Type: Subbase - Aggregate Is Major M&R: False **Last Insp. Date:** 3/1/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:**

4734.00 SqFt

PCI: 100

Sample Number: 01 **Sample Comments:**

R

Area:

Type:

Network: Sunriver Name: Sunriver **Branch:** T04SU Taxiway 04 Sunriver Use: TAXIWAY 19,210 SqFt Name: Area: **Section:** 03 of 4 T04SU-01 Last Const.: 7/1/2020 From: To: End Surface: ACFamily: 2022_Central_Cat4/5_Taxi Zone: Rank: S Category: way_AC/AAC 3,980 SqFt Width: Length: 115 Ft 25 Ft Area: Ft Slabs: Slab Length: Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: Grade: **Section Comments:** Work Date: 7/1/2020 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True Code: SB-AG Work Date: 7/1/2020 Work Type: Subbase - Aggregate Is Major M&R: False **Last Insp. Date:** 3/1/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:**

3980.00 SqFt

PCI: 100

Sample Number: 01 **Sample Comments:**

R

Area:

Type:

Network:	Sunriver					Nam	ie: Su	nriver					
Branch:	T04SU			Name:	Taxiwa	y 04 Su	ınriver	Use:	TAXIW	AY	Area:	19,210 Sc	qFt
Section:	02	o	f 4	I	From: T	Γ04SU-	01		To:	SU-01		Last C	onst.: 1/1/1970
Surface:	AC	Family:		_Central_ _AC/AAC	Cat4/5_Taxi	Zone	e: S21		Cate	gory: L		Rank:	S
Area:	4,	135 SqFt		Length:		120 F	t	Width:		35 Ft			
Slabs:		Slab Ler	igth:		Ft		Slab Width	:	Ft		Joint Length	ı:	Ft
Shoulder:		Street T	ype:				Grade:	0			Lanes: 0)	
Section Co	omments:												
Work Dat	te: 1/1/1970	W	ork T	ype: New	Construction	n - AC		C	ode: NC	-AC	Is Major	r M&R: Ti	rue
Last Insp.	Date: 3/1/202	2		TotalS	amples: 1			Surveyo	ed: 1				
Condition	s: PCI: 70)											
Inspection	Comments:												
Sample N	umber: 01	Tyl	pe:	R	Ai	rea:	41	35.00 SqFt		PCI: 70			
Sample Co	omments:												
41 AL	LIGATOR CR		L		20.00	SqFt							
	& T CR		N		119.00								
	EATHERING LIGATOR CR		L		4135.00 18.00	-							
			L										

Network: Sunriver			Name	: Sun	river						
Branch: T05SU]	Name: Taxi	way 05 Sur	nriver	Use	: TA	XIWAY	Ar	ea:	13,690 SqFt	
Section: 01	of 1	From:	T01SU-0	2			To: R18S	U-01		Last Const.:	7/1/2019
Surface: AC		_Central_Cat4/5_T _AC/AAC	axi Zone:	S21			Category:	L		Rank: P	
Area: 13,69	0 SqFt	Length:	160 Ft		Width:		75 Ft				
Slabs:	Slab Length:	F	t S	Slab Width:			Ft		Joint Length	: F	t
Shoulder:	Street Type:		•	Grade: 0					Lanes: 0		
Section Comments:											
Work Date: 6/1/2014	Work Ty	vpe: New Construc	tion - AC			Code:	NC-AC		Is Major	M&R: True	
Work Date: 7/1/2019	Work Ty	vpe: Subbase - Agg	regate			Code:	SB-AG		Is Major	M&R: False	
Work Date: 7/1/2019	Work Ty	vpe: Base Course -	Aggregate			Code:	BA-AG		Is Major	M&R: False	
Work Date: 7/1/2019	Work Ty	vpe: New Construc	tion - AC			Code:	NC-AC		Is Major	M&R: True	
Last Insp. Date: 3/1/2022		TotalSamples:	4		Surve	yed: 3	3				
Conditions: PCI: 100											
Inspection Comments:											
Sample Number: 01	Type:	R	Area:	3573	3.00 SqFt		PCI:	100			
Sample Comments:											
<no distress=""></no>											
Sample Number: 02	Type:	R	Area:	3627	7.00 SqFt		PCI:	100			
Sample Comments:											
<no distress=""></no>											
Sample Number: 04	Type:	R	Area:	323	1.00 SqFt		PCI:	100			
Sample Comments:											

Network: Sunriver Name: Sunriver Branch: T06SU Taxiway 06 Sunriver Use: TAXIWAY 13,970 SqFt Name: Area: **Last Const.:** 7/1/2019 01 of 1 T01SU-02 R18SU-01 Section: From: To: Surface: ACFamily: 2022_Central_Cat4/5_Taxi Zone: Rank: P Category: way AC/AAC Width: 13,970 SqFt Length: 160 Ft 75 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: Shoulder: Grade: **Section Comments:** Work Date: 7/1/2019 Work Type: Base Course - Aggregate Code: BA-AG Is Major M&R: False Work Date: 7/1/2019 Work Type: Subbase - Aggregate Code: SB-AG Is Major M&R: False Work Date: 7/1/2019 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True TotalSamples: 4 **Last Insp. Date:** 3/1/2022 Surveyed: 3 **Conditions:** PCI: **Inspection Comments:** Sample Number: 02 R 3470.00 SqFt **PCI:** 100 Type: Area: **Sample Comments:** <No Distress> **PCI:** 100 Sample Number: 03 Type: R Area: 3513.00 SqFt **Sample Comments:** <No Distress>

3570.00 SqFt

PCI: 100

Sample Number: 04 Sample Comments: R

Area:

Type:

Network: Sunriver Name: Sunriver 7,431 SqFt Branch: T07SU Taxiway 07 Sunriver Use: TAXIWAY Name: Area: 01 T01SU-01 R18SU-01 Last Const.: 7/1/2019 Section: of 1 From: To: Surface: ACFamily: 2022_Central_Cat4/5_Taxi Zone: Rank: P Category: way AC/AAC Width: 7,431 SqFt Length: 130 Ft 45 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: Shoulder: Grade: **Section Comments:** Work Date: 7/1/2019 Work Type: Base Course - Aggregate Code: BA-AG Is Major M&R: False Work Date: 7/1/2019 Work Type: Subbase - Aggregate Code: SB-AG Is Major M&R: False Work Date: 7/1/2019 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True TotalSamples: 2 **Last Insp. Date:** 3/1/2022 Surveyed: 2 **Conditions:** PCI: **Inspection Comments:** Sample Number: 01 R 2744.00 SqFt **PCI:** 100 Type: Area: **Sample Comments:** <No Distress>

No Distress

Sample Number:02Type:RArea:4687.00 SqFtPCI:100

Sample Comments:

Netw	ork: Sunrive	r				Name	: Sum	river						
Bran	ch: THANG	GARSU		Name:	T-Han	gar Taxiw	ays Sunriver	Use:	TAXIWAY	A	rea:	76	,038 SqFt	
Section	on: 02		of 5	Fı	om:	THANGA	AR-01		To: End	1]	Last Const.:	1/1/1970
Surfa	ace: AC	Family:		2_Central_C _AC/AAC	at4/5_Tax	i Zone:	S21		Category	: L		1	Rank: S	
Area	:	18,181 SqFt		Length:		260 Ft		Width:	70	Ft				
Slabs	:	Slab Le	ngth:		Ft	S	Slab Width:		Ft		Joint Le	ngth:	F	t
Shou	lder:	Street 7	Type:			(Grade: 0				Lanes:	0		
Section	on Comments:		• •											
	k Date: 1/1/1970	v	Vork T	ype: New C	Construction	on - AC		C	Code: NC-AC		Is M	Iajor M&	kR: True	
Last	Insp. Date: 3/1	/2022		TotalSa	mples:	<u></u>		Surveyo	ed: 3					
	litions: PCI:			Totalsa	iipics.	•		Survey						
Inspe	ection Comments	5:												
Samp	ole Number: 01	Ту	pe:	R	A	rea:	5250	0.00 SqFt	PCI	: 71				
Samp	ole Comments:	Created by In	spectio	on Schedule										
50	PATCHING		I	L	108.00	SaFt								
48	L & T CR			M	150.00	-								
57	WEATHERING	G	I	L	5250.00									
Samp	ole Number: 02	. Ty	pe:	R	A	rea:	5250	0.00 SqFt	PCI	: 72				
Samp	ole Comments:	Created by In	spection	on Schedule										
50	PATCHING		I	L	200.00	SqFt								
48	L & T CR		1	M	119.00	Ft								
48	L & T CR		I	Ĺ	14.00	Ft								
57	WEATHERING	G	I	Ĺ	5250.00	SqFt								
Samp	ole Number: 03	Ту	pe:	R	A	rea:	3500	0.00 SqFt	PCI	: 72				
Samp	ole Comments:	Created by In	spectio	on Schedule										
57	WEATHERING	G	I	L	3500.00	SqFt								
48	L & T CR			M	113.00	-								
50	PATCHING		I	Ĺ	27.00	SqFt								

L

27.00 SqFt

Network:	Sunriver				Name: Sur	nriver			
Branch:	THANGAR	SU	Name:	T-Hangar	Taxiways Sunrive	r Use:	TAXIWAY	Area:	76,038 SqFt
Section: 0	01	of 5	Fr	om: T04	4		To: End		Last Const.: 1/1/1970
Surface: A	AC		22_Central_Ca y_AC/AAC	at4/5_Taxi	Zone: S21		Category: I		Rank: S
Area:	17,4	460 SqFt	Length:	3	888 Ft	Width:	45 Ft		
Slabs:		Slab Length:		Ft	Slab Width:		Ft	Joint Length	r: Ft
Shoulder:		Street Type:			Grade: 0			Lanes: 0	
Section Con	nments:								
Work Date:	: 1/1/1970	Work 7	Гуре: New C	onstruction -	- AC	C	Code: NC-AC	Is Major	r M&R: True
Last Insp. D	Date: 3/1/2022	2	TotalSan	nples: 4		Surveyo	ed: 3		
Conditions:	PCI: 65								
Inspection C	Comments:								
Sample Nun	nber: 01	Type:	R	Are	a: 450	0.00 SqFt	PCI:	66	
Sample Con	nments: C	reated by Inspecti	on Schedule						
57 WEA	ATHERING		L	4500.00 Sc	ηFt				
	CHING		L	54.00 Sc	•				
48 L&7	T CR		M	220.00 Ft	t				
Sample Nun	nber: 02	Type:	R	Are	45 0	0.00 SqFt	PCI:	62	
Sample Con	nments: C	reated by Inspecti	on Schedule						
48 L&7	T CR		L	61.00 Ft	t				
50 PATO	CHING		L	100.00 Sc	qFt				
57 WEA	ATHERING		L	4500.00 Sc	qFt				
48 L&7	T CR		M	200.00 Ft	t				
Sample Nun	nber: 03	Type:	R	Are	a: 450	0.00 SqFt	PCI:	68	
Sample Con	nments: C	reated by Inspecti	on Schedule			-			

 L & T CR
 M
 253.00 Ft

 WEATHERING
 L
 4500.00 SqFt

Network:	Sunriver			Nan	ne: Sunr	iver			
Branch:	THANGARS	SU	Name:	T-Hangar Tax	iways Sunriver	Use:	TAXIWAY	Area:	76,038 SqFt
Section:	03	of	5	From: THANG	GAR-01		To: End		Last Const.: 1/1/1
Surface:	AC	Family:	2022_Central way_AC/AAC	_Cat4/5_Taxi	e: S21		Category: L		Rank: S
Area:	15,58	84 SqFt	Length:	260 F	t	Width:	60 Ft		
Slabs:		Slab Leng	gth:	Ft	Slab Width:		Ft	Joint Length:	: Ft
Shoulder:		Street Ty	pe:		Grade: 0			Lanes: 0	
Section Co	omments:								
Work Dat	e: 1/1/1970	Wo	ork Type: New	v Construction - AC		C	ode: NC-AC	Is Major	M&R: True
Last Insp.	Date: 3/1/2022		Totals	Samples: 3		Surveye	ed: 2		
Last Insp. Condition			Totals	Samples: 3		Surveyo	ed: 2		
Condition			Totals	Samples: 3		Surveye	ed: 2		
Condition: Inspection	s: PCI : 71	Тур		Samples: 3 Area:	6000.	Surveyo	PCI: 7	1	
Condition: Inspection	s: PCI: 71 a Comments: umber: 02	Тур		Area:	6000.			1	
Condition Inspection Sample No	s: PCI: 71 a Comments: umber: 02	Тур	e: R	Area:	6000.			1	
Conditional Inspection Sample Notes Sample Construction Sample Construction WE	s: PCI: 71 a Comments: umber: 02 omments: Cr	Тур	e: R	Area:	6000.			1	
Condition: Inspection Sample No Sample Co 57 WF 48 L &	s: PCI: 71 n Comments: umber: 02 comments: Cr	Тур	e: R pection Schedu	Area: le 6000.00 SqFt	6000.			1	
Condition: Inspection Sample No Sample Co 57 WF 48 L & 50 PA	s: PCI: 71 n Comments: umber: 02 comments: Cr EATHERING	Тур	e: R Dection Schedul L M L	Area: le 6000.00 SqFt 164.00 Ft					
Condition: Inspection Sample No Sample Co 57 WF 48 L & 50 PA	s: PCI: 71 n Comments: umber: 02 comments: Cr EATHERING & T CR TCHING umber: 03	Type reated by Insp	e: R Dection Schedul L M L	Area: le 6000.00 SqFt 164.00 Ft 135.00 SqFt Area:		.00 SqFt	PCI: 7		
Condition: Inspection Sample No Sample Co 57 WE 48 L & 50 PA Sample No Sample Co	s: PCI: 71 n Comments: umber: 02 comments: Cr EATHERING & T CR TCHING umber: 03	Type reated by Insp	e: R pection Schedul L M L e: R	Area: le 6000.00 SqFt 164.00 Ft 135.00 SqFt Area:		.00 SqFt	PCI: 7		
Condition: Inspection Sample No Sample Co 57 WF 48 L & 50 PA Sample No Sample Co 50 PA	s: PCI: 71 a Comments: umber: 02 comments: Cr EATHERING & T CR TCHING umber: 03 comments: Cr	Type reated by Insp	e: R pection Schedu L M L e: R pection Schedu	Area: le 6000.00 SqFt 164.00 Ft 135.00 SqFt Area:		.00 SqFt	PCI: 7		
Condition: Inspection Sample No Sample Co 57 WE 48 L & 50 PA Sample No Sample Co 50 PA 57 WE	s: PCI: 71 Comments: umber: 02 comments: Cr EATHERING & T CR TCHING umber: 03 comments: Cr TCHING	Type reated by Insp	e: R pection Schedu L M L e: R pection Schedu L	Area: le 6000.00 SqFt 164.00 Ft 135.00 SqFt Area: le 159.00 SqFt		.00 SqFt	PCI: 7		

Network:	Sunriver			I	Name: Sun	river					
Branch:	THANGA	RSU	Name:	T-Hangar	Taxiways Sunriver	Use:	TAXIWA	Y	Area:	76,038 SqFt	
Section:	04	of	5	From: TH	ANGAR-01		To:	End		Last Cons	t.: 1/1/1970
Surface:	AC	Family:	2022_Centra way_AC/AA	l_Cat4/5_Taxi Z C	Zone: S21		Catego	ory: L		Rank: S	
Area:	15	5,584 SqFt	Length	: 26	60 Ft	Width:	(60 Ft			
Slabs:		Slab Leng	gth:	Ft	Slab Width:		Ft		Joint Length	h:	Ft
Shoulder:		Street Ty	pe:		Grade: 0				Lanes: 0	0	
Section Co	omments:										
Work Date	e: 1/1/1970	Wo	ork Type: Ne	w Construction -	AC		ode: NC-A	·C	Is Maio	r M&R: True	
		****	ork Type. Ive	w Construction -	110	C			13 1410/01	ivicer. True	
Last Insp.	Date: 3/1/20			Samples: 3		Surveye			13 1414101	Tivica, Tiuc	
-	Date: 3/1/20	22			710				13 1414101	Tivian. True	
Conditions	Date: 3/1/20	22			AC .				13 1/14/01	THER. He	
Conditions Inspection	Date: 3/1/20 s: PCI: 7	22	Total				ed: 2	PCI: 73	13 1124301	THE THE	
Conditions Inspection Sample Nu	Date: 3/1/20 s: PCI: 7 Comments:	22	Total	Samples: 3		Surveye	ed: 2		13 1124301	T Meet. The	
Conditions Inspection Sample Nu Sample Co	Date: 3/1/20 s: PCI: 7 Comments:	22 '4 Typ	Total	Samples: 3	ı: 6000	Surveye	ed: 2		13 112430	T MCC. THE	
Conditions Inspection Sample Nu Sample Co	Date: 3/1/20 s: PCI: 7 Comments: umber: 01 comments:	22 '4 Typ	Total e: R pection Schedu	Samples: 3 Area	ı: 6000	Surveye	ed: 2		13 1144	T MCCC THE	
Conditions Inspection Sample Nu Sample Co 50 PA' 57 WE	Date: 3/1/20 s: PCI: 7 Comments: umber: 01 omments:	22 '4 Typ	Total e: R pection Schedu L	Area ale 76.00 Sq	ı: 6000 Ft Ft	Surveye	ed: 2		13 1124301	T Meet. The	
Conditions Inspection Sample Nu Sample Co 50 PA' 57 WE 48 L &	Date: 3/1/20 s: PCI: 7 Comments: umber: 01 omments: TCHING	22 '4 Typ	Total e: R pection Schedu L L M	Area ale 76.00 Sq 6000.00 Sq	ı: 6000 Ft Ft	Surveye	ed: 2		13 1111301	T MCC. THE	
Conditions Inspection Sample Nu Sample Co 50 PA 57 WE 48 L & Sample Nu	Date: 3/1/20 ss: PCI: 7 Comments: umber: 01 omments: TCHING EATHERING a T CR umber: 02	22 74 Typ Created by Insp	Total e: R pection Schedu L L M e: R	Area alle 76.00 Sq 6000.00 Sq 154.00 Ft	ı: 6000 Ft Ft	Surveye	ed: 2	PCI: 73	13 112430	T Meet. The	
Conditions Inspection Sample Nu Sample Co 50 PA 57 WE 48 L & Sample Nu Sample Co	Date: 3/1/20 ss: PCI: 7 Comments: umber: 01 omments: TCHING EATHERING a T CR umber: 02	22 '4 Typ Created by Insp	Total e: R pection Schedu L L M e: R	Area alle 76.00 Sq 6000.00 Sq 154.00 Ft	i: 6000 Ft Ft I: 6000	Surveye	ed: 2	PCI: 73	13 1124	THERE THE	
Conditions Inspection Sample Nu Sample Co 50 PA' 57 WE 48 L & Sample Nu Sample Co 48 L &	Date: 3/1/20 s: PCI: 7 Comments: Imber: 01 Domments: TCHING EATHERING T CR Imber: 02 Domments:	22 '4 Typ Created by Insp	Total e: R pection Schedu L L M e: R pection Schedu	Area ale 76.00 Sq 6000.00 Sq 154.00 Ft Area ale	i: 6000 Ft Ft I: 6000	Surveye	ed: 2	PCI: 73	13 1124		

Network: Sunriv	/er		Nam	ne: Sun	river			
Branch: THAN	NGARSU	Name:	T-Hangar Tax	iways Sunriver	Use:	TAXIWAY	Area:	76,038 SqFt
Section: 05	of	5	From: THANG	GAR-01		To: End		Last Const.: 1/1/1970
Surface: AC		2022_Central_ way_AC/AAC	Cat4/5_Taxi Zon	e: S21		Category: L		Rank: S
Area:	9,229 SqFt	Length:	260 F	t	Width:	35 Ft		
Slabs:	Slab Leng	gth:	Ft	Slab Width:		Ft	Joint Length:	Ft
Shoulder:	Street Typ	pe:		Grade: 0			Lanes: 0	
Section Comments:								
Work Date: 1/1/197	70 Wo	rk Type: New	Construction - AC		C	ode: NC-AC	Is Major	M&R: True
Last Insp. Date: 3/	1/2022	TotalS	amples: 2		Surveye	ed: 2		
Conditions: PCI:								
Inspection Commen	ts:							
Sample Number: ()1 Type	e: R	Area:	5309	0.00 SqFt	PCI: 77	7	
Sample Comments:	Created by Insp		e		1			
57 WEATHERIN	NG	L	5309.00 SqFt					
50 PATCHING		L	35.00 SqFt					
48 L & T CR		M	97.00 Ft					
Sample Number: ()2 Туре	: R	Area:	3120	0.00 SqFt	PCI: 72	2	
Sample Comments:	Created by Insp	ection Schedule	e					
48 L & T CR		M	96.00 Ft					
57 WEATHERIN	NG	L	3120.00 SqFt					
48 L & T CR		L	12.00 Ft					

12.00 SqFt

L

50

PATCHING



APPENDIX F

Work History Report

Page 1 of 7

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network: Sunriver		Branch: A01SU	J Apron	01 Sunriver	Section:	01 Surface:AC		
L.C.D. 7/1/2	020 U:	se: APRON Rank: P	Length: 625	5.00 (Ft) Wi	dth: 175.0	0 (Ft) True Area: 76472.00002 (SqFt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
7/1/2020	CR-AC	Complete Reconstruction - AC	0.00	4.00				
7/1/2020	SB-AG	Subbase - Aggregate	0.00	12.00				
9/2/2015	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2015		
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2015		
9/2/2012	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2012, includes Joint Repair		
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2012		
9/1/2003	CS-AC	Crack Sealing - AC	0.00	0.10				
9/1/1999	ST-SC	Surface Treatment - Seal Coat (Global MR)	0.00	0.10				
9/1/1997	OL-AT	Overlay - AC Thin	0.00	2.00				
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10		UNKNOWN DATE		
9/2/1985	NC-AC	New Construction - AC	0.00	2.00				
9/1/1985	BA-AG	Base Course - Aggregate	0.00	24.00				
Network:	Sunriver	Branch: A01SU	J Apron	01 Sunriver	Section:	02 Surface:PCC		
L.C.D. 7/1/2	L.C.D. 7/1/2020 Use: APRON Rank: P Length: 300.00 (Ft) Width: 67.00 (Ft) True Area: 20575.00000 (SqFt							
		sc. Alkon Kaik, i i	Angui. 300	.00 (11) **1	utii: 07.0	o (11) True Area. 20375.00000 (Sqrt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
	Work		Cost	Thickness	Major			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R			
Work Date 7/1/2020	Work Code CR-PC	Work Description Complete Reconstruction - PCC	Cost 172,000.00	Thickness (in)	Major M&R			
Work Date 7/1/2020 7/1/2020	Work Code CR-PC SB-AG	Work Description Complete Reconstruction - PCC Subbase - Aggregate	Cost 172,000.00 0.00	Thickness (in) 6.00 10.00	Major M&R	Comments		
Work Date 7/1/2020 7/1/2020 9/1/1997	Work Code CR-PC SB-AG CS-AC	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat	Cost 172,000.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10	Major M&R	Comments UNKNOWN DATE		
7/1/2020 7/1/2020 9/1/1997 9/3/1970	Work Code CR-PC SB-AG CS-AC ST-SC	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR)	Cost 172,000.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10	Major M&R	Comments UNKNOWN DATE		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970	Work Code CR-PC SB-AG CS-AC ST-SC	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum.	Cost 172,000.00 0.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50	Major M&R	Comments UNKNOWN DATE UNKNOWN		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum.	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50	Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00	Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder Surface: AC		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network:	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00	Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder Surface: AC		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network: L.C.D. 7/1/2	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG Sunriver 020 Us Work	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU se: APRON Rank: P I	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00 Apron ength: 925	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00 01 Sunriver 6.00 (Ft) Wi	Major M&R W Section: dth: 400.0	Comments UNKNOWN DATE UNKNOWN Cinder 03 Surface:AC 0 (Ft) True Area: 349900.0001 (SqFt		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network: L.C.D. 7/1/2 Work Date	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG Sunriver 020 Work Code	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU se: APRON Rank: P I	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00 Apron cength: 925	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00 01 Sunriver .00 (Ft) Wir	Major M&R W Section: dth: 400.0 Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder 03 Surface:AC 0 (Ft) True Area: 349900.0001 (SqFt		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network: L.C.D. 7/1/2 Work Date 7/1/2020	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG Sunriver 020 Us Work Code CR-AC	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU See: APRON Rank: P I Work Description Complete Reconstruction - AC	Cost 172,000.00 0.00 0.00 0.00 0.00 Apron cength: 925 Cost 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00 01 Sunriver 6.00 (Ft) Wi Thickness (in) 4.00	Major M&R W Section: dth: 400.0 Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder 03 Surface:AC 0 (Ft) True Area: 349900.0001 (SqFt		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network: L.C.D. 7/1/2 Work Date 7/1/2020 7/1/2020	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG Sunriver 020 U: Work Code CR-AC SB-AG	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU se: APRON Rank: P I Work Description Complete Reconstruction - AC Subbase - Aggregate	Cost 172,000.00 0.00 0.00 0.00 0.00 0.00 Apron cength: 925 Cost 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00 01 Sunriver 00 (Ft) Wie Thickness (in) 4.00 12.00	Major M&R W Section: dth: 400.0 Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder 03 Surface:AC 0 (Ft) True Area: 349900.0001 (SqFt		
Work Date 7/1/2020 7/1/2020 9/1/1997 9/3/1970 9/2/1970 9/1/1970 Network: L.C.D. 7/1/2 Work Date 7/1/2020 7/1/2020 9/1/2003	Work Code CR-PC SB-AG CS-AC ST-SC SU-DB BA-AG Sunriver 020 US Work Code CR-AC SB-AG CS-AC	Work Description Complete Reconstruction - PCC Subbase - Aggregate Crack Sealing - AC Surface Treatment - Seal Coat (Global MR) Surface Course - Double Bitum. Base Course - Aggregate Branch: A01SU See: APRON Rank: P I Work Description Complete Reconstruction - AC Subbase - Aggregate Crack Sealing - AC	Cost 172,000.00 0.00 0.00 0.00 0.00 Apron cength: 925 Cost 0.00 0.00 0.00 0.00 0.00	Thickness (in) 6.00 10.00 0.10 0.10 1.50 14.00 01 Sunriver 00 (Ft) Wid Thickness (in) 4.00 12.00 0.10	Major M&R W Section: dth: 400.0 Major M&R	Comments UNKNOWN DATE UNKNOWN Cinder 03 Surface:AC 0 (Ft) True Area: 349900.0001 (SqFt		

Page 2 of 7

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network:	Sunriver	Branch: A01SU	Apron	01 Sunriver	Section:	04 Surface:PCC
L.C.D. 7/1/2	020 Us	se: APRON Rank: P L	ength: 130	.00 (Ft) Wi	dth: 150.0	0 (Ft) True Area: 19409.00000 (SqI
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2020	CR-PC	Complete Reconstruction - PCC	353,800.00	0.00	~	
9/1/1999	ST-SC	Surface Treatment - Seal Coat (Global MR)	0.00	0.10		
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10		UNKNOWN DATE
9/1/1982	OL-AT	Overlay - AC Thin	0.00	0.00		UNKNOWN
9/2/1970	SU-DB	Surface Course - Double Bitum.	0.00	1.50		
9/1/1970	BA-AG	Base Course - Aggregate	0.00	14.00		Cinder
			I			
Network:	Sunriver	Branch: A01SU	Apron	01 Sunriver	Section:	05 Surface:PCC
L.C.D. 7/1/2	020 Us	se: APRON Rank: P L	ength: 275	.00 (Ft) Wie	dth: 75.0	0 (Ft) True Area: 20625.00000 (Sql
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2020	NC-PC	New Construction - PCC	0.00	6.00	V	
7/1/2020	SB-AG	Subbase - Aggregate	0.00	22.00		
Network:	Sunriver	Branch: A01SU	Apron	01 Sunriver	Section:	06 Surface:PCC
L.C.D. 7/1/2	020 Us	se: APRON Rank: P L	ength: 90	.00 (Ft) Wie	dth: 20.0	0 (Ft) True Area: 1868.000000 (SqI
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2020	NU-IN	New Construction - Initial	0.00	0.00	~	
Network:		Branch: A02SU	1	02 Sunriver	Section:	
L.C.D. 7/1/2		se: APRON Rank: P L	ength: 100	.00 (Ft) Wie		0 (Ft) True Area: 7016.000002 (Sql
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019		New Construction - AC	0.00	4.00	~	
7/1/2019		Base Course - Aggregate	0.00	6.00		
7/1/2019	SU-CA	Subbase - Crushed Aggregate	0.00	24.00		
	<i>a</i> :	D 1 D1001		10/26 0	G	
Network:		Branch: R18SU		ay 18/36 Sun	Section:	
L.C.D. 9/2/2		se: RUNWAY Rank: P L	ength: 5,460			0 (Ft) True Area: 409820.0001 (SqI
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2012
9/2/2009	CR-AC	Complete Reconstruction - AC	0.00	2.50		
9/1/2009	BA-PA	Base Course - Pulverized AC	0.00	8.00		
9/1/1985	OL-AT	Overlay - AC Thin	0.00	2.00	~	
9/1/1970	BA-AG	Base Course - Aggregate	0.00	9.50		Cinder

Page 3 of 7

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network:	Sunriver	Branch: T01SU	Taxiwa	ay 01 Sunriv	Section:	01 Surface:AC
L.C.D. 7/1/20	019 Us	se: TAXIWAY Rank: P L	ength: 1,880	-	dth: 35.0	0 (Ft) True Area: 76490.00002 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00		
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	4.00		
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00	<u> </u>	
9/2/2008	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2008
9/1/2008	CS-WD	Crack Seal - Wide Cracks	0.00	0.00		PMP 2008
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10		
9/1/1990	OL-AT	Overlay - AC Thin	0.00	0.00		UNKNOWN DEPTH
9/2/1970	SU-DB	Surface Course - Double Bitum.	0.00	1.50		
9/1/1970	BA-AG	Base Course - Aggregate	0.00	14.00		Cinder
Network:	Sunriver	Branch: T01SU	Taxiwa	ay 01 Sunriv	Section:	02 Surface:AC
L.C.D. 7/1/20	019 Us	se: TAXIWAY Rank: P L	ength: 3,590	.00 (Ft) Wid	dth: 35.0	0 (Ft) True Area: 141040.0000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00		
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	4.00	~	
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00		
9/2/2015	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2015
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2012
9/2/2008	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2008
9/1/2008	CS-WD	Crack Seal - Wide Cracks	0.00	0.00		PMP 2008
9/1/2003	CS-AC	Crack Sealing - AC	0.00	0.10		
9/1/1999	ST-SC	Surface Treatment - Seal Coat (Global MR)	0.00	0.10		
9/1/1997	OL-AT	Overlay - AC Thin	0.00	2.00		
9/2/1985	NC-AC	New Construction - AC	0.00	2.00		
9/1/1985	BA-AG	Base Course - Aggregate	0.00	24.00	,	
Network:	Sunriver	Branch: T02SU	Taxiwa	ay 02 Sunriv	Section:	01 Surface:AC
L.C.D. 7/1/2	019 Us	se: TAXIWAY Rank: P L	ength: 160	.00 (Ft) Wid	dth: 75.0	0 (Ft) True Area: 11900.00000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019		Base Course - Aggregate	0.00	6.00		
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	4.00		
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00		
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<u></u>	PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<u> </u>	PMP 2012
9/2/2008	PA-AD	Patching - AC Deep	0.00	0.00	<u> </u>	PMP 2008
9/1/2008	CS-WD	Crack Seal - Wide Cracks	0.00	0.00		PMP 2008
9/1/1999	ST-SC	Surface Treatment - Seal Coat (Global MR)	0.00	0.10		
9/1/1997	OL-AT	Overlay - AC Thin	0.00	0.00	~	UNKNOWN
9/2/1970	SU-DB	Surface Course - Double Bitum.	0.00	1.50	~	
9/1/1970	BA-AG	Base Course - Aggregate	0.00	14.00	1.1	Cinder

Page 4 of 7

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network:	Sunriver	Branch: T03SU	Taxiwa	ay 03 Sunriv	Section:	01	Surface:AC
L.C.D. 7/1/20	019 Us	se: TAXIWAY Rank: P L	ength: 160	.00 (Ft) Wid	dth: 75.0	0 (Ft) True Are	a: 14230.00000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Со	mments
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00			
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	4.00			
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00			
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00		PMP 2012	
9/2/2008	PA-AD	Patching - AC Deep	0.00	0.00		PMP 2008	
9/1/2008	CS-WD	Crack Seal - Wide Cracks	0.00	0.00		PMP 2008	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10			
9/1/1985	OL-AT	Overlay - AC Thin	0.00	2.00			
9/2/1970	SU-DB	Surface Course - Double Bitum.	0.00	1.50			
9/1/1970	BA-AG	Base Course - Aggregate	0.00	14.00		Cinder	
Network:	Sunriver	Branch: T04SU	Taxiwa	ay 04 Sunriv	Section:	01	Surface:AC
L.C.D. 7/1/20	020 Us	se: TAXIWAY Rank: S L	ength: 190	.00 (Ft) Wid	lth: 35.0	0 (Ft) True Are	a: 6361.000001 (SqFt
	Work			Thickness	Major		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Work Date	Code	Work Description	Cost	(in)	M&R	Co	mments
7/1/2020	CR-AC	Complete Reconstruction - AC	31,805.00	4.00			
7/1/2020	SB-AG	Subbase - Aggregate	0.00	12.00			
Network:	Sunriver	Branch: T04SU	Taxiwa	ay 04 Sunriv	Section:	02	Surface:AC
L.C.D. 1/1/19	970 Us	se: TAXIWAY Rank: S L	ength: 120	.00 (Ft) Wid	lth: 35.0	0 (Ft) True Are	a: 4135.000001 (SqFt
Ward Data	Work	Warls Dagarintian	Cont	Thickness	Major	Ca	mments
Work Date	Code	Work Description	Cost	(in)	M&R	Co	
1/1/1970	NC-AC	INT C 4 4' AC		` '	Mark		innenes
		New Construction - AC	0.00	0.00	V		milients
		New Construction - AC					mments
Network:	Sunriver	Branch: T04SU		0.00 ay 04 Sunriv		03	Surface:AC
Network: L.C.D. 7/1/20		Branch: T04SU	Taxiwa		Section:		
L.C.D. 7/1/20	020 Us Work	Branch: T04SU se: TAXIWAY Rank: S L	Taxiwa	ay 04 Sunriv .00 (Ft) Wic	Section: dth: 25.0	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt
L.C.D. 7/1/20 Work Date	020 Us Work Code	Branch: T04SU se: TAXIWAY Rank: S L Work Description	Taxiwa ength: 115 Cost	ay 04 Sunriv .00 (Ft) Wic	Section: Ith: 25.0 Major M&R	0 (Ft) True Are	Surface:AC
L.C.D. 7/1/20 Work Date 7/1/2020	Work Code NC-AC	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC	Taxiwa ength: 115 Cost 0.00	ay 04 Sunriv .00 (Ft) Wid Thickness (in) 4.00	Section: dth: 25.0	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt
L.C.D. 7/1/20 Work Date	020 Us Work Code	Branch: T04SU se: TAXIWAY Rank: S L Work Description	Taxiwa ength: 115 Cost	ay 04 Sunriv .00 (Ft) Wic	Section: Ith: 25.0 Major M&R	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt
Work Date 7/1/2020 7/1/2020	Work Code NC-AC SB-AG	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC Subbase - Aggregate	Taxiwa ength: 115 Cost 0.00 0.00	ay 04 Sunriv .00 (Ft) Wic Thickness (in) 4.00 12.00	Section: dth: 25.0 Major M&R	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt mments
Work Date 7/1/2020 7/1/2020 Network:	Work Code NC-AC SB-AG	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC Subbase - Aggregate Branch: T04SU	Taxiwa ength: 115 Cost 0.00 0.00 Taxiwa	ay 04 Sunriv .00 (Ft) Wic Thickness (in) 4.00 12.00 ay 04 Sunriv	Section: Section: Major M&R Section:	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt mments Surface:AC
Work Date 7/1/2020 7/1/2020	Work Code NC-AC SB-AG Sunriver	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC Subbase - Aggregate Branch: T04SU	Taxiwa ength: 115 Cost 0.00 0.00 Taxiwa	ay 04 Sunriv .00 (Ft) Wic Thickness (in) 4.00 12.00 ay 04 Sunriv .00 (Ft) Wic	Section: Ath: 25.0 Major M&R Section: Ath: 25.0	0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt mments
Work Date 7/1/2020 7/1/2020 Network:	Work Code NC-AC SB-AG	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC Subbase - Aggregate Branch: T04SU	Taxiwa ength: 115 Cost 0.00 0.00 Taxiwa	ay 04 Sunriv .00 (Ft) Wic Thickness (in) 4.00 12.00 ay 04 Sunriv	Section: th: 25.0 Major M&R Section: th: 25.0 Major	0 (Ft) True Are Co 04 0 (Ft) True Are	Surface:AC a: 3980.000001 (SqFt mments Surface:AC
Work Date 7/1/2020 7/1/2020 Network: L.C.D. 7/1/20	Work Code NC-AC SB-AG Sunriver 020 Us Work	Branch: T04SU se: TAXIWAY Rank: S L Work Description New Construction - AC Subbase - Aggregate Branch: T04SU se: TAXIWAY Rank: S L	Taxiwa ength: 115 Cost 0.00 0.00 Taxiwa ength: 135	ay 04 Sunriv .00 (Ft) Wic Thickness (in) 4.00 12.00 ay 04 Sunriv .00 (Ft) Wic Thickness	Section: Ath: 25.0 Major M&R Section: Ath: 25.0	0 (Ft) True Are Co 04 0 (Ft) True Are	Surface: AC a: 3980.000001 (SqFt mments Surface: AC a: 4734.000001 (SqFt

Page 5 of 7

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Network:	Sunriver	Branch: T05SU	Taxiw	ay 05 Sunriv	Section:	Ol Surface: AC
L.C.D. 7/1/20	019 Us	se: TAXIWAY Rank: P	ength: 160	.00 (Ft) Wid	lth: 75.00	(Ft) True Area: 13690.00000 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	NC-AC	New Construction - AC	0.00	4.00	V	
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00		
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00		
6/1/2014	NC-AC	New Construction - AC	0.00	0.00	~	
Network:	Sunriver	Branch: T06SU	Taxiw	ay 06 Sunriv	Section:	Ol Surface: AC
L.C.D. 7/1/20		se: TAXIWAY Rank: P I	ength: 160	.00 (Ft) Wid		(Ft) True Area: 13970.00000 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	NC-AC	New Construction - AC	0.00	4.00	\	
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00		
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00		
Network:		Branch: T07SU		ay 07 Sunriv	Section:	
L.C.D. 7/1/20		se: TAXIWAY Rank: P I	ength: 130	.00 (Ft) Wid	1) (Ft) True Area: 7431.000002 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	NC-AC	New Construction - AC	0.00	4.00	V :	
7/1/2019	BA-AG	Base Course - Aggregate	0.00	6.00		
7/1/2019	SB-AG	Subbase - Aggregate	0.00	24.00		
,,1,2019					Ш.	
Network:	Sunriver	Branch: THAN	GARS T-Han	gar Taxiway	Section:	
	Sunriver 970 Us	Branch: THAN	GARS T-Han	gar Taxiway .00 (Ft) Wic	lth: 45.00	01 Surface: AC 0 (Ft) True Area: 17460.00000 (SqF
Network:	Sunriver	Branch: THAN	GARS T-Han	gar Taxiway		
Network: L.C.D. 1/1/19	Sunriver 970 Us Work	Branch: THAN se: TAXIWAY Rank: S I	GARS T-Han	gar Taxiway .00 (Ft) Wic	dth: 45.00 Major) (Ft) True Area: 17460.00000 (SqF
Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code	Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han ength: 388	gar Taxiway .00 (Ft) Wic	Major M&R) (Ft) True Area: 17460.00000 (SqF
Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han Length: 388 Cost 0.00	gar Taxiway .00 (Ft) Wid Thickness (in) 0.00	Major M&R	(Ft) True Area: 17460.00000 (SqF Comments
Network: L.C.D. 1/1/19 Work Date 1/1/1970	Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN	GARS T-Han ength: 388 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wid Thickness (in) 0.00	Major M&R	(Ft) True Area: 17460.00000 (SqF Comments
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network:	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN	GARS T-Han ength: 388 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness	Major M&R Section: 0 Major Major	Comments Surface:AC
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260	gar Taxiway .00 (Ft) Wid Thickness (in) 0.00 gar Taxiway .00 (Ft) Wid Thickness (in)	Major M&R Section: (dth: 70.00 Major M&R	Comments 22 Surface: AC 24 (Ft) True Area: 18181.00000 (SqF
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness	Major M&R Section: 0 Major Major	Comments 22 Surface: AC 24 (Ft) True Area: 18181.00000 (SqF
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00	Major M&R Section: (dth: 70.00 Major M&R	Comments 22 Surface: AC 2 (Ft) True Area: 18181.00000 (SqF
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN	GARS T-Han cength: 388 Cost 0.00 GARS T-Han cength: 260 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00	Major M&R Section: (dth: 70.00 Major M&R V Section: (Comments 22 Surface: AC 24 (Ft) True Area: 18181.00000 (SqF) Comments
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network:	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN	GARS T-Han cength: 388 Cost 0.00 GARS T-Han cength: 260 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in)	Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Major M&R Major M&R	Comments 22 Surface: AC 29 (Ft) True Area: 18181.00000 (SqF) Comments 20 Surface: AC 20 (Ft) True Area: 18181.00000 (SqF) Comments 23 Surface: AC
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han ength: 260	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway	Major M&R Section: 0 Major M&R Section: 0 Major M&R V Section: 0 Ith: 60.00	Comments 22 Surface: AC 23 (Ft) True Area: 18181.00000 (SqF Comments 24 Comments 25 Comments 26 Comments 27 Comments 28 Comments 29 Surface: AC Comments 29 Comments 20 (Ft) True Area: 15584.00000 (SqF
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code Code	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han ength: 260 Cost	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in)	Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Major M&R	Comments 22 Surface: AC 23 (Ft) True Area: 18181.00000 (SqF Comments 24 Comments 25 Comments 26 Comments 27 Comments 28 Comments 29 Surface: AC Comments 29 Comments 20 (Ft) True Area: 15584.00000 (SqF
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han ength: 260 Cost 0.00	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00	Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Major M&R	Comments Comments 17460.00000 (SqF Comments Co
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han congth: 260 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00	Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0	Comments Comments 17460.00000 (SqF Comments Co
Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network: L.C.D. 1/1/19 Work Date 1/1/1970 Network:	Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC Sunriver 970 Us Work Code NC-AC	Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC Branch: THAN se: TAXIWAY Rank: S I Work Description New Construction - AC	GARS T-Han ength: 388 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han ength: 260 Cost 0.00 GARS T-Han congth: 260 Cost 0.00 GARS T-Han	gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway .00 (Ft) Wic Thickness (in) 0.00 gar Taxiway	Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0 Major M&R Section: 0	Comments 17460.00000 (SqF Comments Comments Comments Comments Commen

10/7/2022	Work History Report	Page 6 of 7
	Pavement Database: ODA_WOC3_8-20-2022_PostSurvey	

Network:	Sunriver	Branch: THAN	IGARS T-Han	gar Taxiway	Section:	05 Surface:AC
L.C.D. 1/1/19	970 Us	se: TAXIWAY Rank: S	Length: 260	0.00 (Ft) Wie	dth: 35.0	0 (Ft) True Area: 9229.000002 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1970	NC-AC	New Construction - AC	0.00	0.00	V	

Page 7 of 7

Work History Report

Pavement Database: ODA_WOC3_8-20-2022_PostSurvey

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	17	1,405,603.00	11.15	5.91
Base Course - Pulverized AC	1	409,820.00	8.00	0.00
Complete Reconstruction - AC	8	1,086,213.00	3.81	0.50
Complete Reconstruction - PCC	2	39,984.00	3.00	3.00
Crack Seal - Wide Cracks	4	243,660.00	0.00	0.00
Crack Sealing - AC	17	2,067,282.00	0.05	0.05
New Construction - AC	15	362,196.00	1.87	1.86
New Construction - Initial	1	1,868.00	0.00	0.00
New Construction - PCC	1	20,625.00	6.00	0.00
Overlay - AC Thin	8	1,099,261.00	1.19	0.93
Patching - AC Deep	7	537,644.00	0.00	0.00
Subbase - Aggregate	14	761,398.00	18.57	6.02
Subbase - Crushed Aggregate	1	7,016.00	24.00	0.00
Surface Course - Double Bitum.	6	492,504.00	1.50	0.00
Surface Treatment - Seal Coat (Global MR)	5	269,396.00	0.10	0.00