

2022 ODA Pavement Evaluation Program The Dalles Municipal Airport

The Dalles, Oregon

May 8, 2023

Prepared for

State of Oregon Department of Aviation
3040 25th Street SE
Salem, OR 97303-1125

Prepared by



16520 SW Upper Boones Ferry Road, Suite 100
Tigard, OR 97224-7661
(503) 641-3478 | www.gri.com

TABLE OF CONTENTS

1	OVERVIEW.....	1
2	PAVEMENT INVENTORY	1
3	PAVEMENT CONDITION INSPECTION RESULTS.....	4
	3.1 Introduction.....	4
	3.2 Pavement Condition Index Survey Results	4
4	FUTURE PAVEMENT CONDITION ANALYSIS.....	5
	4.1 Introduction.....	5
	4.2 Future Condition Analysis	5
	4.3 Functional Remaining Life.....	6
5	MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS	7
	5.1 Introduction.....	7
	5.2 Recommended Localized Maintenance.....	7
	5.3 Global Maintenance and Rehabilitation Plan	8
6	LIMITATIONS.....	9

TABLES

Table 3-1:	ASTM PCI Rating Scale
Table 5-1:	Localized Maintenance Quantities
Table 5-2:	Global Maintenance and Rehabilitation Quantities

FIGURES

Figure 2.1:	The Dalles Municipal Airport Location Map
Figure 2.2:	The Dalles Municipal Airport Percent of Pavement Area by Surface Type
Figure 2.3:	The Dalles Municipal Airport Pavement Area by Branch Use
Figure 2.4:	The Dalles Municipal Airport Pavement Inventory
Figure 3.1:	2022 PCI Survey Results The Dalles Municipal Airport
Figure 3.2:	The Dalles Municipal Airport Pavement Condition Rating by Percent of Area
Figure 4.1:	Future Pavement Condition The Dalles Municipal Airport
Figure 5.1:	The Dalles Municipal Airport Pavement Network General Treatment Type Distribution Based on PCI
Figure 5.2:	5-Year Pavement Management Plan The Dalles Municipal Airport

APPENDICES

Appendix A:	Pavement Inventory Report and Maps
Appendix B:	Pavement Condition Index Survey Results
Appendix C:	Future Pavement Condition Analysis
Appendix D:	Unit Cost Data and Maintenance and Rehabilitation Plan
Appendix E:	Reinspection Report

APPENDICES (continued)

Appendix F: Work History Report

1 OVERVIEW

GRI assisted with updating the Oregon Department of Aviation (ODA) airport pavement management system and developing a five-year plan for global maintenance and rehabilitation (M&R) and preservation work for The Dalles Municipal Airport in Dallesport, Washington. This project was implemented as a part of the ODA and Federal Aviation Administration (FAA) *Oregon Continuous Aviation System Plan*. The information provided in this report ensures compliance with FAA Grant Assurance Number 11, which outlines that an airport shall have an effective airport pavement maintenance-management program in place to receive federal financial assistance for the construction, reconstruction, or repair of airport pavements.

GRI conducted surveys of the airside pavement at The Dalles Municipal Airport in 2022 in accordance with the procedures of Advisory Circular 150/5380-7B and ASTM International (ASTM) D5340. We uploaded the survey data into the PAVER database and used the software to provide a rapid calculation of the pavement condition index (PCI) rating. The PCI is a numerical indicator that defines the functional condition of the pavement based on visual inspection. The scale ranges from zero to 100, where zero represents a pavement in the worst possible condition with no remaining functional life and 100 represents a pavement in the best possible condition with no defects.

2 PAVEMENT INVENTORY

The Dalles Municipal Airport is located in Dallesport, Washington, and is owned and operated by the City of The Dalles and Klickitat County. The airport consists of two runways that serve a variety of general aviation aircraft and military aircraft. The general location of the airport is shown below on The Dalles Municipal Airport Location Map, Figure 2.1.



Figure 2.1 - THE DALLES MUNICIPAL AIRPORT LOCATION MAP

The Dalles Municipal Airport contains two runways, two primary parallel taxiways, multiple connector taxiways, taxilanes, aprons, and one helipad. The types of airside pavements include asphalt concrete (AC), AC overlaid with AC (AAC), and portland cement concrete (PCC). The airport pavements, delineated by surface type and branch use, are shown on The Dalles Municipal Airport Percent of Pavement Area by Surface Type, Figure 2.2, and on The Dalles Municipal Airport Pavement Area by Branch Use, Figure 2.3. The pavement inventory, including work history for each pavement section, is displayed spatially on The Dalles Municipal Airport Pavement Inventory, Figure 2.4. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively, in Appendix A. The sample unit layout for each section is shown on Figure 1A in Appendix A. We used the sampling rates outlined in Table 3A of Appendix A in our survey. The pavement inventory, including work history for individual airport pavement sections, is provided in the work history report located in Table 1F.




Figure 2.2 - THE DALLES MUNICIPAL AIRPORT PERCENT OF PAVEMENT AREA BY SURFACE TYPE





Figure 2.3 - THE DALLES MUNICIPAL AIRPORT PAVEMENT AREA BY BRANCH USE



ABBREVIATIONS: AC = ASPHALT CONCRETE; PCC = PORTLAND CEMENT CONCRETE; Cr. = CRUSHED; Agg. = AGGREGATE; Unk. = UNKNOWN








3 PAVEMENT CONDITION INSPECTION RESULTS

3.1 Introduction

GRI conducted a visual PCI survey of the airside pavements at The Dalles Municipal Airport in July 2022. The 2022 survey work was performed on sections last inspected in 2017 in order to update The Dalles Municipal Airport inspection data. GRI performed the 2022 PCI survey in accordance with the methods described in FAA Advisory Circular 150/5380-6C and ASTM D5340, and further discussed in Appendix B of this report.


The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. Further discussion of distress types for flexible and rigid pavement is provided in Appendix B and summarized in Table 1B in Appendix B. The results of the PCI survey are displayed using a seven-category rating scale in accordance with ASTM D5340. Details of the ASTM PCI rating scale are provided in Table 3-1 below.

Table 3-1: ASTM PCI RATING SCALE

PCI Color Legend	PCI Range	PCI Rating and Definition
	86 – 100	GOOD: Pavement has minor or no distresses and should require only routine maintenance.
	71 – 85	SATISFACTORY: Pavement has scattered low-severity distresses that should require only routine maintenance.
	56 – 70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. Maintenance and repair needs may range from routine to major.
	41 – 55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. M&R needs will be major.
	26 – 40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. M&R needs will be major.
	11 – 25	SERIOUS: Pavement has mainly high-severity distresses that may affect operational safety; immediate repairs are needed.
	0 – 10	FAILED: Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.



3.2 Pavement Condition Index Survey Results

The area-weighted average PCI for all airport pavements at The Dalles Municipal Airport is approximately 83. The section PCIs ranged from a low of 39 to a high of 100. The primary distresses observed during the inspection were weathering, longitudinal and transverse cracking, fatigue (alligator) cracking, bleeding, and patching on AC-surfaced pavements, and linear cracking, scaling, corner and joint spalling, and patching on PCC pavements. Section PCIs following our pavement survey are displayed below spatially on the 2022 PCI Survey Results The Dalles Municipal Airport, Figure 3.1.



2022 SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



2022 PCI SURVEY RESULTS
THE DALLES MUNICIPAL AIRPORT

The condition distribution of the network by percent of total pavement area is provided below on The Dalles Municipal Airport Pavement Condition Rating by Percent of Area, Figure 3.2. A summary of the pavement condition results by branch and section is included in Tables 2B and 3B of Appendix B, respectively. A comparison between the previous inspection and the 2022 inspection is provided in Table 4B in Appendix B. The re-inspection report that includes inspection details for individual sample units is provided in Table 1E in Appendix E.




Figure 3.2 - THE DALLES MUNICIPAL AIRPORT PAVEMENT CONDITION RATING BY PERCENT OF AREA

4 FUTURE PAVEMENT CONDITION ANALYSIS

4.1 Introduction

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy the future condition. Additional details regarding our future pavement condition analysis, including pavement condition prediction models, are provided in Appendix C. PCI performance curves developed for The Dalles Municipal Airport are displayed on Figures 1C through 4C in Appendix C.

4.2 Future Condition Analysis

Using the condition prediction models discussed above, the projected condition of each pavement section was determined for 5- and 10-year periods. Based on this analysis, we

project the PCI to decrease from a current value of 83 to a value of 76 in the year 2027 and 69 in year the 2032 if no maintenance or rehabilitation work is performed. The projected pavement condition in five years and ten years for each pavement section at The Dalles Municipal Airport is displayed spatially on the Future Pavement Condition The Dalles Municipal Airport, Figure 4.1 and listed in Table 1C in Appendix C, along with the past and present PCI values for the pavement network.


4.3 Functional Remaining Life

The functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated solely based on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement and typically a field exploration and testing program that includes core explorations and falling weight deflectometer (FWD) deflection tests.


We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at The Dalles Municipal Airport. The first type of functional remaining life is the time until rehabilitation such as an overlay is needed. The critical PCI, further discussed in Section C.3 of Appendix C, is the threshold used for this type of functional remaining life analysis. The second type of functional remaining life is the time until the pavement is no longer operational due to high foreign object debris (FOD) potential and increased safety concerns for trafficking aircraft. A PCI of 40 was set as the trigger point for the end of the pavement's functional service life with regard to FOD potential.

The two types of functional remaining life for each section at The Dalles Municipal Airport are summarized in Table 2C in Appendix C.

PREDICTED CONDITION IN 2027




PREDICTED CONDITION IN 2032



SECTION PCI

- (86 - 100) GOOD
- (71 - 85) SATISFACTORY
- (56 - 70) FAIR
- (41 - 55) POOR
- (26 - 40) VERY POOR
- (11 - 25) SERIOUS
- (0 - 10) FAILED



5 MAINTENANCE AND REHABILITATION PROJECT RECOMMENDATIONS

5.1 Introduction

We evaluated M&R needs, as determined from the PAVER analysis results, in order to develop localized maintenance, global maintenance, and rehabilitation needs. Details of our M&R work priority and unit costs for work activities are provided in Tables 1D and 2D, respectively, in Appendix D.

Based on the 2022 PCI-survey results, shown on The Dalles Municipal Airport Pavement Network General Treatment Type Distribution Based on PCI, Figure 5.1 displays a breakdown of The Dalles Municipal Airport network pavement condition by percent of area and general M&R treatment categories. Approximately 92%, 7%, and 1% of the area require preservation treatments, rehabilitation, and reconstruction, respectively.




Figure 5.1 - THE DALLES MUNICIPAL AIRPORT PAVEMENT NETWORK GENERAL TREATMENT TYPE DISTRIBUTION BASED ON PCI

5.2 Recommended Localized Maintenance

Localized maintenance refers to activities such as crack sealing and patching, which should be performed annually in order to properly maintain aging pavements. Using the PAVER Localized Distress Maintenance Analysis tool, we developed a list of recommended localized maintenance. This list is shown in Table 3D in Appendix D and is independent of the global maintenance and rehabilitation projects associated with the five-year global

maintenance and rehabilitation work plan. A summary of total localized maintenance quantities is provided in Table 5-1 below.

Table 5-1: LOCALIZED MAINTENANCE QUANTITIES


Localized Maintenance Operation	Quantity
Asphalt Concrete Crack Sealing	47,063 linear feet
Asphalt Concrete Wide Crack Sealing	63 linear feet
Portland Cement Concrete Crack Sealing	207 linear feet
Asphalt Concrete Full-Depth Patching	73 square feet

5.3 Global Maintenance and Rehabilitation Plan


To develop the five-year work plan, we first ran the eliminate backlog scenario with the PAVER M&R Work Planning Module in order to generate a list, organized by year, of global M&R projects. We then reviewed the project list and refined it into practical construction projects for each year. A summary of global M&R quantities is provided in Table 5-2 below, and maps of the project locations by year are shown on the 5-Year Pavement Management Plan The Dalles Municipal Airport, Figure 5.2. The complete list of recommended global M&R projects is presented in Table 4D in Appendix D.

Table 5-2: GLOBAL MAINTENANCE AND REHABILITATION QUANTITIES



Global Maintenance or Rehabilitation Operation	Quantity, square feet
Reconstruction	14,889
Fog Seal	211,476
Slurry Seal	1,454,608



ACTION TIMING



ACTION



6 LIMITATIONS

This report has been prepared to assist the Oregon Department of Aviation (ODA) with pavement-related project planning for The Dalles Municipal Airport. The scope is limited to the specific pavement areas described within this report. The conclusions and recommendations provided in this report are based on information provided by ODA, estimated costs, and an understanding of the pavement conditions based solely on visual assessment. The global maintenance and rehabilitation recommendations and project selections provided in this report, as well as their corresponding cost estimates, are based on a practical grouping of projects and an estimate of the structural requirements. It is possible that recommendations based on a structural evaluation would differ materially from the recommendations given herein. Therefore, the information included in this report should be used solely for project planning purposes, and it should be understood that rehabilitation costs may vary from the cost estimates given within this report.

Because the condition of the airport pavement network is dynamic, an effective maintenance and rehabilitation program should be reviewed and updated on a regular basis. In addition to regularly surveying and updating the pavement condition, completed construction activities should be tracked in the PAVER database. If The Dalles Municipal Airport would like to know more about the results presented in this report, please contact the undersigned.

Submitted for GRI,



RENEWS: 06/2023

Lindsy A. Hammond, PE
Principal

Matthew A. Haynes, PE
Project Engineer

Ana-Maria Coca, PhD
Engineering Staff

This document has been submitted electronically.

APPENDIX A

Pavement Inventory Report and Maps

APPENDIX A

PAVEMENT INVENTORY REPORTS AND MAPS

A.1 PAVEMENT NETWORK

The Dalles Municipal Airport is located in Dallesport, Washington, and is owned and operated by the City of Dallesport and Klickitat County. The pavement network/facilities at The Dalles Municipal Airport serve a variety of general aviation aircraft and military aircraft. The Dalles Municipal Airport consists of two runways, two primary parallel taxiways, multiple connector taxiways, taxilanes, several aprons, and one helipad. The types of airside pavements include asphalt concrete (AC), AC overlaid with AC (AAC), and portland cement concrete (PCC).

The current airport pavement management system (APMS) network at The Dalles Municipal Airport has an approximate area of 1.87 million square feet of paved airside facilities. The pavement network has previously been divided (by others) into a hierarchical order of branches, sections, and sample units that facilitate inspection and maintenance planning. The pavement facilities summarized by branch and section are listed in Tables 1A and 2A, respectively. Pavement sections and the sample unit layout for each section are shown on Figure 1A in this appendix.

A.2 BRANCHES

A branch, as defined in the PAVER system, is a facility that is a readily identifiable part of the pavement system and has a distinct function. For airports, branches typically consist of individual runways, taxiways, and aprons. The current pavement network for The Dalles Municipal Airport contains 15 branches, tabulated in Table 1A and shown on Figure 1A.

A.3 SECTIONS AND SAMPLE UNITS

A pavement section is the smallest management unit used when considering the application and selection of maintenance and rehabilitation (M&R) repairs and treatments and is defined by Section 2.1.8 of ASTM International (ASTM) D5340 as *"a contiguous pavement area having uniform construction, maintenance, usage history, and condition."* All sections should also have the same traffic volume and load intensity. The current pavement network included in the PAVER database for The Dalles Municipal Airport contains 43 sections that are managed by the City of The Dalles, which are tabulated in Table 2A and shown spatially on Figure 1A.

PAVER assigns a rank, which designates that pavement's prioritization in receiving maintenance and repair. The highest use or priority pavements, such as runways, taxiways, and terminal aprons, are ranked *Primary*, while the surrounding aprons and shoulders are

ranked *Secondary* and low-use areas are ranked *Tertiary*. The ranks for all sections are shown on Table 2A.

To facilitate the visual survey of the airport pavement, each section is further subdivided into smaller areas called sample units. Similar sizing of these units is critical, and studies have found that maintaining the size of the sample units to within 40% of the established normal distribution reduces the standard error of the average pavement condition index (PCI) values. To meet this criterion, the ASTM method recommends sample units for flexible pavements be $5,000 \pm 2,000$ square feet and $20 \text{ slabs} \pm 8 \text{ slabs}$ for rigid pavements. The delineation of sample units for each section is displayed on Figure 1A.

A.4 SAMPLE UNIT DELINEATION

For an APMS survey, a PCI confidence level of 92% and an allowable error (e) of eight PCI points are used for all airport pavements. To determine the number of sample units that need to be inspected to achieve the required confidence level and allowable error, the following equation is used:

$$n = \frac{N \times s^2}{\left(\frac{e^2}{4}\right)(N-1) + s^2} \quad (\text{Equation 1})$$

where:

- n = number of sample units to be inspected
- N = total number of samples in the pavement sections
- e = allowable error
- s = section standard deviation

For the 2022 The Dalles Municipal Airport PCI survey, Table 3A was used as a guideline in developing sampling rates for flexible and rigid pavement that reflect similar rates used for other large airport pavement networks. In general, this sampling rate distribution provides a 92% confidence level with a standard error of eight PCI points.

Sample unit locations at The Dalles Municipal Airport were selected using a systematic random sampling model method. This technique is implemented by first determining the number of sample units needed based on the confidence interval calculated using Equation 1. The first sample unit is randomly placed in the section and then the remaining sample units are systematically spaced throughout the section at an equal distance apart.

Table 1A – THE DALLES AIRPORT PAVEMENT BRANCHES

Facility Designation (Branch ID)	Branch Name	Number of Sections	Approximate Area, square feet
A01TD	Apron 01 The Dalles	8	300,168
A02TD	Apron 02 The Dalles	2	108,547
R07TD	Rwy 07/25 The Dalles	5	464,300
R13TD	Runway 13/31 The Dalles	3	497,720
T02TD	Taxiway 02 The Dalles	1	1,768
T03TD	Taxiway 03 The Dalles	1	1,768
T04TD	Taxiway 04 The Dalles	2	6,634
T05TD	Taxiway 05 The Dalles	3	28,264
TA1TD	Taxiway A1 The Dalles	1	15,935
TA2TD	Taxiway A2 The Dalles	2	19,429
TA3TD	Taxiway A3 The Dalles	4	117,331
TA4TD	Taxiway A4 The Dalles	1	12,777
TATD	Taxiway A The Dalles	5	185,105
TBTD	Taxiway B The Dalles	4	91,823
TCTD	Taxiway C The Dalles	2	18,024

Table 2A - THE DALLES AIRPORT CURRENT PAVEMENT INVENTORY

BranchID	Branch Name	Branch Use	SectionID	From	To	Rank	Length, feet	Width, feet	Approximate	LCD	Surface Type
									Area, square feet		
A01TD	Apron 01 The Dalles	APRON	01	T05-01	A01-02	P	195	115	16,167	9/2/1983	AC
A01TD	Apron 01 The Dalles	APRON	02	A01-01	END	P	60	60	2,568	9/2/1997	AC
A01TD	Apron 01 The Dalles	APRON	03	A01-02	A01-06	P	40	24	1,032	9/1/1997	PCC
A01TD	Apron 01 The Dalles	APRON	04	T05TD-01	A01-05	P	260	320	70,840	9/2/1983	AC
A01TD	Apron 01 The Dalles	APRON	05	A01-04	A01-06	P	305	277	78,753	9/1/1983	AAC
A01TD	Apron 01 The Dalles	APRON	06	A01-05	A01-07	P	215	156	44,046	9/2/1943	PCC
A01TD	Apron 01 The Dalles	APRON	07	A01-06	T10-01	P	200	391	83,735	9/2/1983	AC
A01TD	Apron 01 The Dalles	APRON	08	TA	PCC	P	38	70	3,027	6/3/2017	AC
A02TD	Apron 02 The Dalles	APRON	01	T06-01	T08, T09	S	435	209	89,259	9/2/1995	AC
A02TD	Apron 02 The Dalles	APRON	02	South Hangar	-	S	325	50	19,288	1/1/2009	AC
R07TD	Rwy 07/25 The Dalles	RUNWAY	01	25 END	R07-02	P	200	100	20,000	9/2/1943	AC
R07TD	Rwy 07/25 The Dalles	RUNWAY	02	R07-01	R07-03	P	2,328	100	232,750	9/2/1943	AC
R07TD	Rwy 07/25 The Dalles	RUNWAY	03	R07-02	R07-04	P	575	100	57,500	7/1/2012	AAC
R07TD	Rwy 07/25 The Dalles	RUNWAY	04	R07-03	R07-05	P	1,081	100	108,050	9/2/1943	AC
R07TD	Rwy 07/25 The Dalles	RUNWAY	05	R07-04	R07 END	P	460	100	46,000	9/2/1943	AC
R13TD	Runway 13/31 The Dalles	RUNWAY	01	R13 End	R07	P	1,070	100	107,010	7/1/2012	AAC
R13TD	Runway 13/31 The Dalles	RUNWAY	02	R07	R13TD-03	P	1,464	100	146,010	7/1/2012	AAC
R13TD	Runway 13/31 The Dalles	RUNWAY	03	R12TD-02	R31 End	P	2,447	100	244,700	10/4/2012	AC
T02TD	Taxiway 02 The Dalles	TAXIWAY	01	A01-07	T05-01	P	50	30	1,768	6/3/2017	AC
T03TD	Taxiway 03 The Dalles	TAXIWAY	01	A01-07	T05-01	P	50	30	1,768	6/3/2017	AC
T04TD	Taxiway 04 The Dalles	TAXIWAY	01	TA	T04-02	S	75	24	2,068	6/3/2017	AC
T04TD	Taxiway 04 The Dalles	TAXIWAY	02	A01-07	T04-01	P	175	24	4,566	9/2/1983	AC
T05TD	Taxiway 05 The Dalles	TAXIWAY	01	End	T05-02	S	75	35	2,625	1/1/2009	AC
T05TD	Taxiway 05 The Dalles	TAXIWAY	02	T05-01	T05-03	S	646	35	22,606	9/2/1995	AC
T05TD	Taxiway 05 The Dalles	TAXIWAY	03	TA	T05-02	S	56	35	3,033	6/3/2017	AC
TA1TD	Taxiway A1 The Dalles	TAXIWAY	01	R13TD End	TATD-01	P	230	35	15,935	11/3/2013	AC
TA2TD	Taxiway A2 The Dalles	TAXIWAY	01	TATD / TBTD	Intersection	P	133	50	6,658	11/3/2013	AC
TA2TD	Taxiway A2 The Dalles	TAXIWAY	02	TA2TD-01	T05TD-01	P	210	50	12,771	6/3/2017	AC
TA3TD	Taxiway A3 The Dalles	TAXIWAY	01	R02 End	TA3TD-02	P	2,010	35	70,507	9/2/1943	AC
TA3TD	Taxiway A3 The Dalles	TAXIWAY	02	TA3TD-01	R12	P	190	35	7,481	7/1/2012	AAC
TA3TD	Taxiway A3 The Dalles	TAXIWAY	03	T05-01	R13	P	148	50	8,321	9/2/1943	AC
TA3TD	Taxiway A3 The Dalles	TAXIWAY	04	TA3-03	TA	P	610	50	31,022	6/3/2017	AC
TA4TD	Taxiway A4 The Dalles	TAXIWAY	01	TA-04	R30 End	P	233	38	12,777	10/4/2012	AC
TATD	Taxiway A The Dalles	TAXIWAY	01	TA1TD-01	R07TD	P	864	35	32,262	11/3/2013	AC
TATD	Taxiway A The Dalles	TAXIWAY	02	R07TD	TA2TD	P	253	35	12,219	11/3/2013	AC
TATD	Taxiway A The Dalles	TAXIWAY	03	TA2	TA3	P	1,383	50	69,061	6/3/2017	AC
TATD	Taxiway A The Dalles	TAXIWAY	04	TA3	TA-05	P	1,670	35	59,321	5/3/2014	AC
TATD	Taxiway A The Dalles	TAXIWAY	05	TA-04	TA4-01	P	375	35	12,242	10/4/2012	AC
TBTD	Taxiway B The Dalles	TAXIWAY	01	R07 END	TBTD-02	P	800	50	43,800	9/2/1943	AC
TBTD	Taxiway B The Dalles	TAXIWAY	02	TBTD-01	R02 END	P	633	50	35,181	9/2/1943	AC
TBTD	Taxiway B The Dalles	TAXIWAY	03	R13TD	TATD-02	P	300	35	12,842	11/3/2013	AC
TCTD	Taxiway C The Dalles	TAXIWAY	01	TA	TC-02	S	128	25	3,135	6/3/2017	AC
TCTD	Taxiway C The Dalles	TAXIWAY	02	TC-01	End	S	596	25	14,889	1/1/1985	AC

Abbreviations:

P = Primary pavement, S = Secondary pavement

LCD = Last Construction Date. The date of the last major rehabilitation (e.g. overlay)


AC = Asphalt Concrete, AAC = AC overlaid AC, PCC = Portland Cement Concrete

Table 3A: EXAMPLE SAMPLE RATES FOR AC AND PCC PAVEMENTS

AC Sampling Rate		PCC Sampling Rate	
Total Number of Sample Units, N	Sample Units to Survey, n	Total Number of Sample Units, N	Sample Units to Survey, n
1	1	1	1
2-3	2	2	2
4-6	3	3-4	3
7-13	4	5-6	4
14-38	5	7-8	5
39+	6	9-11	6
		12-14	7
		15-19	8
		20-27	9
		28-38	10
		39-58	11
		59-104	12
		105-313	13
		314+	14

Note: AC = Asphalt Concrete

PCC = Portland Cement Concrete



SAMPLE UNIT LAYOUT
THE DALLES MUNICIPAL AIRPORT

MAY 2023

JOB NO. 6593-C

FIG. 1A

APPENDIX B

Pavement Condition Index Survey Results

APPENDIX B

PAVEMENT CONDITION INDEX SURVEY RESULTS

B.1 METHODOLOGY

As previously discussed, the PCI is a measure of the pavement's functional surface condition and provides a methodology for assessing the causes of distress and whether the distress is related to a load or climatic conditions. Although the PCI is not a direct measure of structural capacity, it provides a suggestion of the structural needs of the pavement.

The PCI is based on the type, severity, and quantity of each distress found in an inspected sample unit. The results are displayed using a seven-category rating scale in accordance with ASTM D5340. Flexible pavement (e.g., AC and AAC) and rigid pavement (e.g., PCC) distress types are presented in Table 1B. A summary of the pavement condition results by branch and section are included in Tables 2B and 3B of Appendix B, respectively.

Table 1B: PAVER DISTRESS CODES FOR FLEXIBLE AND RIGID PAVEMENT

Flexible Pavement			Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause	PAVER Code	Pavement Distress	Related Cause
41	Alligator Cracking	Load	61	Blow-Up	Load
42	Bleeding	Other	62	Corner Break	Load
43	Block Cracking	Climate/ Durability	63	Longitudinal, Transverse, & Diagonal Cracks	Climate/ Durability
44	Corrugation	Other	64	Durability Cracking	Climate/ Durability
45	Depression	Other	65	Joint Seal Damage	Other
46	Jet Blast	Other	66	Small Patch	Other
47	Joint Reflection Cracking	Climate/ Durability	67	Large Patch	Other
48	Longitudinal & Transverse Cracking	Climate/ Durability	68	Pop Outs	Other
49	Oil Spillage	Other	69	Pumping	Other
50	Patching	Climate/ Durability	70	Scaling	Other
51	Polished Aggregate	Other	71	Faulting	Other
52	Raveling	Climate/ Durability	72	Shattered Slab	Load

Flexible Pavement		
PAVER Code	Pavement Distress	Related Cause
53	Rutting	Load
54	Shoving	Other
55	Slippage Cracking	Other
56	Swelling	Other
57	Weathering	Climate/ Durability

Rigid Pavement		
PAVER Code	Pavement Distress	Related Cause
73	Shrinkage Cracking	Other
74	Joint Spalls	Other
75	Corner Spalls	Other
76	Alkali-Silica Reactivity (ASR)	Other

To obtain the section PCI, we extrapolated the PCI of each selected sample unit over the entire section area. Distresses found in sample units classified as “additional”– defined as nonrepresentative instead of random- are not extrapolated over the entire section but merely added to the extrapolated quantity. The PCI rating scale presented previously in Table 3-1 of Section 3.1 and is based on ASTM D5340.

Section 4.1 of ASTM D5340, governing PCI surveys, offers this caution:

“The PCI is a numerical indicator that rates the surface condition of the pavement. The PCI provides a measure of the **present condition** of the pavement based on the distress observed on the surface of the pavement, which also indicates the structural integrity and surface operational condition (localized roughness and safety). The PCI **cannot** measure structural capacity, nor does it provide a direct measurement of skid resistance or roughness. It provides an objective and rational basis for determining maintenance and repair needs and priorities. Continuous monitoring of the PCI is used to establish the rate of pavement deterioration, which permits early identification of major rehabilitation needs. The PCI provides feedback on pavement performance for validation or improvement of current pavement design and maintenance procedures.”

Based on the limitations of the PCI method, it is imperative that engineers and planners treat the PCI as a tool that will assist them during the M&R planning process. Any major project should always be preceded by an up-to-date, detailed, 100% project-level inspection of the pavement in order to reevaluate maintenance needs prior to the project design process.

B.2 DISTRESS TYPES

Distress tends to fall into one of the following four cause categories:

- **Load-related:** Flexible pavement distresses include alligator/fatigue cracking, corrugation, depression, polished aggregate, rutting, and slippage cracking. Rigid

pavement distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping, and joint spalling.

- **Climate- and durability-related:** Flexible pavement distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, and raveling/weathering. Rigid pavement distresses include blow-ups, durability cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- **Moisture- and drainage-related:** Flexible pavement distresses include alligator/fatigue cracking, depressions, potholes, and swelling. Rigid pavement distresses include corner breaks, divided slabs, and pumping.
- **Other factors:** Oil spillage, jet blast erosion, bleeding, patching, and concrete slab joint faulting.

As described above, a distress may be the result of more than one cause. For example, depressions may be caused by incorrect compaction during construction or by subgrade softening due to environmental factors. In addition, a distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual cause or causes of the distress.

B.3 PAVEMENT CONDITION INDEX SURVEY RESULTS

The evaluated The Dalles Municipal Airport pavement network consists of 15 branches and 43 sections. A total of 129 sample units were visually inspected in the field. Data from the inspected sample units were input into the PAVER database, and a resultant PCI for each section was computed. Additional details regarding the PCI and distress types observed for each surveyed sample unit are provided in the re-inspection report, Table 1E, in Appendix E. Based on the 2022 PCI survey, the area-weighted average PCI for the entire pavement network at The Dalles Municipal Airport is approximately 83, which corresponds to a PCI rating of Satisfactory.

To investigate the rate of deterioration of each pavement section we compared the PCI results from the 2022 survey to the PCI results from the previous inspection. The variation in PCI between inspections for The Dalles Municipal Airport pavement sections is outlined in Table 4B in this appendix.

Table 2B - THE DALLES AIRPORT CURRENT BRANCH CONDITION REPORT

Branch ID	Number of Sections	Approximate Area, square feet	Use	Area Weighted Average Branch PCI	PCI Category
A01TD	8	300,168	APRON	85	Satisfactory
A02TD	2	108,547	APRON	72	Satisfactory
R07TD	5	464,300	RUNWAY	78	Satisfactory
R13TD	3	497,720	RUNWAY	87	Good
T02TD	1	1,768	TAXIWAY	92	Good
T03TD	1	1,768	TAXIWAY	84	Satisfactory
T04TD	2	6,634	TAXIWAY	75	Satisfactory
T05TD	3	28,264	TAXIWAY	70	Fair
TA1TD	1	15,935	TAXIWAY	94	Good
TA2TD	2	19,429	TAXIWAY	87	Good
TA3TD	4	117,331	TAXIWAY	80	Satisfactory
TA4TD	1	12,777	TAXIWAY	94	Good
TATD	5	185,105	TAXIWAY	93	Good
TBTD	3	126,835	TAXIWAY	86	Good
TCTD	2	18,024	TAXIWAY	48	Poor

Use Category	Number of Sections	Total Area, square feet	Area Weighted Average PCI
APRON	10	408,715	82
RUNWAY	8	962,020	83
TAXIWAY	25	533,870	85
ALL	43	1,904,605	83

Abbreviation: I = Pavement Condition Index

Table 3B - THE DALLES AIRPORT 2022 PAVEMENT CONDITION INDEX SURVEY RESULTS

BranchID	SectionID	Last Construction Date	Surface Type	Use	Last Inspection Date	Age at Inspection	PCI	PCI Category	PCI % Climate	PCI % Load	PCI % Other
A01TD	01	9/2/1983	AC	APRON	7/1/2022	39	61	Fair	100	0	0
A01TD	02	9/2/1997	AC	APRON	7/1/2022	25	62	Fair	100	0	0
A01TD	03	9/1/1997	PCC	APRON	7/1/2022	25	87	Good	0	83	17
A01TD	04	9/2/1983	AC	APRON	7/1/2022	39	100	Good	73	27	0
A01TD	05	9/1/1983	AAC	APRON	7/1/2022	39	100	Good	100	0	0
A01TD	06	9/2/1943	PCC	APRON	7/1/2022	79	82	Satisfactory	10	25	65
A01TD	07	9/2/1983	AC	APRON	7/1/2022	39	65	Fair	100	0	0
A01TD	08	6/3/2017	AC	APRON	7/1/2022	5	94	Good	100	0	0
A02TD	01	9/2/1995	AC	APRON	7/1/2022	27	71	Satisfactory	100	0	0
A02TD	02	1/1/2009	AC	APRON	7/1/2022	14	78	Satisfactory	100	0	0
R07TD	01	9/2/1943	AC	RUNWAY	7/1/2022	79	85	Satisfactory	100	0	0
R07TD	02	9/2/1943	AC	RUNWAY	7/1/2022	79	76	Satisfactory	100	0	0
R07TD	03	7/1/2012	AAC	RUNWAY	7/1/2022	10	91	Good	100	0	0
R07TD	04	9/2/1943	AC	RUNWAY	7/1/2022	79	74	Satisfactory	76	24	0
R07TD	05	9/2/1943	AC	RUNWAY	7/1/2022	79	81	Satisfactory	100	0	0
R13TD	01	7/1/2012	AAC	RUNWAY	7/1/2022	10	90	Good	100	0	0
R13TD	02	7/1/2012	AAC	RUNWAY	7/1/2022	10	90	Good	59	41	0
R13TD	03	10/4/2012	AC	RUNWAY	7/1/2022	10	84	Satisfactory	51	49	0
T02TD	01	6/3/2017	AC	TAXIWAY	7/1/2022	5	92	Good	100	0	0
T03TD	01	6/3/2017	AC	TAXIWAY	7/1/2022	5	84	Satisfactory	100	0	0
T04TD	01	6/3/2017	AC	TAXIWAY	7/1/2022	5	89	Good	100	0	0
T04TD	02	9/2/1983	AC	TAXIWAY	7/1/2022	39	69	Fair	100	0	0
T05TD	01	1/1/2009	AC	TAXIWAY	7/1/2022	14	75	Satisfactory	100	0	0
T05TD	02	9/2/1995	AC	TAXIWAY	7/1/2022	27	68	Fair	100	0	0
T05TD	03	6/3/2017	AC	TAXIWAY	7/1/2022	5	79	Satisfactory	100	0	0
TA1TD	01	11/3/2013	AC	TAXIWAY	7/1/2022	9	94	Good	100	0	0
TA2TD	01	11/3/2013	AC	TAXIWAY	7/1/2022	9	75	Satisfactory	100	0	0
TA2TD	02	6/3/2017	AC	TAXIWAY	7/1/2022	5	94	Good	100	0	0
TA3TD	01	9/2/1943	AC	TAXIWAY	7/1/2022	79	75	Satisfactory	100	0	0
TA3TD	02	7/1/2012	AAC	TAXIWAY	7/1/2022	10	94	Good	100	0	0
TA3TD	03	9/2/1943	AC	TAXIWAY	7/1/2022	79	60	Fair	100	0	0
TA3TD	04	6/3/2017	AC	TAXIWAY	7/1/2022	5	94	Good	100	0	0
TA4TD	01	10/4/2012	AC	TAXIWAY	7/1/2022	10	94	Good	100	0	0
TATD	01	11/3/2013	AC	TAXIWAY	7/1/2022	9	93	Good	100	0	0
TATD	02	11/3/2013	AC	TAXIWAY	7/1/2022	9	78	Satisfactory	100	0	0
TATD	03	6/3/2017	AC	TAXIWAY	7/1/2022	5	94	Good	100	0	0
TATD	04	5/3/2014	AC	TAXIWAY	7/1/2022	8	94	Good	100	0	0
TATD	05	10/4/2012	AC	TAXIWAY	7/1/2022	10	94	Good	100	0	0
TBTD	01	9/2/1943	AC	TAXIWAY	7/1/2022	79	87	Good	73	27	0
TBTD	02	9/2/1943	AC	TAXIWAY	7/1/2022	79	87	Good	73	27	0
TBTD	03	11/3/2013	AC	TAXIWAY	7/1/2022	9	78	Satisfactory	100	0	0
TCTD	01	6/3/2017	AC	TAXIWAY	7/1/2022	5	90	Good	100	0	0
TCTD	02	1/1/1985	AC	TAXIWAY	7/1/2022	38	39	Very Poor	45	8	47

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC, PCC = Portland Cement Concrete

Table 4B - THE DALLES AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2022 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2017 Survey			2022 Survey		Age ³	Δ PCI/yr ⁴	Rate of Deterioration
					PCI	PCI Category	Insp. Date	PCI	PCI Category			
A01TD	01	AC	16,167	9/2/1983	75	Satisfactory	6/9/2017	61	Fair	34	-2.77	NORMAL
A01TD	02	AC	2,568	9/2/1997	87	Good	6/9/2017	62	Fair	20	-4.94	HIGH
A01TD	03	PCC	1,032	9/1/1997	87	Good	6/9/2017	87	Good	20	0.00	NONE
A01TD	04	AC	70,840	9/2/1983	77	Satisfactory	6/9/2017	100	Good	34	4.54	NONE
A01TD	05	AAC	78,753	9/1/1983	62	Fair	6/9/2017	100	Good	34	7.51	NONE
A01TD	06	PCC	44,046	9/2/1943	80	Satisfactory	6/9/2017	82	Satisfactory	74	0.40	NONE
A01TD	07	AC	83,735	9/2/1983	72	Satisfactory	6/9/2017	65	Fair	34	-1.38	NORMAL
A01TD	08	AC	3,027	6/3/2017	100	Good	6/9/2017	94	Good	0	-1.19	NORMAL
A02TD	01	AC	89,259	9/2/1995	82	Satisfactory	6/9/2017	71	Satisfactory	22	-2.17	NORMAL
A02TD	02	AC	19,288	1/1/2009	100	Good	6/9/2017	78	Satisfactory	8	-4.35	HIGH
R07TD	01	AC	20,000	9/2/1943	94	Good	6/9/2017	85	Satisfactory	74	-1.78	NORMAL
R07TD	02	AC	232,750	9/2/1943	86	Good	6/9/2017	76	Satisfactory	74	-1.98	NORMAL
R07TD	03	AAC	57,500	7/1/2012	100	Good	6/9/2017	91	Good	5	-1.78	NORMAL
R07TD	04	AC	108,050	9/2/1943	84	Satisfactory	6/9/2017	74	Satisfactory	74	-1.98	NORMAL
R07TD	05	AC	46,000	9/2/1943	88	Good	6/9/2017	81	Satisfactory	74	-1.38	NORMAL
R13TD	01	AAC	107,010	7/1/2012	100	Good	6/9/2017	90	Good	5	-1.98	NORMAL
R13TD	02	AAC	146,010	7/1/2012	100	Good	6/9/2017	90	Good	5	-1.98	NORMAL
R13TD	03	AC	244,700	10/4/2012	100	Good	6/9/2017	84	Satisfactory	5	-3.16	NORMAL
T02TD	01	AC	1,768	6/3/2017	100	Good	6/9/2017	92	Good	0	-1.58	NORMAL
T03TD	01	AC	1,768	6/3/2017	100	Good	6/9/2017	84	Satisfactory	0	-3.16	NORMAL
T04TD	01	AC	2,068	6/3/2017	100	Good	6/9/2017	89	Good	0	-2.17	NORMAL
T04TD	02	AC	4,566	9/2/1983	80	Satisfactory	6/9/2017	69	Fair	34	-2.17	NORMAL
T05TD	01	AC	2,625	1/1/2009	90	Good	6/9/2017	75	Satisfactory	8	-2.96	NORMAL
T05TD	02	AC	22,606	9/2/1995	79	Satisfactory	6/9/2017	68	Fair	22	-2.17	NORMAL
T05TD	03	AC	3,033	6/3/2017	79	Satisfactory	6/9/2017	79	Satisfactory	0	0.00	NONE
TA1TD	01	AC	15,935	11/3/2013	99	Good	6/9/2017	94	Good	4	-0.99	NORMAL
TA2TD	01	AC	6,658	11/3/2013	100	Good	6/9/2017	75	Satisfactory	4	-4.94	HIGH
TA2TD	02	AC	12,771	6/3/2017	100	Good	6/9/2017	94	Good	0	-1.19	NORMAL
TA3TD	01	AC	70,507	9/2/1943	75	Satisfactory	6/9/2017	75	Satisfactory	74	0.00	NONE
TA3TD	02	AAC	7,481	7/1/2012	100	Good	6/9/2017	94	Good	5	-1.19	NORMAL
TA3TD	03	AC	8,321	9/2/1943	76	Satisfactory	6/9/2017	60	Fair	74	-3.16	NORMAL

Table 4B - THE DALLES AIRPORT COMPARISON OF PREVIOUS INSPECTION AND 2022 RESULTS

Branch ID	Section ID	Surface Type ¹	Approximate Area, square feet	LCD ²	2017 Survey			2022 Survey		Age ³	Δ PCI/yr ⁴	Rate of Deterioration
					PCI	PCI Category	Insp. Date	PCI	PCI Category			
TA3TD	04	AC	31,022	6/3/2017	100	Good	6/9/2017	94	Good	0	-1.19	NORMAL
TA4TD	01	AC	12,777	10/4/2012	99	Good	6/9/2017	94	Good	5	-0.99	NORMAL
TATD	01	AC	32,262	11/3/2013	100	Good	6/9/2017	93	Good	4	-1.38	NORMAL
TATD	02	AC	12,219	11/3/2013	100	Good	6/9/2017	78	Satisfactory	4	-4.35	HIGH
TATD	03	AC	69,061	6/3/2017	100	Good	6/9/2017	94	Good	0	-1.19	NORMAL
TATD	04	AC	59,321	5/3/2014	100	Good	6/9/2017	94	Good	3	-1.19	NORMAL
TATD	05	AC	12,242	10/4/2012	99	Good	6/9/2017	94	Good	5	-0.99	NORMAL
TBTD	01	AC	43,800	9/2/1943	87	Good	6/9/2017	87	Good	74	0.00	NONE
TBTD	02	AC	35,181	9/2/1943	87	Good	6/9/2017	87	Good	74	0.00	NONE
TBTD	03	AC	12,842	11/3/2013	98	Good	6/9/2017	78	Satisfactory	4	-3.95	NORMAL
TCTD	01	AC	3,135	6/3/2017	100	Good	6/9/2017	90	Good	0	-1.98	NORMAL
TCTD	02	AC	14,889	1/1/1985	84	Satisfactory	6/9/2017	39	Very Poor	32	-8.89	HIGH

Abbreviations:

¹ PCI = Pavement Condition Index; AC = Asphalt Concrete, AAC = AC overlaid AC, PCC = Portland Cement Concrete

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

³ Age = Pavement age in years at the time of the PCI survey in 2017

⁴ Δ PCI/yr = Change in PCI points per year between 2017 survey and 2022 survey

APPENDIX C

Future Pavement Condition Analysis

APPENDIX C

PAVEMENT CONDITION ANALYSIS

C.1 METHODOLOGY

In addition to assessing the current condition of a pavement, it is very important from a planning standpoint to be able to predict with reasonable accuracy its future condition. In a pavement management plan (PMP), this is done with the aid of a prediction model. When an APMS is initially implemented, the default models are typically used to predict the future condition of a pavement. However, after PCI surveys are completed, the historical data are then used to refine the models, so they better represent the deterioration of a particular class of pavement based on local climatic conditions, loading, material sources, construction procedures, etc. The importance of accurate prediction models is part of the reason it is essential to conduct periodic, routine surveys in order to track the rate of deterioration.

In PAVER, the pavement deterioration curves are developed based on the “family” model procedure. A pavement “family” is defined as a group of pavements with similar deterioration characteristics. The procedure for developing the prediction models is:

- 1) Define the pavement families.
- 2) Review the data.
- 3) Conduct a data outlier analysis.
- 4) Model the data.

C.2 PREDICTION MODELS

We developed separate condition prediction models for each pavement “family” at The Dalles Municipal Airport. The delineation is based on branch use, surface type, section rank, and structural design life. We use five distinct models for the following “families” of pavements at The Dalles Municipal Airport. For each model, we reviewed the data in order to filter out any inconsistent or inaccurate data or any data that fall outside boundary values set by PAVER. After outliers are removed and the data are checked for accuracy and reasonableness, the PAVER program calculates a best-fit curve using a polynomial-constrained, least-squares analysis procedure. This best-fit curve for each family is used in the analysis to predict the average behavior of all sections within each “family.” Our condition prediction models for each “family” are provided on Figures 1C through 4C below.




Figure 1C: CONDITION PREDICTION MODEL FOR EASTERN CATEGORY PCC RUNWAYS, TAXIWAYS, AND APRONS




Figure 2C: CONDITION PREDICTION MODEL FOR EASTERN CATEGORY 3 AC AND AAC APRONS




Figure 3C: CONDITION PREDICTION MODEL FOR EASTERN CATEGORY 3 AC AND AAC RUNWAYS




Figure 4C: CONDITION PREDICTION MODEL FOR EASTERN CATEGORY 3 AAC TAXIWAYS

C.3 CRITICAL PCI

Each of the condition-prediction models have an assigned critical PCI. The critical PCI is the point at which the pavement condition begins to deteriorate more quickly over time. As the condition deteriorates to a worse state, major M&R is triggered because the cost to apply localized M&R increases significantly. Pavement sections with PCI above the critical value are given a higher priority for funding during budget analysis in order to

prevent them from deteriorating to the point where more costly rehabilitation is necessary. We used the following critical PCI values at The Dalles Municipal Airport:

- Runways – 60
- Taxiways/Taxilanes – 55
- Aprons – 50

C.4 FUTURE CONDITION ANALYSIS

As previously discussed, the projected condition of each pavement section was determined for 5- and 10-year periods. The projected pavement conditions in 5 years and 10 years for each pavement section at The Dalles Municipal Airport, along with the conditions at the previous inspection, are listed in Table 1C.

C.5 FUNCTIONAL REMAINING LIFE

As mentioned above, functional remaining life is the practical amount of time a pavement is in service before requiring rehabilitation, as estimated based solely on visual condition. This is not to be confused with structural remaining life, which requires analysis of the structural capacity of a pavement.

We calculated two forms of functional remaining life based on the current visual condition surveys of the pavement at The Dalles Municipal Airport, the time until rehabilitation, and the time until the pavement is no longer operational due to high foreign object debris potential and increased safety concerns for trafficking aircraft (PCI less than 40). The results of the functional life analysis are provided in Table 2C.

Table 1C - PAST, PRESENT AND FUTURE PCI

BranchID	SectionID	Past Inspection PCI	Current PCI	Predicted Future PCI	
		2017	2022	2027	2032
A01TD	01	75	61	54	46
A01TD	02	87	62	55	47
A01TD	03	87	87	83	77
A01TD	04	77	100	93	85
A01TD	05	62	100	93	85
A01TD	06	80	82	76	68
A01TD	07	72	65	58	50
A01TD	08	100	94	87	79
A02TD	01	82	71	64	56
A02TD	02	100	78	71	63
R07TD	01	94	85	78	71
R07TD	02	86	76	69	62
R07TD	03	100	91	84	77
R07TD	04	84	74	67	60
R07TD	05	88	81	74	67
R13TD	01	100	90	83	76
R13TD	02	100	90	83	76
R13TD	03	100	84	77	70
T02TD	01	100	92	85	78
T03TD	01	100	84	77	70
T04TD	01	100	89	82	75
T04TD	02	80	69	62	55
T05TD	01	90	75	68	61
T05TD	02	79	68	61	54
T05TD	03	79	79	72	65
TA1TD	01	99	94	87	80
TA2TD	01	100	75	68	61
TA2TD	02	100	94	87	80
TA3TD	01	75	75	68	61
TA3TD	02	100	94	87	80
TA3TD	03	76	60	53	46
TA3TD	04	100	94	87	80
TA4TD	01	99	94	87	80
TATD	01	100	93	86	79
TATD	02	100	78	71	64
TATD	03	100	94	87	80
TATD	04	100	94	87	80
TATD	05	99	94	87	80
TBTD	01	87	87	80	73
TBTD	02	87	87	80	73
TBTD	03	98	78	71	64
TCTD	01	100	90	83	76
TCTD	02	84	39	32	25

Abbreviation: PCI = Pavement Condition Index

Table 2C - THE DALLES AIRPORT FUNCTIONAL REMAINING LIFE ANALYSIS

Branch ID	Section ID	Surface Type	Current PCI	Years to Major M&R	Major M&R Trigger PCI ¹	Years to End of Functional Service
						Life
A01TD	01	AC	61	6 - 10	50	11 - 15
A01TD	02	AC	62	6 - 10	50	11 - 15
A01TD	03	PCC	87	> 20	50	> 20
A01TD	04	AC	100	> 20	50	> 20
A01TD	05	AAC	100	> 20	50	> 20
A01TD	06	PCC	82	> 20	50	> 20
A01TD	07	AC	65	6 - 10	50	16 - 20
A01TD	08	AC	94	> 20	50	> 20
A02TD	01	AC	71	11 - 15	50	> 20
A02TD	02	AC	78	> 20	50	> 20
R07TD	01	AC	85	16 - 20	60	> 20
R07TD	02	AC	76	11 - 15	60	> 20
R07TD	03	AAC	91	> 20	60	> 20
R07TD	04	AC	74	6 - 10	60	> 20
R07TD	05	AC	81	11 - 15	60	> 20
R13TD	01	AAC	90	> 20	60	> 20
R13TD	02	AAC	90	> 20	60	> 20
R13TD	03	AC	84	16 - 20	60	> 20
T02TD	01	AC	92	> 20	55	> 20
T03TD	01	AC	84	> 20	55	> 20
T04TD	01	AC	89	> 20	55	> 20
T04TD	02	AC	69	6 - 10	55	> 20
T05TD	01	AC	75	11 - 15	55	> 20
T05TD	02	AC	68	6 - 10	55	> 20
T05TD	03	AC	79	16 - 20	55	> 20
TA1TD	01	AC	94	> 20	55	> 20
TA2TD	01	AC	75	11 - 15	55	> 20
TA2TD	02	AC	94	> 20	55	> 20
TA3TD	01	AC	75	11 - 15	55	> 20
TA3TD	02	AAC	94	> 20	55	> 20
TA3TD	03	AC	60	0 - 5	55	11 - 15
TA3TD	04	AC	94	> 20	55	> 20
TA4TD	01	AC	94	> 20	55	> 20
TATD	01	AC	93	> 20	55	> 20
TATD	02	AC	78	16 - 20	55	> 20
TATD	03	AC	94	> 20	55	> 20
TATD	04	AC	94	> 20	55	> 20
TATD	05	AC	94	> 20	55	> 20
TBTD	01	AC	87	> 20	55	> 20
TBTD	02	AC	87	> 20	55	> 20
TBTD	03	AC	78	16 - 20	55	> 20
TCTD	01	AC	90	> 20	55	> 20
TCTD	02	AC	39	0 - 5	55	0 - 5

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC,
PCC = Portland Cement Concrete

APPENDIX D

Unit Cost Data and Maintenance and Rehabilitation Plan

APPENDIX D

UNIT COST DATA AND MAINTENANCE AND REHABILITATION PLAN

D.1 ANALYSIS METHODOLOGY

We evaluated the M&R needs, as determined from the PAVER analysis results, in order to develop project recommendations for the next five years. The purpose of this analysis is to determine the M&R needs of The Dalles Municipal Airport pavement network condition over time. We used PAVER v7.0.8 software to develop network-level project recommendations for the next five years.

The PAVER M&R Work Planning Module identifies when and where M&R is required and how much it will cost. M&R plans can be developed either by assuming an annual budget or by identifying specific constraints, such as a condition goal, to determine the budget required to meet the goal. The M&R work planning analysis was based on a five-year period beginning on August 1, 2023. A backlog elimination analysis scenario was selected to generate a list of global maintenance and rehabilitation projects in order to optimize the allocation of capital and establish preservation-based project recommendations. The repair strategies considered for pavement sections in our analysis are as follows:

- Reconstruction – Considered for pavements with a PCI less than 40.
- Flexible Overlay – Considered for pavements between 40 PCI and the critical PCI, and for pavements exhibiting significant load-related distresses.
- Global Maintenance – Treatments (fog seal, slurry seal, thin AC overlay) applied to an entire pavement section with the intent of slowing the rate of deterioration.
- Localized Maintenance – Maintenance performed on a routine basis such as crack sealing, wide crack repair, and patching.

It should be noted that the five-year list of recommended projects only includes the highest-cost maintenance items and does not include routine localized maintenance (e.g., crack sealing) work that should also be conducted in addition to and concurrently with the five-year work plan.

D.1.1 Pavement Rank and Use Prioritization

Pavement sections are assigned a rank to establish their relative importance in the overall pavement network, which is most commonly defined by their use (e.g., Taxiway, Apron, Runway). The PAVER analysis uses the combination of the section rank and the branch use

to define the priority of each section during the M&R analysis. Table 1D displays the branch use and section rank prioritization schema we used for analysis.

Table 1D: M&R WORK PRIORITY BY BRANCH USE AND SECTION RANK

Branch Use	Section Rank		
	Primary	Secondary	Tertiary
RUNWAY	1	3	6
TAXIWAY	2	5	8
APRON	4	7	9

D.2 MAINTENANCE POLICIES AND UNIT COSTS

The distress-maintenance policies are policies that determine what type of work should be applied to a specific distress type and severity. For example, on an AC pavement, a medium-severity longitudinal/transverse crack would be repaired by crack sealing. Policies for all the distress types and severities are established by ASTM D5340.

Although our work scope does not include budget analysis, we did assign construction costs to the maintenance work so that PAVER would allocate M&R projects that were approximately equal in cost for each year of the five-year period. The anticipated cost of performing M&R is based on cost tables that relate M&R work type costs to PCI. We reviewed the unit costs from the 2017 report and updated them by reviewing the bid tabulations for recent projects within the vicinity of The Dalles Municipal Airport and information provided by the project team. The costs for reconstruction are based on the existing pavement sections present within each branch use at The Dalles Municipal Airport. The costs represent the fully loaded costs and include aspects of the project such as administration, contingencies, mobilization, and striping. The cost tables used in the analysis are presented in Table 2D below.

Table 2D: THE DALLES MUNICIPAL AIRPORT UNIT COST DATA

Type of M&R	Work Type	Unit Cost	Work Unit
Major M&R	Complete Reconstruction with AC	\$13.32	Sq Ft
	Cold Mill and Overlay – 2 Inches Thick	\$5.88	Sq Ft
Global M&R	Surface Treatment - Slurry Seal	\$0.40	Sq Ft
	Surface Treatment - Fog Seal	\$0.24	Sq Ft
Localized Preventive M&R	Crack Sealing - AC	\$2.40	Ft
	Crack Sealing - PCC	\$18.00	Ft
	Crack Sealing – Wide Cracks	\$39.60	Ft
	AC Patching – Full Depth	\$60.00	Sq Ft
	PCC Patching – Full Depth	\$120.00	Sq Ft

D.3 RECOMMENDED LOCALIZED MAINTENANCE

In order to properly maintain aging pavements, localized M&R activities such as crack sealing and patching should be performed on a routine basis. A list of recommended localized maintenance activities is provided in Table 3D of this appendix.

D.4 RECOMMENDED GLOBAL MAINTENANCE AND REHABILITATION PROJECTS

Global maintenance and rehabilitation projects refer to activities such as slurry seal and thin AC overlays, as well as thick AC overlays and reconstruction. A list of recommended global M&R activities is provided in Table 4D of this appendix.

Table 3D - THE DALLES AIRPORT NETWORK MAINTENANCE REPORT

Network	Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
Columbia	A01TD	01	Long. & Transv. Cracking	Medium	Crack Sealing - AC	1,387	Ft	\$2.40	\$3,329	\$3,329
Columbia	A01TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	180	Ft	\$2.40	\$432	\$648
Columbia	A01TD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	90	Ft	\$2.40	\$216	
Columbia	A01TD	03	Linear Cracking	Low	Crack Sealing - PCC	12	Ft	\$18.00	\$225	\$225
Columbia	A01TD	06	Linear Cracking	Low	Crack Sealing - PCC	195	Ft	\$18.00	\$3,502	\$3,502
Columbia	A01TD	07	Long. & Transv. Cracking	Low	Crack Sealing - AC	469	Ft	\$2.40	\$1,125	\$12,355
Columbia	A01TD	07	Long. & Transv. Cracking	Medium	Crack Sealing - AC	4,679	Ft	\$2.40	\$11,230	
Columbia	A02TD	01	Long. & Transv. Cracking	High	Crack Seal - Wide Cracks	63	Ft	\$39.60	\$2,499	\$10,345
Columbia	A02TD	01	Long. & Transv. Cracking	Medium	Crack Sealing - AC	3,124	Ft	\$2.40	\$7,497	
Columbia	A02TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	145	Ft	\$2.40	\$348	
Columbia	A02TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	12	Ft	\$2.40	\$28	\$273
Columbia	A02TD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	102	Ft	\$2.40	\$244	
Columbia	R07TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	564	Ft	\$2.40	\$1,354	\$1,354
Columbia	R07TD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	466	Ft	\$2.40	\$1,117	\$36,123
Columbia	R07TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	14,586	Ft	\$2.40	\$35,006	
Columbia	R07TD	03	Long. & Transv. Cracking	Low	Crack Sealing - AC	420	Ft	\$2.40	\$1,007	\$1,007
Columbia	R07TD	04	Long. & Transv. Cracking	Medium	Crack Sealing - AC	847	Ft	\$2.40	\$2,033	\$20,540
Columbia	R07TD	04	Long. & Transv. Cracking	Low	Crack Sealing - AC	5,869	Ft	\$2.40	\$14,086	
Columbia	R07TD	04	Alligator Cracking	Medium	Patching - AC Deep	73	SqFt	\$60.00	\$4,421	
Columbia	R07TD	05	Long. & Transv. Cracking	Low	Crack Sealing - AC	2,077	Ft	\$2.40	\$4,985	\$4,985
Columbia	R13TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	663	Ft	\$2.40	\$1,592	\$1,592
Columbia	R13TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	642	Ft	\$2.40	\$1,542	\$1,610
Columbia	R13TD	02	Alligator Cracking	Low	Crack Sealing - AC	29	Ft	\$2.40	\$68	
Columbia	R13TD	03	Long. & Transv. Cracking	Low	Crack Sealing - AC	4,160	Ft	\$2.40	\$9,984	\$10,699
Columbia	R13TD	03	Alligator Cracking	Low	Crack Sealing - AC	298	Ft	\$2.40	\$716	
Columbia	T04TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	26	Ft	\$2.40	\$62	\$62
Columbia	T04TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	10	Ft	\$2.40	\$24	\$564
Columbia	T04TD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	225	Ft	\$2.40	\$540	
Columbia	T05TD	01	Long. & Transv. Cracking	Medium	Crack Sealing - AC	54	Ft	\$2.40	\$130	\$144
Columbia	T05TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	6	Ft	\$2.40	\$14	
Columbia	T05TD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	1,199	Ft	\$2.40	\$2,879	\$2,995
Columbia	T05TD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	48	Ft	\$2.40	\$116	
Columbia	T05TD	03	Long. & Transv. Cracking	Low	Crack Sealing - AC	17	Ft	\$2.40	\$41	\$41
Columbia	TA2TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	103	Ft	\$2.40	\$247	\$247
Columbia	TA3TD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	2,912	Ft	\$2.40	\$6,988	\$6,988
Columbia	TA3TD	03	Long. & Transv. Cracking	Medium	Crack Sealing - AC	605	Ft	\$2.40	\$1,452	\$1,481
Columbia	TA3TD	03	Long. & Transv. Cracking	Low	Crack Sealing - AC	12	Ft	\$2.40	\$29	
Columbia	TATD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	53	Ft	\$2.40	\$128	\$128
Columbia	TATD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	39	Ft	\$2.40	\$94	\$94
Columbia	TBTD	01	Alligator Cracking	Low	Crack Sealing - AC	50	Ft	\$2.40	\$120	\$1,564
Columbia	TBTD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	601	Ft	\$2.40	\$1,444	
Columbia	TBTD	03	Long. & Transv. Cracking	Low	Crack Sealing - AC	19	Ft	\$2.40	\$46	\$46

Table 3D - THE DALLES AIRPORT NETWORK MAINTENANCE REPORT

Network	Branch ID	Section ID	Distress	Severity	Action	Work Quantity	Unit	Unit Cost	Work Cost	Section Total
Columbia	TCTD	01	Long. & Transv. Cracking	Low	Crack Sealing - AC	15	Ft	\$2.40	\$36	\$36
Columbia	TCTD	02	Long. & Transv. Cracking	Medium	Crack Sealing - AC	118	Ft	\$2.40	\$282	\$624
Columbia	TCTD	02	Long. & Transv. Cracking	Low	Crack Sealing - AC	128	Ft	\$2.40	\$307	
Columbia	TCTD	02	Alligator Cracking	Low	Crack Sealing - AC	14	Ft	\$2.40	\$35	

Abbreviations:

Long. = Longitudinal; Trans. = Transverse; AC = Asphalt Concrete; Ft = Feet; SqFt = Square Feet

Table 4D - FIVE-YEAR GLOBAL MAINTENANCE AND REHABILITATION PLAN

Action Year	Branch ID	Section ID	Branch Use	Surface Type	Current PCI	Action	Area, square feet	Unit Cost per square foot	Total Cost
2024	R07TD	01	RUNWAY	AC	85	Slurry Seal	20,000	\$0.40	\$8,000
	R07TD	02	RUNWAY	AC	76	Slurry Seal	232,750	\$0.40	\$93,101
	R07TD	03	RUNWAY	AAC	91	Slurry Seal	57,500	\$0.40	\$23,000
	R07TD	04	RUNWAY	AC	74	Slurry Seal	108,050	\$0.40	\$43,220
	R07TD	05	RUNWAY	AC	81	Slurry Seal	46,000	\$0.40	\$18,400
2025	R13TD	01	RUNWAY	AAC	90	Slurry Seal	107,010	\$0.40	\$42,804
	R13TD	02	RUNWAY	AAC	90	Slurry Seal	146,010	\$0.40	\$58,404
	R13TD	03	RUNWAY	AC	84	Slurry Seal	244,700	\$0.40	\$97,881
	TA3TD	02	TAXIWAY	AAC	94	Slurry Seal	7,481	\$0.40	\$2,992
2026	T02TD	01	TAXIWAY	AC	92	Slurry Seal	1,768	\$0.40	\$707
	T03TD	01	TAXIWAY	AC	84	Slurry Seal	1,768	\$0.40	\$707
	T04TD	01	TAXIWAY	AC	89	Slurry Seal	2,068	\$0.40	\$827
	T04TD	02	TAXIWAY	AC	69	Slurry Seal	4,566	\$0.40	\$1,826
	T05TD	01	TAXIWAY	AC	75	Slurry Seal	2,625	\$0.40	\$1,050
	T05TD	02	TAXIWAY	AC	68	Slurry Seal	22,606	\$0.40	\$9,042
	T05TD	03	TAXIWAY	AC	79	Slurry Seal	3,033	\$0.40	\$1,213
	TA1TD	01	TAXIWAY	AC	94	Slurry Seal	15,935	\$0.40	\$6,374
	TA2TD	01	TAXIWAY	AC	75	Slurry Seal	6,658	\$0.40	\$2,663
	TA2TD	02	TAXIWAY	AC	94	Slurry Seal	12,771	\$0.40	\$5,108
	TA3TD	01	TAXIWAY	AC	75	Slurry Seal	70,507	\$0.40	\$28,203
	TA3TD	03	TAXIWAY	AC	60	Slurry Seal	8,321	\$0.40	\$3,328
	TA3TD	04	TAXIWAY	AC	94	Slurry Seal	31,022	\$0.40	\$12,409
	TA4TD	01	TAXIWAY	AC	94	Slurry Seal	12,777	\$0.40	\$5,111
	TATD	01	TAXIWAY	AC	93	Slurry Seal	32,262	\$0.40	\$12,905
	TATD	02	TAXIWAY	AC	78	Slurry Seal	12,219	\$0.40	\$4,888
	TATD	03	TAXIWAY	AC	94	Slurry Seal	69,061	\$0.40	\$27,625
	TATD	04	TAXIWAY	AC	94	Slurry Seal	59,321	\$0.40	\$23,729
	TATD	05	TAXIWAY	AC	94	Slurry Seal	12,242	\$0.40	\$4,897
	TBTD	01	TAXIWAY	AC	78	Slurry Seal	43,800	\$0.40	\$17,520
	TBTD	02	TAXIWAY	AC	87	Slurry Seal	43,800	\$0.40	\$17,520
	TBTD	03	TAXIWAY	AC	78	Slurry Seal	12,842	\$0.40	\$5,137
	TCTD	01	TAXIWAY	AC	90	Slurry Seal	3,135	\$0.40	\$1,254
2027	TCTD	02	TAXIWAY	AC	39	Reconstruction	14,889	\$13.32	\$198,328
2028	A01TD	01	APRON	AC	61	Fog Seal	16,167	\$0.24	\$3,880
	A01TD	02	APRON	AC	62	Fog Seal	2,568	\$0.24	\$616
	A01TD	07	APRON	AC	65	Fog Seal	83,735	\$0.24	\$20,096
	A01TD	08	APRON	AC	94	Fog Seal	3,027	\$0.24	\$726
	A02TD	01	APRON	AC	71	Fog Seal	89,259	\$0.24	\$21,422
	A02TD	02	APRON	AC	78	Fog Seal	19,288	\$0.24	\$4,629

Abbreviations:

PCI = Pavement Condition Index, AC = Asphalt Concrete, AAC = AC overlaid AC

Cost Summary	
2024 Total Project Cost	\$185,722
2025 Total Project Cost	\$202,082
2026 Total Project Cost	\$194,044
2027 Total Project Cost	\$198,328
2028 Total Project Cost	\$51,370
Total 5-Year Project Cost	\$831,546

APPENDIX E

Reinspection Report

Re-Inspection Report

ODA_WOC3_4-17-2023

Generated Date

4/27/2023

Page 1 of 48

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal					
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt	
Section:	01	of	8	From:	T05-01		To:	A01-02	Last Const.:	9/2/1983
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS	Category:	K	Rank:	P
Area:	16,167 SqFt		Length:	195 Ft		Width:	115 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		

Section Comments:

Work Date:	9/1/1983	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	True
Work Date:	9/2/1983	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Work Date:	9/1/1997	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/1999	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	6/1/2001	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2004	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2012	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	9/2/2012	Work Type:	Patching - AC Deep		Code:	PA-AD	Is Major M&R:	False

Last Insp. Date: 7/1/2022

TotalSamples: 3

Surveyed: 2

Conditions: PCI: 61

Inspection Comments:

Sample Number:	01	Type:	R	Area:	6466.00 SqFt	PCI:	64
Sample Comments:							
48	L & T CR	M	232.00	Ft			
48	L & T CR	M	220.00	Ft			
57	WEATHERING	M	6466.00	SqFt			
Sample Number:	02	Type:	R	Area:	3405.00 SqFt	PCI:	56
Sample Comments:							
48	L & T CR	M	216.00	Ft			
48	L & T CR	M	179.00	Ft			
57	WEATHERING	M	3045.00	SqFt			

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt				
Section:	06	of	8	From:	A01-05		To:	A01-07		Last Const.:	9/2/1943		
Surface:	PCC	Family:	2022_Eastern_Cat1/2/3_AIUses_PCC		Zone:	KDLS	Category:	K		Rank:	P		
Area:	44,046 SqFt		Length:	215 Ft		Width:	156 Ft						
Slabs:	294	Slab Length:	15 Ft		Slab Width:	10 Ft		Joint Length:	5,219 Ft				
Shoulder:	Street Type:		Grade:		0		Lanes:	0					
Section Comments:													
Work Date:	9/1/1943		Work Type:				Subbase - Aggregate		Code:	SB-AG		Is Major M&R:	True
Work Date:	9/2/1943		Work Type:				New Construction - PCC		Code:	NC-PC		Is Major M&R:	True
Work Date:	9/1/1988		Work Type:				Joint Seal - Silicon		Code:	JS-SI		Is Major M&R:	False
Work Date:	6/1/2001		Work Type:				Patching - PCC Partial Depth		Code:	PA-PP		Is Major M&R:	False
Work Date:	6/2/2001		Work Type:				Joint Seal (Localized)		Code:	JS-LC		Is Major M&R:	False
Work Date:	9/1/2004		Work Type:				Crack Sealing - PCC		Code:	CS-PC		Is Major M&R:	False
Work Date:	9/1/2012		Work Type:				Crack Sealing - PCC		Code:	CS-PC		Is Major M&R:	False
Work Date:	9/1/2015		Work Type:				Crack Sealing - PCC		Code:	CS-PC		Is Major M&R:	False
Work Date:	9/2/2015		Work Type:				Patching - PCC Partial Depth		Code:	PA-PP		Is Major M&R:	False
Last Insp. Date:	7/1/2022		TotalSamples:	14		Surveyed:	8						
Conditions:	PCI:		82										
Inspection Comments:													
Sample Number:	02	Type:	R	Area:	25.00 Slabs		PCI:	87					
Sample Comments:													
65	JT SEAL DMG	L	25.00 Slabs										
66	SMALL PATCH	L	4.00 Slabs										
66	SMALL PATCH	L	1.00 Slabs										
67	LARGE PATCH	L	1.00 Slabs										
74	JOINT SPALL	M	1.00 Slabs										
75	CORNER SPALL	L	1.00 Slabs										
Sample Number:	03	Type:	R	Area:	20.00 Slabs		PCI:	83					
Sample Comments:													
63	LINEAR CR	L	1.00 Slabs										
63	LINEAR CR	L	1.00 Slabs										
65	JT SEAL DMG	L	20.00 Slabs										
66	SMALL PATCH	L	1.00 Slabs										
66	SMALL PATCH	L	3.00 Slabs										
66	SMALL PATCH	L	1.00 Slabs										
70	SCALING	L	1.00 Slabs										
74	JOINT SPALL	L	1.00 Slabs										
Sample Number:	05	Type:	R	Area:	20.00 Slabs		PCI:	71					
Sample Comments:													
63	LINEAR CR	L	1.00 Slabs										
63	LINEAR CR	L	1.00 Slabs										
63	LINEAR CR	L	1.00 Slabs										
65	JT SEAL DMG	L	20.00 Slabs										
66	SMALL PATCH	L	3.00 Slabs										
66	SMALL PATCH	L	1.00 Slabs										
67	LARGE PATCH	L	2.00 Slabs										
67	LARGE PATCH	L	2.00 Slabs										
74	JOINT SPALL	M	1.00 Slabs										
75	CORNER SPALL	L	1.00 Slabs										
75	CORNER SPALL	L	1.00 Slabs										

Sample Number: 06		Type:	R	Area:		20.00 Slabs	PCI: 75
Sample Comments:							
65	JT SEAL DMG		L	20.00	Slabs		
66	SMALL PATCH		L	1.00	Slabs		
67	LARGE PATCH		L	2.00	Slabs		
67	LARGE PATCH		L	4.00	Slabs		
70	SCALING		L	2.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
74	JOINT SPALL		M	2.00	Slabs		
Sample Number: 08		Type:	R	Area:		20.00 Slabs	PCI: 80
Sample Comments:							
63	LINEAR CR		L	1.00	Slabs		
63	LINEAR CR		L	1.00	Slabs		
65	JT SEAL DMG		L	20.00	Slabs		
66	SMALL PATCH		L	2.00	Slabs		
66	SMALL PATCH		L	3.00	Slabs		
70	SCALING		L	2.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
Sample Number: 09		Type:	R	Area:		20.00 Slabs	PCI: 90
Sample Comments:							
63	LINEAR CR		L	1.00	Slabs		
65	JT SEAL DMG		L	20.00	Slabs		
66	SMALL PATCH		L	1.00	Slabs		
66	SMALL PATCH		L	1.00	Slabs		
73	SHRINKAGE CR		N	1.00	Slabs		
73	SHRINKAGE CR		N	1.00	Slabs		
Sample Number: 12		Type:	R	Area:		25.00 Slabs	PCI: 88
Sample Comments:							
65	JT SEAL DMG		L	25.00	Slabs		
66	SMALL PATCH		L	4.00	Slabs		
66	SMALL PATCH		L	1.00	Slabs		
67	LARGE PATCH		L	2.00	Slabs		
70	SCALING		L	1.00	Slabs		
70	SCALING		L	1.00	Slabs		
Sample Number: 13		Type:	R	Area:		20.00 Slabs	PCI: 83
Sample Comments:							
63	LINEAR CR		L	1.00	Slabs		
65	JT SEAL DMG		L	20.00	Slabs		
73	SHRINKAGE CR		N	1.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
74	JOINT SPALL		M	2.00	Slabs		

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal					
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt
Section:	04	of 8	From:	T05TD-01			To:	A01-05	Last Const.: 9/1/2021
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC	Zone:	KDLS	Category:	K	Rank:	P
Area:	70,840 SqFt		Length:	260 Ft		Width:	320 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	9/1/1983		Work Type: Base Course - Aggregate			Code:	BA-AG	Is Major M&R:	True
Work Date:	9/2/1983		Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	7/1/1997		Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/1999		Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	9/2/2012		Work Type: Patching - AC Deep			Code:	PA-AD	Is Major M&R:	False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	9/2/2015		Work Type: Patching - AC Full Depth			Code:	PA-AF	Is Major M&R:	False
Work Date:	9/1/2021		Work Type: Cold Mill and Overlay			Code:	MOL	Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	15		Surveyed:	5		
Conditions:	PCI: 100								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	05	Type:	R	Area:	5000.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	06	Type:	R	Area:	5000.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	07	Type:	R	Area:	5000.00 SqFt		PCI:	100	
Sample Comments:									
<No Distress>									

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt		
Section:	07	of	8	From:	A01-06		To:	T10-01		Last Const.:	9/2/1983
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS	Category:	K		Rank:	P
Area:	83,735 SqFt		Length:	200 Ft		Width:	391 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1983		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1983		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/1999		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	6/1/2001		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2008		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	7/1/2022		TotalSamples:	17		Surveyed:	5				
Conditions:	PCI: 65										
Inspection Comments:											
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	70			
Sample Comments:											
48	L & T CR	L	25.00 Ft								
48	L & T CR	L	50.00 Ft								
48	L & T CR	M	50.00 Ft								
57	WEATHERING	M	5000.00 SqFt								
Sample Number:	05	Type:	R	Area:	5000.00 SqFt		PCI:	67			
Sample Comments:											
48	L & T CR	L	45.00 Ft								
48	L & T CR	M	142.00 Ft								
48	L & T CR	M	100.00 Ft								
57	WEATHERING	M	5000.00 SqFt								
Sample Number:	10	Type:	R	Area:	5000.00 SqFt		PCI:	66			
Sample Comments:											
48	L & T CR	M	132.00 Ft								
48	L & T CR	M	182.00 Ft								
57	WEATHERING	M	5000.00 SqFt								
Sample Number:	12	Type:	R	Area:	5000.00 SqFt		PCI:	63			
Sample Comments:											
48	L & T CR	M	237.00 Ft								
48	L & T CR	M	146.00 Ft								
57	WEATHERING	M	5000.00 SqFt								
Sample Number:	14	Type:	R	Area:	5000.00 SqFt		PCI:	61			
Sample Comments:											
48	L & T CR	L	20.00 Ft								
48	L & T CR	M	80.00 Ft								
48	L & T CR	M	178.00 Ft								

48	L & T CR	M	150.00	Ft
57	WEATHERING	M	5000.00	SqFt

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal									
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt				
Section:	05	of	8	From:	A01-04		To:	A01-06		Last Const.:	9/1/2021		
Surface:	AAC		Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	78,753 SqFt		Length:	305 Ft		Width:	277 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	9/1/1977		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/1977		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1983		Work Type:	Overlay - AC Thin				Code:	OL-AT		Is Major M&R:	True	
Work Date:	9/1/1988		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/1988		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	7/1/1997		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1998		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1999		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2004		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2012		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/2012		Work Type:	Patching - AC Deep				Code:	PA-AD		Is Major M&R:	False	
Work Date:	9/1/2021		Work Type:	Cold Mill and Overlay				Code:	MOL		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	16		Surveyed:	6						
Conditions:	PCI:	100											
Inspection Comments:													
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													
Sample Number:	06	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													
Sample Number:	07	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													
Sample Number:	09	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													
Sample Number:	13	Type:	R	Area:	5000.00 SqFt		PCI:	100					
Sample Comments:													
<No Distress>													

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON		Area:	300,168 SqFt	
Section:	02 of 8		From:	A01-01			To:	END		Last Const.:	9/2/1997
Surface:	AC		Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS		Category:	K Rank: P	
Area:	2,568 SqFt		Length:	60 Ft		Width:	60 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	9/1/1997		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True	
Work Date:	9/2/1997		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	6/1/2001		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	9/1/2015		Work Type: Patching - AC Full Depth				Code:	PA-AF		Is Major M&R: False	
Last Insp. Date:	7/1/2022		TotalSamples:	1			Surveyed:	1			
Conditions:	PCI: 62										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	2568.00 SqFt		PCI:	62	
Sample Comments:											
48	L & T CR		L	60.00 Ft							
48	L & T CR		L	120.00 Ft							
48	L & T CR		M	90.00 Ft							
50	PATCHING		L	1.00 SqFt							
50	PATCHING		L	1.00 SqFt							
50	PATCHING		L	12.00 SqFt							
50	PATCHING		L	1.00 SqFt							
57	WEATHERING		M	2568.00 SqFt							

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal			
Branch:	A01TD	Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt
Section:	08	of	8	From:	TA	To:	PCC	Last Const.: 6/3/2017
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS	Category:	K Rank: P
Area:	3,027 SqFt	Length:	38 Ft		Width:	70 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length: Ft
Shoulder:		Street Type:			Grade:	0		Lanes: 0
Section Comments:								
Work Date:	6/1/2017	Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	6/2/2017	Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	6/3/2017	Work Type: Complete Reconstruction - AC				Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	7/1/2022	TotalSamples:	1		Surveyed:	1		
Conditions:	PCI: 94							
Inspection Comments:								
Sample Number:	01	Type:	R	Area:	3027.00 SqFt		PCI:	94
Sample Comments:								
57	WEATHERING	L	3027.00 SqFt					

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	A01TD		Name:	Apron 01 The Dalles		Use:	APRON	Area:	300,168 SqFt		
Section:	03	of 8	From:	A01-02		To:	A01-06		Last Const.:	9/1/1997	
Surface:	PCC	Family:	2022_Eastern_Cat1/2/3_AIUses_PCC		Zone:	KDLS		Category:	K	Rank:	P
Area:	1,032 SqFt		Length:	40 Ft		Width:	24 Ft				
Slabs:	7	Slab Length:	13 Ft		Slab Width:	12 Ft		Joint Length:	90 Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1997		Work Type:	New Construction - PCC			Code:	NC-PC		Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	87									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	7.00 Slabs		PCI:	87			
Sample Comments:											
63	LINEAR CR	L	1.00 Slabs								
66	SMALL PATCH	L	1.00 Slabs								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	A02TD		Name:	Apron 02 The Dalles		Use:	APRON	Area:	108,547 SqFt		
Section:	01	of	2	From:	T06-01		To:	T08, T09			
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC		Zone:	KDLS	Category:	K	Rank:	S	
Area:	89,259 SqFt		Length:	435 Ft		Width:	209 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1995		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1995		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	6/1/2001		Work Type: Surface Seal - Fog Seal				Code:	SS-FS		Is Major M&R:	False
Work Date:	9/1/2008		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	7/1/2022		TotalSamples:	18		Surveyed:	5				
Conditions:	PCI: 71										
Inspection Comments:											
Sample Number:	03		Type:	R		Area:	5625.00 SqFt		PCI:	68	
Sample Comments:											
48	L & T CR		L	39.00 Ft							
48	L & T CR		M	26.00 Ft							
48	L & T CR		M	179.00 Ft							
48	L & T CR		M	75.00 Ft							
57	WEATHERING		M	5625.00 SqFt							
Sample Number:	04		Type:	R		Area:	5625.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		M	200.00 Ft							
48	L & T CR		M	150.00 Ft							
48	L & T CR		H	20.00 Ft							
57	WEATHERING		M	5625.00 SqFt							
Sample Number:	09		Type:	R		Area:	6000.00 SqFt		PCI:	75	
Sample Comments:											
48	L & T CR		M	75.00 Ft							
48	L & T CR		M	60.00 Ft							
57	WEATHERING		M	6000.00 SqFt							
Sample Number:	13		Type:	R		Area:	6000.00 SqFt		PCI:	75	
Sample Comments:											
48	L & T CR		L	5.00 Ft							
48	L & T CR		L	2.00 Ft							
48	L & T CR		M	100.00 Ft							
48	L & T CR		M	25.00 Ft							
57	WEATHERING		M	6000.00 SqFt							
Sample Number:	16		Type:	R		Area:	5038.00 SqFt		PCI:	75	
Sample Comments:											
48	L & T CR		M	100.00 Ft							
57	WEATHERING		M	5038.00 SqFt							

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	A02TD		Name:	Apron 02 The Dalles		Use:	APRON		Area:	108,547 SqFt	
Section:	02	of 2	From:	South Hangar			To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	2022_Eastern_Cat3_Apron_AC/AAC	Zone:	KDLS		Category:	K		Rank:	S
Area:	19,288 SqFt		Length:	325 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:			Grade:	0		Lanes:		0		
Section Comments:											
Work Date:	1/1/2009		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	7/1/2022		TotalSamples:	4		Surveyed: 3					
Conditions:	PCI:	78									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	86			
Sample Comments:											
48	L & T CR		M	28.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR		M	38.00 Ft							
57	WEATHERING		M	5000.00 SqFt							
Sample Number:	03	Type:	R	Area:	6288.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR		L	10.00 Ft							
48	L & T CR		M	20.00 Ft							
57	WEATHERING		M	6288.00 SqFt							

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	R07TD		Name:	Rwy 07/25 The Dalles		Use:	RUNWAY	Area:	464,300 SqFt		
Section:	02	of	5	From:	R07-01		To:	R07-03			
Surface:	AC	Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS	Category:	K	Rank:	P	
Area:	232,750 SqFt		Length:	2,328 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG		Is Major M&R:	True
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/2/2015		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	7/1/2022		TotalSamples:	47		Surveyed:	6				
Conditions:	PCI: 76										
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	74			
Sample Comments:											
48	L & T CR	L	25.00 Ft								
48	L & T CR	L	266.00 Ft								
48	L & T CR	L	125.00 Ft								
57	WEATHERING	L	5000.00 SqFt								
Sample Number:	09	Type:	R	Area:	5000.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR	L	243.00 Ft								
48	L & T CR	L	3.00 Ft								
48	L & T CR	L	150.00 Ft								
57	WEATHERING	L	5000.00 SqFt								
Sample Number:	17	Type:	R	Area:	5000.00 SqFt		PCI:	79			
Sample Comments:											
48	L & T CR	L	168.00 Ft								
48	L & T CR	L	110.00 Ft								
57	WEATHERING	L	5000.00 SqFt								
Sample Number:	25	Type:	R	Area:	5000.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR	L	110.00 Ft								
48	L & T CR	L	134.00 Ft								
48	L & T CR	M	10.00 Ft								
57	WEATHERING	L	5000.00 SqFt								

Sample Number: 33		Type: R	Area: 5000.00 SqFt		PCI: 78
Sample Comments:					
48	L & T CR	L	160.00	Ft	
48	L & T CR	L	136.00	Ft	
57	WEATHERING	L	5000.00	SqFt	
Sample Number: 41		Type: R	Area: 5000.00 SqFt		PCI: 75
Sample Comments:					
48	L & T CR	L	10.00	Ft	
48	L & T CR	L	50.00	Ft	
48	L & T CR	L	190.00	Ft	
48	L & T CR	M	50.00	Ft	
57	WEATHERING	L	5000.00	SqFt	

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	R07TD		Name:	Rwy 07/25 The Dalles		Use:	RUNWAY		Area:	464,300 SqFt		
Section:	05	of 5	From:	R07-04			To:	R07 END		Last Const.:	9/2/1943	
Surface:	AC	Family:	2022_Eastern_Cat3_RW_AC/AAC	Zone:	KDLS			Category:	K		Rank:	P
Area:	46,000 SqFt		Length:	460 Ft		Width:	100 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG		Is Major M&R:	True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2015		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Last Insp. Date:	7/1/2022		TotalSamples:	9		Surveyed:	4					
Conditions:	PCI:	81										
Inspection Comments:												
Sample Number:	02	Type:	R	Area:	5000.00 SqFt			PCI:	81			
Sample Comments:												
48	L & T CR	L	50.00	Ft								
48	L & T CR	L	70.00	Ft								
48	L & T CR	L	120.00	Ft								
57	WEATHERING	L	5000.00	SqFt								
Sample Number:	04	Type:	R	Area:	5000.00 SqFt			PCI:	81			
Sample Comments:												
48	L & T CR	L	128.00	Ft								
48	L & T CR	L	114.00	Ft								
57	WEATHERING	L	5000.00	SqFt								
Sample Number:	06	Type:	R	Area:	5000.00 SqFt			PCI:	83			
Sample Comments:												
48	L & T CR	L	95.00	Ft								
48	L & T CR	L	98.00	Ft								
57	WEATHERING	L	5000.00	SqFt								
Sample Number:	08	Type:	R	Area:	5000.00 SqFt			PCI:	81			
Sample Comments:												
48	L & T CR	L	71.00	Ft								
48	L & T CR	L	157.00	Ft								
57	WEATHERING	L	5000.00	SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	R07TD		Name:	Rwy 07/25 The Dalles		Use:	RUNWAY	Area:	464,300 SqFt
Section:	01	of	5	From:	25 END		To:	R07-02	Last Const.: 9/2/1943
Surface:	AC	Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS	Category:	K	Rank: P
Area:	20,000 SqFt		Length:	200 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG Is Major M&R: True	
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG Is Major M&R: True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/2015		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Last Insp. Date:	7/1/2022		TotalSamples:	4		Surveyed:	3		
Conditions:	PCI: 85								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR		L	14.00 Ft					
48	L & T CR		L	50.00 Ft					
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	87	
Sample Comments:									
48	L & T CR		L	50.00 Ft					
48	L & T CR		L	58.00 Ft					
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	80	
Sample Comments:									
48	L & T CR		L	100.00 Ft					
48	L & T CR		L	5.00 Ft					
48	L & T CR		L	13.00 Ft					
48	L & T CR		L	133.00 Ft					
57	WEATHERING		L	5000.00 SqFt					

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	R07TD		Name:	Rwy 07/25 The Dalles		Use:	RUNWAY		Area:	464,300 SqFt		
Section:	03	of	5	From:	R07-02			To:	R07-04		Last Const.:	7/1/2012
Surface:	AAC	Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	57,500 SqFt		Length:	575 Ft		Width:	100 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True		
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG		Is Major M&R: True		
Work Date:	9/2/1943		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True		
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	7/1/2012		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R: True		
Last Insp. Date:	7/1/2022		TotalSamples:	12		Surveyed:	4					
Conditions:	PCI: 91											
Inspection Comments:												
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	04		Type:	R		Area:	5000.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	13.00 Ft								
48	L & T CR		L	50.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	07		Type:	R		Area:	5000.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	20.00 Ft								
48	L & T CR		L	49.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	10		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	14.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	R07TD		Name:	Rwy 07/25 The Dalles		Use:	RUNWAY	Area:	464,300 SqFt
Section:	04	of	5	From:	R07-03		To:	R07-05	Last Const.: 9/2/1943
Surface:	AC	Family:	2022_Eastern_Cat3_RW_AC/AAC	Zone:	KDLS		Category:	K	Rank: P
Area:	108,050 SqFt		Length:	1,081 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade: 0		Lanes: 0				
Section Comments:									
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: True
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG	Is Major M&R: True
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS	Is Major M&R: False
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS	Is Major M&R: False
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS	Is Major M&R: False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	9/2/2015		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS	Is Major M&R: False
Last Insp. Date:	7/1/2022		TotalSamples:	22		Surveyed:	5		
Conditions:	PCI:	74							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	69	
Sample Comments:									
41	ALLIGATOR CR	M	10.00 SqFt						
48	L & T CR	L	115.00 Ft						
48	L & T CR	L	50.00 Ft						
48	L & T CR	L	220.00 Ft						
48	L & T CR	L	50.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	06	Type:	R	Area:	5000.00 SqFt		PCI:	75	
Sample Comments:									
48	L & T CR	L	64.00 Ft						
48	L & T CR	L	50.00 Ft						
48	L & T CR	L	131.00 Ft						
48	L & T CR	M	10.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	13	Type:	R	Area:	5000.00 SqFt		PCI:	76	
Sample Comments:									
48	L & T CR	L	89.00 Ft						
48	L & T CR	L	140.00 Ft						
48	L & T CR	M	10.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	18	Type:	R	Area:	5000.00 SqFt		PCI:	79	
Sample Comments:									
48	L & T CR	L	89.00 Ft						
48	L & T CR	L	180.00 Ft						

57	WEATHERING	L	5000.00	SqFt		
<hr/>						
Sample Number:		21	Type:	R	Area:	5000.00 SqFt
Sample Comments:					PCI:	69
48	L & T CR	L	180.00	Ft		
48	L & T CR	M	176.00	Ft		
57	WEATHERING	L	5000.00	SqFt		

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	R13TD		Name:	Runway 13/31 The Dalles		Use:	RUNWAY		Area:	497,720 SqFt		
Section:	01	of 3		From:	R13 End		To:	R07		Last Const.:	7/1/2012	
Surface:	AAC	Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	107,010 SqFt		Length:	1,070 Ft		Width:	100 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/1943		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	7/1/2012		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	22		Surveyed:	5					
Conditions:	PCI: 90											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	89				
Sample Comments:												
48	L & T CR		L	50.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	05	Type:	R	Area:	5000.00 SqFt		PCI:	90				
Sample Comments:												
48	L & T CR		L	20.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	09	Type:	R	Area:	5000.00 SqFt		PCI:	89				
Sample Comments:												
48	L & T CR		L	60.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	13	Type:	R	Area:	5000.00 SqFt		PCI:	90				
Sample Comments:												
48	L & T CR		L	15.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	17	Type:	R	Area:	5000.00 SqFt		PCI:	91				
Sample Comments:												
48	L & T CR		L	10.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	R13TD		Name:	Runway 13/31 The Dalles		Use:	RUNWAY		Area:	497,720 SqFt			
Section:	03		of	3	From:	R12TD-02		To:	R31 End		Last Const.:	10/4/2012	
Surface:	AC		Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	244,700 SqFt			Length:	2,447 Ft			Width:	100 Ft				
Slabs:				Slab Length:	Ft			Slab Width:	Ft			Joint Length:	Ft
Shoulder:				Street Type:				Grade:	0			Lanes:	0
Section Comments:													
Work Date:	10/1/2012			Work Type:	Geotextile				Code:	FB-TX		Is Major M&R:	False
Work Date:	10/2/2012			Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	10/3/2012			Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	10/4/2012			Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022			TotalSamples:	49			Surveyed:	6				
Conditions:	PCI: 84												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5000.00 SqFt			PCI:	79		
Sample Comments:													
41	ALLIGATOR CR		L	5.00 SqFt									
48	L & T CR		L	110.00 Ft									
48	L & T CR		L	50.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	08		Type:	R		Area:	5000.00 SqFt			PCI:	63		
Sample Comments:													
41	ALLIGATOR CR		L	100.00 SqFt									
48	L & T CR		L	100.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	16		Type:	R		Area:	5000.00 SqFt			PCI:	84		
Sample Comments:													
48	L & T CR		L	50.00 Ft									
48	L & T CR		L	50.00 Ft									
48	L & T CR		L	25.00 Ft									
48	L & T CR		L	25.00 Ft									
48	L & T CR		L	25.00 Ft									
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	24		Type:	R		Area:	5000.00 SqFt			PCI:	94		
Sample Comments:													
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	32		Type:	R		Area:	5000.00 SqFt			PCI:	96		
Sample Comments:													
48	L & T CR		L	25.00 Ft									
Sample Number:	40		Type:	R		Area:	5000.00 SqFt			PCI:	89		
Sample Comments:													
48	L & T CR		L	50.00 Ft									
57	WEATHERING		L	5000.00 SqFt									

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	R13TD		Name:	Runway 13/31 The Dalles		Use:	RUNWAY	Area:	497,720 SqFt
Section:	02	of	3	From:	R07	To:	R13TD-03		Last Const.: 7/1/2012
Surface:	AAC	Family:	2022_Eastern_Cat3_RW_AC/AAC		Zone:	KDLS	Category:	K	Rank: P
Area:	146,010 SqFt		Length:	1,464 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG Is Major M&R: True	
Work Date:	9/2/1943		Work Type: New Construction - AC				Code:	NC-AC Is Major M&R: True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC Is Major M&R: False	
Work Date:	5/2/2005		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS Is Major M&R: False	
Work Date:	7/1/2012		Work Type: Overlay - AC Structural				Code:	OL-AS Is Major M&R: True	
Last Insp. Date:	7/1/2022		TotalSamples:	30		Surveyed:	5		
Conditions:	PCI: 90								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5000.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR	L	50.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	08	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	16	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	24	Type:	R	Area:	5000.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR	L	40.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	29	Type:	R	Area:	5000.00 SqFt		PCI:	83	
Sample Comments:									
41	ALLIGATOR CR	L	10.00 SqFt						
48	L & T CR	L	20.00 Ft						
57	WEATHERING	L	5000.00 SqFt						

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	T02TD		Name:	Taxiway 02 The Dalles		Use:	TAXIWAY	Area:	1,768 SqFt			
Section:	01	of	1	From:	A01-07		To:	T05-01		Last Const.:	6/3/2017	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	1,768 SqFt		Length:	50 Ft		Width:	30 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	9/1/1983		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1983		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1998		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2004		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2008		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2012		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	6/1/2017		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	6/2/2017		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	6/3/2017		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	1768.00 SqFt		PCI:	92				
Sample Comments:												
50	PATCHING		L	4.00 SqFt								
57	WEATHERING		L	1768.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	T03TD		Name:	Taxiway 03 The Dalles		Use:	TAXIWAY	Area:	1,768 SqFt			
Section:	01	of	1	From:	A01-07			To:	T05-01	Last Const.:	6/3/2017	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K	Rank:	P	
Area:	1,768 SqFt		Length:	50 Ft		Width:	30 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0		Lanes:	0				
Section Comments:												
Work Date:	9/1/1983			Work Type:	Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1983			Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1998			Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2004			Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2008			Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2012			Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	6/1/2017			Work Type:	Subbase - Aggregate			Code:	SB-AG		Is Major M&R:	False
Work Date:	6/2/2017			Work Type:	Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	False
Work Date:	6/3/2017			Work Type:	Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022			TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 84											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	1768.00 SqFt		PCI:	84				
Sample Comments:												
57	WEATHERING		L	1238.00 SqFt								
57	WEATHERING		M	530.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal						
Branch:	T04TD		Name:	Taxiway 04 The Dalles		Use:	TAXIWAY		Area:	6,634 SqFt	
Section:	02 of 2		From:	A01-07			To:	T04-01		Last Const.:	9/2/1983
Surface:	AC		Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K Rank: P	
Area:	4,566 SqFt		Length:	175 Ft		Width:	24 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	9/1/1983		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True
Work Date:	9/2/1983		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	9/1/1997		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/1999		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2008		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 69										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	4566.00 SqFt		PCI:	69	
Sample Comments:											
48	L & T CR		L	10.00 Ft							
48	L & T CR		M	200.00 Ft							
48	L & T CR		M	25.00 Ft							
57	WEATHERING		M	4566.00 SqFt							

Network:		Columbia		Name:		Columbia Gorge Regional / The Dalles Municipal							
Branch:	T04TD		Name:	Taxiway 04 The Dalles		Use:	TAXIWAY	Area:	6,634 SqFt				
Section:	01	of 2		From:	TA		To:	T04-02		Last Const.:	6/3/2017		
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	S	
Area:	2,068 SqFt		Length:	75 Ft		Width:	24 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	6/1/2017		Work Type:				Subbase - Aggregate		Code:	SB-AG		Is Major M&R:	False
Work Date:	6/2/2017		Work Type:				Base Course - Aggregate		Code:	BA-AG		Is Major M&R:	False
Work Date:	6/3/2017		Work Type:				Complete Reconstruction - AC		Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 89												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	2068.00 SqFt		PCI:	89					
Sample Comments:													
48	L & T CR		L	26.00 Ft									
57	WEATHERING		L	2068.00 SqFt									

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	T05TD		Name:	Taxiway 05 The Dalles		Use:	TAXIWAY	Area:	28,264 SqFt			
Section:	02	of 3	From:	T05-01			To:	T05-03		Last Const.:	9/2/1995	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	S
Area:	22,606 SqFt		Length:	646 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1995		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/1995		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	6/1/2001		Work Type: Surface Seal - Fog Seal				Code:	SS-FS		Is Major M&R:	False	
Work Date:	9/1/2008		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2022		TotalSamples:	4		Surveyed:	3					
Conditions:	PCI: 68											
Inspection Comments:												
Sample Number:	02	Type:	R	Area:	5250.00 SqFt		PCI:	66				
Sample Comments:												
48	L & T CR	L	10.00 Ft									
48	L & T CR	L	27.00 Ft									
48	L & T CR	M	40.00 Ft									
48	L & T CR	M	105.00 Ft									
48	L & T CR	M	150.00 Ft									
57	WEATHERING	M	5250.00 SqFt									
Sample Number:	03	Type:	R	Area:	5250.00 SqFt		PCI:	67				
Sample Comments:												
48	L & T CR	M	75.00 Ft									
48	L & T CR	M	150.00 Ft									
48	L & T CR	M	85.00 Ft									
57	WEATHERING	M	5250.00 SqFt									
Sample Number:	04	Type:	R	Area:	6856.00 SqFt		PCI:	70				
Sample Comments:												
48	L & T CR	M	196.00 Ft									
48	L & T CR	M	120.00 Ft									
57	WEATHERING	M	6856.00 SqFt									

Network:		Columbia		Name:		Columbia Gorge Regional / The Dalles Municipal									
Branch:		T05TD		Name:		Taxiway 05 The Dalles		Use:		TAXIWAY		Area:		28,264 SqFt	
Section:		03		of 3		From:		TA		To:		T05-02		Last Const.: 6/3/2017	
Surface:		AC		Family:		2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:		KDLS		Category:		K Rank: S	
Area:		3,033 SqFt		Length:		56 Ft		Width:		35 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date: 6/1/2017				Work Type: Subbase - Aggregate						Code: SB-AG		Is Major M&R: False			
Work Date: 6/2/2017				Work Type: Base Course - Aggregate						Code: BA-AG		Is Major M&R: False			
Work Date: 6/3/2017				Work Type: Complete Reconstruction - AC						Code: CR-AC		Is Major M&R: True			
Last Insp. Date: 7/1/2022				TotalSamples:		1		Surveyed:		1					
Conditions: PCI: 79															
Inspection Comments:															
Sample Number:		01		Type:		R		Area:		3033.00 SqFt		PCI: 79			
Sample Comments:															
48		L & T CR		L		17.00 Ft									
57		WEATHERING		L		2033.00 SqFt									
57		WEATHERING		M		1000.00 SqFt									

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	T05TD		Name:	Taxiway 05 The Dalles		Use:	TAXIWAY	Area:	28,264 SqFt			
Section:	01	of 3	From:	End			To:	T05-02		Last Const.:	1/1/2009	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	S
Area:	2,625 SqFt		Length:	75 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	1/1/2009		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI:		75									
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	2625.00 SqFt		PCI:	75				
Sample Comments:												
48	L & T CR		L	6.00 Ft								
48	L & T CR		M	18.00 Ft								
48	L & T CR		M	36.00 Ft								
57	WEATHERING		M	2625.00 SqFt								

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	TA1TD		Name:	Taxiway A1 The Dalles		Use:	TAXIWAY		Area:	15,935 SqFt		
Section:	01	of 1	From:	R13TD End			To:	TATD-01		Last Const.:	11/3/2013	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	15,935 SqFt		Length:	230 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	11/1/2013		Work Type:	Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False
Work Date:	11/2/2013		Work Type:	Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False
Work Date:	11/3/2013		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	3		Surveyed:	2					
Conditions:	PCI:	94										
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	4763.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	4763.00 SqFt								
Sample Number:	02	Type:	R	Area:	4702.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	4702.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TA2TD		Name:	Taxiway A2 The Dalles		Use:	TAXIWAY		Area:	19,429 SqFt		
Section:	02	of	2	From:	TA2TD-01			To:	T05TD-01		Last Const.:	6/3/2017
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	12,771 SqFt		Length:	210 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:		0		
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True		
Work Date:	9/2/1943		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True		
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/1999		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	6/1/2001		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2008		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2012		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	6/1/2017		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: False		
Work Date:	6/2/2017		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False		
Work Date:	6/3/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed: 2						
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	3210.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	3210.00 SqFt								
Sample Number:	02	Type:	R	Area:	3977.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	3977.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TA2TD		Name:	Taxiway A2 The Dalles		Use:	TAXIWAY		Area:	19,429 SqFt		
Section:	01	of	2	From:	TATD / TBTD			To:	Intersection		Last Const.:	11/3/2013
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	6,658 SqFt		Length:	133 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	11/1/2013		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	11/2/2013		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	11/3/2013		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI:	75										
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	6658.00 SqFt			PCI:	75			
Sample Comments:												
48	L & T CR		L	103.00 Ft								
57	WEATHERING		L	3323.00 SqFt								
57	WEATHERING		M	3323.00 SqFt								

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TA3TD	Name:	Taxiway A3 The Dalles		Use:	TAXIWAY	Area:	117,331 SqFt			
Section:	03	of 4	From:	T05-01		To:	R13		Last Const.:	9/2/1943	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC	Zone:	KDLS		Category:	K		Rank:	P
Area:	8,321 SqFt		Length:	148 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0	Lanes:		0			
Section Comments:											
Work Date:	9/1/1943		Work Type: Base Course - Aggregate			Code:	BA-AG		Is Major M&R:	True	
Work Date:	9/2/1943		Work Type: New Construction - AC			Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/1988		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/1999		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Work Date:	6/1/2001		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2004		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2008		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Work Date:	9/1/2012		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed:	2				
Conditions:	PCI:	60									
Inspection Comments:											
Sample Number:	01	Type:	R	Area:	4184.00 SqFt		PCI:	51			
Sample Comments:											
48	L & T CR	L	12.00	Ft							
48	L & T CR	M	465.00	Ft							
50	PATCHING	L	804.00	SqFt							
57	WEATHERING	M	4184.00	SqFt							
Sample Number:	02	Type:	R	Area:	4136.00 SqFt		PCI:	69			
Sample Comments:											
48	L & T CR	M	140.00	Ft							
50	PATCHING	L	312.00	SqFt							
57	WEATHERING	M	4136.00	SqFt							

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	TA3TD		Name:	Taxiway A3 The Dalles		Use:	TAXIWAY	Area:	117,331 SqFt
Section:	01	of	4	From:	R02 End		To:	TA3TD-02	Last Const.: 9/2/1943
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC	Zone:	KDLS		Category:	K	Rank: P
Area:	70,507 SqFt		Length:	2,010 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	9/1/1943		Work Type: Base Course - Aggregate			Code:	BA-AG		Is Major M&R: True
Work Date:	9/2/1943		Work Type: New Construction			Code:	HI-AG		Is Major M&R: True
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R: False
Work Date:	9/1/1988		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R: False
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R: False
Work Date:	9/1/1998		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R: False
Work Date:	9/1/2004		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R: False
Work Date:	9/1/2012		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R: False
Work Date:	9/1/2015		Work Type: Crack Sealing - AC			Code:	CS-AC		Is Major M&R: False
Last Insp. Date:	7/1/2022		TotalSamples:	14		Surveyed:	5		
Conditions:	PCI:	75							
Inspection Comments:									
Sample Number:	04	Type:	R	Area:	5250.00 SqFt		PCI:	75	
Sample Comments:									
48	L & T CR	L	80.00 Ft						
48	L & T CR	L	150.00 Ft						
48	L & T CR	L	22.00 Ft						
57	WEATHERING	M	5250.00 SqFt						
Sample Number:	07	Type:	R	Area:	5250.00 SqFt		PCI:	75	
Sample Comments:									
48	L & T CR	L	50.00 Ft						
48	L & T CR	L	10.00 Ft						
48	L & T CR	L	16.00 Ft						
48	L & T CR	L	150.00 Ft						
48	L & T CR	L	50.00 Ft						
48	L & T CR	L	87.00 Ft						
57	WEATHERING	M	5250.00 SqFt						
Sample Number:	10	Type:	R	Area:	5250.00 SqFt		PCI:	75	
Sample Comments:									
48	L & T CR	L	32.00 Ft						
48	L & T CR	L	20.00 Ft						
48	L & T CR	L	20.00 Ft						
48	L & T CR	L	2.00 Ft						
48	L & T CR	L	150.00 Ft						
57	WEATHERING	M	5250.00 SqFt						
Sample Number:	12	Type:	R	Area:	5250.00 SqFt		PCI:	75	
Sample Comments:									
48	L & T CR	L	100.00 Ft						
48	L & T CR	L	85.00 Ft						
57	WEATHERING	M	5000.00 SqFt						
Sample Number:	14	Type:	R	Area:	5250.00 SqFt		PCI:	75	
Sample Comments:									

48	L & T CR	L	60.00	Ft
57	WEATHERING	M	5000.00	SqFt

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	TA3TD		Name:	Taxiway A3 The Dalles		Use:	TAXIWAY	Area:	117,331 SqFt
Section:	04	of	4	From:	TA3-03		To:	TA	Last Const.: 6/3/2017
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS	Category:	K	Rank: P
Area:	31,022 SqFt		Length:	610 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0
Section Comments:									
Work Date:	6/1/2017		Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	6/2/2017		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	6/3/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	7/1/2022		TotalSamples:	6		Surveyed:	3		
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	04	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	05	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TA3TD		Name:	Taxiway A3 The Dalles		Use:	TAXIWAY		Area:	117,331 SqFt		
Section:	02	of	4	From:	TA3TD-01			To:	R12		Last Const.:	7/1/2012
Surface:	AAC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	7,481 SqFt		Length:	190 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: True		
Work Date:	9/2/1943		Work Type: New Construction				Code:	HI-AG		Is Major M&R: True		
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	9/1/1988		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/2/1988		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False		
Work Date:	9/1/1998		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	9/1/2004		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False		
Work Date:	7/1/2012		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R: True		
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed:	2					
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	3466.00 SqFt			PCI:	94			
Sample Comments:												
57	WEATHERING		L	3466.00 SqFt								
Sample Number:	02	Type:	R	Area:	4015.00 SqFt			PCI:	94			
Sample Comments:												
57	WEATHERING		L	4015.00 SqFt								

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	TA4TD	Name:	Taxiway A4 The Dalles		Use:	TAXIWAY	Area:	12,777 SqFt
Section:	01	of	1	From:	TA-04	To:	R30 End	Last Const.: 10/4/2012
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS	Category: K	Rank: P
Area:	12,777 SqFt		Length:	233 Ft	Width:	38 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0	Lanes: 0		
Section Comments:								
Work Date:	10/1/2012	Work Type: Geotextile				Code:	FB-TX	Is Major M&R: False
Work Date:	10/2/2012	Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	10/3/2012	Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	10/4/2012	Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True
Last Insp. Date:	7/1/2022	TotalSamples:		2	Surveyed:		2	
Conditions:	PCI: 94							
Inspection Comments:								
Sample Number:	01	Type:	R	Area:	6761.00 SqFt	PCI: 94		
Sample Comments:								
57	WEATHERING	L	6761.00 SqFt					
Sample Number:	02	Type:	R	Area:	6015.00 SqFt	PCI: 94		
Sample Comments:								
57	WEATHERING	L	6015.00 SqFt					

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal			
Branch:	TATD	Name:	Taxiway A The Dalles		Use:	TAXIWAY	Area: 185,105 SqFt
Section:	04	of 5	From:	TA3	To:	TA-05	Last Const.: 5/3/2014
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiw ay_AC/AAC	Zone:	KDLS	Category:	K Rank: P
Area:	59,321 SqFt	Length:	1,670 Ft	Width:	35 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	9/1/1983	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R: True
Work Date:	5/1/2014	Work Type:	Subbase - Aggregate		Code:	SB-AG	Is Major M&R: False
Work Date:	5/2/2014	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R: False
Work Date:	5/3/2014	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R: True
Last Insp. Date:	7/1/2022	TotalSamples:	11	Surveyed:	4		
Conditions:	PCI: 94						
Inspection Comments:							
Sample Number:	02	Type:	R	Area:	5250.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5250.00	SqFt			
Sample Number:	04	Type:	R	Area:	5250.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5250.00	SqFt			
Sample Number:	07	Type:	R	Area:	5250.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5250.00	SqFt			
Sample Number:	10	Type:	R	Area:	5250.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5250.00	SqFt			

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TATD		Name:	Taxiway A The Dalles		Use:	TAXIWAY	Area:	185,105 SqFt			
Section:	03	of	5	From:	TA2		To:	TA3		Last Const.:	6/3/2017	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	69,061 SqFt		Length:	1,383 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	6/1/2017		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R: False		
Work Date:	6/2/2017		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False		
Work Date:	6/3/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Last Insp. Date:	7/1/2022		TotalSamples:	14		Surveyed:	5					
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	05	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	08	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	10	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	12	Type:	R	Area:	5000.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	TATD		Name:	Taxiway A The Dalles		Use:	TAXIWAY	Area:	185,105 SqFt
Section:	02	of	5	From:	R07TD		To:	TA2TD	Last Const.: 11/3/2013
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS	Category:	K	Rank: P
Area:	12,219 SqFt		Length:	253 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade:		0		Lanes: 0		
Section Comments:									
Work Date:	11/1/2013		Work Type: Subbase - Aggregate				Code:	SB-AG	Is Major M&R: False
Work Date:	11/2/2013		Work Type: Base Course - Aggregate				Code:	BA-AG	Is Major M&R: False
Work Date:	11/3/2013		Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed: 2			
Conditions:	PCI: 78								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	6190.00 SqFt		PCI:	76	
Sample Comments:									
48	L & T CR		L	39.00 Ft					
57	WEATHERING		L	3095.00 SqFt					
57	WEATHERING		M	3095.00 SqFt					
Sample Number:	02	Type:	R	Area:	6028.00 SqFt		PCI:	80	
Sample Comments:									
57	WEATHERING		L	3014.00 SqFt					
57	WEATHERING		M	3014.00 SqFt					

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal				
Branch:	TATD	Name:	Taxiway A The Dalles		Use:	TAXIWAY	Area:	185,105 SqFt	
Section:	05	of 5	From:	TA-04		To:	TA4-01	Last Const.: 10/4/2012	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS	Category:	K	Rank: P
Area:	12,242 SqFt		Length:	375 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft	
Shoulder:	Street Type:		Grade: 0		Lanes: 0				
Section Comments:									
Work Date:	10/1/2012		Work Type: Geotextile			Code:	FB-TX	Is Major M&R: False	
Work Date:	10/2/2012		Work Type: Subbase - Aggregate			Code:	SB-AG	Is Major M&R: False	
Work Date:	10/3/2012		Work Type: Base Course - Aggregate			Code:	BA-AG	Is Major M&R: False	
Work Date:	10/4/2012		Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R: True	
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed:	2		
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5250.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5250.00 SqFt					
Sample Number:	02	Type:	R	Area:	6238.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5250.00 SqFt					

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	TATD		Name:	Taxiway A The Dalles		Use:	TAXIWAY	Area:	185,105 SqFt			
Section:	01	of 5	From:	TA1TD-01			To:	R07TD		Last Const.:	11/3/2013	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	32,262 SqFt		Length:	864 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	11/1/2013		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	11/2/2013		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	11/3/2013		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	6		Surveyed:	3					
Conditions:	PCI: 93											
Inspection Comments:												
Sample Number:	02	Type:	R	Area:	5250.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	03	Type:	R	Area:	5250.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	05	Type:	R	Area:	5250.00 SqFt		PCI:	90				
Sample Comments:												
48	L & T CR		L	26.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	Columbia			Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TBTD		Name:	Taxiway B The Dalles		Use:	TAXIWAY	Area:	170,804 SqFt			
Section:	01	of 4		From:	R07 END		To:	TBTD-02		Last Const.:	9/2/1943	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	43,800 SqFt		Length:	800 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	9/2/1943		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False	
Work Date:	9/1/2015		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date:	7/1/2022		TotalSamples:	9		Surveyed:	3					
Conditions:	PCI:	78										
Inspection Comments:												
Sample Number:	03	Type:	R	Area:	5000.00 SqFt		PCI:	70				
Sample Comments:												
41	ALLIGATOR CR	L	40.00 SqFt									
48	L & T CR	L	40.00 Ft									
48	L & T CR	L	71.00 Ft									
57	WEATHERING	M	5000.00 SqFt									
Sample Number:	06	Type:	R	Area:	5000.00 SqFt		PCI:	75				
Sample Comments:												
48	L & T CR	L	38.00 Ft									
57	WEATHERING	M	5000.00 SqFt									
Sample Number:	08	Type:	R	Area:	5000.00 SqFt		PCI:	89				
Sample Comments:												
48	L & T CR	L	25.00 Ft									
48	L & T CR	L	7.00 Ft									
48	L & T CR	L	25.00 Ft									
57	WEATHERING	L	5000.00 SqFt									

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal							
Branch:	TBTD		Name:	Taxiway B The Dalles		Use:	TAXIWAY		Area:	170,804 SqFt	
Section:	02 of 4		From:	TBTD-01			To:	R02 END		Last Const.:	9/1/2021
Surface:	AC		Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K Rank: P	
Area:	35,181 SqFt		Length:	633 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	9/1/1943		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	9/2/1943		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	9/1/1965		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Work Date:	9/1/2021		Work Type: Cold Mill and Overlay				Code:	MOL		Is Major M&R: True	
Last Insp. Date:	7/1/2022		TotalSamples:	7		Surveyed: 2					
Conditions:	PCI: 100										
Inspection Comments:											
Sample Number:	03		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											
Sample Number:	06		Type:	R		Area:	5000.00 SqFt		PCI:	100	
Sample Comments:											
<No Distress>											

Network:	Columbia		Name:	Columbia Gorge Regional / The Dalles Municipal								
Branch:	TBTD		Name:	Taxiway B The Dalles		Use:	TAXIWAY		Area:	170,804 SqFt		
Section:	03	of 4	From:	R13TD			To:	TATD-02		Last Const.:	11/3/2013	
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	P
Area:	12,842 SqFt		Length:	300 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	11/1/2013		Work Type: Subbase - Aggregate				Code:	SB-AG		Is Major M&R:	False	
Work Date:	11/2/2013		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	11/3/2013		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	2		Surveyed:	2					
Conditions:	PCI:	78										
Inspection Comments:												
Sample Number:	01	Type:	R	Area:	5948.00 SqFt		PCI:	76				
Sample Comments:												
48	L & T CR	L	19.00 Ft									
57	WEATHERING	L	2974.00 SqFt									
57	WEATHERING	M	2974.00 SqFt									
Sample Number:	02	Type:	R	Area:	6893.00 SqFt		PCI:	80				
Sample Comments:												
57	WEATHERING	L	3446.00 SqFt									
57	WEATHERING	M	3446.00 SqFt									

Network:		Columbia		Name:		Columbia Gorge Regional / The Dalles Municipal							
Branch:	TCTD		Name:	Taxiway C The Dalles		Use:	TAXIWAY	Area:	18,024 SqFt				
Section:	01	of 2		From:	TA		To:	TC-02		Last Const.:	6/3/2017		
Surface:	AC	Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	S	
Area:	3,135 SqFt		Length:	128 Ft		Width:	25 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	6/1/2017		Work Type:				Subbase - Aggregate		Code:	SB-AG		Is Major M&R:	False
Work Date:	6/2/2017		Work Type:				Base Course - Aggregate		Code:	BA-AG		Is Major M&R:	False
Work Date:	6/3/2017		Work Type:				Complete Reconstruction - AC		Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	7/1/2022		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 90												
Inspection Comments:													
Sample Number:	01	Type:	R	Area:	3135.00 SqFt		PCI:	90					
Sample Comments:													
48	L & T CR		L	15.00 Ft									
57	WEATHERING		L	3135.00 SqFt									

Network:		Columbia		Name:		Columbia Gorge Regional / The Dalles Municipal							
Branch:	TCTD		Name:	Taxiway C The Dalles		Use:	TAXIWAY	Area:	18,024 SqFt				
Section:	02		of	2		From:	TC-01		To:	End	Last Const.:	1/1/1985	
Surface:	AC		Family:	2022_Eastern_Cat3_Taxiway_AC/AAC		Zone:	KDLS		Category:	K		Rank:	S
Area:	14,889 SqFt		Length:	596 Ft		Width:	25 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1985		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	7/1/2022		TotalSamples:	3		Surveyed:	2						
Conditions:	PCI: 39												
Inspection Comments:													
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI:	35			
Sample Comments:													
42	BLEEDING		N	975.00 SqFt									
48	L & T CR		L	4.00 Ft									
48	L & T CR		L	22.00 Ft									
48	L & T CR		M	22.00 Ft									
50	PATCHING		L	390.00 SqFt									
57	WEATHERING		M	4610.00 SqFt									
Sample Number:	02		Type:	R		Area:	5000.00 SqFt		PCI:	42			
Sample Comments:													
41	ALLIGATOR CR		L	16.00 SqFt									
42	BLEEDING		N	500.00 SqFt									
48	L & T CR		L	60.00 Ft									
48	L & T CR		M	57.00 Ft									
57	WEATHERING		M	5000.00 SqFt									

APPENDIX F

Work History Report

4/26/2023

Work History Report

Page 1 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 01 Surface: AC
 L.C.D. 9/2/1983 Use: APRON Rank: P Length: 195.00 (Ft) Width: 115.00 (Ft) True Area: 16167 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2012	PA-AD	Patching - AC Deep	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
6/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	ODOT CLASS C
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 02 Surface: AC
 L.C.D. 9/2/1997 Use: APRON Rank: P Length: 60.00 (Ft) Width: 60.00 (Ft) True Area: 2568 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2015	PA-AF	Patching - AC Full Depth	0.00	0.00	<input type="checkbox"/>	PMP 2015
6/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program
9/2/1997	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/1997	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 03 Surface: PCC
 L.C.D. 9/1/1997 Use: APRON Rank: P Length: 40.00 (Ft) Width: 24.00 (Ft) True Area: 1032 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/1997	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown thickness, assumed LCD

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 04 Surface: AC
 L.C.D. 9/1/2021 Use: APRON Rank: P Length: 260.00 (Ft) Width: 320.00 (Ft) True Area: 70840 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2021	MOL	Cold Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Unknown Thickness
9/2/2015	PA-AF	Patching - AC Full Depth	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/2/2012	PA-AD	Patching - AC Deep	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
7/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

4/26/2023

Work History Report

Page 2 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 05 Surface: AAC
 L.C.D. 9/1/2021 Use: APRON Rank: P Length: 305.00 (Ft) Width: 277.00 (Ft) True Area: 78753 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2021	MOL	Cold Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
9/2/2012	PA-AD	Patching - AC Deep	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
7/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1983	OL-AT	Overlay - AC Thin	0.00	2.00	<input checked="" type="checkbox"/>	ODOT CLASS C
9/2/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	
9/1/1977	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 06 Surface: PCC
 L.C.D. 9/2/1943 Use: APRON Rank: P Length: 215.00 (Ft) Width: 156.00 (Ft) True Area: 44046 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2015	PA-PP	Patching - PCC Partial Depth	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2015	CS-PC	Crack Sealing - PCC	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2012	CS-PC	Crack Sealing - PCC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2004	CS-PC	Crack Sealing - PCC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
6/2/2001	JS-LC	Joint Seal (Localized)	0.00	0.10	<input type="checkbox"/>	UNKNOWN MATERIAL; Oregon D
6/1/2001	PA-PP	Patching - PCC Partial Depth	0.00	0.00	<input type="checkbox"/>	Epoxy Mortar; Oregon DOA 2001 Ma
9/1/1988	JS-SI	Joint Seal - Silicon	0.00	0.10	<input type="checkbox"/>	
9/2/1943	NC-PC	New Construction - PCC	0.00	6.00	<input checked="" type="checkbox"/>	
9/1/1943	SB-AG	Subbase - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: A01TD Apron 01 The Dall Section: 07 Surface: AC
 L.C.D. 9/2/1983 Use: APRON Rank: P Length: 200.00 (Ft) Width: 391.00 (Ft) True Area: 83735 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
6/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	ODOT CLASS C
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

4/26/2023

Work History Report

Page 3 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi		Branch: A01TD		Apron 01 The Dall		Section: 08	Surface: AC
L.C.D. 6/3/2017	Use: APRON	Rank: P	Length: 38.00 (Ft)	Width: 70.00 (Ft)	True Area: 3027 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: A02TD		Apron 02 The Dall		Section: 01	Surface: AC
L.C.D. 9/2/1995	Use: APRON	Rank: S	Length: 435.00 (Ft)	Width: 209.00 (Ft)	True Area: 89259 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008	
6/1/2001	SS-FS	Surface Seal - Fog Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program	
9/2/1995	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/1995	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: A02TD		Apron 02 The Dall		Section: 02	Surface: AC
L.C.D. 1/1/2009	Use: APRON	Rank: S	Length: 325.00 (Ft)	Width: 50.00 (Ft)	True Area: 19288 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2009	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: R07TD		Rwy 07/25 The Da		Section: 01	Surface: AC
L.C.D. 9/2/1943	Use: RUNWAY	Rank: P	Length: 200.00 (Ft)	Width: 100.00 (Ft)	True Area: 20000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>		
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1965	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>		

4/26/2023

Work History Report

Page 4 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi Branch: R07TD Rwy 07/25 The Da Section: 02 Surface: AC
 L.C.D. 9/2/1943 Use: RUNWAY Rank: P Length: 2,327.50 (Ft) Width: 100.00 (Ft) True Area: 232750 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: R07TD Rwy 07/25 The Da Section: 03 Surface: AAC
 L.C.D. 7/1/2012 Use: RUNWAY Rank: P Length: 575.00 (Ft) Width: 100.00 (Ft) True Area: 57500 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2012	OL-AS	Overlay - AC Structural	0.00	6.50	<input checked="" type="checkbox"/>	P401
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>	
9/2/1943	NC-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: R07TD Rwy 07/25 The Da Section: 04 Surface: AC
 L.C.D. 9/2/1943 Use: RUNWAY Rank: P Length: 1,080.50 (Ft) Width: 100.00 (Ft) True Area: 108050 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/2/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

4/26/2023

Work History Report

Page 5 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi Branch: R07TD Rwy 07/25 The Da Section: 05 Surface: AC
 L.C.D. 9/2/1943 Use: RUNWAY Rank: P Length: 460.00 (Ft) Width: 100.00 (Ft) True Area: 46000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	PMP 2015
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: R13TD Runway 13/31 The Section: 01 Surface: AAC
 L.C.D. 7/1/2012 Use: RUNWAY Rank: P Length: 1,070.00 (Ft) Width: 100.00 (Ft) True Area: 107010 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2012	OL-AS	Overlay - AC Structural	0.00	6.50	<input checked="" type="checkbox"/>	P401
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi Branch: R13TD Runway 13/31 The Section: 02 Surface: AAC
 L.C.D. 7/1/2012 Use: RUNWAY Rank: P Length: 1,464.00 (Ft) Width: 100.00 (Ft) True Area: 146010 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2012	OL-AS	Overlay - AC Structural	0.00	6.50	<input checked="" type="checkbox"/>	P401
5/2/2005	ST-SS	Surface Treatment - Slurry Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/1/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1965
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>	

4/26/2023

Work History Report

Page 6 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi **Branch:** R13TD Runway 13/31 The **Section:** 03 **Surface:** AC
L.C.D. 10/4/2012 **Use:** RUNWAY **Rank:** P **Length:** 2,447.00 (Ft) **Width:** 100.00 (Ft) **True Area:** 244700 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
10/4/2012	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
10/3/2012	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
10/2/2012	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154
10/1/2012	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>	

Network: Columbia Gorge Regi **Branch:** T02TD Taxiway 02 The D **Section:** 01 **Surface:** AC
L.C.D. 6/3/2017 **Use:** TAXIWAY **Rank:** P **Length:** 50.00 (Ft) **Width:** 30.00 (Ft) **True Area:** 1768 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi **Branch:** T03TD Taxiway 03 The D **Section:** 01 **Surface:** AC
L.C.D. 6/3/2017 **Use:** TAXIWAY **Rank:** P **Length:** 50.00 (Ft) **Width:** 30.00 (Ft) **True Area:** 1768 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>	

Network: Columbia Gorge Regi **Branch:** T04TD Taxiway 04 The D **Section:** 01 **Surface:** AC
L.C.D. 6/3/2017 **Use:** TAXIWAY **Rank:** S **Length:** 75.00 (Ft) **Width:** 24.00 (Ft) **True Area:** 2068 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154

4/26/2023

Work History Report

Page 7 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi		Branch: T04TD		Taxiway 04 The D		Section: 02	Surface: AC
L.C.D. 9/2/1983	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 24.00 (Ft)	True Area: 4566 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008	
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1997	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/2/1983	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: T05TD		Taxiway 05 The D		Section: 01	Surface: AC
L.C.D. 1/1/2009	Use: TAXIWAY	Rank: S	Length: 75.00 (Ft)	Width: 35.00 (Ft)	True Area: 2625 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2009	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: T05TD		Taxiway 05 The D		Section: 02	Surface: AC
L.C.D. 9/2/1995	Use: TAXIWAY	Rank: S	Length: 646.00 (Ft)	Width: 35.00 (Ft)	True Area: 22606 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008	
6/1/2001	SS-FS	Surface Seal - Fog Seal	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program	
9/2/1995	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		
9/1/1995	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: T05TD		Taxiway 05 The D		Section: 03	Surface: AC
L.C.D. 6/3/2017	Use: TAXIWAY	Rank: S	Length: 56.00 (Ft)	Width: 35.00 (Ft)	True Area: 3033 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TA1TD		Taxiway A1 The D		Section: 01	Surface: AC
L.C.D. 11/3/2013	Use: TAXIWAY	Rank: P	Length: 230.00 (Ft)	Width: 35.00 (Ft)	True Area: 15935 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
11/3/2013	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
11/2/2013	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
11/1/2013	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

4/26/2023

Work History Report

Page 8 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi		Branch: TA2TD		Taxiway A2 The D		Section: 01	Surface: AC
L.C.D. 11/3/2013	Use: TAXIWAY	Rank: P	Length: 133.00 (Ft)	Width: 50.00 (Ft)	True Area: 6658 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
11/3/2013	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
11/2/2013	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
11/1/2013	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TA2TD		Taxiway A2 The D		Section: 02	Surface: AC
L.C.D. 6/3/2017	Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 50.00 (Ft)	True Area: 12771 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008	
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.	
6/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	DATE UNKNOWN	
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: TA3TD		Taxiway A3 The D		Section: 01	Surface: AC
L.C.D. 9/2/1943	Use: TAXIWAY	Rank: P	Length: 2,010.00 (Ft)	Width: 35.00 (Ft)	True Area: 70507 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2015	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.	
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>	circa 1965	
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>		

4/26/2023

Work History Report

Page 9 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi		Branch: TA3TD		Taxiway A3 The D		Section: 02	Surface: AAC
L.C.D. 7/1/2012	Use: TAXIWAY	Rank: P	Length: 190.00 (Ft)	Width: 35.00 (Ft)	True Area: 7481 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2012	OL-AS	Overlay - AC Structural	0.00	5.00	<input checked="" type="checkbox"/>	Oregon DOA 2004 Maint. circa 1965	
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1998	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/2/1988	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/2/1943	HI-AG	New Construction	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: TA3TD		Taxiway A3 The D		Section: 03	Surface: AC
L.C.D. 9/2/1943	Use: TAXIWAY	Rank: P	Length: 148.00 (Ft)	Width: 50.00 (Ft)	True Area: 8321 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
9/1/2012	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	PMP 2012	
9/1/2008	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	PMP 2008	
9/1/2004	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2004 Maint.	
6/1/2001	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	Oregon DOA 2001 Maint. Program	
9/1/1999	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>	DATE UNKNOWN	
9/1/1988	CS-AC	Crack Sealing - AC	0.00	0.10	<input type="checkbox"/>		
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	0.00	0.50	<input type="checkbox"/>		
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>		
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: TA3TD		Taxiway A3 The D		Section: 04	Surface: AC
L.C.D. 6/3/2017	Use: TAXIWAY	Rank: P	Length: 610.00 (Ft)	Width: 50.00 (Ft)	True Area: 31022 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TA4TD		Taxiway A4 The D		Section: 01	Surface: AC
L.C.D. 10/4/2012	Use: TAXIWAY	Rank: P	Length: 232.50 (Ft)	Width: 37.50 (Ft)	True Area: 12777 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
10/4/2012	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
10/3/2012	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
10/2/2012	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	
10/1/2012	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>		

4/26/2023

Work History Report

Page 10 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi		Branch: TATD		Taxiway A The Da		Section: 01	Surface: AC
L.C.D. 11/3/2013	Use: TAXIWAY	Rank: P	Length: 864.00 (Ft)	Width: 35.00 (Ft)	True Area: 32262 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
11/3/2013	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
11/2/2013	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
11/1/2013	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TATD		Taxiway A The Da		Section: 02	Surface: AC
L.C.D. 11/3/2013	Use: TAXIWAY	Rank: P	Length: 253.00 (Ft)	Width: 35.00 (Ft)	True Area: 12219 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
11/3/2013	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
11/2/2013	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
11/1/2013	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TATD		Taxiway A The Da		Section: 03	Surface: AC
L.C.D. 6/3/2017	Use: TAXIWAY	Rank: P	Length: 1,383.00 (Ft)	Width: 50.00 (Ft)	True Area: 69061 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	

Network: Columbia Gorge Regi		Branch: TATD		Taxiway A The Da		Section: 04	Surface: AC
L.C.D. 5/3/2014	Use: TAXIWAY	Rank: P	Length: 1,670.00 (Ft)	Width: 35.00 (Ft)	True Area: 59321 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/3/2014	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
5/2/2014	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
5/1/2014	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	
9/1/1983	BA-AG	Base Course - Aggregate	0.00	6.00	<input checked="" type="checkbox"/>		

Network: Columbia Gorge Regi		Branch: TATD		Taxiway A The Da		Section: 05	Surface: AC
L.C.D. 10/4/2012	Use: TAXIWAY	Rank: P	Length: 375.00 (Ft)	Width: 35.00 (Ft)	True Area: 12242 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
10/4/2012	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401	
10/3/2012	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209	
10/2/2012	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154	
10/1/2012	FB-TX	Geotextile	0.00	0.00	<input type="checkbox"/>		

4/26/2023

Work History Report

Page 11 of 12

Pavement Database: ODA_WOC3_4-17-2023

Network: Columbia Gorge Regi **Branch:** TBTD Taxiway B The Da **Section:** 01 **Surface:** AC
L.C.D. 9/2/1943 **Use:** TAXIWAY **Rank:** P **Length:** 800.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 43800 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2015	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	15,330.00	0.50	<input type="checkbox"/>	
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input type="checkbox"/>	

Network: Columbia Gorge Regi **Branch:** TBTD Taxiway B The Da **Section:** 02 **Surface:** AC
L.C.D. 9/1/2021 **Use:** TAXIWAY **Rank:** P **Length:** 633.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 35181 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2021	MOL	Cold Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Unknown Thickness
9/1/1965	ST-SS	Surface Treatment - Slurry Seal	12,313.35	0.50	<input type="checkbox"/>	
9/2/1943	NC-AC	New Construction - AC	0.00	2.25	<input checked="" type="checkbox"/>	
9/1/1943	BA-AG	Base Course - Aggregate	0.00	6.75	<input type="checkbox"/>	

Network: Columbia Gorge Regi **Branch:** TBTD Taxiway B The Da **Section:** 03 **Surface:** AC
L.C.D. 11/3/2013 **Use:** TAXIWAY **Rank:** P **Length:** 300.00 (Ft) **Width:** 35.00 (Ft) **True Area:** 12842 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/3/2013	NC-AC	New Construction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
11/2/2013	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
11/1/2013	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154

Network: Columbia Gorge Regi **Branch:** TCTD Taxiway C The Da **Section:** 01 **Surface:** AC
L.C.D. 6/3/2017 **Use:** TAXIWAY **Rank:** S **Length:** 128.00 (Ft) **Width:** 25.00 (Ft) **True Area:** 3135 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/3/2017	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	P401
6/2/2017	BA-AG	Base Course - Aggregate	0.00	6.00	<input type="checkbox"/>	P209
6/1/2017	SB-AG	Subbase - Aggregate	0.00	8.00	<input type="checkbox"/>	P154

Network: Columbia Gorge Regi **Branch:** TCTD Taxiway C The Da **Section:** 02 **Surface:** AC
L.C.D. 1/1/1985 **Use:** TAXIWAY **Rank:** S **Length:** 596.00 (Ft) **Width:** 25.00 (Ft) **True Area:** 14889 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1985	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Base Course - Aggregate	42	1,863,341.01	6.23	0.35
Cold Mill and Overlay	3	184,774.00	0.00	0.00
Complete Reconstruction - AC	11	384,595.00	4.00	0.00
Crack Sealing - AC	102	6,136,683.04	0.07	0.04
Crack Sealing - PCC	3	132,138.00	0.03	0.05
Geotextile	3	269,719.00	0.00	0.00
Joint Seal - Silicon	1	44,046.00	0.10	0.00
Joint Seal (Localized)	1	44,046.00	0.10	0.00
New Construction	7	542,288.00	2.25	0.00
New Construction - AC	26	913,939.01	2.42	1.18
New Construction - Initial	1	57,500.00	0.00	0.00
New Construction - PCC	2	45,078.00	3.00	3.00
Overlay - AC Structural	4	318,001.00	6.13	0.65
Overlay - AC Thin	1	78,753.00	2.00	0.00
Patching - AC Deep	3	165,760.00	0.00	0.00
Patching - AC Full Depth	2	73,408.00	0.00	0.00
Patching - PCC Partial Depth	2	88,092.00	0.00	0.00
Subbase - Aggregate	19	580,655.00	7.89	0.45
Surface Seal - Fog Seal	2	111,865.00	0.10	0.00
Surface Treatment - Slurry Seal	34	2,893,562.00	0.35	0.21