RECORD IDENTIFICATION

MAP CODE NO. DE REC ..

REPORTER

NAME LEE, W DATE 74 01 UPDATED 78 10

BY BRADLEY, R.; WALKER, G. W.

NAME AND LOCATION

DEPOSIT NAME GEIGER CREEK MINES, INC.

MINING DISTRICT/AREA/SUBDIST. BEACH AREA

COUNTRY CODE..... US COUNTRY NAME: UNITED STATES

STATE CODE..... OR STATE NAME: OREGON

COUNTY COOS

QUAD SCALE QUAD NO DR NAME BANDON

LATITUDE LONGITUDE 43-06-20N 124-22-39W

UTM NORTHING UTM EASTING UTM ZONE NO 4773250. 387900. +10

TWP..... 28S RANGE.... 14W SECTION.. 32

MERIDIAN. WILLAMETTE

LOCATION COMMENTS: SE 1/4 OF SE 1/4; 90 ACRES

COMMODITY INFORMATION
COMMODITIES PRESENT..... AU PT

DRE MATERIALS (MINERALS, ROCKS, ETC.):
HEAVY MINERALS

ANALYTICAL DATA (GENERAL)
ASSAYED 0.01 DUNCE OF GOLD AND PLATINUM A TON.

STATUS OF EXPLOR. OR DEV. 1
BY WHOM.........................JOHN GEIGER

DESCRIPTION OF DEPOSIT

DEPOSIT TYPES: BEACH PLACER

DESCRIPTION OF WORKINGS

COMMENTS (DESCRIP. OF WORKINGS):
PROPERTY WORKED BY GROUND SLUICING UNTIL PAY SANDS WERE UNDER WATER LEVEL.

PRODUCTION COMMENTS REPORTED THAT CONSIDERABLE GOLD AND PLATINUM WERE RECOVERED.

GEDLOGY AND MINERALOGY
HOST ROCK TYPES..... BLACK SANDS

GENERAL REFERENCES

- 1) DREGON METAL MINES HANDBOOK, 1940 , DDGMI BULL. 14-C, V. 1 , P. 21 22
- 2) LIBBEY, F. W., 1963 , LEST WE FORGET: ODGMI ORE BIN VOL. 25 , NO. 6 , P. 102 103

SERVE CONTRACTOR OF COMM.

CONTRACT OF STREET STREET

STORE STORE INCOME OF THE STORE STORE

TERCOTT Application to the contract of the con

(株成ので、なる) あとかる マンカン かんしょ かんしょ まる

....

GEIGER CREEK MINES, INC.

Beach Area Owner: Oregon corporation; capitalization \$5,000; C.B. Gresham, San Francisco California, President; Stuart C. McLean, Pistol River, Oregon, Sec.-Treas.; office, c/o Herbert R. Dewart, Bandon, Oregon; no production (1937 report).

The Geiger or Little mine (90 acres) is situated on the south branch of Fairy Creek, in the SEA of SEA of sec. 32, T.28 S., R.14 W.

"This property was opened in the early days by John Geiger, who worked it by ground sluicing. Some two acres of ground were worked over, and it is reported that considerable gold and platinum were recovered.

"As the workings were advanced toward the hillsides the overburden became heavier and the gold and platinum content less, until the sluicing was no longer profitable. Also, the pay sands were gradually getting below water level.

"These difficulties all contributed to the closing of the mine. In recent years several attempts have been made to work the mine, and the wrecks of numerous gold-saving devices of which much was expected may be seen on the property.

"A sample was taken from an exposure in the south end of the old workings at the foot of a 35 to 40 foot bluff. At this point the deposit is just above the water level. The sample represents 2 feet of black sand. It assayed 0.01 ounce of gold and platinum a ton". (Ref: Hornor, 18:25quoted).