

# Steel is Real



# Outline of Lecture

- How iron and steel are made
- Basic material properties of iron and steel
- Fatigue behavior of steel
- Fatigue behavior of welded steel structures
- Heat straightening of steel structures theory
- Heat straightening of steel structures practice



# What is iron (Fe)?

## Periodic Table of Elements

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1 H Hydrogen 1.00794	2 He Helium 4.002602																
3 Li Lithium 6.941	4 Be Beryllium 9.012182																
5 Na Sodium 22.98976928	6 Mg Magnesium 24.304																
7 K Potassium 39.0983	8 Ca Calcium 40.078	9 Sc Scandium 44.955912	10 Ti Titanium 47.88	11 V Vanadium 50.9415	12 Cr Chromium 51.9961	13 Mn Manganese 54.938045	14 Fe Iron 55.845	15 Co Cobalt 58.933194	16 Ni Nickel 58.6934	17 Cu Copper 63.546	18 Zn Zinc 65.38	19 Ga Gallium 69.723	20 Ge Germanium 72.64	21 As Arsenic 74.9216	22 Se Selenium 78.96	23 Br Bromine 79.904	24 Kr Krypton 83.798
25 Rb Rubidium 85.4678	26 Sr Strontium 87.62	27 Y Yttrium 88.90585	28 Zr Zirconium 91.224	29 Nb Niobium 92.90638	30 Mo Molybdenum 95.94	31 Tc Technetium 98.90625	32 Ru Ruthenium 101.07	33 Rh Rhodium 102.90550	34 Pd Palladium 106.42	35 Ag Silver 107.8682	36 Cd Cadmium 112.411	37 In Indium 114.818	38 Sn Tin 118.710	39 Sb Antimony 121.757	40 Te Tellurium 127.6	41 I Iodine 126.90545	42 Xe Xenon 131.29
53 Cs Cesium 132.90545196	54 Ba Barium 137.327	55 La Lanthanum 138.9047	56 Ce Cerium 140.116	57 Pr Praseodymium 140.90765	58 Nd Neodymium 144.242	59 Pm Promethium 144.9127	60 Sm Samarium 150.36	61 Eu Europium 151.964	62 Gd Gadolinium 157.25	63 Tb Terbium 158.92535	64 Dy Dysprosium 162.500	65 Ho Holmium 164.93032	66 Er Erbium 167.259	67 Tm Thulium 168.93041	68 Yb Ytterbium 173.054	69 Lu Lutetium 174.967	70 Hf Hafnium 178.49
87 Fr Francium [223]	88 Ra Radium [226]	89-103 Actinoids	104 Rf Rutherfordium [261]	105 Db Dubnium [262]	106 Sg Seaborgium [266]	107 Bh Bohrium [264]	108 Hs Hassium [277]	109 Mt Meitnerium [268]	110 Ds Darmstadtium [271]	111 Rg Roentgenium [272]	112 Uub Ununbium [285]	113 Uut Ununtrium [284]	114 Uuq Ununquadium [289]	115 Uup Ununpentium [288]	116 Uuh Ununhexium [292]	117 Uus Ununseptium [294]	118 Uuo Ununoctium [294]

For elements with no stable isotopes, the mass number of the isotope with the longest half-life is in parentheses.


Design and Interface Copyright © 1997 Michael Dayah (michael@dayah.com). <http://www.ptable.com/>

57 La Lanthanum 138.9047	58 Ce Cerium 140.116	59 Pr Praseodymium 140.90765	60 Nd Neodymium 144.242	61 Pm Promethium 144.9127	62 Sm Samarium 150.36	63 Eu Europium 151.964	64 Gd Gadolinium 157.25	65 Tb Terbium 158.92535	66 Dy Dysprosium 162.500	67 Ho Holmium 164.93032	68 Er Erbium 167.259	69 Tm Thulium 168.93041	70 Yb Ytterbium 173.054	71 Lu Lutetium 174.967
89 Ac Actinium [227]	90 Th Thorium 232.0377	91 Pa Protactinium 231.03688	92 U Uranium 238.02891	93 Np Neptunium [237]	94 Pu Plutonium [244]	95 Am Americium [243]	96 Cm Curium [247]	97 Bk Berkelium [247]	98 Cf Californium [251]	99 Es Einsteinium [252]	100 Fm Fermium [257]	101 Md Mendelevium [258]	102 No Nobelium [259]	103 Lr Lawrencium [262]

- Pure iron is an element on the periodic table that is a metal Fe
- Pure iron is not easily found as iron typically existing as iron oxide  $\text{Fe}_2\text{O}_3$
- Iron ore contains iron oxide, carbon (C), phosphorus (P), sulfur (S), manganese (Mn), and silicon (Si)
- The additional elements and compounds must be greatly reduced to yield a useable metal

# Iron Making

- In the blast furnace iron ore, coke and limestone are added at the top.
- Coke is a rich source of carbon made from heating coal in the absence of oxygen. It provides a reducing agent and heat for the reaction with iron oxide
- Limestone is a fluxing agent used to collect impurities
- Air/oxygen is injected below thru the tuyeres



# Iron Making: Stage 1 - Pig Iron

- After several hours of reaction the iron is removed from the bottom of the furnace
- At this point the iron ore has been reduced to pig iron
- Pig iron is still very impure and only good for making other irons and steel

Element	Periodic Symbol	Composition %
Iron	Fe	89 to 96
Carbon	C	3.5 to 4.5
Phosphorus	P	0.05 to 2.00
Sulfur	S	0.01 to 0.1
Manganese	Mn	0.5 to 2.0
Silicon	Si	0.3 to 2.0



# Pig iron is further reduced by heat to produce these common forms of iron

- Wrought iron- nearly pure iron ( less than 0.1% carbon and 2% silicon) used in architectural applications ( fences and gates)
- Ingot iron- very pure iron ( less than 0.003% carbon) used in magnets and gaskets. Very soft, low strength
- Enamelling iron – very pure iron ( 99.07% iron) used for good formability and enameling properties
- Cast iron – Alloys of Fe, C, Si and P with Fe making up 70 to 97% of the composition. Excellent casting properties including pourability and low shrinkage

# Cast Irons

- ***Gray iron*** – 3% C 2% Si 95% Fe Most widely used form of cast iron. High carbon content forms graphite flakes within microstructure which is good for vibration damping. Modest strength and poor ductility. Used in engine blocks.
- ***White iron*** – Similar chemistry but is quenched so the excess carbon does not precipitate out into graphite, but forms iron carbides. Very hard and brittle. Excellent wear resistance.
- ***Chilled iron*** – A combination of gray and white iron which produces a relatively tough core with hardened exterior surfaces. Rail road wheels and stamping shoes are made from chilled iron

# Cast Irons

- ***Malleable iron*** – White iron that has been tempered or annealed to improve ductility
- ***Ductile iron*** – Also called nodular iron. Same strength as grey iron with improved ductility due to the shape of the graphite ( round vs. string )
- ***Compacted graphite iron*** – Graphite shape is between round and string producing better ductility and thermal shock resistance than gray iron. Used for disk brake rotors and diesel engine cylinder heads
- ***Alloy iron*** – Specialized high alloy contents ( up to 30% ) make for special abrasion, corrosion and thermal shock resistance



# Summary of Cast Iron

- Excellent casting properties for making complicated shapes
- Moderate strength 25 to 90 ksi yield strength range
- Low ductility ( brittle failure ) typically less than 2% elongation
- Thermal shock, wear and corrosion resistance can be tailored for special uses
- Very difficult to weld, typically brazed if stresses allow
- Typically composed of Fe 90 to 95%, C + Si 5 to 10 %

# Solutions and Slurries

- A solution is a miscible mixture of 2 or more substances
- Solutions are homogeneous ( same composition in all parts of the mixture)
- Solutions are composed of a solvent ( main portion) and the solute (added portion)
- Solutions have physical properties in between those of the solvent and the solute

# Example Solution

- Using 1 quart of water (  $\text{H}_2\text{O}$  ) at room temperature add 2 table spoons of salt (  $\text{NaCl}$  ) and mix thoroughly
- The solid form salt dissolves completely in the water and you have a 3% salt water solution.
- The salt affects the physical properties of the water including solidification ( freezing) and boiling points

# Example Saturated Solution

- Continue to add table spoons of salt to the mixture and mixing thoroughly
- After adding approximately 22 to 23 table spoons of salt to the solution it will no longer dissolve anymore salt and the remaining salt is not in solution but solid form
- This is a 35% salt water solution and it is saturated with salt. Anymore added salt will not go into solution.
- You have liquid salt water solution with undissolved solid phase salt


# Example Slurry

- Once enough salt has been added such that it will not dissolve no matter the vigor of mixing a slurry has been created
- A slurry is a saturated liquid solution with excess solid phase solute
- In general increasing the temperature of the solvent increases the amount of solute that can be dissolved into solution, up to a point



# Solutions and Slurries

- Example Iron-Carbon-2% Silicon Phase diagram for Cast Iron
- Saturation occurs around 1.5 to 2% C
- Multiple solid phases are possible, e.g. Austenite, Ferrite and precipitated graphite
- The iron solid phases of austenite and ferrite are crystalline



# Iron into Steel


- Cast iron is a mixture in of Fe, C, and Si
- When in liquid form it is a slurry of Fe and C with Fe being the solvent and C being the solute
- More carbon is present than can be dissolved by the iron
- Excess carbon forms graphite and carbides which weaken the tensile strength and reduce ductility in most cases
- Steel does not have this extra carbon nor appreciable amounts of Si

# Making of Steel

- Taking cast iron and further reducing and refining it until the carbon content is less than 1 ½% and removing other elements to near zero steel is made
- When steel is in liquid form it is not saturated with carbon which occurs near 2% carbon 98% Fe
- Typical structural steels have 0.05 to 0.30% carbon
- Tool steels have higher carbon up to 1.2%
- Higher carbon can lead to higher strength and lower ductility

# Iron-Carbon Phase Diagram

- Steel has less than 2% carbon
- Melting temperature is near 2800 F
- Multiple solid phases are possible all of which are crystalline
- The graph is for slow cooling
- Slow cooled to room temperature yields pearlite which is a particular microstructure of steel often found in structural steel
- Fast cooling ( quenching) can have a huge effects on the type of steel microstructure you end up with





# Effects of Carbon Content on Steel

Steel Type	Carbon Content %	Typical use
Low carbon	Less than 0.20	Modest strength high ductility Structural, ease of welding
Medium carbon	0.2 to 0.6	Higher strength with retained ductility machine parts
High carbon	0.6 to 1.5	High strength, very heat treatable, low ductility tools and cutters

- Carbon addition from 0% to 1.5% in iron has a significant effect on the strength properties of the steel
- Adding carbon alone and allowing to solidify slowly increase strength and lowers ductility
- More importantly the added carbon responds to rapid cooling by forming different microstructures when solidified at service temperatures
- In general an increase in strength causes a decrease in ductility.
- Fancy alloys other than carbon can obtain both high strength and ductility



# Time-Temperature Transformation



# Heat treatment of Steel

- By choosing the appropriate carbon content and heat treatment of steel the material properties can have a very large range
- Heat treatment usually involves heating the steel up to a critical temperature ( typically 1400 F in carbon steels) which turns the solid crystalline microstructure from ferrite, pearlite, cementite, etc into austenite.
- Austenite is non magnetic which is one way to tell you are at temperature, also red-orange in color
- The carbon content and cooling rate will determine the resulting microstructure

# Heat treating steel

- Ferrite and pearlite are common structural steel microstructures which have moderate strength and good ductility. Low carbon steels often result in this type of microstructure regardless of quench rate
- Martensite is common for high strength steels. It is very brittle as quenched and must be tempered ( post heat treatment) to restore some ductility.
- Untempered martensite is very brittle and notch sensitive. It is to be avoided. Welding high carbon steels have leave such microstructures

# Summary of Steel

- A low carbon ( less than 2%) solid solution of iron and carbon
- Often heat treated to alter strengths
- Huge range of strengths available 30 to 300 ksi tensile strength
- Huge range of ductility 1% to 25%
- Excellent fatigue strength including an endurance limit
- Generally easy to fabricate with


# Engineering Properties of Steel

- Steels are typically characterized by physical testing of representative specimens
- Import tests are tensile, toughness, hardness, chemistry






# General Mechanical Loadings




# Tensile Testing is most common

Test specimen



Tensile Testing Machine




# Data presentation: Stress vs. Strain

## Force on test specimen

- The test machine applies a precisely measured tensile force to the specimen
- Engineering **Stress** is defined as the applied force divided by the reference area of specimen, typically the reduce cross sectional area

## Elongation of the test specimen


- The loaded test specimen stretches (elongates) and its elongation over a reference gage length is precisely measured
- Engineering **Strain** is defined as the measured stretch divided by the unloaded reference gage length



# Common Stresses


# Typical Tensile Test Results for Ductile Steel

- A- Proportional limit
- B- Elastic limit
- C- Yield Point
- E- Lower yield point
- F- Ultimate tensile strength
- G-Point of Failure





# High strength steel behaves differently




# Strength range of common carbon steels

Steel type	Yield Strength (ksi)	Tensile Strength (ksi)	Elongation (%)
Low carbon ASTM A36	36 to 40	58-80	22-25
Medium Carbon SAE 1045	70 to 180	85 to 265	< 11%
High Carbon SAE 1090	100-150	185-220	< 5%

# Toughness Testing

Specimens are tested at different temperature




Impact loading with falling hammer



# Charpy V-notch toughness test results

- Carbon steels have a Body-Center-Cubic BCC crystalline structure which leads to a loss of ductility at low temperatures
- Ductile steels can behave in a brittle manner at low temperatures and/ or high loading rate
- CVN toughness is measured in energy absorbed ( ft-lbf) at a given test temperature




# Hardness Testing


- Hardness testing is used to quickly assess the tensile strength of steel, especially following heat treatment
- A test machine applies a controlled load on a pointed indenter which produces a dimple in the test specimen.
- The softer the steel, the larger the indent
- Many scales exist for hardness testing depending on the material being tested
- Common hardness scales used for testing steel are Rockwell B and C, Vickers and Brinell

# Hardness Testing

- Schematic of test machine



- Deformation details of indent




# Chemical Analysis of Steel

- The chemical content of steels is commonly provided with the materials certifications when purchased
- The AWS steel welding code provides a simple equation to calculate the hardenability of steel using the Carbon Equivalent
- Steel with C.E.  $> 0.45$  needs special care when welding ( usually preheat) to prevent brittle behavior of the welded joint
- For common structural steels weldability is typically not a problem
- If in doubt add 200 to 300 F preheat before welding




# Fatigue Performance of Steel


- Metal fatigue is cumulative damage from repetitive alternating stress cycles
- The amplitude of the alternating stress is of primary importance
- The stress ratio ( max / min ) has a secondary effect
- Fatigue failures can occur at relatively low stress ranges compared to tensile strengths



# Moore Rotating Fatigue Test Machine




Test Sample




R.R. Moore Fatigue Test Machine

# Stress –Life ( S-N) Fatigue Test Data



# The S- N diagram

- Very high stress ranges produce short fatigue lives (  $N < 1000$  cycles) called low cycle fatigue
- Moderated stress ranges produce a finite fatigue life (  $1000 < N < 1,000,000$  cycles ) called high cycle fatigue
- Stress ranges below the endurance limit will yield infinite fatigue life (  $N = \text{infinite}$  )




# The Endurance Limit

- Steel is one of the few engineering materials that exhibits an endurance limit with respect to cyclic loading
- It is common to design steel components to have an infinite fatigue life
- Notches, cracks and other geometric defects can make the endurance limit disappear and cause a shortened service life
- The endurance strength of a steel is approximately 40% of the tensile strength. Higher strength steels have a higher endurance limit in general.


# Notches, sharp corners and holes

- Geometric defects such as sharp notches, corners, changes in section cause a stress concentration
- The stress field is locally magnified by these defects
- Most fatigue and brittle failure originate as these types of defects






# Example Stress Concentration






$$K_t = 2 \text{ to } 3$$




# Welding Affects Fatigue

- Welds typically aggravate the fatigue problem by adding sharp geometric features and high residual stress
- The fatigue strength of common welded details has been well tested and documented
- The tensile strength of the welded steel has little effect on the fatigue strength




# The higher the stress concentration the shorter the fatigue life




# Example Category A

( No stress concentrations or welds)







# Example Category B details




Category B - Longitudinal Full Penetration Groove Weld



Category B - Web-to-Flange Connections and Longitudinal Stiffener




Category B - Longitudinal Fillet Weld




Category B - Transverse Full Penetration Groove Weld


# Example Category B details




Category B - Traverse Groove Weld, NDI and Ground Flush



Category B - Traverse Groove Weld, Straight Transition




Category B - Transverse Groove Weld, Curved Transition




Category B - Groove-Welded Attachment, Weld Parallel to Stress


# Example Category B details




# Example Category B/details




Category B' - Longitudinal Full Penetration Groove Weld  
Backing Bar Not Removed



Category B' - Partial Penetration Groove Weld




Category B' - Partial Penetration Groove Weld Connections




Category B' - Transverse Groove Welded Connections, A514 or A517 Steel




# Example Category C details



Category C - Transverse Stiffeners on Web





Category C - Transverse Gusset Plate on Web




Category C - Transverse Groove Welded Splice, NDI but Not Ground Flush


# Example Category C details



# Example Category C details




Category C - Transverse Groove Welded Attachment,  
Weld Not Ground Flush




\* Reduction of fatigue strength if  $t > 0.5$ "

Category C - Fillet Welded Connection (Load Carrying)




Category C - Fillet Welded Connection (Non Load Carrying)




Category C - Stud Shear Connectors


# Example Category D details




Category D - Groove or Fillet Welded Attachment, Intermediate Length



Category D - Welded Gusset Plate, Intermediate Length




Category D - Welded Gusset Plate on Rolled Shape, Intermediate Length




Category D - Longitudinally Welded Attachment, Short Transition Radius

# Example Category D details





Category D - Fillet Welded Attachment,  
Transition Radius 2" or More




Category D - Riveted Connections

# Example Category E and E' details







# Example Category E and E' details



Category E - Welded Attachment,  
Very Short Transition Radius




Category E - Longitudinally Welded Attachment,  
Any Transition Radius



Category E - Intermittent Fillet Welds

# Example Category E and E' details




- Under direct stress loading only E and E' details are likely to develop cracks under common service loading




# Best and worst welded fatigue details

- Category B CJP butt weld, ground smooth




- Category E' Added cover plate



# Welded Structure Summary

- Welding when properly designed and installed will match the strength and ductility of the parent structure
- Poor design or installation practices can greatly reduce the strength and ductility of welded structures
- Most bridge and structural steels are very weldable provided good design and workmanship are included
- If the carbon content of the steel is unknown, preheat is always your friend when welding

# Distortion induced fatigue is far more common than direct loading induced fatigue



# Heat Straightening of Steel Structures






# How to get this straight again?




# Thermal expansion induced yielding

- Steel will elongate when heated if it is not constrained
- If it is prevented from elongating, compressive stresses build
- If yielding occurs, the part will shorten when cooled



# Basic heating pattern for a bent beam


- Overload caused top flange to compress and bottom flange to stretch
- Heat pattern will reverse this deformation (bottom flange is heated in a strip shape)
- Optional restraining force expedites the movement per heat cycle






# Strong and Weak Axis Repairs

Both V and Strip heat patterns are applied in successively overlapping regions



# Torsional Axis and Localized Dimpling Repairs

V, Strip and circular heat patterns are used



# FHWA has published useful guides for heat straightening

## **Heat-Straightening Repairs of Damaged Steel Bridges**

A technical Guide and Manual of Practice

FHWA-IF-99-004

October 1998

## **Guide for Heat-Straightening of Damaged Steel Bridge Members**

FHWA-IF-08-999

August 2008

FHWA and Texas DOT have sponsored  
studies on the effects of heat straightening  
bridge members multiple times

**EFFECTS OF BENDING AND HEAT ON THE DUCTILITY AND  
FRACTURE TOUGHNESS OF FLANGE PLATE**

FHWA/TX-10/0-4624-2

March 2012

# Hot Working versus Heat Straightening

## Hot working

- Steel is heated above the transition temperature ( 1400 F)
- At high temp yield strength goes down and ductility goes up
- Mechanical force is used to move the steel
- Does not rely on thermal expansion

## Heat straightening

- Steel is heated below the transition temperature ( 1200 F maximum)
- Strength is also reduced and ductility increased but to a smaller degree
- Applied forces are low and are intended to only apply constraint
- Constrained thermal expansion is used to move the steel

# Proper Heat straightening requires patience and skill

- Constraining forces ( jacks, chains, hoists and struts) are carefully applied to the member before heating in many cases
- Heat patterns are often marked out on the member as a guide
- Oxy/fuel rosebuds are used to apply localized heating
- Temperatures are typically control by experience and subtle changes in the color of the heating steel. Temp crayons and FLIR are used by novices and inspectors.
- Heats are applied and allowed to cool and then applied again and again to different areas ( 5 to 10 heats is not uncommon).

# Hot working is sometimes used

- Very localized deformations such as flange gouge can be straightened with localized hot working
- Mostly used for cosmetic repairs after the major straightening is complete
- Hot working is not used for major straightening unless a significant strength reduction in the finished member is acceptable



# Scottsburg bridge Hit April 2017



Driver walked away after being cut out of the cab



Tractor frame is bent into a U shape





# The bridge is shut down until repairs are made



# Two Stages of Repairs

- Compression post L0-U1 is severally damaged and close to buckling under dead load only
- I have straightened this particular member 4 times since 1996 so the integrity of the steel is in question and the probability of another strike or three is not small.
- After heat straightening the member must be reinforced to maintain sufficient reliability
- In 28 years of this kind of work, this is by far the closest to collapse I have witnessed

# First Straighten, then strengthen





# Myself and Darrel Thomas discussing his approach to the repairs






# Adding bracing with small jacks for restraint





# Applying V heat to the webs and strip heats to the top flange





# Cool to hand touch after heat application



# Working upper connection







# Thermal Camera View of Heat Straightening



1220 F is the highest temperature I  
witnessed



# Lower end cools while they start on the top





# Repaired and Strengthened



# Replace battens with slotted plates





# A previous hit September 2014



Another previous hit September 2006





# Other notes of interest

- Riveted steel bridge members are extremely tough and damage tolerant
- Many engineers like to get very worried about fracture critical members
- That worry may or may not be warranted when compared to the loss of a non-redundant compression member
- Compression members can act like tension members if called upon to do so
- The same cannot be said of a typical tension member under compression