

Over-Height Vehicle Collision Assessment and Repair Methodology

Tanarat Potisuk, PhD, PE, SE

Prestressed Concrete Standards Engineer






SCOPE


- Past incident
- Damage level
- Repair or replace
- Guideline development
- Reference materials


PAST INCIDENT


- State Bridge Engineer's Collection
- 21 Bridges (2007 – 2018)

















Steel Plate



Truss



PSDG



RCDG



DAMAGE LEVEL – STEEL GIRDERS

- Minor
- Moderate
- Severe

DAMAGE LEVEL – STEEL GIRDERS

- Minor - no repair or minimal repair
 - Paint scrapes
 - Small nicks or gouges
 - Small girder web out of plumb

Hwy 162 Culver Rd



DAMAGE LEVEL – STEEL GIRDERS

- Minor - no repair or minimal repair
 - Paint scrapes
 - Small nicks or gouges
 - Small girder web out of plumb

Hwy 162 Culver Rd



DAMAGE LEVEL – STEEL GIRDERS

- Moderate - repair or partial replacement
 - Moderate flange bends
 - Moderate girder web out of plumb
 - Tearing of web and flange


Morrison Ramp



DAMAGE LEVEL – STEEL GIRDERS

- Moderate - repair or partial replacement
 - Moderate flange bends
 - Moderate girder web out of plumb
 - Tearing of web and flange


Chandler Bridge



DAMAGE LEVEL – STEEL GIRDERS

SW Sagert Rd over I-5

- Severe - partial or full replacement
 - Significant web and flange bends
 - Significant girder web out of plumb
 - Extensive gouges
 - Tearing of web and flange




DAMAGE LEVEL – STEEL GIRDERS

- Severe - partial or full replacement
 - Significant web and flange bends
 - Significant girder web out of plumb
 - Extensive gouges
 - Tearing of web and flange



N Ontario IC



DAMAGE LEVEL – CONCRETE GIRDERS

- Minor
- Moderate
- Severe

DAMAGE LEVEL – CONCRETE GIRDERS

- Minor - no repair or minimal repair
 - Minor concrete spalling
 - Partially exposed rebar or strands
 - Not through cracks

Barbur Blvd over I-5



DAMAGE LEVEL – CONCRETE GIRDERS

- Minor - no repair or minimal repair
 - Minor concrete spalling
 - Partially exposed rebar or strands
 - Not through cracks

Hwy 1 over McAndrews



DAMAGE LEVEL – CONCRETE GIRDERS

- Moderate - repair or partial replacement
 - Moderate concrete spalling
 - Exposed rebar or strands
 - Through cracks
 - Less than 25%? of rebar or strands severed

Hwy 1 over McAndrews



DAMAGE LEVEL – CONCRETE GIRDERS

- Moderate - repair or partial replacement
 - Moderate concrete spalling
 - Exposed rebar or strands
 - Through cracks
 - Less than 25%? of rebar or strands severed

Boardman IC



DAMAGE LEVEL – CONCRETE GIRDERS

- Severe - partial or full replacement
 - Large area of concrete spalling
 - Exposed rebar or strands
 - Large through cracks
 - More than 25%? of rebar or strands severed

Saginaw Br



DAMAGE LEVEL – CONCRETE GIRDERS

- Severe - partial or full replacement
 - Large area of concrete spalling
 - Exposed rebar or strands
 - Large through cracks
 - More than 25%? of rebar or strands severed


Hwy 37 over Hwy 102 at Banks



DAMAGE LEVEL – CONCRETE GIRDERS

- Severe - partial or full replacement

Hwy 37 over Hwy 102 at Banks



INCIDENT RESPONSE



INCIDENT RESPONSE

Hwy 37 over Hwy 102 at Banks




Call
Engineer


INCIDENT RESPONSE

- Detour
- Partial or full closure
- Cleanup
- Catching net
- Shoring

DETOUR



CLOSURE



CLOSURE



CLOSURE



INCIDENT RESPONSE

- Detour
- Partial or full closure
- Cleanup
- Catching net
- Shoring

Conventional Reinforced
Concrete or Steel
vs
Prestressed Concrete

SHORING

Conventional Reinforced
Concrete or Steel
VS
Prestressed Concrete




SHORING

Hwy 37 over Hwy 102 at Banks

RCDG or Steel vs PSDG




Bending
Moment



BENDING MOMENT

Concrete – Strong in Compression, Weak in Tension




SHORING

Hwy 37 over Hwy 102 at Banks

RCDG or Steel vs PSDG



Bending
Moment



SHORING

RCDG or Steel vs PSDG



Bending
Moment




Shear



SHORING


RCDG or Steel vs PSDG



Bending
Moment




Shear




SHORING


RCDG or Steel vs PSDG



Bending
Moment



Shear



PAST INCIDENT – SHORING RCDG

Hwy 37 over Hwy 102 at MP 49.09

- 2016
- Banks













SHORING



SHORING



DAMAGE ASSESSMENT



Geometric Properties



	Gross Conc.	Trans (n=8.80)
Area (in ²)	756.5	793.0
Inertia (in ⁴)	94660.8	110349.6
y _t (in)	12.6	13.5
y _b (in)	23.9	23.0
S _t (in ³)	7533.5	8148.6
S _b (in ³)	3955.0	4806.6

Crack Spacing

$$2 \times \text{dist} + 0.1 d_b / \rho$$

Loading (N,M,V + dN,dM,dV)

0.0, -0.0, 0.0 + 0.0, 1.0, 0.0



All dimensions in inches
 Clear cover to transverse reinforcement = 1.50 in





PosBendSection

TP

2016/7/8

REPAIR OPTION – CONCRETE GIRDERS



SECTION A-A
Scale: 3/4"=1'-0"





REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch

REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch



REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch




REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch



REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch



REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch
- Splicing rebar, mechanical couplers
- Splicing prestressed strands, GRABB-IT

REPAIR OPTION – CONCRETE GIRDERS

- Preloading
- Effectiveness of patch
- Splicing rebar, mechanical couplers
- Splicing prestressed strands, **GRABB-IT**



GRABB-IT® CABLE SPLICE									
SUGGESTED INSTALLATION TORQUE VALUES									
STEM SIZE 3/4" (19.05mm) NOM. DIA. 3/4" (19.05mm)									
STRESS AREA 3780 IN² (243.7 CM²) GRADE 70									
CABLE									
TORQUE VALUES									
CABLE DIA.	70% ULTIMATE STRENGTH (LBS)	80% ULTIMATE STRENGTH (LBS)	90% ULTIMATE STRENGTH (LBS)	100% ULTIMATE STRENGTH (LBS)	110% ULTIMATE STRENGTH (LBS)	120% ULTIMATE STRENGTH (LBS)	130% ULTIMATE STRENGTH (LBS)	140% ULTIMATE STRENGTH (LBS)	150% ULTIMATE STRENGTH (LBS)
3/8"	14000	20000	15175	131					
7/16"	18500	27000	2126	177					
1/2"	25200	36500	2835	236					
3/8"	16100	23000	1811	151					
7/16"	21700	31000	2441	203					
1/2"	28700	41800	3232	271					

GRABB-IT® CABLE SPLICE									
SUGGESTED INSTALLATION TORQUE VALUES									
STEM SIZE 3/4" (19.05mm) NOM. DIA. 3/4" (19.05mm)									
STRESS AREA 3780 IN² (243.7 CM²) GRADE 70									
CABLE									
TORQUE VALUES									
CABLE DIA.	70% ULTIMATE STRENGTH (LBS)	80% ULTIMATE STRENGTH (LBS)	90% ULTIMATE STRENGTH (LBS)	100% ULTIMATE STRENGTH (LBS)	110% ULTIMATE STRENGTH (LBS)	120% ULTIMATE STRENGTH (LBS)	130% ULTIMATE STRENGTH (LBS)	140% ULTIMATE STRENGTH (LBS)	150% ULTIMATE STRENGTH (LBS)
3/8"	14000	20000	15175	131					
7/16"	18500	27000	2126	177					
1/2"	25200	36500	2835	236					
3/8"	16100	23000	1811	151					
7/16"	21700	31000	2441	203					
1/2"	28700	41800	3232	271					

GRABB-IT® CABLE SPLICE									
SUGGESTED INSTALLATION TORQUE VALUES									
STEM SIZE 3/4" (19.05mm) NOM. DIA. 3/4" (19.05mm)									
STRESS AREA 3780 IN² (243.7 CM²) GRADE 70									
CABLE									
TORQUE VALUES									
LOAD (LBS)	PROV. TENSILE (LBS)	100% (LBS)	110% (LBS)	120% (LBS)	130% (LBS)	140% (LBS)	150% (LBS)	160% (LBS)	170% (LBS)
1000	105000	33000	113	09					
2000	105000	33000	225	19					
3000	105000	33000	338	28					
4000	105000	33000	450	38					
5000	105000	33000	563	47					
10000	105000	33000	1125	94					
15000	105000	33000	1688	141					
20000	105000	33000	2250	188					
25000	105000	33000	2813	234					
30000	105000	33000	3375	281					
35000	105000	33000	3938	328					
40000	105000	33000	4500	375					
45000	105000	33000	5063	422					
50000	105000	33000	5625	469					

REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan




REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan




REPLACE OPTION – CONCRETE GIRDERS

- Cutout girders
- Formwork
- Falsework
- Closure pour plan



REPLACE OPTION – CONCRETE GIRDERS


- Cutout girders
- Formwork
- Falsework
- Closure pour plan



PAST INCIDENT – REPLACED RCDG

Saginaw Bridge

- 2008
- South of Eugene









PAST INCIDENT – REPLACED RCDG






REPAIR OPTION – STEEL GIRDERS

- Localized repair or replacement
- Flame straightening
- Hot mechanical straightening
- Cold mechanical straightening

PAST INCIDENT – REPAIR BY BOLTING

Chandler Bridge

- 2013
- Coos Bay













PAST INCIDENT – REPAIR BY BOLTING



PAST INCIDENT – REPAIR THEN REPLACED

N Ontario Interchange

- 2007
- Ontario








IMPACT POINT

7/8 INCH WIDE CRACK

BR# 08635 GIRDER 1 SPAN 3 PRIOR TO REPAIR







PAST INCIDENT – REPAIR THEN REPLACED

N ONTARIO I/C
BR# 20398 HWY 455 MP 25.20
RT ELEV 10/27/08
IM20398_A1.jpg



OTHER STATE AGENCIES

- Washing State DOT
- Iowa DOT
- Pennsylvania DOT
- Texas DOT
- Virginia DOT

WORK TO BE DONE

- Emergency Operations Plan
- Bridge Inspection Program Manual
- Bridge Design Manual
- Coordination with Crash Data Unit

REFERENCES

- NCHRP Report 226
- NCHRP Report 271
- NCHRP Report 280
- NCHRP 20-07 Task 307
- NCHRP Report 678
- Iowa DOT Emergency Response Manual



?

or

Comments



SB I-5 at MP 149
Equipment Pass