

State Department of Geology and Mineral Industries

1069 State Office Building
Portland 1, Oregon

MEMO

MIRIAM OIL COMPANY BLIVEN #3
(Permit #29)

Location: Approximately 70 feet east of well #1.

I made an inspection of the well site on Friday afternoon, November 1, 1957. The annular space between the surface casing and open hole was found to be filled with hard cement at the surface. Mr. Thornhill reported that about 20 feet of cement was drilled out from the inside of the casing when drilling was resumed (This indicates that the annular space between the surface casing and open hole is filled with cement from top to bottom).

It was also noted that a (150 psi test?) gate valve was flanged to the surface pipe for blow out prevention.

Report by: Vernon C. Newton, Jr.
Petroleum Engineer

Date: November 1, 1957