

## Oregon Seismic Status Report - 2016



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Klamath County

County: KLAMATH

Contact Name: Justin Azevedo

Contact Email: azevedoj2@kcsd.k12.or.us

**Structures Replaced?** Yes

Name and Address: Henley Elementary School 8227 Highway 39 Klamath Falls, Oregon 97603

Kind of Structure: New School

Type of Replacement: Tilt - Up and Steel Structure

Max Occupancy: 520

Date Occupied:

**Structures Modified?** No

Name and Address:

Kind of Structure:

Type of Modification:

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*


Cost of Rehab:

Method of Funding:

Local School Bond

Notes:

## Oregon Seismic Status Report - 2016



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Klamath County

County: KLAMATH

Contact Name: Justin Azevedo

Contact Email: azevedoj2@kcsd.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Henley Middle School 7925 Highway 39 Klamath Falls, Oregon 97603

Kind of Structure: Main Building and Hallways

Type of Modification: Ceiling tile grid and HVAC piping updates were completed

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Local School Bond

Notes: