

Oregon Seismic Status Report -



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Medford 549C

County: JACKSON

Contact Name: Ron Havniear

Contact Email: ron.havniear@medford.k12.or.us

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of
Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Howard Elementary 286 Mace Rd, Medford, OR 97501

Kind of Structure: Howard
Classrooms 21-32, the gymnasium/stage, cafeteria . All of the
above structures were upgraded to life safety standards. The
gymnasium was upgraded to immediate occupancy standards.

Type of Modification:
See Notes section below.

Date Re-occupied: 08/27/2018

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab: Howard
\$1,498,690


Method of Funding: Seismic Rehabilitation Grant Program

Notes:

- Structural reinforcement	- New Sheathing and Additional Nailing
- HTT4 Tension Ties (Roof To Walls)	- Blocking Throughout
- Steel Columns and Spandrels (Gym/Cafeteria)	
- Drag Beams Added	
- Windows removed/Shear walls added	
- Lighting/Ceiling Grid Braced	
- Duct Work Braced	

Submission Date: 09/13/18 12:37 PM

Oregon Seismic Status Report -



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Medford 549C

County: JACKSON

Contact Name: Ron Havniear

Contact Email: ron.havniear@medford.k12.or.us

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of
Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Griffin Creek Elementary 2430 Griffin Creek Rd, Medford, OR 97501

Kind of Structure: Griffin Creek
Classrooms - 9-20, The Media Center, The Music Room, The Office Area, Staff Work Room and Staff Break Room were all upgraded to life safety standards.

Type of Modification: See Notes section below.

Date Re-occupied: 08/27/18

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab: Griffin Creek
\$1,498,160

Method of Funding: Seismic Rehabilitation Grant Program

Notes:

- Griffin Creek
- Structural reinforcement
- HTT4 Tension Ties (Roof To Walls)
- Multiple X - Braces
- Drag Beams Added
- Windows removed/Shear walls added
- Lighting/Ceiling Grid Braced
- Duct Work Braced
- Seismic Gap Added Between Buildings and Walkways
- New Sheathing and Additional Nailing
- Blocking Throughout

Submission Date: 09/13/18 12:35 PM