

Oregon Seismic Status Report - 2019



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Medford 549C

County: JACKSON

Contact Name: Ron Havniear

Contact Email: ron.havniear@medford.k12.or.us

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of
Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: 2323 Siskiyou Blvd, Medford, Or 97504

Kind of Structure: All buildings on the site were modified.

Type of Modification: Gym and cafeteria were upgraded to immediate occupancy standards. All other buildings were upgraded to life safety standards. Work included moment frames, brackets, fasteners, roof nailing patterns, drag beams, awnings, footings, structural reinforcement, shear walls, etc.

Date Re-occupied: 08/19/19

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab: \$2,000,000

Method of Funding: SRGP Grant - \$1.5M; District Capital Funding - ~\$500,00

Notes: