

# Corvallis Fire Station #3

City of Corvallis

Bent\_fir04A

Building Type Fire - City	County Benton	
Street 1310 NW Circle Blvd		
City Corvallis	State OR	Zip 97330
Latitude 44.58837	Longitude 123.26738	
Tracking Code RVS in 2006	Inspection Date 6/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Corvallis Fire Station #3

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Corvallis Fire Station #3

Bent\_fir04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:U shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
			
N	General Site out-of-plane lateral system	S	Primary Structural Type
E	Vertical Irregularity Primary	E	Vertical Irregularity Primary
			
E	Vertical Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries