


Building Type	County	
EOC-Public Safety Answering P	Benton	
Street		
200 Cascade Hall		
City	State	Zip
Corvallis	OR	97331
Latitude		Longitude
44.56148		123.27531
Tracking Code		Inspection Date
RVS in 2006		6/26/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	-1.5	-0.5	0	0	0	-0.6	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

OSP - OSU Campus

Final RVS Score

Final Type


Final Score

S2

0.4

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Primary Structural Type
brace behind glass



S Other
old / new connection



SW Plan Irregularity Primary



SE General Site



S Vertical Irregularity Primary