

Estacada RFPD

Clac_fir19A

Estacada RFPD

Building Type		County	
Fire - RFPD		Clackamas	
Street			
261 Se 5th Ave			
City	State	Zip	
Estacada	OR	97023	
Latitude		Longitude	
45.28595		122.33321	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	0	0	0	-0.6	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Estacada RFPD

Final RVS Score

Final Type

Final Score

PC1

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1964	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
9225	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site