

Canby Fire District 62

Canby RFPD

Clac_fir48A

| | | | |
|-----------------|-------|-----------------|--|
| Building Type | | County | |
| Fire - RFPD | | Clackamas | |
| Street | | | |
| 26815 S Hwy 170 | | | |
| City | State | Zip | |
| Canby | OR | 97013 | |
| Latitude | | Longitude | |
| 45.2188 | | 122.67931 | |
| Tracking Code | | Inspection Date | |
| Hasenberg 02 | | 9/15/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.2 | 0 | 0 | 0 | 0 | -0.4 | 0 | 0 | 2.8 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Canby Fire District 62

Final RVS Score

Final Type

Final Score

S3

2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|----------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| <input type="text"/> | <input type="text"/> | 1985 | <input type="text"/> |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 3700 | 1 | No | No |

| | |
|----------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |

| | |
|----------------------|----------------------|
| Falling Hazards | Poor Conditions |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |



S General Site