

Estacada RFPD

Clac_fir50A

Estacada RFPD

Building Type	County	
Fire - RFPD	Clackamas	
Street		
40595 SE George Rd		
City	State	Zip
Estacada	OR	97023
Latitude	Longitude	
45.2985	122.24487	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	-0.2	0	0	5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Estacada RFPD

Final RVS Score

Final Type

Final Score

W1

5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1976	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2200	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site

