

Canby Police Dept

City of Canby

Clac_pol08A

Building Type		County	
Police - City		Clackamas	
Street			
122 N Holly St			
City	State	Zip	
Canby	OR	97013	
Latitude		Longitude	
45.26275		122.6938	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	0	0	-0.2	0	-0.4	0	0	1.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canby Police Dept

Final RVS Score

Final Type

Final Score

URM

1.2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1920	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5600	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site