

Ogden Middle School

Oregon City SD 62

Clac_sch50A

Building Type	County	
School	Clackamas	
Street		
14133 S Donovan Rd		
City	State	Zip
Oregon City	OR	97045
Latitude	Longitude	
45.35617	122.57603	
Tracking Code	Inspection Date	
RVS in 2006	12/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ogden Middle School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Ogden Middle School

Clac_sch50A

Enrollment 663	Year Built (Field Verified) 1965	Year Built (Alt. Source) 1965	Est. Decade Built 1970
Total Area (square ft) 100370	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
 NE Elevation View		 NE Vertical Irregularity Primary	
 N Primary Structural Type		 N Primary Structural Type	
 S Falling Hazard		 S Falling Hazard	

Ogden Middle School

Oregon City SD 62

Clac_sch50B

Building Type School	County Clackamas	
Street 14133 S Donovan Rd		
City Oregon City	State OR	Zip 97045
Latitude 45.35622	Longitude 122.57667	
Tracking Code RVS in 2006	Inspection Date 12/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Ogden Middle School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Ogden Middle School

Clac_sch50B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
663	1966	1965	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
100370	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		Cracks	
Unreinforced Chimneys		None	
None		None	
			
NW Vertical Irregularity Primary	W Poor Condition	W Plan Irregularity Primary	
			
W Falling Hazard	SW Vertical Irregularity Primary	SE Plan Irregularity Tertiary	
			
S Field Verified Year Built 1966			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries