

# Ninety-One School

Canby SD 86

Clac\_sch56A

Building Type	County	
School	Clackamas	
Street		
5811 S Whiskey Hill Rd		
City	State	Zip
Hubbard	OR	97032
Latitude	Longitude	
45.17686	122.74707	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ninety-One School

## Final RVS Score

Final Type	Final Score
W2	3

## FEMA-154 Collapse Potential

Low (<1%)

# Ninety-One School

Clac\_sch56A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
516		1945	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
89957	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Ninety-One School

Clac\_sch56A



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries