

Canby High School

Canby SD 86

Clac_sch66A

Building Type	County
School	Clackamas
Street	
721 Sw 4th Ave	
City	State Zip
Canby	OR 97013
Latitude	Longitude
45.25693	122.6985
Tracking Code	Inspection Date
Hasenberg 02	9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Canby High School

Final RVS Score

Final Type	Final Score
C2	2.2

FEMA-154 Collapse Potential

Low (<1%)

Canby High School

Clac_sch66A

Enrollment 1695	Year Built (Field Verified) 1929	Year Built (Alt. Source) 1929	Est. Decade Built
Total Area (square ft) 210170	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Canby High School

Clac_sch66A



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries