

Bolton Primary School

West Linn-Wilsonville SD 3J

Clac_sch82A

Building Type		County	
School		Clackamas	
Street			
5933 Holmes St			
City	State	Zip	
West Linn	OR	97068	
Latitude		Longitude	
45.36992		122.619	
Tracking Code		Inspection Date	
RVS in 2006		12/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Bolton Primary School

Final RVS Score

Final Type

Final Score

RM1

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
328	1950	1955	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55718	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
Other: Brick Veneer	None
None	None



S Secondary Structural Type



S Building Name

S Field Verified Year Built
1950 and interior brick

S Secondary Structural Type



NW Falling Hazard




E Vertical Irregularity Secondary

Bolton Primary School

West Linn-Wilsonville SD 3J

Clac_sch82B

Building Type		County	
School		Clackamas	
Street			
5933 Holmes St			
City	State	Zip	
West Linn	OR	97068	
Latitude		Longitude	
45.37003		122.61844	
Tracking Code		Inspection Date	
RVS in 2006		12/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Bolton Primary School

Final RVS Score

Final Type

Final Score

RM1

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
328		1955	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55718	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



NW Plan Irregularity Primary



E Vertical Irregularity Primary