

# Walter L Kraxberger Middle School

Gladstone SD 115

Clac\_sch90A

Building Type		County	
School		Clackamas	
Street			
17777 Webster Rd			
City	State	Zip	
Gladstone	OR	97027	
Latitude		Longitude	
45.39408		122.58669	
Tracking Code		Inspection Date	
RVS in 2006		12/22/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Walter L Kraxberger Middle School

## Final RVS Score

Final Type

Final Score

RM1

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
676		1969	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
76000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



E Primary Structural Type  
kla-all type brick



SE General Site



NE Vertical Irregularity Primary



NW Plan Irregularity Secondary



SW Vertical Irregularity Secondary



# Walter L Kraxberger Middle School

Clac\_sch90B

Gladstone SD 115

Building Type		County	
School		Clackamas	
Street			
17777 Webster Rd			
City	State	Zip	
Gladstone	OR	97027	
Latitude		Longitude	
45.39425		122.58612	
Tracking Code		Inspection Date	
RVS in 2006		12/22/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary	S2	3	-1.5	-0.5	0	0	0	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Walter L Kraxberger Middle School

## Final RVS Score

Final Type

Final Score

S2

1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
676		1969	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
76000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Elevation View



NE Elevation View



NE Plan Irregularity Primary



NW Vertical Irregularity Primary

Gladstone SD 115

A photograph of a large, modern, rectangular building with a flat roof and several windows, situated on a grassy area with trees in the background. The building is light-colored and has a minimalist design. It is surrounded by a green lawn and some trees, with a paved area in the foreground.

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
676		1969	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
76000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
Other: Light Cladding	None
None	None
None	None



S Primary Structural Type  
caulked vert jts and cladding



SW Plan Irregularity Primary



# Walter L Kraxberger Middle School

Gladstone SD 115

Clac\_sch90D

Building Type		County	
School		Clackamas	
Street			
17777 Webster Rd			
City	State	Zip	
Gladstone	OR	97027	
Latitude		Longitude	
45.39367		122.58702	
Tracking Code		Inspection Date	
RVS in 2006		12/22/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Walter L Kraxberger Middle School

## Final RVS Score

Final Type

Final Score

RM1

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
676		1969	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
76000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Primary Structural Type



S Pounding Potential

