

Knappa Svensen RFPD

Clat_fir09A

Knappa Fire District

Building Type		County	
Fire - RFPD		Clatsop	
Street			
43114 Hillcrest Lp			
City	State	Zip	
Knappa	OR	97103	
Latitude		Longitude	
46.16745		123.58369	
Tracking Code		Inspection Date	
RVS in 2006		9/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	-0.4	0	0	5.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Knappa Svensen RFPD

Final RVS Score

Final Type

Final Score

W2

5.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
Torsion: Eccentric Stiffness	None
None	None


Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View



S Plan Irregularity Primary



SW Primary Structural Type



E Elevation View



NE General Site

