

# Providence Seaside Hospital

Providence Health System - Oregon NFP

Clat\_hos02A

Building Type	County	
Hospital	Clatsop	
Street		
725 S Wahanna Rd		
City	State	Zip
Seaside	OR	97138
Latitude	Longitude	
45.98904	123.91198	
Tracking Code	Inspection Date	
RVS in 2006	9/13/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Providence Seaside Hospital

## Final RVS Score

Final Type	Final Score
S1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Providence Seaside Hospital

Clat\_hos02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: Brick Veneer		None	
None		None	
			
NE Elevation View		SW Primary Structural Type	
		SE Plan Irregularity Secondary	
		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Providence Seaside Hospital

Providence Health System - Oregon NFP

Clat\_hos02B

Building Type	County	
Hospital	Clatsop	
Street		
725 S Wahanna Rd		
City	State	Zip
Seaside	OR	97138
Latitude	Longitude	
45.98883	123.91221	
Tracking Code	Inspection Date	
RVS in 2006	9/13/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Providence Seaside Hospital

Final RVS Score

Final Type	Final Score
S1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Providence Seaside Hospital

Clat\_hos02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built		
			1960		
Total Area (square ft)	Number of Stories	Basement	Pounding Potential		
	2	No	Yes		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)			
Reentrant Corners: Other (Adjacent Build/Entity)		Building On Hill or Sloped Site			
None		None			
Falling Hazards		Poor Conditions			
Other: Brick Veneer		None			
None		None			
None		None			
	SE Vertical Irregularity Secondary		W Elevation View		NW Plan Irregularity Primary
	NW Elevation View		SW Plan Irregularity Secondary		SW Falling Hazard
	N Elevation View 96 bldg lower part of photo		NW Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries