

Seaside High School

Clat_sch07A

Seaside SD 10

Building Type	County	
School	Clatsop	
Street		
1901 N Holladay Dr		
City	State	Zip
Seaside	OR	97138
Latitude	Longitude	
46.00625	123.91692	
Tracking Code	Inspection Date	
RVS in 2006	9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seaside High School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Seaside High School

Clat_sch07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
521	1958	1958	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94256	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
None	None

Falling Hazards	Poor Conditions
Other: Light Cladding	None
Unreinforced Chimneys	None
None	None



N Building Name



SW Elevation View



NW Plan Irregularity Primary



W Elevation View



SW Elevation View



SE Primary Structural Type



W Plan Irregularity Primary



SW Elevation View



SE Elevation View



NW Plan Irregularity Secondary



E Plan Irregularity Primary



SE Falling Hazard



S Elevation View



E Plan Irregularity Secondary



NW Vertical Irregularity Secondary



NW Elevation View



SW Vertical Irregularity Secondary

Seaside High School

Seaside SD 10

Clat_sch07B

Building Type		County	
School		Clatsop	
Street			
1901 N Holladay Dr			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
46.00575		123.91638	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	-1.5	-0.5	0	0	-0.4	0	0	0.6
Secondary	S1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9

Seaside High School

Final RVS Score

Final Type

Final Score

S2

0.6

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
521		1958	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94256	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Elevation View



SW Primary Structural Type



W Primary Structural Type



NE Elevation View



NW Plan Irregularity Primary



Seaside High School

Seaside SD 10

Clat_sch07C

Building Type		County	
School		Clatsop	
Street			
1901 N Holladay Dr			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
46.0062		123.91648	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seaside High School

Final RVS Score

Final Type

Final Score

C2

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
521		1958	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94256	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	None
None	None
None	None


Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



N Primary Structural Type



NW Number of Stories



Seaside High School

Seaside SD 10

Clat_sch07D

Building Type		County	
School		Clatsop	
Street			
1901 N Holladay Dr			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
46.0067		123.91666	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seaside High School

Final RVS Score

Final Type

Final Score

C2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
521		1958	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94256	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Primary Structural Type



SE Vertical Irregularity Primary



SE Plan Irregularity Primary



NE Vertical Irregularity Primary



NE Vertical Irregularity Primary



NW Vertical Irregularity Secondary



Seaside High School

Seaside SD 10

Clat_sch07E

Building Type		County	
School		Clatsop	
Street			
1901 N Holladay Dr			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
46.0068		123.91736	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seaside High School

Final RVS Score

Final Type

Final Score

W2

5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
521		1958	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94256	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
Other: Light Cladding	None
None	None
None	None



W Elevation View



S Elevation View

