


# Col R F&R Fire Station - Fairgrounds

Columbia River Fire & Rescue

Colu\_fir02A

Building Type	County
Fire - RFPD	Columbia
Street	
58798 Saulser Rd	
City	State Zip
St Helens	OR 97051
Latitude	Longitude
45.84902	122.87208
Tracking Code	Inspection Date
RVS in 2006	9/21/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Fairgrounds

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Col R F&R Fire Station - Fairgrounds

Colu\_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1975	1975	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: 2 to 3 Changes	
Lateral-Force-Resistance in One Direction Only		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Vertical Irregularity Primary		SE Elevation View	
		NE Plan Irregularity Primary	
			
NW Plan Irregularity Primary		SW Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries