

Col R F&R Fire Station - Maintenance

Colu_fir05A

Columbia River Fire & Rescue

Building Type		County	
Fire - RFPD		Columbia	
Street			
58555 McNulty Wy			
City	State	Zip	
St Helens	OR	97051	
Latitude		Longitude	
45.84489		122.83081	
Tracking Code		Inspection Date	
RVS in 2006		9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Maintenance

Final RVS Score

Final Type

Final Score

S3

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Col R F&R Fire Station - Maintenance

Colu_fir05A


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	Internal Discontinuous Diaphragm (large internal opening)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Primary Structural Type



SW Other



N Elevation View