

Scappoose RFPD

Scappoose RFPD

Colu_fir09A

Building Type Fire - RFPD	County Columbia	
Street 52751 Columbia River Hwy		
City Scappoose	State OR	Zip 97056
Latitude 45.76138	Longitude 122.87908	
Tracking Code RVS in 2006	Inspection Date 9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scappoose RFPD

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built		
	1988	1988	1980		
Total Area (square ft)	Number of Stories	Basement	Pounding Potential		
	2	No	No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes			
Lateral-Force-Resistance in One Direction Only		None			
None		None			
Falling Hazards		Poor Conditions			
None		None			
None		None			
None		None			
	E Primary Structural Type		NE Plan Irregularity Primary		NW Elevation View
	SW Field Verified Year Built 1988				