

Prosper Hall

Southwest Oregon CC

Coos_coc03A

Building Type Community_College	County Coos
Street 1988 Newmark Ave	
City Coos Bay	State Zip OR 97420
Latitude 43.39483	Longitude 124.25138
Tracking Code Miller 2004-05	Inspection Date 7/14/2005

Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Prosper Hall


Final RVS Score

Final Type
C2

Final Score
0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Prosper Hall

Coos_coc03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1967	1967	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
25835	3	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)			
None			
None			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries