

Newmark Center

Southwest Oregon CC

Coos_coc09A

| | | |
|-------------------|-----------------|-------|
| Building Type | County | |
| Community_College | Coos | |
| Street | | |
| 1988 Newmark Ave. | | |
| City | State | Zip |
| Coos Bay | OR | 97420 |
| Latitude | Longitude | |
| 43.39191 | 124.251 | |
| Tracking Code | Inspection Date | |
| New Building | 3/1/2007 | |

Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Newmark Center


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



Directory by Building

- | | |
|--------------------|--------------------------------|
| 1. DELLWOOD HALL | 23. OFFICES |
| 2. STENSLAND | 24. SOCCER FIELD |
| 3. RANDOLPH HALL | 25. GUARD SHACK |
| 4. EMPIRE HALL/ | 26. PLANT SERVICES / MAINT. |
| PERF. ARTS CENTER | 27. FAMILY CENTER / CHILD CARE |
| 5. TIOGA HALL | 28. NEWMARK CENTER |
| 6. SITKUM HALL | 29. NORTH HEAD |
| 7. COALEDO HALL | 30. LIGHTHOUSE DEPOT |
| 8. EDEN HALL | 31. ST. GEORGE REEF |
| 9. LAMPA HALL | 32. CAPE BLANCO |
| 10. B-2 | 33. COQUILLE RIVER |
| 11. SUNSET HALL | 34. CAPE ARAGO |
| 12. SUMNER HALL | 35. UMPQUA RIVER |
| 13. FAIRVIEW HALL | 36. HECETA HEAD |
| 14. TENNIS COURTS | 37. YAQUINA HEAD |
| 15. FIELD HOUSE | 38. CAPE MEARES |
| 16. FIRE SCIENCE | 39. TILLAMOOK ROCK |
| 17. BASEBALL FIELD | 40. POINT ADAMS |
| 18. FIRE TOWER | 41. DESDEMONA SANDS |
| 19. SOFTBALL FIELD | 42. WARRIOR ROCK |
| 20. PROSPER HALL | 43. WILLAMETTE RIVER |
| 21. UMPQUA HALL | 44. VOLLEYBALL COURT |
| 22. B-3 STORAGE | 45. BASKETBALL COURT |

Directory by Code

- | | |
|------------------------|---------------------|
| STEN- Stensland | EMPH- Empire Hall |
| NEW- Newmark Center | RAND- Randolph Hall |
| SITK- Sitkum Hall | TIOG- Tioga Hall |
| SUMN- Sumner Hall | UMPQ- Umpqua Hall |
| EDEN- Eden | FLD- Field |
| COAL- Coaledo | B3- B3 Storage |
| PROS- Prosper Hall Gym | SUNS- Sunset Hall |
| FAIR- Fairview Hall | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------------|-----------------------------------|---------------------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| <input type="text"/> | <input type="text" value="1996"/> | <input type="text" value="1996"/> | <input type="text"/> |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| <input type="text"/> | <input type="text"/> | <input type="text" value="No"/> | <input type="text" value="No"/> |

| | |
|----------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |

| | |
|----------------------|----------------------|
| Falling Hazards | Poor Conditions |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |