

Stensland Hall

Southwest Oregon CC

Coos_coc10A

Building Type Community_College	County Coos
Street 1988 Newmark Ave.	
City Coos Bay	State Zip OR 97420
Latitude 43.39442	Longitude 124.25368
Tracking Code New Building	Inspection Date 3/1/2007

Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Stensland Hall

Final RVS Score

Final Type	Final Score
------------	-------------

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1995	1995	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	