

# Bandon RFPD

Bandon RFPD

Coos\_fir09A

Building Type Fire - RFPD	County Coos	
Street 555 Hwy 1010		
City Bandon	State OR	Zip 97411
Latitude 43.11717	Longitude 124.41381	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bandon RFPD

## Final RVS Score

Final Type	Final Score
W1	3.9

## FEMA-154 Collapse Potential

Low (<1%)

Bandon RFPD 8  
555 Hwy 101  
Bandon, OR 97411



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1969	1969	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Vertical Irregularity Primary	W	Field Verified Year Built

