

Myrtle Point Police Department

City of Myrtle Point

Coos_pol08A

Building Type	County
EOC-Public Safety Answering P	Coos
Street	
424 5th St	
City	State Zip
Myrtle Point	OR 97458
Latitude	Longitude
43.06393	124.1424
Tracking Code	Inspection Date
RVS in 2006	8/10/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Point Police Department

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Myrtle Point Police Department

Coos_pol08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1924	1924	1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		Cracks	
None		None	
None		None	
			
NW Plan Irregularity Primary		N Falling Hazard	
			
W Vertical Irregularity Primary		S General Site	
			
E Field Verified Year Built		S Poor Condition These cracks are all over the building.	