

Myrtle Crest School

Myrtle Point SD 41

Coos_sch10A

Building Type		County	
School		Coos	
Street			
903 Myrtle Crest Ln			
City	State	Zip	
Myrtle Point	OR	97458	
Latitude		Longitude	
43.06008		124.13101	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9

Myrtle Crest School

Final RVS Score

Final Type

Final Score

C2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
344		1945	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
72000	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Myrtle Crest School

Myrtle Point SD 41

Coos_sch10B

Building Type		County	
School		Coos	
Street			
903 Myrtle Crest Ln			
City	State	Zip	
Myrtle Point	OR	97458	
Latitude		Longitude	
43.06056		124.13099	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Crest School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
344		1945	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
72000	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
Out of Plane Lateral-Force-Resistance Elements	None
Non-Parallel System	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



NW General Site



N Plan Irregularity Primary



N Plan Irregularity Secondary



N Falling Hazard



E Plan Irregularity Tertiary



S Basement



W Vertical Irregularity Primary

Myrtle Crest School

Myrtle Point SD 41

Coos_sch10C

Building Type		County	
School		Coos	
Street			
903 Myrtle Crest Ln			
City	State	Zip	
Myrtle Point	OR	97458	
Latitude		Longitude	
43.05963		124.13093	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Crest School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
344		1945	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
72000	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Plan Irregularity Primary



SW General Site



Myrtle Crest School

Myrtle Point SD 41

Coos_sch10D

Building Type		County	
School		Coos	
Street			
903 Myrtle Crest Ln			
City	State	Zip	
Myrtle Point	OR	97458	
Latitude		Longitude	
43.05965		124.13057	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	0	0	2.4	0	0	0	4.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Crest School

Final RVS Score

Final Type

Final Score

W1

4.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
344		1945	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
72000	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

