

# Harbor Lights Middle School

Bandon SD 54

Coos\_sch12A

Building Type		County	
School		Coos	
Street			
390 SW 9th St			
City	State	Zip	
Bandon	OR	97411	
Latitude		Longitude	
43.11565		124.41943	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harbor Lights Middle School

## Final RVS Score

Final Type

Final Score

W2

3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
240		1957	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
37235	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW General Site

# Harbor Lights Middle School

Bandon SD 54

Coos\_sch12B

Building Type		County	
School		Coos	
Street			
390 SW 9th St			
City	State	Zip	
Bandon	OR	97411	
Latitude		Longitude	
43.11582		124.41874	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Secondary	C2	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

Harbor Lights Middle School

## Final RVS Score

Final Type

Final Score

C2

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
240		1957	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
37235	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Vertical Irregularity Primary



NW Secondary Structural Type



NW Plan Irregularity Primary

