

Pacific Child Care Center

North Bend SD 13

Coos_sch23A

| | | |
|-----------------|-----------------|-------|
| Building Type | County | |
| School | Coos | |
| Street | | |
| 2345 Marion St. | | |
| City | State | Zip |
| North Bend | OR | 97459 |
| Latitude | Longitude | |
| 43.40223 | 124.23619 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 8/18/2006 | |



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 4.4 | -2.5 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.4 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pacific Child Care Center

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 1.4 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pacific Child Care Center

Coos_sch23A

| | | | |
|--|-----------------------------|---|---------------------------|
| Enrollment 12 | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built 1970 |
| Total Area (square ft) | Number of Stories 2 | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: L Shaped | | Building On Hill or Sloped Site | |
| Torsion: Eccentric Stiffness | | Vertical Change in Structural Type (Soft over Stiff) | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| N Vertical Irregularity Primary sloped site | | E General Site | |
|  | | E Seismic Upgrade Building was settling on the east side and this footing was placed. Most of the soil at this site looks like a fine sand. | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries