

Pioneer Memorial Hospital - Prineville

NFP - Pioneer

Croo_hos01A

Building Type Hospital	County Crook	
Street 1201 NE Elm St		
City Prineville	State OR	Zip 97754
Latitude 44.31024	Longitude 120.84332	
Tracking Code RVS in 2006	Inspection Date 7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	RM1	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Tertiary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1

Pioneer Memorial Hospital - Prineville

Final RVS Score

Final Type C2	Final Score -0.5
------------------	---------------------

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Memorial Hospital - Prineville

Croo_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Smokestack		None	
None		None	
None		None	
			
E Elevation View		E Plan Irregularity Primary	
		NE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Memorial Hospital - Prineville

NFP - Pioneer

Croo_hos01B

Building Type Hospital	County Crook	
Street 1201 NE Elm St		
City Prineville	State OR	Zip 97754
Latitude 44.31031	Longitude 120.84279	
Tracking Code RVS in 2006	Inspection Date 7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Pioneer Memorial Hospital - Prineville

Final RVS Score

Final Type C2	Final Score -0.1
------------------	---------------------

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Memorial Hospital - Prineville

Croo_hos01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:T shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Vertical Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Memorial Hospital - Prineville

NFP - Pioneer

Croo_hos01C

Building Type Hospital	County Crook	
Street 1201 NE Elm St		
City Prineville	State OR	Zip 97754
Latitude 44.31002	Longitude 120.84371	
Tracking Code RVS in 2006	Inspection Date 7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Tertiary	C1	3	-2	0	0	0	0	-1	0	0

Pioneer Memorial Hospital - Prineville

Final RVS Score

Final Type C1	Final Score 0
------------------	------------------

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Memorial Hospital - Prineville

Croo_hos01C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW General Site		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries