

Cape Ferrelo RFPD

Curr_fir05A

Cape Ferrelo RFPD

Building Type		County	
Fire - RFPD		Curry	
Street			
96349 Cape Ferrelo Rd.			
City	State	Zip	
Brookings	OR	97415	
Latitude	Longitude		
42.12583	124.32287		
Tracking Code	Inspection Date		
RVS in 2006	8/4/2006		



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Tertiary		0	0	0	0	0	0	0	0	0

Cape Ferrelo RFPD

Final RVS Score

Final Type

Final Score

S3

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Out of Plane Lateral-Force-Resistance Elements	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Secondary Structural Type



N Plan Irregularity Secondary



SW Vertical Irregularity Primary