

Agness Elementary School

Central Curry SD 1

Curr_sch01A

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Curry | |
| Street 3925 Cougar Ln. | | |
| City Agness | State OR | Zip 97406 |
| Latitude 42.55561 | Longitude 124.06784 | |
| Tracking Code RVS in 2006 | Inspection Date 8/4/2006 | |



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 4.4 | 0 | -0.5 | 0 | 0 | 0 | 0 | 0 | 3.9 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Agness Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 3.9 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Agness Elementary School

Curr_sch01A

| | | | |
|---|-------------------------------------|---|---------------------------|
| Enrollment 8 | Year Built (Field Verified) 1939 | Year Built (Alt. Source) 1930 | Est. Decade Built 1930 |
| Total Area (square ft) 4000 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | | | |
| NW Plan Irregularity Primary | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries