

# Blanco School

Port Orford-Langlois SD 2CJ

Curr\_sch07A

Building Type	County
School	Curry
Street	
48241 Hwy 101	
City	State Zip
Langlois	OR 97450
Latitude	Longitude
42.92168	124.44866
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Blanco School

## Final RVS Score

Final Type	Final Score
W2	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



Oregon Geology

# Blanco School

Curr\_sch07A

Enrollment 105	Year Built (Field Verified) 1939	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 27044	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
SW Plan Irregularity Primary	SW Vertical Irregularity Primary		
		N General Site	
			
N Falling Hazard	E Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries