


Pioneer Hall

Central Oregon CC

Desc_coc10A

| | | | |
|---------------------|-------|-----------------|--|
| Building Type | | County | |
| Community_College | | Deschutes | |
| Street | | | |
| 2600 NW College Way | | | |
| City | State | Zip | |
| Bend | OR | 97701 | |
| Latitude | | Longitude | |
| 44.07253 | | 121.34654 | |
| Tracking Code | | Inspection Date | |
| Missed | | 3/1/2007 | |

| | | | | | | | | | | | | |
|--|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------------|------------|-------------|
| Seismicity Zone: Moderate | | | | | | | | | | Pioneer Hall | | |
| FEMA 154 Rapid Visual Screening Score Card | | | | | | | | | | Final RVS Score | | |
| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score | Final Type | Final Score |
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | | |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | | |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | | |
| FEMA-154 Collapse Potential | | | | | | | | | | High (>10%) | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | 1976 | 1976 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 24752 | 2 | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |