

Redmond - College Center

Desc_coc14A

Central Oregon CC

Building Type	County	
Community_College	Deschutes	
Street		
2030 SE College Loop		
City	State	Zip
Redmond	OR	97756
Latitude		Longitude
44.25679		121.16626
Tracking Code		Inspection Date
New Building		3/1/2007

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redmond - College Center


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1997	1997	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
11311	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions

