

Central Oregon CC

| | | |
|------------------------------------|-----------------------------|--------------|
| Building Type Community_College | County Deschutes | |
| Street 2030 SE College Loop | | |
| City Redmond | State OR | Zip 97756 |
| Latitude 44.25502 | Longitude 121.16544 | |
| Tracking Code New Building | Inspection Date 3/1/2007 | |

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Redmond - MATL


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

| | | | |
|------------------------------------|-----------------------------------|-----------------------------------|---------------------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| <input type="text"/> | <input type="text" value="2001"/> | <input type="text" value="2001"/> | <input type="text"/> |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| <input type="text" value="27000"/> | <input type="text" value="1"/> | <input type="text" value="No"/> | <input type="text" value="No"/> |
| Plan Irregularities | | Vertical Irregularities | |
| <input type="text"/> | | <input type="text"/> | |
| <input type="text"/> | | <input type="text"/> | |
| <input type="text"/> | | <input type="text"/> | |
| Falling Hazards | | Poor Conditions | |
| <input type="text"/> | | <input type="text"/> | |
| <input type="text"/> | | <input type="text"/> | |
| <input type="text"/> | | <input type="text"/> | |