

# Sisters-Camp Sherman RFPD

Desc\_fir05A

Sisters/Camp Sherman RFPD

Building Type		County	
Fire - RFPD		Deschutes	
Street			
301 S Elm			
City	State	Zip	
Sisters	OR	97759	
Latitude		Longitude	
44.28942		121.55033	
Tracking Code		Inspection Date	
RVS in 2006		6/27/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	0	-0.2	0	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sisters-Camp Sherman RFPD

## Final RVS Score

Final Type

Final Score

W1

1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Vertical Irregularity Primary



E Elevation View



# Sisters-Camp Sherman RFPD

Desc\_fir05B

Sisters/Camp Sherman RFPD

Building Type		County	
Fire - RFPD		Deschutes	
Street			
301 S Elm			
City	State	Zip	
Sisters	OR	97759	
Latitude		Longitude	
44.28929		121.55043	
Tracking Code		Inspection Date	
RVS in 2006		6/27/2006	

Seismicity Zone: Moderate											Sisters-Camp Sherman RFPD	
FEMA 154 Rapid Visual Screening Score Card											Final RVS Score	
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	W1	5.2	-3.5	-0.5	0	0	-0.2	0	0	1	W1	1
Secondary		0	0	0	0	0	0	0	0	0		
Tertiary		0	0	0	0	0	0	0	0	0		
											FEMA-154 Collapse Potential	
											High (>10%)	



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7576	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	Steps in Elevation View: Single Change
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

